

PROCESSOR TYPE All

CR04-A0001 CODE: F

DEC-72 - PROBLEM: This is a DEC distribution of vendor ECO's : Documentation #EO-2091, 2099, and 3000. Card stacking problems with model M200 card readers in low humidity environments.

CORRECTION: Add new stacker plates.

In-plant effectivity -02 phase-in

Field effectivity -Retrofit all CR10-F, CR11, CR12-F, CR15-F, CR8-F, CR8/I-F with serial numbers under 720400.

(Time To Install And Test .5 Hour.) (Kit Contents -FCO/Prints And Parts)

CR04-B0002 CODE: F

JAN-73 - PROBLEM: This is a DEC distribution of a vendor ECO : Documentation #EO-2009. Picking problems may occur under low humidity operation.

CORRECTION: Add new raffle cap and follower.

NOTE: For DEC SYSTEM-10, reference FCO CR10-A0009.

In-plant effectivity -03 retrofit

Field effectivity -Retrofit all CD11's, CR15-D's and CR15-E's, M1000's and M1200's, with serial numbers under 720400.

(Time To Install And Test 1.0 Hour.) (Kit Contents -FCO/Prints And Parts)

CR04-B0003 CODE: F

JAN-73 - PROBLEM: This is a DEC distribution of a vendor ECO : Documentation #EO-2009. Picking problems may occur under low humidity operation.

CORRECTION: Add new raffle cap and follower.

NOTE: For DEC SYSTEM-10, reference FCO CR10-A0009.

In-plant effectivity -03 retrofit all CD11 and CR8/I-F. Retrofit CR11 as required.

Field effectivity -Retrofit all CD11's, CR8/I-F, CR8/F and CR15-F, M200's, with serial numbers under 720400. Retrofit CR11's as required.

(Time To Install And Test 1.0 Hour.) (Kit Contents -FCO/Prints And Parts)

CR04-B0004 CODE: F

JAN-73 - PROBLEM: This is a DEC distribution of a vendor ECO : Documentation #EO-2009. Last card may not pick when using new raffle cap.

CORRECTION: Add new input follower.

NOTE: FCO CR10-A0009, which adds a new raffle cap, is a prerequisite to this FCO.

In-plant effectivity -03 retrofit

Field effectivity -Retrofit all CR10-D's and CR10-E's, M1000's and M1200's, with serial numbers under 720400.

(Time To Install And Test .5 Hour.) (Kit Contents -FCO/Prints And Parts)

CR04-B0005 CODE: F

JAN-73 - PROBLEM: This is a DEC distribution of a vendor ECO : Documentation #EO-2009. Last card may not pick when using new raffle cap.

CORRECTION: Add new input follower.

NOTE: FCO CR10-A0009, which adds a new raffle cap, is a prerequisite to this FCO.

In-plant effectivity -03 retrofit

Field effectivity -Retrofit all CR10-F's, M200's, with serial numbers under 720400.

(Time To Install And Test .5 Hour.) (Kit Contents -FCO/Prints And Parts)

CR04-E0006 CODE: F

MAY-73 - PROBLEM: This is a DEC distribution of a vendor FCO : Documentation ECO #00000896. Drive motor shutdown may be desired.

CORRECTION: Rewire so that drive motors shutdown when last card is read.

In-plant effectivity -Install at customer request.

Field effectivity -Optional: Install only at customer request on CR04-H and CR04-J.

(Time To Install And Test 1.0 Hour.) (Documentation \$ 5.00 , Parts \$ 45.00 , DEC Labor -See Note) NOTE: The DEC on-site labor charge will be the time required to install and test the FCO at the current hourly rate. (Kit Contents -FCO/Prints And Parts)

CR04-B0007 CODE: F

MAY-73 - CORRECTION: This is a DEC distribution of a vendor ECO, Documentation ECO M/L1140769J K1. Changes the blower motor capacitor from 10 ufd, 365 volts to 10 ufd, 370 volts; the new part required is Documentation #45F276.

In-plant effectivity -None

Field effectivity -Retrofit all 230 volt, 50 Hz CRO4's with serial number below 7301001.

(Time To Install And Test .5 Hour.) (Kit Contents -FCO/Prints And Parts)

CR04-E0008 CODE: F

MAY-73 - CORRECTION: This is a DEC distribution of a vendor ECO : Documentation ECO #101393-01. It shuts off drive motors after the last card has been read. This FCO is applicable to CR04-E, CR04-F, CR10-D, and CR15-D.

In-plant effectivity -None

Field effectivity -Optional; install only at customer request.

(Time To Install And Test 1.0 Hour.) (Documentation \$ 5.00 , Parts \$ 30.00) The DEC on-site labor charge will be the time required to install and test the FCO at the then current hourly rate. (Kit Contents -FCO/Prints And Parts)

CR04-E0009 CODE: F

MAY-73 - CORRECTION: This is a DEC distribution of a vendor ECO : Documentation ECO #00000895. It shuts off drive motors after the last card has been read. This FCO is applicable to CR04-A, CR04-B, CR04-C, CR04-D, CR8-F, CR8/I-F, CR10-F, CR11, CR12-F, and CR15-F.

In-plant effectivity -None

Field effectivity -Optional; install only at customer request.

(Time To Install And Test 1.0 Hour.) (Documentation \$ 5.00 , Parts \$ 15.00)

the DEC on-site labor charge will be the time required to install and test the FCO at the then current hourly rate. (Kit Contents --FCO/Prints And Parts)