DIGITAL SOFTWARE NEWS

FOR THE

PDP-8 & PDP-12

Software Information Service Digital Equipment Corporation Maynard, Massachusetts 01754

DIGITAL SOFTWARE NEWS FOR THE PDP-8 AND THE PDP-12

Digital Software News for the PDP-8 & PDP-12 is designed to provide users of PDP-8 and PDP-12 software with up to date information on software problems, programming notes, and new and revised software. Each article, other than announcements and documentation corrections, is coded sequentially by system program in the lower right corner for ease in maintaining a quick reference file. The original material for such a file is supplied in the Software Performance Summary for the PDP-8 & PDP-12. This publication which is placed in each basic software kit, is a collection of all current information on known software problems, patches, and programming notes. As new versions correct software problems and obsolete patches, and reprinted manuals include programming notes and manual corrections, new articles in the Digital Software News will announce the revised software and specify by code which article should be removed from your Software Performance Summary file. Articles may also be replaced when new information becomes available; such as, procedure to circumvent a problem may replace the original report of the problem. All articles in the Digital Software News which should be added to your file will be appropriately coded.

Any questions or problems on the articles contained in these publications or concerning the use of Digital's software should be reported to the Software Specialist or Sales Engineer at your nearest Digital Office.

Additional copies of the current <u>Software Performance Summary</u> and updated issues of the PDP-8 and PDP-12 software price lists are available at no charge upon request from the Software Distribution Center. As with usual orders for software, the Software Distribution Center will accept orders received directly from U.S. customers. All other customer orders must be routed through the nearest Digital Representative.

PDP-8 & PDP-12 DIGITAL SOFTWARE NEWS

OCTOBER 1972

TABLE OF CONTENTS

	<u>C0</u>	DE
SPECIAL NOTE OS/8 PIP		
EduSystem SOFTWARE Loading Instruction for systems with Hardware Bootstraps	EDUSYSTEM	2
OS/8 LOADER (DEL-S8-OLIDA-A) Patch to correct the two-page buffer allocation algorithm	OS/8 LOADER	1
RTPS FORTRAN IV Patch to enable support of a 12% characters/line line printer	RTPS FORTRAN	16
RTPS FORTRAN IV Patch for error with Unformatted Writes	RTPS FORTRAN	17
TSS/8 INIT Correction to prevent improper loading of INIT tape	TSS/8	1

SPECIAL NOTE:

OS/8 PIP

Erroneous Address in published patch

An article OS/8PIP 1 in this newsletter concerning a correction to OS/8 PIP was previously published. The patch was to correct a problem in compressing files with the TD8E system. Unfortunately, the address was printed incorrectly. The patch indicated that location 51352 was to be altered from \emptyset 177 to \emptyset 171. That should be location 15352.

The correct patch follows:

. GET SYS PIP

· ODT

15276/762Ø 764Ø

15352/Ø177 Ø171

↑C

• SAVE SYS PIP

EduSystem PDP-8 SOFTWARE

Loading Instructions for Systems with Hardware Bootstraps

Users who have as part of their EduSystem configuration, an item called a Hardware Bootstrap, should note the following instructions to be followed during loading procedures:

- A. Loading from PAPER TAPE (high or low speed):
 - 1. Set SR to 5356
 - 2. Flip "SW" key on console panel.
- B. Loading from DISC (DF32 or RF08)
 - Set SR to 5350
 - 2. Flip "SW" key on console panel.
- C. Loading from DECTAPE (TC01 or TC08)
 - 1. Set SR to 0600
 - 2. Flip "SW" switch on console panel.

The above instructions replace that portion of the loading routine which includes the RIM loader, in the existing manuals.

OS/8 LOADER (DEC-S8-OLLDA-A)

Patch to correct the two-page buffer allocation algorithm

This problem can cause errors when doing I/O with two-page handlers at run-time. The following ODT patch will correct this problem:

```
.GET SYS LOADER
ODT.
Ø1312/UNUSED 1765
Ø1313/UNUSED
             71Ø6
Ø1314/UNUSED 762Ø
Ø1315/UNUSED 5321
Ø1316/UNUSED 1326
Ø1317/UNUSED 3254
Ø132Ø/UNUSED 5262
Ø1321/UNUSED 1765
Ø1322/UNUSED 62Ø1
Ø1323/UNUSED 6212
Ø1324/UNUSED 5725
Ø1325/UNUSED 7474
Ø1326/UNUSED 1321
17472/13,51
              62Ø2
17473/6201
              5752
17552/UNUSED 1312
```

1 C

.SAVE SYS LOADER

RTPS FORTRAN IV

Patch to enable support of a 120 characters/line line printer

The RTPS FORTRAN IV run-time system can support an OS/8 compatible 120 character/line line printer by adding the following patch to FORIO.SV:

LOCATION	OLD CONTENTS	NEW CONTENTS
2571	7660	7610

After changing the location, run EZGEN as usual to include the new line printer handler.

RTPS FORTRAN IV

Patch for error with Unformatted Writes

When performing an unformatted write from a buffer starting at location 7400 of any field, RTPS FORTRAN causes an error. This problem is independent of loader allocation of requested files. Because users generally do not know where their buffers are, the following patch is suggested for those who have lengthy programs and/or several devices declared at load time (D option) requiring unformatted writes. Add the patch using EPIC as follows:

```
.R EPIC
*FORRTS.FT </1$
                           /Edit FORRTS.FT
R, 342
                           /Read block 34
0,1472
                           /Open location 147
2356/5366
                           /Change it to 5366
0,1662
                           /Open location 166
XXXX/2356 →
                           /Change it to 2356
XXXX77000 →
                           /Change 167 to 7000
XXXX/2354 →
                          /Change 170 to 2354
XXXX/7000 ->
                          /Change 171 to 7000
XXXX/5351,
                           /Change 172 to 5351
WV
                           /Write the block
EV
                           /Exit EPIC edit
*AC
                           /Return to OS/8
```

Note: → means type LINE FEED:

means type RETURN

\$ means type ALTMODE

TSS/8 INIT

Correction to prevent improper loading of INIT tape

INIT contains it's own binary loader for TSS/8 building purposes; therefore, attempting to load it into the same field as the binary loader will cause the binary loader to be overlayed and hence "crash". To load INIT properly, use the binary loader in a field other than the field into which you wish to load INIT.

REGISTER HERE FOR DEC SOFT WARE INFORMATION

A new mailing list is being established to provide better service to readers of $\underline{Digital}$ Software \underline{News} .

THIS TECHNICAL PUBLICATION IS DESIGNED FOR ACTUAL USERS OF DEC COMPUTERS.

TO BE PLACED ON THE NEW MAILING LIST, YOU MUST COMPLETE

DIGITAL SOFTWARE NEWS CONTAINS:

ANNOUNCEMENTS OF NEW AND REVISED SOFTWARE SOFTWARE PROBLEM REPORTS AND PATCHES SPECIAL PROGRAMMING NOTES

AND RETURN THE FOLLOWING POSTAGE PAID FORM.

USER'S NAME	
COMPANY NAME	
DEPARTMEN	VT
FULL MAILING ADDRESS	
	ZIP CODE
	THE SERIAL NUMBER FOR MY PDP-12 ISIS