



# Desktop Board VC820 Specification Update

Release Date: May 2001

Order Number: 738244-009

The Intel® Desktop Board VC820 may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are documented in this Specification Update.

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. INTEL PRODUCTS ARE NOT INTENDED FOR USE IN MEDICAL, LIFE SAVING, OR LIFE SUSTAINING APPLICATIONS.

Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights.

Intel retains the right to make changes to specifications and product descriptions at any time, without notice.

The VC820 desktop board may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications before placing your product order.

\* Third party brands and names are the property of their respective owners.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature, may be obtained from:

Intel Corporation  
P.O. Box 5937  
Denver, CO 80217-9808

or call in North America 1-800-548-4725, Europe 44-0-1793-431-155, France 44-0-1793-421-777,

Germany 44-0-1793-421-333, other Countries 708-296-9333

Copyright © 2001, Intel Corporation. All rights reserved.

# CONTENTS

REVISION HISTORY .....v

PREFACE .....vi

## **Specification Update for Intel® Desktop Boards VC820**

GENERAL INFORMATION .....3

SPECIFICATION CHANGES .....5

ERRATA.....9

DOCUMENTATION CHANGES .....10



## REVISION HISTORY

Date of Revision	Version	Description
November 1999	-001	This document is the first Specification Update for the Intel® Desktop Board VC820.
December 1999	-002	Updated revision level tables in the General Information section.
April 2000	-003	Added Specification Changes 1.
August 2000	-004	Added Specification Change 2 and Document Change 1.
September 2000	-005	Added Erratum 1.
October 2000	-006	Added Documentation Changes 2,3.
February 2001	-007	Removed BIOS/Errata cross reference table, Added Erratum 2.
April 2001	-008	Added Documentation Change 4.
May 2001	-009	Added Erratum 3.

## PREFACE

This document is an update to the specifications contained in the *Intel® Desktop Board VC820 Technical Product Specification* (Order number 737611). It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools. It will contain Specification Changes, Errata, Specification Clarifications, and Documentation Changes.

Refer to the *Pentium® III Processor Specification Update* (Order number 244453) for specification updates concerning the Pentium III processor. Items contained in the *Pentium III Processor Specification Update* that either do not apply to the VC820 desktop board or have been worked around are noted in this document. Otherwise, it should be assumed that any processor errata for a given stepping are applicable to the PBA revision(s) associated with that stepping.

Refer to the *Intel® Celeron™ Processor Specification Update* (Order number 243748) for specification updates concerning the Intel Celeron processor. Items contained in the *Intel Celeron Processor Specification Update* that either do not apply to the Desktop Board VC820 or have been worked around are noted in this document. Otherwise, it should be assumed that any processor errata for a given stepping are applicable to the PBA revision(s) associated with that stepping.

Refer to the *Intel® 82820 Chipset: 82820 Memory Controller Hub (MCH) Specification Update* (Order Number 290630) for specification updates concerning the 82820 MCH Controller. Items contained in the *82820 MCH Specification Update* that either do not apply to the VC820 desktop board or have been worked around are noted in this document. Otherwise, it should be assumed that any MCH errata for a given stepping are applicable to the PBA revision(s) associated with that stepping.

Refer to the *Intel® 82801 I/O Controller Hub (ICH) Specification Update* (Order Number 290677) for specification updates concerning the 82801 I/O Controller Hub. Items contained in the *Intel 82801 ICH Specification Update* that either do not apply to the VC820 desktop board or have been worked around are noted in this document. Otherwise, it should be assumed that any ICH errata for a given stepping are applicable to the Printed Board Assembly (PBA) revision(s) associated with that stepping.

Refer to the *Intel® 82802 Firmware Hub (FWH) Specification Update* (Order Number TBD) for specification updates concerning the 82802 Firmware Hub. Items contained in the *Intel 82802 FWH Specification Update* that either do not apply to the VC820 desktop board or have been worked around are noted in this document. Otherwise, it should be assumed that any ICH errata for a given stepping are applicable to the Printed Board Assembly (PBA) revision(s) associated with that stepping.

## Nomenclature

**Specification Changes** are modifications to the current published specifications. These changes will be incorporated in the next release of the specifications.

**Errata** are design defects or errors. Characterized errata may cause the VC820 desktop board's behavior to deviate from published specifications. Hardware and software designed to be used with any given Printed Board Assembly (PBA) and BIOS revision level must assume that all errata documented for that PBA and BIOS revision level are present on all desktop boards.

**Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.

**Documentation Changes** include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.

**Specification Update for  
Intel® Desktop Boards VC820**



## GENERAL INFORMATION

**Basic Intel® Desktop Board VC820 Identification Information**

AA Revision	PBA Revision	BIOS Revision	Notes
744044-401	744045-401	VC82010A.86A.0014.P03	1-7
744044-402	744045-402	VC82010A.86A.0014.P03	1-7
744044-403	744045-403	VC82010A.86A.0016.P04	1-7
744044-407	744045-407	VC82010A.86A.0031.P11	1-7
744044-408	744045-408	VC82010A.86A.0036.P16	1-7

**NOTES:**

1. The PBA number or AA number is found on a small label on the component side of the board.
2. The 82820 Chipset kit used on this PBA revision consists of three components as follows:

Device	Stepping	S-Spec Numbers
82820 MCH	B1	SL3FT
82801AA ICH	B1	SL3MA
82802AB FWH	A0	SB48

3. The following errata are contained in the *Pentium® III Processor Specification Update* (Order Number 244453) for the Pentium III processor and either do not apply to the Desktop Board VC820 or have been worked-around in this PBA and/or BIOS revision: 3. All other errata associated with the processor apply to this PBA revision.
4. The following errata are contained in the *Intel® Celeron™ Processor Specification Update* (Order Number 243748) for the Celeron processor and either do not apply to the Desktop Board VC820 or have been worked-around in this PBA and/or BIOS revision: None. All other errata associated with the processor apply to this PBA revision.
5. The following items are contained in the *Intel® 82820 Memory Controller Hub (MCH) Specification Update* (Order Number 290630) and either do not apply to the Desktop Board VC820 or have been worked around in this PBA and/or BIOS revision: None. All other errata associated with the MCH apply to this PBA revision.
6. The following items are contained in the *Intel® 82801 I/O Controller Hub Specification Update* (Order Number 290677) and either do not apply to the Desktop Board VC820 or have been worked around in this PBA and/or BIOS revision: None. All other errata associated with the ICH apply to this PBA revision.
7. The following items are contained in the *Intel® 82802 Firmware Hub Specification Update* (Order Number TBD) and either do not apply to the Desktop Board VC820 or have been worked around in this PBA and/or BIOS revision: None. All other errata associated with the FWH apply to this PBA revision.

## Summary Table of Changes

The following table indicates the Specification Changes, Errata, Specification Clarifications, or Documentation Changes which apply to the VC820 desktop board. Intel intends to fix some of the errata in a future revision of the desktop board, and to account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

### CODES USED IN SUMMARY TABLE

Doc:	Document change or update that will be implemented.
Fix:	This erratum is intended to be fixed in a future revision of the desktop board, driver, or BIOS.
Fixed:	This erratum has been previously fixed.
NoFix:	There are no plans to fix this erratum.
Shaded:	This erratum is either new or modified from the previous version of the document.

NO.	PLANS	SPECIFICATION CHANGES
1	Doc	Diagnostic LED display changes
2	Doc	Addition of new feature, fast booting systems with Intel® Rapid BIOS BOOT
NO.	PLANS	ERRATA
1	Fix	Some SCSI host bus adapters may not boot to the hard disk drive with a bootable CD-ROM drive attached
2	Fixed	A heavily loaded PCI bus may cause excessive noise on the NMI signal to the processor
3	Fixed	Intel® Pentium® III processor Erratum E76
NO.	PLANS	DOCUMENTATION CHANGES
1	Doc	Change to description of BIOS main menu memory option
2	Doc	Change to description of section 1.6.4, Real-Time Clock, CMOS SRAM, and Battery
3	Doc	Change to description of Section 4.4.4.1, IDE Configuration Sub-Submenus
4	Doc	Change to description of Section 1.5.2, Memory Features

## SPECIFICATION CHANGES

The Specification Changes listed in this section apply to the *VC820 Motherboard Technical Product Specification* (Order Number 737611). All Specification Changes will be incorporated into a future version of that specification.

### 1. Diagnostic LED Display Changes

In Section 5.6, Enhanced Diagnostics, Table 85 will be updated to reflect the following changes of the diagnostic LED's.

**Table 85. Diagnostic LED Codes**

Display		BIOS Operation	Display		BIOS Operation
	Amber Amber Amber Amber	Power on, starting BIOS		Amber Amber Amber Green	Undefined
	Green Amber Amber Amber	Recovery mode		Green Amber Amber Green	Undefined
	Amber Green Amber Amber	Processor, cache, etc.		Amber Green Amber Green	Undefined
	Green Green Amber Amber	Memory, auto-size, shadow, etc.		Green Green Amber Green	Undefined
	Amber Amber Green Amber	PCI bus initialization		Amber Amber Green Green	Undefined
	Green Amber Green Amber	Video		Green Amber Green Green	Undefined
	Amber Green Green Amber	IDE bus initialization		Amber Green Green Green	Reserved
	Green Green Green Amber	USB initialization		Green Green Green Green	Booting operating system

## **2. *Addition of New Feature, Fast Booting Systems With Intel® Rapid BIOS Boot***

Section 3.8, Overview of BIOS Features will be added. All subsequent sections will be renumbered accordingly:

### **3.8 *Fast Booting Systems with Intel Rapid BIOS Boot***

There are three factors that affect system boot speed:

- Selecting and configuring peripherals properly
- Using an optimized BIOS, such as the Intel® Rapid BIOS
- Selecting a compatible operating system

The BIOS is not configured by default to boot at the fastest possible speed. Empirical measurements have shown that some Intel® Desktop boards, when optimized as described above, can complete POST (Power On Self Test) in six seconds or less and boot to an active Microsoft Windows\* Millennium (Me) operating system in 21 seconds.

In addition to the appliance-like speed that benefits end users, fast booting systems can also increase an OEM's manufacturing line throughput.

#### **3.8.1 Peripheral Selection and Configuration**

The following techniques will help improve system boot speed:

- Choose a hard drive with parameters, such as a "power-up to data ready" of less than eight seconds which will minimize hard drive startup delays. The Western Digital Caviar AA or BA series are examples of drives that meet this parameter.
- Select a CD-ROM drive with a fast initialization rate; variations can influence POST times.
- Eliminate unnecessary features such as video-company-logo displaying, screen repaints, or mode changes. These all add time in the boot process. The Plug and Play communication between the video BIOS and the monitor shows time variances.
- Try different monitors. Some monitors initialize more quickly, thereby enabling the system to boot more quickly.

### 3.8.2 Intel® Rapid BIOS Boot

There are several BIOS settings, which if adjusted, can reduce the execution time of the POST:

- Set the hard disk drive as the first boot device. As a result, the POST will not seek a diskette drive (saving about one second from the POST time) or a CD-ROM drive (saving about two seconds).
- Disable Quiet Boot to eliminate the logo splash screen. This could save several seconds of painting complex graphic images and changing video modes.
- Make sure the Intel® Rapid BIOS Boot option (in the Boot menu of the BIOS Setup Program) is enabled (this is typically the default setting). This feature bypasses memory count and floppy seek.
- Disable the LAN feature PXE (Preboot eXecutable Environment) if it will not be used. Doing so can reduce up to four seconds of option ROM boot time.

#### ⇒ NOTE

*It is possible to optimize the boot process to the point where the system boots so quickly that the Intel® Logo Screen (or a custom logo splash screen) will not be seen. Monitors and hard disk drives with minimum initialization times can also contribute to a boot time that might be so fast that necessary logo screens and POST messages cannot be seen. If this should occur, it is possible to introduce a programmable delay ranging from 3 to 30 seconds (using the Hard Disk Pre-Delay feature of the Advanced menu in the IDE Configuration Submenu of the BIOS Setup Program).*

For information about	Refer to
IDE Configuration Submenu in the BIOS Setup Program	Table 67, page 102

### 3.8.3 Operating System

#### 3.8.3.1 Selection

The Microsoft Windows\* Millennium Edition (Windows Me) operating system has built-in capabilities for making PCs boot more quickly. For additional information, see the following URL:

<http://www.microsoft.com/hwdev/newpc/fast-boot.htm>

### 3.8.3.2 Optimization

To speed operating system availability at boot time, limit the number of applications that load into the system tray or the task bar.

⇒ **NOTE**

*The Intel® Rapid BIOS Boot technology is only available with BIOS revision VC82010A.86A.0026.P09 or later.*

## ERRATA

### 1. ***Some SCSI Host Bus Adapters May Not Boot to The Hard Disk Drive With a Bootable CD-ROM Drive Attached***

**PROBLEM:** If a bootable CD-ROM is attached to the SCSI host bus adapter (HBA) and set as bootable in the setup menu of the SCSI HBA without bootable media installed, the system may not boot to the attached hard drive.

**IMPLICATION:** Users who wish to utilize a bootable SCSI CD-ROM in conjunction with a bootable hard drive on an add-in SCSI host bus adapter may not be able to boot to the hard drive if the SCSI adapter is set to recognize the CD-ROM as a bootable device.

**WORKAROUND:** Enable the CD-ROM as a bootable SCSI device only when using bootable media.

**STATUS:** This erratum will be fixed in a future BIOS revision.

### 2. ***A Heavily Loaded PCI Bus May Cause Excessive Noise on The NMI Signal to The Processor***

**PROBLEM:** If the PCI bus is heavily loaded, excessive noise on the NMI signal to the processor may cause system hangs or blue screens.

**IMPLICATION:** Users requiring multiple PCI add in cards that generate heavy traffic on the PCI bus and who are using higher frequency Pentium® III processors, may experience system hangs or blue screens.

**WORKAROUND:** None.

**STATUS:** This erratum was fixed in PBA revision 744044-403.

### 3. ***Intel® Pentium® III Processor Erratum E76***

**PROBLEM:** For a complete description of the Pentium® III processor erratum E76, see the Pentium III Specification Update, order number 244453 found at <http://developer.intel.com/design/PentiumIII/specupdt/>.

**IMPLICATION:** For a complete description of the Pentium III processor erratum E76, see the Pentium III Specification Update, order number 244453 found at <http://developer.intel.com/design/PentiumIII/specupdt/>.

**WORKAROUND:** Update the VC820 desktop board with BIOS revision VC82010A.86A.0040.P17.

**STATUS:** This erratum was addressed in BIOS revision VC82010A.86A.0040.P17.

## DOCUMENTATION CHANGES

### 1. *Change to Description of BIOS Main Menu Memory Option*

In section 4.3, Table 62, BIOS Main Menu will be changed as follows:

**Table 1. Main Menu**

Feature	Options	Description
BIOS Version	No options	Displays the version of the BIOS.
Processor Type	No options	Displays processor type.
Processor Speed	No options	Displays processor operating frequency.
System Bus Frequency	No options	Displays the of the system front side bus frequency.
Cache RAM	No options	Displays the size of second-level cache and whether it is ECC-capable.
Total Memory	No options	Displays the total amount of RAM.
Memory Bank 0 Memory Bank 1	No options	Displays type of RIMM installed in each memory bank.
Language	<ul style="list-style-type: none"> <li>• <b>English (US) (default)</b></li> <li>• German</li> <li>• French</li> <li>• Italian</li> <li>• Spanish</li> </ul>	Selects the default language used by the BIOS.
Processor Serial Number	<ul style="list-style-type: none"> <li>• <b>Disabled (default)</b></li> <li>• Enabled</li> </ul>	Enables and disables the processor serial number.
Memory Configuration	<ul style="list-style-type: none"> <li>• Non-ECC</li> <li>• <b>ECC (default)</b></li> </ul>	Allows selection of ECC-mode memory operation if ECC-type memory is installed.
System Time	Hour, minute, and second	Specifies the current time.
System Date	Month, day, and year	Specifies the current date.

### 2. *Change to Description of Section 1.6.4, Real-Time Clock, CMOS SRAM, and Battery*

The first note in section 1.6.4 will be changed in its entirety as follows:

#### ⇒ **NOTE**

*If the battery and AC power fail, custom defaults if previously saved, will be loaded into CMOS RAM at power-on.*

### 3. **Change to Description of Section 4.4.4.1, IDE Configuration Sub-Submenus**

Table 68 in section 4.4.4.1 will be changed in its entirety as follows:

**Table 68. IDE Configuration Sub-Submenus**

Feature	Options	Description
Type	<ul style="list-style-type: none"> <li>• None</li> <li>• User</li> <li>• <b>Auto (default)</b></li> <li>• CD-ROM</li> <li>• ATAPI Removable</li> <li>• Other ATAPI</li> <li>• IDE Removable</li> </ul>	Specifies the IDE configuration mode for IDE devices. <i>User</i> allows the LBA Mode Control, Multi-sector Transfers, PIO Mode, and Ultra DMA features to be changed. <i>Auto</i> automatically selects the values for the LBA Mode Control, Multi-sector Transfers, PIO Mode, and Ultra DMA features.
LBA Mode Control (Note)	<ul style="list-style-type: none"> <li>• Disabled</li> <li>• <b>Enabled (default)</b></li> </ul>	Enables or disables LBA Mode Control.
Multi-sector Transfers (Note)	<ul style="list-style-type: none"> <li>• Disabled</li> <li>• 2 Sectors</li> <li>• 4 Sectors</li> <li>• 8 Sectors</li> <li>• <b>16 Sectors (default)</b></li> </ul>	Specifies number of sectors per block for transfers from the hard disk drive to memory. Check the hard disk drive's specifications for optimum setting.
PIO Mode (Note)	<ul style="list-style-type: none"> <li>• <b>Auto (default)</b></li> <li>• 0</li> <li>• 1</li> <li>• 2</li> <li>• 3</li> <li>• 4</li> </ul>	Specifies the transfer mode.
Ultra DMA (Note)	<ul style="list-style-type: none"> <li>• <b>Disabled (default)</b></li> <li>• Mode 0</li> <li>• Mode 1</li> <li>• Mode 2</li> <li>• Mode 3</li> <li>• Mode 4</li> </ul>	Specifies the Ultra DMA mode for the drive. Note that when <i>Auto</i> is selected in PIO Mode, the BIOS sets Ultra DMA to the fastest speed supported. If the drive doesn't support Ultra DMA, the BIOS sets Ultra DMA to <i>Disabled</i> and the fastest supported PIO mode is used instead.

Note: The setting of *Type* determines whether these features display.

### 4. **Change to Description of Section 1.5.2, Memory Features**

Section 1.5.2, Memory Features will be changed in its entirety as follows:

### 1.5.2 Memory Features

The Intel® 82820 Memory Controller Hub (MCH) integrates a single Rambus\* channel as an electrically pipelined serial bus (16 data bits in width) with uniform impedance of 28 ohms and single-ended termination. This Rambus channel is capable of providing a processor-to-memory bandwidth up to 1.6 GB/sec.

The board supports the following memory features:

- Up to two 2.5 V, 184-pin, RIMM\* modules
- 512 MB maximum onboard capacity using 128 or 144 Mbit technology
- Single or double-sided RIMM modules
- Serial Presence Detect (SPD) memory only
- Non-ECC memory with 16-bit components (128 Mbit technology)
- ECC memory with 18-bit components (144 Mbit technology)

<b>For information about</b>	<b>Refer to</b>
<i>The Rambus RIMM Specification</i>	Section 1.3, page 16
<i>The Direct Rambus Serial Presence Detect (SPD) Specification</i>	Section 1.3, page 16