



Intel AP450GX MP Server Board Set

Technical Product Specification

The AP450GX MP Server Board Set may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Characterized errata that may cause the AP450GX MP Server Board Set's behavior to deviate from published specifications are documented in the AP450GX MP Server Board Set Specification Update.

Revision History

Revision	Revision History	Date
-001	Preliminary release of the AP450GX MP Server Board Set Technical Product Specification	7/96
-002	Second release of the AP450GX MP Server Board Set Technical Product Specification with additions and corrections.	3/97

This product specification applies only to the standard AP450GX MP Server Board Set with BIOS identifier CD0.

Changes to this specification will be published in the AP450GX MP Server Board Set Specification Update before being incorporated as a revision to this document.

The AP450GX MP Server Board Set may contain design defects or errors known as errata which may cause the product to deviate from published specifications

NOTE: If printing this document from an electronic file, use a PostScript printer with the appropriate PostScript print driver to insure the drawings print clearly.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Technical updates should be obtained by calling Intel Literature or writing:

Intel Corporation
P.O. Box 7641
Mt. Prospect, IL 60056-7641

or call in North America 1-800-879-4683, Europe 44-0-1793-431-155, France 44-0-1793-421-777,
Germany 44-0-1793-421-333, Japan (fax only) 81-0-120-478-832, other Countries 708-296-9333

* Third-party brands and trademarks are the property of their respective owners.

Copyright © 1997, Intel Corporation. All rights reserved

Table of Contents

1 Board Set Description.....	5
1.1 Overview	5
1.2 Board Set Options.....	7
1.3 Form Factor.....	7
1.4 Placement Diagrams	8
1.5 Connector Locations	12
1.6 Microprocessor	13
1.7 Bus Termination Module.....	15
1.8 Processor Population Order.....	16
1.9 Memory	18
1.10 Intel 450GX PCIset	24
1.11 Onboard SCSI Controllers	24
1.12 EISA Expansion Slots	24
1.13 PCI Expansion Slots.....	25
1.14 Boot Order	25
1.15 Super VGA Controller.....	26
1.16 Keyboard and Mouse	29
1.17 Advanced Integrated Peripheral (AIP).....	29
1.18 Miscellaneous Functions.....	30
1.19 Control Signals.....	35
1.20 Baseboard Jumper Settings.....	36
1.21 Processor Module Jumper Settings.....	44
1.22 Regulatory Compliance.....	48
1.23 Product Certification Markings	48
2 System Resources.....	52
2.1 Memory Map.....	52
2.2 I/O Map	53
2.3 PCI Configuration Space Map.....	55
2.4 DMA Channels.....	55
2.5 Interrupts	56

3 BIOS, Setup, SCU and SCSISelect Utilities	57
3.1 Introduction.....	57
3.2 BIOS	57
3.3 BIOS Setup	62
3.4 System Configuration Utility (SCU)	63
3.5 SCSI <i>Select</i> Utility.....	69
4 Error Messages and Beep Codes	71
4.1 BIOS Beep Codes.....	71
4.2 POST Codes and Countdown Codes.....	71
4.3 POST Error Codes and Messages.....	77
5 Electrical, Environmental and Mechanical Specifications	81
5.1 Absolute Maximum Ratings	82
5.2 Electrical Specifications.....	82
5.3 Environmental.....	83
5.4 Cooling Requirements	83
5.5 Power Budget	84
5.6 Mechanical Drawings	86
5.7 Connector Specifications.....	90

1 Board Set Description

1.1 Overview

The AP450GX MP Server Board Set is a modular, high performance server system capable of supporting up to four Pentium® Pro processors. The board set includes the system baseboard, one or two processor modules, a memory module, and an optional bus terminator module.

Board Set Feature	Description
Multi-processing support	Two expansion slots for processor modules; up to four Pentium® Pro microprocessors (two on each module). The system may include one processor module and one terminator module, or two processor modules.
Upgradable memory	One expansion slot for a memory module, supporting up to 1GB of memory using 64 MB SIMMs. The module will support up to 2GB of memory using 128MB SIMMs. An alternate memory module is available to support up to 4GB of memory using 128MB DIMMs.
Bus Termination Module	Required per the GTL+ processor bus specification if only one processor module is installed in the system.
PCI bus support	Two PCI "peer" buses, each with three 32-bit PCI slots on the system base board.
EISA bus support	Four dedicated EISA bus master slots on the system baseboard.
SCSI controller	Two PCI based, integrated AIC-7880 controllers; fast and wide, Fast 20/Ultra SCSI-2 support.
Integrated Drive Electronics (IDE) interface	Provides access to two IDE hard drives; ISA-based controller.
BIOS	Basic Input/Output System (BIOS) stored in enhanced 512 KB (4Mbit) Paged flash memory device.
Video controller	Integrated ISA based CL-GD5424 super VGA controller shipped with 512 KB of video memory (expandable to 1 MB).
External device connectors	Onboard connectors for 2 serial ports, parallel port, PS/2-compatible keyboard and mouse, and VGA monitor.
Clock	Real-time clock/calendar (RTC) chip with 8 KB of NVRAM.
Flash memory	Contains Power-on Self Test (POST), BIOS core and Setup utilities.
System hardware monitoring	Detects chassis intrusion and contains sensors for temperature, voltage, power supply and fan failure.
I ² C Bus Support	I ² C bus connects all major system components together for diagnostic information
Configuration utilities	System Configuration Utility (SCU) and SCSISelect Utility

The following diagram shows the functional blocks and system architecture.




Figure 1.1 System Block Diagram

1.2 Board Set Options

The server design allows expanded processor and memory capacity.

- Baseboard has two slots for processor modules and one slot for the memory module.
- Each processor module may contain one or two processors, for a configurable range from one to a maximum of four processors.
- A bus termination module is available to terminate the processor bus if only one processor module is installed in the system. Both processor slots must be filled to correctly terminate the processor bus.
- The standard memory module will support up to 2GB of memory using 128MB SIMMs.
- An optional memory module with 32 DIMM connectors is available which will support up to 4GB of memory using 128MB DIMMs.
- The video memory is expandable up to 1MB with a 512KB memory component.

1.3 Form Factor

The board set is designed to fit into a custom form factor chassis. Currently Intel's chassis, identified as the AP450GX Chassis, is the only Intel designed chassis qualified for the AP450GX Board Set.

1.4 Placement Diagrams

The following diagram shows the placement of major components and connector interfaces on the system baseboard, and the modules. See Chapter 5 for complete mechanical drawings.




Figure 1.2 Baseboard Layout




Figure 1.3 Fab 3.x Processor Module Layout (supports 166MHz/512KB processors only)




Figure 1.4 Fab 4.x Processor Module Layout (supports both 166MHz/512KB & 200MHz/512KB processors)




Figure 1.5 1GB Memory Module Layout




Figure 1.6 4GB Memory Module Layout

1.5 Connector Locations

Baseboard connector locations are shown in the figure below. See Appendix C for the connector pinouts.




Figure 1.7 AP450GX Board Set Connectors

** *Comments in italics are applicable when the board set is installed into Intel's AP450GX chassis.*

- A Power control and status connector (PS3)
- B +5V, +12V, and 3.3V power connectors (PS1 and PS2) (identical)
- C Diskette drive connector
- D Front panel connector
- E IDE drive connector
- F Memory module connector
- G Secondary processor module (or termination module) connector
- H Primary processor module connector
- I Fan 1 connector (*not used, fan sense jumper should be installed*)
- J Fan 2 connector (*inner chassis fan*)
- K Hard drive LED 1 connector (*not used*)
- L Connector for optional Server Management Module (SMM)
- M I²C connector (*not used*)

N	Fan 3 connector (<i>upper outer chassis fan</i>)
O	Fan 4 connector (<i>lower outer chassis fan</i>)
P	Hard drive LED 2 connector (<i>not used</i>)
Q	SCSI bus connectors: Channel A to the right, Channel B to the left
R	EISA slots 1 - 4 for add-in boards (slot 1 toward top, 4 toward bottom)
S	PCI slots 1 - 6 for add-in boards (slot 1 toward top, 6 toward bottom: PCI Bus 0 = slots 1 - 3; PCI Bus 1 = slots 4 - 6)
T	Configuration switches and jumpers
U	Real-time clock
V	Video DRAM expansion socket
W	VGA monitor connector (bottom)
X	Parallel port connector (top)
Y	Serial port connectors -- Port 1 (top), Port 2 (bottom)
Z	PS/2-compatible keyboard and mouse connectors (interchangeable)



Three connectors are shown in the board drawing as dotted-line boxes. They are not used in this system configuration. Their functions are as follows:

- ITP (In-target Probe) : Located near the upper right corner of the baseboard for low level system debug.
- PCI test connector: Blue connector near middle of board (not used)
- 3.3V PCI power connector: Located near the lower left corner, below the PCI slots.

1.6 Microprocessor

The Pentium Pro processor utilizes a 387-pin dual-cavity PGA package. The package contains two devices: a 5.5 million transistor processing core with 8 KByte primary cache, and 32 million transistor 512 KB secondary cache (L2 cache).

The AP450GX Board Set operates with Pentium Pro processors whose voltage may range from 2.1V to 3.5V and are Voltage ID (VID) enabled (i.e. the processors have the ability to ask for a certain voltage). A voltage regulator circuit on the processor module makes use of the VID capabilities to automatically adjust its voltage output to match that of the installed processor. The board set also has jumpers allowing processors ranging from 133 to 266 MHz to be installed. It should be noted, however, that there will be limitations on which processors will be supported.

The following table indicates which steppings of the Pentium Pro processor can be mixed within the same system. An "X" denotes which steppings can be mixed and a blank indicates the AP450GX MP Server Board Set does not support the given stepping combination.

Table 1.1 Supported Processor Combinations

Stepping (Proc/Cache)	sA1/α	sA1/β	sA1/β	sB1/β	sB1/β
Frequency	166	166	200	166	200
Cache Size	512	512	512	512	512
Stepping ID	0617	0617	0617	0619	0619
QDF #	SY034	SY047	SY048	SL22X	SL22Z
SY034	X	X		X	
SY047	X	X		X	
SY048			X		X
SL22X	X	X		X	
SL22Z			X		X

NOTES:

1. The BIOS used must support each stepping installed in the system.
2. If the sB1 stepping of the Pentium® Pro processor is installed, BIOS revision 1.00.08.CD0 or later is required.
3. Refer to erratum 34 in the Pentium Pro Processor Specification Update for issues related to the sB1 stepping of the Pentium Pro processor.
4. Though Intel recommends using identical steppings of processor silicon in multiprocessor systems whenever possible (as this is the only configuration which receives full validation across all of Intel's testing), Intel supports mixing processor steppings, and does not actively prevent various steppings of the Pentium Pro processor from working together in multiple processor (MP) systems. However, since Intel cannot validate every possible combination of devices, each new stepping of a device is fully validated only against the latest steppings of other processors and chipset components. Refer to Specification Change 1 of the *Pentium Pro Processor Specification Update* for further details on issues related to mixed processor steppings in an MP system.

An approved Pentium Pro processor heatsink (Intel part #644591-002) is necessary for proper thermal dissipation. The processor/heatsink assembly must be securely fastened to the socket by two clips (Intel part #637885-002). These clips fit over the heatsink assembly and attach to the outer wide tabs of the socket assembly. The heat sink must use thermal grease for proper heat dissipation for any processor greater than 35W (i.e. the 200MHz/512KB). "Foil pads" with grease on them will not properly cool a >35W processor. A heat sink kit is available that contains the proper heatsink, two clips and thermal grease. The current Intel order code is ALHSINKKIT.

The Pentium Pro processor maintains full backward compatibility with the 8086, 80286, Intel386™, Intel486™ and Pentium® processors. It also has a numeric coprocessor that significantly increases the speed of floating point operations, while maintaining backward compatibility with the i486DX math coprocessor and complying with ANSI/IEEE standard 754-1985.

**CAUTION**

Do not use the older style of bail-wire clips for securing the heatsink assembly. These clips have been found to cause damage when installed or removed incorrectly.

1.6.1 Processors and Processor Modules

The processor module will support up to two Pentium® Pro processors. The two processor sites are ZIF socketed, so that only one might be installed at the time of shipment with upgrades to be added later. Each processor module contains termination circuitry required by the GTL+ signaling environment, DC to DC converters for proper power to each processor, an I²C controller, and logic for I²C support and clock ratio programming. Each processor module has three DC-DC converters: one for the 1.5V GTL+ termination voltage, and two identical converters for the processors. The processor converters are supplied from the +12V supply. The GTL+ converter is supplied from the +12V supply on Fab 3.x processor modules (identified as 647428-xxx), or from the 3.3V supply on Fab 4.x processor modules (identified as 659506-xxx). The Fab 4.x processor modules will support up to a 40W processor (i.e. the 200MHz/512KB). The Fab 3.x processor modules will only supply enough current for up to a 35W processor (i.e. the 166MHz/512KB).

1.7 Bus Termination Module

This module is required when only one processor module is installed in the system. The terminator module provides GTL+ signal termination and voltage regulation. When used, this module must be installed in the secondary processor module slot on the system. The terminator module contains a single DC-DC converter which provides the 1.5V termination voltage. This converter is driven from the +12V supply.

1.8 Processor Population Order

The system baseboard has a primary processor module connector and a secondary processor module connector. A processor module can have one or two Pentium Pro processors installed. The figures that follow show the different supported population orders for 1, 2, 3 or 4 processors. Other processor configurations are not supported.




Figure 1.8 Processor Module Connector Locations





Figure 1.9 Processor Configuration Models

Refer to section 1.21 for the processor module jumper configurations.

1.9 Memory

1.9.1 System Memory

The memory subsystem consists of the memory chip set, the memory module connector on the system baseboard, and the memory module itself. The system baseboard contains the data path and data control portions of the chip set. The memory module contains the buffer devices from the chip set and 16 SIMM sites for up to 1 GB of system memory (using 64MB SIMMs) and 2 GB of system memory (using 128MB SIMMs). DRAM SIMMs on the module are organized as two 72-bit wide, 2-, or 4-way interleaves and 1 or 2 banks. SIMM sites accept 72-pin single- or double-sided SIMMs (60 or 70ns SIMMs only). All SIMMs in a bank must be identical (same size and speed).

Memory error checking and correction is supported via ECC logic in the chip set while using standard parity SIMM/DIMMs. The chip set will detect double bit errors and correct single bit errors. Errors may be generated by a defective memory module or soft errors. When a bad SIMM/DIMM is detected (i.e. a double bit error), during booting the BIOS will automatically downsize memory to eliminate the bad SIMM/DIMM location.

The 1GB memory module is available in two versions. Both are functionally identical except for the type of metal used in the SIMM connector and the type of capacitors used. One version has tin lead SIMM connectors and must be used with tin lead SIMMs. The other version is available with gold lead SIMM connectors and must be used with gold lead SIMMs. The gold lead module also has fused tantalum capacitors. The tin lead version simply has non-fused tantalum capacitors. There are separate order codes for each version. See Appendix B for the specific order codes.

⇒ **NOTE**

Only use SIMMs approved for use in this system. Contact your Intel representative for an updated list of qualified SIMMs and DIMMs.

1.9.2 Memory Installation Options (1GB Memory Module)

The following SIMM interleaving options are supported:

- Two-way interleave, J1 through J4;
- Four-way interleave, single bank, J1 through J8
- Four-way interleave, dual bank, J1 through J16.




Figure 1.10 Memory Configurations

The 1GB memory module has 16 SIMM sockets, arranged in two banks. The system automatically detects system memory installed, so jumpers do not need to be set to specify memory size although the SCU must be run after you change the memory configuration. See Chapter 3 for details.

Table 1.2 Supported Memory Options

Memory Size	Bank Installation	SIMM Type
Minimum memory configuration is 64 MB of DRAM (with four 16 MB SIMMs installed in J1, J2, J3, and J4).	Always begin with the bottom SIMM sites (lowest number is J1) as you fill the board sockets.	Use 16 MB, 64MB or 128 MB single-sided SIMMs or 32 MB double-sided SIMMs.
Maximum memory configuration is 1GB of DRAM (with 64 MB SIMMs installed in each socket, J1 through J16). Maximum memory configuration is 2GB with 128MB SIMMs.	All SIMMs in a bank must be identical (same size and speed). SIMMs in bank 1 may differ in size from the SIMMs in bank 2, but may not differ in speed. Number of SIMMs supported: 4, 8, or 16 only.	Use only 36-bit, 72-pin, 60 or 70ns fast page mode SIMMs, single- or double-sided. (Single-sided refers to the addressing method, not to the physical layout of the SIMM.) Use the 1 GB memory module with tin lead SIMM connectors when using tin lead SIMMs. Use the 1 GB memory module with gold lead SIMM connectors when using gold lead SIMMs. Use JEDEC-compatible SIMMs. Contact your Intel representative for a list of approved SIMMs.

1.9.3 Memory Performance Hints

Memory performance, and thus system performance, can be increased by changing the number of interleaves, number of banks and the speed of memory installed. For more information about system performance, refer to the *AP450GX MP Server System Performance Brief*.

1.9.4 4GB Memory Module

An optional 4GB memory module is available and will support up to 4GB of memory using 128MB DIMMs. This module fits into the same memory module connector the 1GB module fits into and has the same mechanical form factor. The additional memory capacity is accomplished with the use of TOSP DRAM's packaged in JEDEC standard 16Mx72 60ns DIMMs only. Note these are 3.3V DIMMs, while the 1GB module uses 5V SIMMs. The DIMMs are also installed at a 90° angle to the memory module (vs. 45° for the 1GB memory module) and are 1.25" high. The 4GB module contains 32 DIMM sockets, which when populated in groups of 4 DIMMs, offers memory capacity options of 0.5GB through 4GB in 0.5GB increments. Memory on the module is organized in 8 banks and 4-way interleaves.

1.9.4.1 DIMM Requirements

The 4GB memory module will only support a 128MB DIMM which meet JEDEC Standard No. 21-C, Release 4. In addition the DIMM must utilize TSOP DRAMs and must not exceed 0.157" in width. Two JEDEC standard options with identical mechanical pinouts are listed below.

1. 16Mx72 Fast Page Mode DRAM DIMM with ECC, 8K refresh, 3.3 V, 16Mx4 DRAM based, 13 row addresses, 11 column addresses internally.
2. 16Mx72 Fast Page Mode DRAM DIMM with ECC, 4K refresh, 3.3 V, 8Mx8/9 DRAM based, 12 row addresses, 11 column addresses internally.

⇒ **NOTE**

Only use DIMMs approved for use in this system. Contact your Intel representative for an updated list of qualified SIMMs and DIMMs.

1.9.4.2 Memory Installation Options (4GB Memory Module)

For the 4GB memory module the following DIMM population procedure must be used. The DIMMs are to be populated from J2 through J33 consecutively in groups of 4. All configurations result in a four-way memory interleave. Refer to Figure 1.6.

Table 1.3 Supported 4GB Memory Module Options

Memory Capacity	DIMM population instructions
0.5 GB	populate J2, J3, J4, J5
1.0 GB	add J6, J7, J8, J9
1.5 GB	add J10, J11, J12, J13
2.0 GB	add J14, J15, J16, J17
2.5 GB	add J18, J19, J20, J21
3.0 GB	add J22, J23, J24, J25
3.5 GB	add J26, J27, J28, J29
4.0 GB	add J30, J31, J32, J33

1.9.5 Memory Configuration Options

Error correction and detection, memory downsizing and address bit permuting are capabilities supported by both the 1GB and 4GB memory modules. Some options work slightly differently depending on the module and are described in the following sections.

1.9.5.1 Error Detection and Correction

The memory controller of the Intel 450GX PCIset performs run-time correction of single bit errors and detects double bit errors. Because a double bit error is not correctable, system operation once a double bit error has been detected is unpredictable and dependent on the operating system's ability to recover from it. Both single and double bit errors are recorded in the system error log if error reporting is enabled.

1.9.5.2 Memory Downsizing

During POST the BIOS performs a check of memory to insure all SIMMs/DIMMs are fully functional. Should a bad memory location be detected during POST, the BIOS will resize memory to eliminate the bad memory location. Unlike some memory resizing algorithms which will eliminate an entire SIMM/DIMM module from the system if a bad memory location is detected, the memory resizing algorithm used in the AP450GX system maintains the current memory configuration (i.e. same number of SIMM/DIMMs, same number of banks, same number of interleaves) and eliminates only the bad memory location. This is done by reducing the amount of memory used by each SIMM/DIMM until the bad memory location is no longer allocated.

When an error is detected, the BIOS first determines which bank is affected by the error. The memory allocation for the affected bank is then decreased by a power of two (i.e. only half the memory of each SIMM/DIMM will be allocated). The BIOS will continue decreasing the affected banks memory size by a power of two until the bad memory location is no longer allocated. A BIOS error will also be displayed indicating memory has been resized. If memory for the affected bank is decreased to 4MB and the bad memory location cannot be eliminated, the BIOS will display an error message and will not boot.

The above algorithm is identical for both the 1GB and 4GB memory modules.

⇒ **NOTE**

If double-sided (also called double-banked) SIMMs are used on the 1GB Memory Module, ECC memory errors may be reported on banks 1-4, even though the Memory Module only contains two physical memory banks. In this case, ECC errors on bank #1 would indicate a bad SIMM location in sockets J1-J8 and the error is on the front side of the SIMM. ECC errors on bank #2 would indicate a bad SIMM location in sockets J1-J8 and the error is on the back side of the SIMM. ECC errors on bank #3 would indicate a bad SIMM location in sockets J9-J16 and the error is on the front side of the SIMM. ECC errors on bank #4 would indicate a bad SIMM location in sockets J9-J16 and the error is on the back side of the SIMM.

1.9.5.3 Address Bit Permuting

The 450GX PCIset has a performance enhancing feature called Address Bit Permuting (ABP). ABP, if enabled, swaps memory row selection bits with the lower order bits in the address. In some applications this can improve system performance by increasing the number of row misses and thus decreasing the number of precharge penalties. ABP can be enabled under certain memory configurations. These configurations are listed below for each memory module. The ABP option in the BIOS setup (Advanced Chip Set Menu) must also be enabled.

1GB Memory Module

ABP can be enabled by the BIOS if all of the following are true:

- ABP BIOS option set to enabled
- Same speed SIMMs in both banks
- Same sized SIMMs in both banks

Note: The ABP bit in the \mathcal{I}^C register is used to allow ABP with single sided SIMMs and will only be set if all of the above are true and the SIMMs installed in the system are single-sided. ABP will still be enabled if all of the above are true and double sided SIMMs are installed, but the \mathcal{I}^C register bit will not be set.

4GB Memory Module

ABP can be enabled by the BIOS if all of the following are true:

- ABP BIOS option set to enabled

- Same speed DIMMs in all banks
- The module is populated in a two (1GB), four (2GB) or eight (4GB) bank configuration.

Note: ABP will not be enable if populated in a one, three, five, six or seven bank configuration.

1.10 Intel 450GX PCIset

The Intel 450GX PCIset (B0 stepping & C0 stepping) consists of two functional groups, the PCI controller and the memory controller. The PCI controller consists of a single 82454GX PCI Bridge (PB) component, which supports PCI Bus mastering. Two of 82454GX components are on the system baseboard, each supporting a single PCI (peer) bus. The memory controller consists of six components; the 82452GX (DP) Data Path component, 82453GX (DC) Data path Controller, and the 82451GX (MIC) Memory Interface Controller. The DP and DC each reside on the system baseboard. Four of the MIC components are located on the memory module.

1.11 Onboard SCSI Controllers

The baseboard includes two embedded wide SCSI-2 controllers (Adaptec AIC-7880, channels A and B) integrated as PCI bus masters. The controllers support data path widths of 8-bit (narrow SCSI) at a data transfer rate of 10 MB/sec, 16-bit (wide fast SCSI) at a data transfer rate of 20 MB/sec and 16-bit (Fast-20/Ultra) at a data transfer rate of 40MB/sec. As PCI bus masters, these controllers support data transfer rates of 133 MB/sec.

You can connect up to seven 8-bit narrow SCSI devices or up to fifteen 8-bit narrow and/or 16-bit wide SCSI devices and one controller (maximum of seven 8-bit narrow devices) to each channel. Devices can be tape drives, printers, optical media drives, and other devices. Narrow SCSI devices are not supported in Fast-20/Ultra mode.

Active termination must be provided on the far end of the SCSI bus to ensure proper termination of the bus. The baseboard provides active termination at the near end.

Active negation outputs reduce the chance of data errors by actively driving both polarities of the SCSI bus and avoiding indeterminate voltage levels and common-mode noise on long cable runs. The SCSI output drivers can directly drive a 48 mA, single-ended SCSI bus with no additional drivers.

1.12 EISA Expansion Slots

The baseboard has four EISA bus slots. The EISA bus is an extension of the Industry Standard Architecture (ISA) bus. Because EISA is fully backward-compatible with ISA, you can install EISA or ISA add-in boards and software in your server. This compatibility is handled by the PCEB and ESC chip set components on the system baseboard.

The EISA bus provides:

- 32-bit memory addressing
- Type A transfers at 5.33 MB per second
- Type B transfers at 8 MB per second
- Burst transfers at 33 MB per second

- 8-, 16-, or 32-bit data transfers
- Automatic translation of bus cycles between EISA and ISA masters
- Interrupt sharing

All four slots have the capability of being bus masters. When EISA masters arbitrate for the bus, the following pairs of slots share arbitration requests: 1 and 2, 3 and 4. Therefore, in the round-robin scheme of letting EISA masters take over the bus, ownership of it occurs in the following sequence: 1, 2, 3, 4, 1, 2, 3, 4, etc.

1.13 PCI Expansion Slots

The system baseboard has six, 32 bit, PCI 2.0 compliant bus slots. The PCI subsystem consists of two I/O bus segments. PCI #0 is the primary or compatibility bus segment, running always at 33 MHz. PCI #0 connects the processor bus to the INCA (Intel's Interrupt Controller ASIC), a PCI/EISA bridge, and three PCI connectors. PCI #1 connects the processor bus to two embedded wide SCSI controllers and three PCI connectors. PCI #1 also always runs at 33MHz. The architecture supports Host-to-PCI, PCI-to-Memory, PCI-to-EISA, EISA-to-Memory, and PCI-to-PCI transfers. The PCI bus provides:

- 32 and 64-bit memory addressing
- +5 V and + 3 V signaling environments
- Burst transfers at 133 MB per second
- 8-, 16-, or 32-bit data transfers
- Plug-and-play configuration
- PeerBus to maximize throughput

The INCA device provides these features:

- PCI clock generation: 14 PCI clocks (7 per PCI segment)
- Three buffered clocks
- Interrupt control
- Arbitration support for six PCI masters on PCI #1
- General purpose I/O ports: two 8-bit I/O ports for control or status
- 3-mode diskette control support
- DMA steering for IDE and parallel port to 1 of 4 DRQs/DACKs
- Keyboard emulation
- Support for front panel interface and LCD
- Security features: watchdog timer (software start/reset) resets system if it expires; monitors keyboard/mouse; monitors system baseboard voltage (+12V, -12V, +5V, -5V, +3.3V); monitors baseboard temperature and chassis door switch

1.14 Boot Order

When the system boots, it will look for a bootable device in a certain order. The system will then boot off the first bootable device it finds. Below is the order in which the system will look for bootable devices.

1. Floppy Drive
2. IDE Drive
3. E1 (EISA bus slot #1)
4. E2 (EISA bus slot #2)

5. E3	(EISA bus slot #3)
6. E4	(EISA bus slot #4)
7. P1	(PCI Bus#0, slot 1)
8. P2	(PCI Bus#0, slot 2)
9. P3	(PCI Bus#0, slot 3)
10. P4	(PCI Bus#1, slot 1)
11. SCSI A	(On-board AIC-7880 SCSI controller)
12. SCSI B	(On-board AIC-7880 SCSI controller)
13. P5	(PCI Bus#1, slot 2)
14. P6	(PCI Bus#1, slot 3)

Notes:

- The actual boot order on the EISA bus may change depending on how the devices installed on the EISA bus are configured, but the EISA bus will always be scanned for bootable devices before the PCI buses.
- If a PCI-to-PCI bridge device (P2P) is installed in the system, the boot order will change and may vary depending on the configuration. Typically, if a P2P is installed in P2, for example, the boot order will likely look for a bootable device on the P2P before looking at P3. However under some circumstance, the system may actually go to P3 before looking for a bootable device on the P2P.

1.15 Super VGA Controller

The onboard, integrated Cirrus Logic CL-GD5424 super VGA controller (ISA based) is fully compatible with these video standards: CGA, EGA, Hercules Graphics, MDA, and VGA. The standard system configuration comes with 512 KB of onboard 70ns video memory. You can optionally expand the onboard video memory buffer size to 1 MB by adding one 40-pin 256 K x 16, 70 ns fast-page DRAM. Contact your Intel representative for an updated list of qualified video memory. The SVGA controller supports only analog monitors (single and multiple frequency, interlaced and noninterlaced) with a maximum vertical retrace interlaced frequency of 87 Hz.

The BIOS will automatically disable the onboard video if another add-in video adapter is installed into the system baseboard. Note, however, the BIOS will only support add-in video adapters in the first PCI bus (slots P1-P3). Video adapters placed in the second PCI bus (slots P4-P6 will not be recognized).

- Supported with 512 KB memory: Pixel resolutions of 640 x 480 x 256 colors, and 800 x 600 and 1024 x 768 in 16 colors.
- Supported with 1 MB memory (optional): 132-column text modes and high resolution graphics with 1280 x 1024 x 16 colors. Depending on the environment, the controller displays up to 64,000 colors in some video resolutions.

Table 1.4 Standard VGA Modes

Mode(s) in Hex	Colors (number /palette size)	Resolution	Pixel Freq. (MHz)	Horiz. Freq. (KHz)	Vert. Freq. (Hz)
0, 1	16/256K	360 X 400	14	31.5	70
2, 3	16/256K	720 X 400	28	31.5	70
4, 5	4/256K	320 X 200	12.5	31.5	70
6	2/256K	640 X 200	25	31.5	70
7	Mono	720 X 400	28	31.5	70
D	16/256K	320 X 200	12.5	31.5	70
E	16/256K	640 X 200	25	31.5	70
F	Mono	640 X 350	25	31.5	70
10	16/256K	640 X 350	25	31.5	70
11	2/256K	640 X 480	25	31.5	60
12	16/256K	640 X 480	25	31.5	60
12+	16/256K	640 X 480	31.5	37.5	75
13	256/256K	320 X 200	12.5	31.5	70

Table 1.5 Extended VGA Modes

Mode(s) in Hex	Colors (number /palette size)	Resolution	Pixel Freq. (MHz)	Horiz. Freq. (KHz)	Vert. Freq. (Hz)
14, 55	16/256K	1056 X 400	41.5	31.5	70
54	16/256K	1056 X 350	41.5	31.5	70
58, 6A	16/256K	800 X 600	40	37.8	60
58, 6A	16/256K	800 X 600	49.5	46.9	75
5C*	256/256K	800 X 600	36	35.2	56
5C*	256/256K	800 X 600	40	37.9	60
5C*	256/256K	800 X 600	49.5	46.9	75
5D	16/256K (interlaced)	1024 X 768	44.9	35.5	87
5D	16/256K	1024 X 768	65	48.3	60
5D	16/256K	1024 X 768	75	56	70
5D	16/256K	1024 X 768	78.7	60	75
5F	256/256K	640 X 480	25	31.5	60
5F	256/256K	640 X 480	31.5	37.5	75
60*	256/256K (interlaced)	1024 X 768	44.9	35.5	87
60*	256/256K	1024 X 768	65	48.3	60
60*	256/256K	1024 X 768	75	56	70
60*	256/256K	1024 X 768	78.7	60	75
64*	64K	640 X 480	25	31.5	60
64*	64K	640 X 480	31.5	37.5	75
65*	64K	800 X 600	36	35.2	56
65*	64K	800 X 600	40	37.8	60
65*	64K	800 X 600	49.5	46.9	75
66*	32K Direct/256 Mixed	640 X 480	25	31.5	60
66*	32K Direct/256 Mixed	640 X 480	31.5	37.5	75
67*	32K Direct/256 Mixed	800 X 600	40	37.8	60
67*	32K Direct/256 Mixed	800 X 600	49.5	46.9	75
6C*	16/256K (interlaced)	1280 X 1024	75	48	87
6C*	16/256K	1280 X 1024	108	65	60
6D*	256/256K (interlaced)	1280 X 1024	75	48	87
6D*	256/256K	1280 X 1024	108	65	60
71*	16M	640 X 480	25	31.5	60
72*	16M 32-bit/pixel	800 X 600	40	37.8	60
73*	16M 32-bit/pixel (interlaced)	1024 X 768	44.9	35.5	87
74*	64K (interlaced)	1024 X 768	44.9	35.5	87
74*	64K	1024 X 768	65	48.3	60
74*	64K	1024 X 768	75	56	70
74*	64K	1024 X 768	78.7	60	75
75*	64K (interlaced)	1280 X 1024	75	48	87
76*	16M 32-bit/pixel	640 X 480	25	31.5	60
76*	16M 32-bit/pixel	640 X 480	31.5	37.5	75

* Requires 1MB video memory option.

1.16 Keyboard and Mouse

The 8742 keyboard controller is PS/2-compatible. The system may be locked automatically if there is no keyboard or mouse activity for a predefined length of time, as specified through the Setup utility. The default keystroke combination to enable this feature is <Ctrl + Alt + Backspace>. Once the inactivity timer has expired, the keyboard or mouse does not respond until the previously stored password in the keyboard controller is entered. The keyboard LED will blink until the password is entered.

The mouse is disabled on power-up; in this state, interrupt IRQ12 is available for use by add-in boards, and the mouse clock input to the keyboard controller is connected to the mouse clock output, with no connection to the external mouse.

1.17 Advanced Integrated Peripheral (AIP)

The AIP resides on the EISA bus and contains a floppy disk controller (FDC), 2 serial ports, a multi-function parallel port and an IDE interface.

1.17.1 Floppy Drive Support

The FDC on the AIP is functionally compatible with the 82077SL, 82077AA and 8272A floppy disk controllers and can provide a data rate up to 2MB/s. The FDC will support up to two floppy disk drives.

1.17.2 Serial Ports

Two 9-pin serial ports are provided in a single stacked housing (ports 1 and 2). Port 1 is located on the top, port 2 on the bottom. Both serial ports are 16550 compatible with 16-byte FIFO's. Each serial port can be set to 1 of 4 different COM ports (via the BIOS setup), and can be enabled separately. When enabled, each port can be programmed to generate edge or level sensitive interrupts. When disabled, serial port interrupts are available to adapter cards.

1.17.3 Parallel Port

A single PS/2 compatible 25-pin bi-directional parallel port is provided. The parallel port supports Extended Capabilities Port (ECP) protocol with DMA, EPP protocol and IEEE 1284 protocol for PS/2 bi-directional compatibility. The parallel port can be enabled or disabled via the BIOS setup. When disabled, the interrupt is available to adapter cards.

1.17.4 IDE Support

IDE is an 8-bit or 16-bit interface for intelligent disk drives with AT disk controller electronics onboard. AC timing constraints allow only Type 2 IDE drives in the CAM specification (or faster) to be supported. The processor can transfer data from the IDE interface at a maximum transfer rate of 2.4Mbytes per second. This IDE implementation will also support DMA to the IDE device, which has a maximum transfer rate of 4.2Mbytes per second. Typical IDE devices can access data at a peak rate of 1.2Mbytes per second. Therefore, the usage of DMA will significantly reduce the bus utilization (with respect to IDE device access), and will significantly improve system performance.

The IDE interface can be disabled. It is disabled on reset; in this state, the I/O address space and interrupt IRQ14 are available for add-in modules. The system BIOS may disable the interface when it finds the registers of another hard disk controller.

1.18 Miscellaneous Functions

The board set provides the additional miscellaneous functions listed below:

- I²C Diagnostic Bus
- Server Management Connector
- System Fan Interface
- Hard Drive LED Interface

1.18.1 I²C Diagnostic Bus

The baseboard has an integral I²C (Inter-Integrated Circuit) bus which can be used for general purpose system management such as providing module revision or status information from anywhere in the system. This bus is routed to processor and memory modules, the front panel and power supply connectors, the Server Management Connector and a single user connector on the baseboard.

A Philips PCF8584 I²C controller is mapped into EISA I/O space and can be used by system software to access the I²C bus. The 8584 appears at addresses CA0h and CA1h. The interrupt from the 8584 is routed to input PCI8 on the INCA component.

The baseboard, processor, memory and terminator modules have PCF8574 and PCF8474A I/O devices on them. These are 8-bit devices that connect the I²C bus and provide system information from each module. Below is the I²C base address for each component.

<u>Component</u>	<u>I²C Base Address</u>
Baseboard	0x40
Primary Processor Module Slot	0x70
Secondary Processor Module Slot	0x72
Primary Processor Module Slot, Reserved	0x90
Secondary Processor Module Slot, Reserved	0x92
Memory Module	0x42

The information available from each module when accessed via the I²C bus is shown in the following table along with the bit definitions.

Table 1.6 Baseboard I²C Bit Map

Bit	Bit Name	Description
2:0	BRDREV(2:0)	Baseboard board revision ID 001 = Fab 1 010 = Fab 2 011 = Fab 3
6:3	RESERVED	Reserved
6:3	FANFAIL(3:0)	A zero (0) indicates a failed fan. Bits 6:3 are valid as FANFAIL when bit 7 = "1". bit 3 = fan 4 (Outer chassis fan, lower) bit 4 = fan 3 (Outer chassis fan, upper) bit 5 = fan 2 (Inner chassis fan) bit 6 = fan 1 (Not used in AP450GX MP Server chassis) (not a supported feature)
7	FANFAILSEL	When "1", bits 6:3 are fan fail When "0", bits 6:3 are Reserved (not a supported feature)

Table 1.7 Processor Module I²C Bit Map

Bit	Bit Name	Description
2:0	P6ID(2:0)	Pentium® Pro processor core/bus frequency ID 000 = 150/60 MHz 001 = 180/60 MHz 010 = 210/60 MHz 011 = 240/60 MHz 100 = 166/66 MHz 101 = 200/66 MHz 110 = 233/66 MHz 111 = 266/66 MHz
4:3	Reserved	
5:3	BRDREV(0:2)	Processor Module Board Revision ID 000 = Fab 3 001 = Fab 4 100 = Fab 3 modified for the sB1 processor 101 = Fab 4 modified for the sB1 processor Bits 5:3 are valid as BRDREV when bit 7 = "1". All previous processor module revisions are not compatible with Fab 3 which is why the numbering starts with 000.
6:5	Reserved	
7	BRDREVSEL	When "1", bits 5:3 indicate the board revision, bit 6 is reserved When "0", bit 6:3 are reserved.

Table 1.8 1GB Memory Module I²C Bit Map

Bit	Bit Name	Description
1:0		Board Revision ID 00 = 1GB Module (Fab1 or Fab2) 01 = 1GB Module (Fab3) 10 = 4GB Module 11 = Reserved
3:2		Bank 0 SIMM Speed 00 = 50ns (bank 0) 01 = 80ns (bank 0) 10 = 70ns (bank 0) 11 = 60ns (bank 0)
5:4		Bank 1 SIMM Speed 00 = 50ns (bank 1) 01 = 80ns (bank 1) 10 = 70ns (bank 1) 11 = 60ns (bank 1)
6		Reserved
7		RAS/CAS Multiplexing for Address Bit permuting 0 = Enabled 1 = Disabled

Table 1.9 4GB Memory Module I²C Bit Map

Bit	Bit Name	Description
1:0	BRDREV(1:0)	Board Revision ID 00 = 1GB Module (Fab1 or Fab2) 01 = 1GB Module (Fab3) 10 = 4GB Module 11 = Reserved
5:2	REFRESH(3:0)	Refresh 1110 = 8Mx8/9 DRAM based 4K refresh 1111 = 16Mx4 DRAM based 8K refresh All others are reserved.
7:6	DIMMSPD(1:0)	DIMM Speed (All Banks) 00 = 50ns 01 = 80ns 10 = 70ns 11 = 60ns

Table 1.10 Termination Module I²C Bit Map

Bit	Bit Name	Description
2:0	BRDREV(2:0)	<p>AP450GX Terminator Module revision ID</p> <p>000 = Fab 3</p> <p>All previous terminator module revisions are not compatible with Fab 3 which is why the numbering starts with 000.</p>
6:3	N/C	These signals are not used.
7	GROUND	<p>Hard wired to ground.</p> <p>To differentiate between a terminator module and a processor module, write a one "1" to bit 7 then do a read of bit 7. If a one "1" is read back, the board is a processor module. If a zero "0" is read back, the board is a terminator module.</p>

1.18.2 Server Management Connector

A 26-pin connector is provided to interface with an emergency management adapter card. It is designed for Intel's Server Monitor Module which allows the user to manage (monitor and control) the server from a remote console, but could be used by other similar implementations. The connector provides access to the I²C bus, power on/off signals, power good from the power supply and a host of other signals. Refer to the connector pin-out in Appendix C for a list of all signals.

1.18.3 System Fan Interface

There are four fan connectors on the system baseboard. The connector pin-out is listed in Appendix C. These connectors provide a ground, 12V power to the fan and a fan-fail input from the fan. The system will be able to detect the failure and will report it via Intel's LANDesk® Server Control Software. These fan failures are also logged in the BIOS event log, and are denoted by the fan fail light on the system front panel. All four fan-fail inputs are tied to A/D channel 8 for monitoring by the INCA component. The current LANDesk software does have the ability to distinguish between the four fans. It simply knows if one fan has failed. If one or more of the fan connectors is not used in a particular application, pins 1 (GND) and 3 (Fan Fail) on the connector must be connected together. This connection is required to prevent an erroneous failed fan indication.

1.18.4 Hard Drive LED Interface

There are two Hard Drive LED interface connectors on the baseboard (locking polarized, 4 position, single in-line, .025 in square pin). See Appendix C for the pinout. Pin 2 of both connectors is tied together as well as to the IDE connector (pin 39), the SCSI A LED signal and the front panel signal HD1_LED_ACT# (pin 10). They are tied together so that any of these sources can activate a light on the front panel to indicate hard drive access.

Likewise pin 3 of both connectors is tied together as well as to the SCSI B LED signal and the front panel signal HD2_LED_ACT# (pin 11).

The purpose of the connectors themselves is to provide a way for a front panel LED to be driven from an add-in disk controller. Note Intel's AP450GX MP Server chassis does provide LED's on its front panel that can be driven by either of these signals.

1.19 Control Signals

1.19.1 Remote Sensing

Remote sensing exists on the +5.1 Vdc, +12 Vdc, and +3.3 Vdc outputs. The -12 Vdc, -5 Vdc, and +5 V standby outputs are referenced to the negative (-) remote sense point. Only voltage drops exterior to the power supply are included. The loss of a remote sense connection will not cause the power supply to go into a high output voltage condition. Intel strongly recommends using the signals for remote sense. Without remote sense capabilities, it will be difficult to keep the power rails within the board set specifications.

Table 1.11 Amount of Drop to Regulate

Output voltage	Maximum voltage drop
+5.1 Vdc	0.3V
+12 Vdc	0.2V
+3.3 Vdc	0.2V
Ground	0.2V

1.19.2 Power Good (PGOOD & PWRGOOD) signals

Each power supply provides a power good signal to the power distribution backplane. This signal indicates that all outputs have reached operating state. The PGOOD signal is deasserted for a minimum of 250uS before any of the output voltages fall below the regulation limit. During normal power on, PGOOD will be asserted between 100mS and 1500mS after the 5.1V output reaches a minimum of 4.75V.

To indicate that all power supplies are within regulation, the PGOOD signals from each supply are OR'd together on the power distribution backplane to create a single PWRGOOD signal which is passed on to the baseboard. The PWRGOOD signal has the same timing parameters as the individual PGOOD signals described above.

1.20 Baseboard Jumper Settings

Table 1.12 Jumper Configuration, Baseboard

Baseboard configuration jumper summary (listed by block number on board)	Pins	Description
J6A1, BIOS Recovery	1-2*	Normal BIOS boot block
	2-3	Recovery BIOS boot block <i>If the normal BIOS gets corrupted, and you are unable to reload a new BIOS from floppy disk, install the jumper into recovery mode which will allow the system to boot from the recovery BIOS.</i>
J6A1, Boot Block Protect	1-2*	BIOS boot block is write-protected
	2-3	BIOS boot block is programmable <i>The programmable mode should only be enabled under carefully controlled circumstances. Incorrect programming of the boot block will render the system unbootable.</i>
J6A4, BIOS write	1-2	Disables BIOS update of flash memory
	2-3*	Enables BIOS update of flash memory with special utility <i>Install the jumper in the enable mode when updating the system BIOS. This jumper should always be set to enable. Some operating systems will not boot without this jumper enabled.</i>
J6A4, Floppy 0	1-2	For 1.44 MB diskette drive size or autodetection. Disables 2.88 MB size detection
	2-3*	For forced 2.88 MB diskette drive size
J6A2, Floppy 1	1-2	For 1.44 MB diskette drive size or autodetection. Disables 2.88 MB size detection
	2-3*	For forced 2.88 MB diskette drive size
J6A2, Video Sleep	1-2	Video Sleep Register resides at 03C3H
	2-3*	Video Sleep Register resides at 46E8H
J6A3, Power Control	1-2	Disables RTC power supply control
	2-3*	Enables power supply control using RTC <i>Under certain conditions the RTC can be programmed via the BIOS setup to turn off the system. Installing the jumper in the enable mode allows the RTC to use this feature.</i>

* Factory default setting

1.20.1 BIOS Recovery Jumper, J6A1




Figure 1.11 BIOS Recovery Jumper

This jumper enables the recovery mode for the BIOS flash memory. This mode is important because the system BIOS can be corrupted—for example, when the update procedure is aborted due to a power outage. The flash memory contains a protected area that cannot be corrupted. Code in this area is used to boot the computer from a diskette in drive A when the BIOS has been corrupted. After booting, the flash Memory Update utility is used to automatically recover the system BIOS from the BIOS recovery files on the diskette. (For normal operation, it is important to keep the jumper on pins 1 and 2.) When the recovery procedure is run, another jumper, BIOS Write at J6A4, must also be in its default position (pins 2 and 3 jumpered).

1.20.1.1 System BIOS, Recovery Procedure

Requirements:

- At least 4 MB of RAM installed.
- Drive A: must be a 3.5-inch 1.44 MB diskette drive.
- On the system board, the configuration jumper at J6A4 must be in the default position (pins 2 and 3, BIOS Write enabled).

The recovery operation automatically updates only the main system BIOS. Video is not initialized, and the keyboard is disabled. Because there is no screen display, you will need to listen for these audible status signals:

Audible Beeps Description

- 1: Signals beginning of recovery process; process takes 2 to 4 minutes.
 - 2: Signals successful completion, no errors.
 - 4: System could not boot from the diskette. Diskette may not be bootable.
- Continuous series of low beeps (like a buzz): Any or all of these causes:

- The wrong BIOS recovery files are being used.
- Configuration switch allowing BIOS Recovery mode is in wrong position.
- Configuration switch allowing BIOS Write to flash memory is in wrong position.
- One or more system BIOS FMUP files is corrupt or missing.


WARNING: If the system has been running, any processor and heat sink installed on the processor board will be hot. The system board configuration switches are immediately adjacent to a processor board connector. To avoid the possibility of a burn while accessing a configuration switch, let the components cool for 10 minutes before continuing with the procedures described here.

Before beginning recovery procedure If you have mapped the BIOS of an add-in board to any part of the E0000H address range, you must either map it to another area before beginning a recovery procedure or physically remove the board from the system.

1. Observe safety and ESD precautions.
2. If you have not already done so, create a bootable MS-DOS diskette, and copy the BIOS update to the diskette.
3. Turn off the system, and unplug the power cord(s).
4. Open the system. On the system board, move the BIOS Recovery jumper from pins 1 and 2 to pins 2 and 3.
5. Insert the Flash Memory Update diskette in drive A. Turn the system on. You will hear a single initial beep that is part of the typical system boot-up process.
6. Then you will hear another single beep that indicates the recovery process is beginning. The process takes two to four minutes. While in the recovery mode, there is no screen display on the monitor, and the keyboard is disabled as the system automatically recovers the BIOS.
7. You will hear two beeps when the process is successfully completed.
8. Make sure the diskette drive activity light is OFF. Turn off the system.
9. At J6A1, remove the BIOS Recovery jumper from pins 2 and 3, and place it back on pins 1 and 2.
10. Remove the FMUP diskette from drive A.
11. Close the system, plug in the power cord(s), and turn on the system. Check the BIOS version number against what you intended to flash in.

CMOS is not cleared when you update the BIOS. After doing the recovery procedure, clear CMOS. Also, you will need to flash in again any additional languages that were present before updating.

1.20.2 Boot Block Jumper, J6A1



1-2 BIOS boot block is write-protected, factory default


Figure 1.12 Boot Block Jumper



CAUTION, leave at factory-default setting, pins 1 and 2

Always leave the Boot Block jumper installed in the factory-default position, on pins 1 and 2, to protect the BIOS boot block from being overwritten.

1.20.3 BIOS Write Jumper, J6A4



2-3 Enables BIOS update of flash memory with special utility, factory default

1-2 Disables BIOS update of flash memory (cannot overwrite the BIOS)

Figure 1.13 BIOS Write Jumper




CAUTION, updating the BIOS requires special utility

Changing this jumper should be done only by a qualified technical person, because updating the BIOS requires a special utility.

This jumper enables updating the BIOS in flash memory with a special utility. The factory default is to leave this function enabled so that you can update the BIOS from a bootable diskette without needing to open the system and change the jumper. For a copy of the utility to update the BIOS, contact your Intel representative.

1.20.4 Floppy 0 Jumper at J6A4; Floppy 1 Jumper at J6A2




OM04485d

- 2-3** For forced 2.88 MB diskette drive size, factory default
- 1-2 For 1.44 MB drive size or autodetection; disables 2.88 MB size detection

Figure 1.14 Floppy Jumpers

The Floppy 0 and Floppy 1 functions are set at separate jumper blocks, but the descriptions are identical. These jumpers configure the floppy drive port to force 2.88 MB drive size or to support automatic size detection.

1.20.5 Video Sleep Jumper, J6A2



2-3 Video Sleep register resides at 46E8H, factory default


1-2 Video Sleep register resides at 03C3H

Figure 1.15 Video Sleep Jumper

The video address jumper determines which I/O port the onboard Cirrus Logic CL-GD5424 super VGA controller uses for its internal AT mode setup port. The starting address of the default port is 046E8H.

If there is no keyboard activity after a specified time-out period (1 to 128 minutes as specified by using the SCU), the video sleep register blanks out the monitor screen. When this happens, you must enter a password to reactivate the monitor and the keyboard.

1.20.6 Power Control Jumper, J6A3



2-3 Enables power supply control using the RTC, factory default

1-2 Disables RTC power supply control

Figure 1.16 Power Control Jumper

This jumper (PWR CTRL) enables power supply control using the real-time clock. Power control from the RTC is typically used for Automatic Server Recovery. An alarm is set in the RTC by the BIOS or a utility program to power the system on or off at a predetermined time.

1.20.7 Configuration Switches




Figure 1.17 Clear CMOS/Password Switch

Table 1.13 Switch Configuration, Baseboard

	Switch	Position	Function
To change setting, slide switch to desired position.	S6A1-1	On	Clear CMOS
		Off*	Normal operation
	S6A1-2	On	Clear password
Off*		Normal operation	
	S6A1-3	Off*	Reserved

*Factory default setting

CMOS Switch, S6A1-1

Switch S6A1-1 controls whether settings stored in CMOS nonvolatile memory (NVRAM) are retained during a system reset:

- Switch OFF: settings in CMOS and real-time clock are preserved during system reset.
- Switch ON: settings in CMOS and real-time clock are reset to factory defaults during system reset.

To clear CMOS (restore to factory default values), do these steps:

1. Observe the safety and ESD precautions. See Chapter 3 of the AP450GX MP Server System Installation Guide for this information.
2. Turn off system power and disconnect the AC power cord(s).
3. Remove the card cage side panel. You do not need to remove the system board, and you probably do not need to remove any add-in boards.
4. On the system board, at switch S6A1-1, CLEAR CMOS, slide switch to ON.
5. Install side panel for your safety. Connect the power cord(s), and turn on the system.

6. Wait for POST to complete and the message “NVRAM cleared by jumper” to appear.
7. Turn off system power and disconnect the AC power cord(s).
8. Remove the side panel again.
9. At switch S6A1-1, slide switch to OFF (the original position). Setting it to OFF preserves the settings during system reset.
10. Install side panel, connect the power cord(s), and turn on the system.
11. Run BIOS Setup to verify the correct settings.

Password Switch, S6A1-2

This switch controls whether a stored password is retained or cleared during a system reset:

- Switch OFF: lets you enter a password that is preserved even during system reset.
- Switch ON: clears the password during system reset.

To clear and enter a password, do these steps:

1. Observe the safety and ESD precautions. See Chapter 3 of the AP450GX MP Server System Installation Guide for this information.
2. On the system board, slide switch to ON (to clear old password).
3. Turn system on and wait for POST to complete. The password will have been cleared automatically.
4. Turn system off.
5. Slide switch to OFF to resume normal operation (your settings are retained during system reset).
6. Run Setup to specify a new password. When you reboot the system, the new password will have been retained.

1.21 Processor Module Jumper Settings

Table 1.14 Jumper Configuration, Processor Module


Processor board jumper summary	Pins	Description
J101 and J106, scan for processor (SCAN)	1-2*	Processor not installed in adjacent socket**
	2-3	Processor installed in adjacent socket
J103, voltage identification (VID)***	1-2	If jumper is installed, VID is disabled, processor 2. If not installed, VID is enabled, processor 2.
	3-4	If jumper is installed, VID is disabled, processor 1. If not installed, VID is enabled, processor 1.
	5-6*	Park - not connected
	7-8*	Park - not connected
J105, processor frequency select (SEL) (see Table 1.15)	1-2*	SEL0
	3-4	SEL1
	5-6	SEL2
	7-8	Park - not connected
	9-10	Park - not connected
	11-12	Park - not connected

* Factory default setting.

** The pins at J101 and J106 are only useful when using the ITP. During normal operation they have no effect on the system.

*** J103 block may not be present on all versions of the processor module. If not present, then VID is enabled and is not selectable.

1.21.1 SCAN Jumpers, J101 and J106




- 1-2 Processor not installed in adjacent socket (SKIP position), factory default
- 2-3 Processor installed in adjacent socket (INCLUDE position)

Figure 1.18 SCAN Jumpers

There are two SCAN jumper blocks, one for each processor socket. These are used to determine if a processor is installed in the socket adjacent to a given jumper block. In normal operation, these jumpers have no function and are useful only during low-level processor ITP bus debugging.

1.21.2 VID Jumpers, J103



- 1-2 VID bypass 1; 3-4 VID bypass 2
- 5-6 Park, factory default; 7-8 Park, factory default

Figure 1.19 VID Jumpers

The settings at J103 depend on whether processors are voltage-ID-ready or not. In general, voltage identification (VID) is default-enabled; that is, the unused jumpers are placed in the Park locations. The J103 block is present only on early versions of the processor board; later versions have VID enabled at all times.

To disable VID for processor 2, move a jumper to pins 1 and 2 (VIDBYP1).

To disable VID for processor 1, move a jumper to pins 3 and 4 (VIDBYP2). (This is the correct description: VIDBYP1 refers to processor 2, and VIDBYP2 to processor 1.)

Note: J103 block may not be present on all versions of the processor module. If not present, then VID is enabled and is not selectable.

1.21.3 Processor Frequency Select Jumpers, J105




Figure 1.20 Processor Frequency Jumpers



CAUTION, select the actual frequency setting


Damage to the processor may occur if you select a jumper setting frequency that is greater than the actual frequency of the processor.

Use this jumper block to select the processor core/bus frequency. The selection must match the frequency of the processor being installed in the system. Be sure that both boards are programmed to the same frequency. Install jumpers for the desired frequency as shown in the following table. Place any unused jumpers in the Park locations (pins 7-8; 9-10; 11-12).


Table 1.15 Frequency Jumper Configurations

Frequency	SEL0 Pins 1-2	SEL1 Pins 3-4	SEL2 Pins 5-6
150/60 MHz	No jumper	No jumper	No jumper
180/60 MHz	Jumper	No jumper	No jumper
210/60 MHz	No jumper	Jumper	No jumper
240/60 MHz	Jumper	Jumper	No jumper
166/66 MHz	No jumper	No jumper	Jumper
200/66 MHz	Jumper	No jumper	Jumper
233/66 MHz	No jumper	Jumper	Jumper
266/66 MHz	Jumper	Jumper	Jumper

Example, jumpering for 150/60 MHz



Example, jumpering for 200/66 MHz



1.21.4 Processor Board Fan Sink Connectors, J102 and J107




Figure 1.21 Fan Sink Connectors

J102 and J107 are connectors to provide power for optional fan sinks to cool the processors while the board set is being tested outside of the chassis on a test bench. Each fan sink comes with a 3-pin connector wire. The connectors are not used in normal system operation.

1.21.5 Power Supply Considerations

The AP450GX MP Server Board Set is designed to operate with 2 or 3 420W custom power supplies when installed in Intel's AP450GX MP Server chassis. Refer to Chapter 5 for the actual power requirements. Intel strongly recommends using the signals provided for remote sense. Without remote sense capabilities, it will be difficult to keep the power rails within the board set's specifications.

1.22 Regulatory Compliance

Table 1.16 Regulatory Specifications

Board	Specification
Safety	UL 1950 CSA 22.2 No. 950 -M93 by cUL EN 60950 by TÜV IEC 950 by TÜV EN 60950 and Nordic deviations by NEMKO
Electromagnetic Emissions	Certified to FCC 47 Class B Tested, CISPR 22/85 Class B, EN 55022 Registered with VCCI Declaration of the Manufacturer or Importer: We hereby certify that this product is in compliance with EU Directive 89/336/EEC, using the EMC standards EN55022, EN61000-3-2 and EN50082-2.
Electromagnetic Immunity	Verified to comply with EN 50082-2

1.23 Product Certification Markings

1.23.1 European CE Marking

Marking on the board or shipping container.

1.23.2 UL Recognition

UL Recognized Marking consists of UL File No. E139761 on component side of board PB No. on solder side of board. Board material flammability is 94V-1 or -0.

1.23.3 Canadian Compliance

Marking consists of small c followed by a stylized backward UR on component side of board.

1.23.4 Installation Requirements



CAUTION

To avoid an adverse impact on the compliance with safety or regulatory requirements due to installation of this board assembly, the following guidelines must be followed.

1.23.4.1 Follow Installation Instructions

Be sure to read and adhere to all of these instructions, and the instructions supplied with the host system and associated modules. If the instructions of the host system appear to be incompatible with these instructions or the instructions of any associated modules, contact the suppliers' technical support organization for the products involved to determine the appropriate action for continued safety and regulatory compliance of the resultant system. Failure to read and follow instructions provided by host system and module suppliers may result in increased safety risk and non-compliance with regional laws and regulations.

1.23.4.2 Assure Host System Compatibility

For electromagnetic compatibility, the host system enclosure and power supply should have passed electromagnetic compatibility testing using a board with a processor from the same family as the processor on this board, operating at the same or higher processor speed. Also, only peripherals (computer input/output devices, terminals, printers, etc.) that are CE Marked and certified by the FCC to comply with Class B limits may be attached to this board. Pay particular attention to the installation instructions of the host system and other modules, particularly concerning certifications, external I/O cable shielding and filtering, mounting, grounding and bonding requirements to assure appropriate shielding effectiveness. Otherwise electromagnetic compatibility testing must be repeated on a representative sample of the complete system.

For safety, if mis-mating of connectors could result in a hazard, assure that all connectors are sufficiently keyed to prevent mis-mating.

1.23.4.3 Use Only In Intended Applications

This product was evaluated for use in systems installed in offices, homes, schools, computer rooms or similar applications. Other applications, such as medical, industrial, alarm systems and test equipment may necessitate a re-evaluation of the product suitability.

1.23.4.4 Assure Host System & Accessory Certifications

Assure that the host system, any other subassemblies such as board and drive assemblies being added in, and internal or external wiring, are properly certified for the region(s) the end-product will be used in. Proof of certification can be determined by the marks on the product. For example:

1.23.4.4.1 Europe

The CE Marking signifies compliance with all relevant EU requirements. If the host system does not bear the CE Marking, obtain a supplier's Declaration of Conformity to the appropriate standards required by the European EMC Directive and Low Voltage Directive. Other directives,

such as the Machinery and Telecommunications Directives, may also apply depending on the type of product. No regulatory assessment is necessary for low voltage DC wiring used internally, or wiring used externally when provided with appropriate overcurrent protection. Appropriate protection is achieved by a maximum 8 Amp current limiting circuit or a maximum 5 Amp fuse or Positive Temperature Coefficient Resistor (PTC). All Intel baseboards presently have PTC's on all external ports which provide DC power externally.

1.23.4.4.2 U.S.

For safety, a certification mark by a Nationally Recognized Testing Laboratory (NRTL) such as UL, CSA or ETL. External wiring must be UL Listed and suitable for the use. Internal wiring must be UL Listed or Recognized and rated appropriately for the voltages and temperatures involved. For electromagnetic interference, the FCC mark: Class A for commercial or industrial only; or Class B for all applications other than described above.

1.23.4.4.3 Canada

For safety, a nationally recognized certification mark such as CSA or cUL. No regulatory assessment is necessary for low voltage DC wiring used internally, or wiring used externally when provided with appropriate overcurrent protection. Appropriate protection is achieved by maximum 8 Amp current limiting circuit or a maximum 5 Amp fuse or Positive Temperature Coefficient Resistor (PTC). All Intel baseboards presently have PTC's on all external ports which provide DC power externally.

1.23.5 Installation Precautions

During installation and initial test, use caution to avoid personal injury and damage to wiring due to sharp pins on connectors and printed circuit assemblies, rough chassis edges and corners, and hot components. Adhere to warnings and limitations regarding accessibility into areas designated only for authorized technical personnel.

1.23.6 Battery Marking

There is insufficient space on this board product to provide the required replacement and disposal instructions for the battery. The following marking must be placed permanently and legibly on the host system as near as possible to the battery:



CAUTION

Danger of explosion if battery is incorrectly replaced.

Replace with only the same or equivalent type recommended by the manufacturer. Dispose of used batteries according to the manufacturer's instructions.

1.23.7 Overload Protection

Unless the power supply is provided with inherent overcurrent protection, use caution to avoid overloading the power supply output. This can be accomplished by assuring that the calculated total current load of all the modules within the system is less than the output current rating of the power supply. Failure to accomplish this could result in overheating in the power supply, which

could result in a fire or could cause damage to insulation separating hazardous AC line circuitry from low-voltage user accessible circuitry. If the load drawn by a particular module cannot be determined by the markings and instructions supplied with the module, contact the module supplier's technical support organization.

2 System Resources

2.1 Memory Map

Table 2.1 Memory Addressing

Address Range (hex)	Amount	Function
0000_0000H – 0007_FFFFH	512 KB	Base system memory (fixed)
0008_0000H – 0009_FFFFH	128 KB	Base system memory or ISA memory enabled in Setup
000A_0000H – 000B_FFFFH	128 KB	ISA video buffer
000C_0000H – 000E_7FFFH	160 KB	Video BIOS, AIC-7880 SCSI BIOS, other option ROMs. All these can be shadowed
000E_8000H – 000F_FFFFH	96 KB	System BIOS and data areas (fixed)
0010_0000H – 00EF_FFFFH	14 MB	System memory or unused
00F0_0000H – 00FF_FFFFH	1 MB	System memory or EISA memory
0100_0000H – FEBF_FFFFH	4060 MB	System memory or add-in cards or unused
FEC0_0000H – FEC0_0FFFH	4 KB	I/O APIC #1
FEC0_1000H – FEC0_1FFFH	4 KB	I/O APIC #2
FEC0_2000H – FEC0_7FFFH	24 KB	Unused
FEC0_8000H – FEC0_8FFFH	4 KB	Local APIC
FEC0_9000H – FFF7_FFFFH	4939 KB	Add-in card or unused
FFF8_0000H – FFFF_FFFFH	512 KB	System BIOS (fixed)

2.2 I/O Map

Table 2.2 I/O Addressing

I/O address	Resource
0000 – 001F	DMA controller 1
0020 – 0021	Interrupt controller 1
0022 – 0023	EISA bridge configuration space access ports
0040 – 005F	Programmable Timer
0060 – 0064	Keyboard Controller
0061	NMI Status & Control Register
0070	NMI Mask (bit 7) & RTC Address (bits 6:0)
0071	Real-time Clock (RTC)
0080 – 0081	PCEB BIOS Timer
0080 – 008F	DMA Low Page Register
0092	System Control Port A (PC-AT control Port)
00A0 – 00BF	Interrupt Controller 2
00C0 – 00DF	DMA Controller 2
00F0	Clear NPX error
00F8 – 00FF	x87 Numeric Coprocessor
0102	Video Display Controller
0170 – 0177	Secondary Fixed Disk Controller (IDE)
01F0 – 01F7	Primary Fixed Disk Controller (IDE)
0278 – 027F	Parallel Port 2 (relocatable)
02E8 – 02EF	Serial Port 4 (relocatable)
02F8 – 02FF	Serial Port 2 (relocatable)
0370 – 0377	Secondary Floppy
0378 – 037F	Parallel Port 1 (relocatable)
03B4 – 03BA	Monochrome Display Port
03BC – 03BF	Parallel Port 3
03C0 – 03CF	Enhanced Graphics Adapter
03D4 – 03DA	Color Graphics Controller

System I/O Map, continued

I/O address	Resource
03E8 – 03EF	Serial Port (relocatable)
03F0 – 03F7	Floppy Disk Controller
03F8 – 03FF	Serial Port 1 (relocatable)
0400 – 043F	DMA Controller 1, Extended Mode Registers
0461	Extended NMI / Reset Control
0462	Software NMI
0464	Last EISA Bus master granted
0480 – 048F	DMA High Page Register
04C0 – 04CF	DMA Controller 2, High Base Register
04D0 – 04D1	Interrupt Controllers 1 and 2 Control Register
04D4 – 04D7	DMA Controller 2, Extended Mode Register
04D8 – 04DF	Reserved
04E0 – 04FF	DMA Channel Stop Registers
0C80 – 0C83	EISA System Identifier Registers
0C84	Board Revision Register
0CA0-0CA1	I ² C Interface Base Address
0CF8	PCI CONFIG_ADDRESS Register
0CFC	PCI CONFIG_DATA Register
n000 –n0FF	EISA Slot n I/O Space (n = 1 to 4)
x100 – x3FF	ISA I/O slot alias address
n400 – n4FF	EISA Slot n I/O Space (n = 1 to 4)
x500 – x7FF	ISA I/O slot alias address
n800 – n8FF	EISA Slot n I/O Space (n = 1 to 4)
x900 – xBFF	ISA I/O slot alias address
nC00 – nCFF	EISA Slot n I/O Space (n = 1 to 4)
xD00 – xFFF	ISA I/O slot alias address

2.3 PCI Configuration Space Map

Table 2.3 PCI Configuration Space Map

Bus Number (hex)	Dev Number (hex)	Function Number (hex)	Description
00	C8	00	Intel 82454GX (PB) PCI Bridge - Bus 0 (Compatibility)
00	D0	00	Intel 82454GX (PB) PCI Bridge - Bus 1
00	A0	00	Intel 82453GX (DC) Memory Controller
00	78	00	INCA
00	70	00	PCEB
00	58	00	P1 (PCI Bus 0, slot 1)
00	60	00	P2 (PCI Bus 0, slot 2)
00	68	00	P3 (PCI Bus 0, slot 3)
01	60	00	On-board SCSI controller, Channel B
01	58	00	On-board SCSI controller, Channel A
01	50	00	P4 (PCI Bus 1, slot 1)
01	68	00	P5 (PCI Bus 1, slot 2)
01	70	00	P6 (PCI Bus 1, slot 3)

2.4 DMA Channels

Table 2.4 DMA Channel Mapping

Channel	Device
0	(add-in board)
1	(add-in board)
2	Diskette drive
3	IDE hard disk drive
4	Reserved
5	(add-in board)
6	(add-in board)
7	(add-in board)

2.5 Interrupts

Table 2.5 Interrupt Mapping

IRQ	Device
NMI	Parity error
0	Interval timer
1	Keyboard buffer full
2	Reserved, cascade interrupt from slave PIC
3	Onboard serial port B (COM2) or add-in board
4	Onboard serial port A (COM1) or add-in board
5	Parallel port LPT2 or add-in board
6	Onboard diskette (floppy) controller, if enabled
7	Parallel port LPT1 or add-in board
8	Real-time clock (RTC)
9	(add-in board)
10	(add-in board)
11	(add-in board)
12	Onboard PS/2 mouse port or add-in board
13	Math coprocessor error
14	IDE hard drive controller, if enabled
15	(add-in board)

3 BIOS, Setup, SCU and SCSISelect Utilities

3.1 Introduction

The AP450GX MP Server Board Set uses an Intel BIOS, which is stored in flash memory and easily upgraded using a floppy disk-based program. In addition to the Intel BIOS, the flash memory also contains the Setup utility, Power-On Self Tests (POST), the PCI auto-configuration utility, and Windows 95 ready Plug-N-Play 1.0a. This board set also supports system BIOS shadowing, allowing the BIOS to execute from 64-bit on-board write-protected DRAM. The Setup and SCU utilities are used to change configuration values in flash memory. In addition, the SCSISelect utility is provided to configure the on-board AIC-7880 SCSI controllers. All three utilities are briefly described in this chapter. Refer to the AP450GX MP Server Installation Guide, Intel Part #642976, for more detail on each utility.

3.2 BIOS

The BIOS displays a sign-on message during POST identifying the type of BIOS and a five-digit revision code. The initial production BIOS in the baseboard is identified as 1.00.04.CD0

3.2.1 BIOS Flash Memory Organization

The Intel 4Mb flash component is organized as 512K x 8 (512 KB). The flash device is divided into eight areas, as described in Table 3.1.

Table 3.1 Flash Memory Organization

System Address		FLASH Memory Area
FFFF0000H	FFFFFFFFH	64 KB Main BIOS
FFFE0000H	FFFEFFFFH	16 KB Boot block (Not FLASH erasable)
FFFEA000H	FFFEBFFFH	8 KB ESCD Area (Plug-N-Play data storage area)
FFFE9000H	FFFE9FFFH	4 KB Reserved for BIOS
FFFE8000H	FFFE8FFFH	4 KB OEM Logo Area
FFFE0000H	FFFE7FFFH	32 KB Reserved for BIOS
FFFD0000H	FFFDFFFFH	64 KB Reserved for BIOS
FFFC0000H	FFFCFFFFH	64 KB Reserved for BIOS

3.2.2 BIOS Upgrades

Flash memory makes distributing BIOS upgrades easy. A new version of the BIOS can be installed from a diskette. BIOS upgrades are available from your Intel representative.

The disk-based flash upgrade utility, FMUP.EXE, has three options for BIOS upgrades:

- The flash BIOS can be updated from a file on a disk;
- The current BIOS code can be copied from the flash memory to a disk file as a backup in the event that an upgrade cannot be successfully completed; or

- The BIOS in the flash device can be compared with a file to ensure the system has the correct version.

The upgrade utility ensures the upgrade BIOS extension matches the target system to prevent accidentally installing a BIOS for a different type of system.

3.2.3 ISA IDE Support

The ISA based IDE connector with independent I/O channel support are setup up automatically by the BIOS if the user selects “Autoconfiguration” in setup. The IDE interface supports PIO Mode 3, and Mode 4 hard drives and recognition of ATAPI CD-ROMs, tape drives, and any other ATAPI devices. The BIOS will determine the capabilities of each drive and configure them to optimize capacity and performance. For the high capacity hard drives typically available today, the drive will be automatically configured for Logical Block Addressing (LBA) for maximum capacity and to PIO Mode 3 or 4 depending on the capability of the drive. The user is able to override the auto-configuration options by using the manual mode setting. The ATAPI Specification Revision 2.5 recommends that an ATAPI device be configured as shown in the table below.

Table 3.2 Recommendations for Configuring an ATAPI Device

Primary Cable		Secondary Cable		
Drive 0	Drive 1	Drive 0	Drive 1	
ATA				Normal, no ATAPI
ATA		ATAPI		Disk and CD-ROM for enhanced IDE systems
ATA	ATAPI			Legacy IDE System with only one cable
ATA		ATAPI	ATAPI	Enhanced IDE with CD-ROM and a tape or two CD-ROMs

3.2.4 PCI Auto-Configuration

The PCI auto-configuration utility operates in conjunction with the system Setup utility to allow the insertion and removal of PCI cards to the system without user intervention (Plug-N-Play). When the system is turned on after adding a PCI add-in card, the BIOS automatically configures interrupts, I/O space, and other parameters. PCI interrupts are distributed to available ISA interrupts that have not been assigned to an ISA card, or system resources.

The PCI Auto-Configuration function complies with version 2.0 of the PCI BIOS specification. System configuration information is stored in ESCD format. The ESCD data may be cleared by setting the CMOS clear jumper to the ON position.

PCI specification 2.0 for add-in card auto-configuration is also a part of the Plug-N-Play BIOS. Peer-to-peer hierarchical PCI Bridge 1.0 is supported, and by using an OEM supplied option ROM or TSR, a PCI-to-PCMCIA bridge capability is possible as well.

3.2.5 ISA Plug-N-Play

The BIOS incorporates ISA Plug-N-Play capabilities as delivered by Plug-N-Play Release 1.0A (Plug-N-Play BIOS version 1.0A, ESCD version 1.03). When used in conjunction with the System Configuration Utility (SCU) for DOS, the system allows auto-configuration of Plug-N-

Play ISA cards, PCI cards, and resource management for legacy ISA and EISA cards. System configuration information is stored in ESCD format. The ESCD data may be cleared by setting the CMOS clear jumper to the ON position.

The BIOS also has a setup option to support the Windows 95 run time Plug-N-Play utilities. When this option is selected, only devices critical to booting are assigned resources by the BIOS. Device node information is available for all devices to ensure compatibility with Windows 95.

Note: copies of the Intel Plug-N-Play specification may be obtained via the Intel BBS , via CompuServe by typing “Go PlugPlay”, or on the Intel corporate web site at www.intel.com.

3.2.6 Language Support

The BIOS setup screen and help messages are supported in 32 languages. There are five languages available at this time: American English, German, Italian, French, and Spanish. Translation to other languages may become available at a later date.

3.2.7 Boot Options

Booting from CD-ROM is supported in adherence to the “El Torito” v. 1.0 bootable CD-ROM format specification developed by Phoenix Technologies and IBM. Under the *Boot Options* field in setup, *CD-ROM* is one of four possible boot devices which are defined in priority order. The default setting is for floppy to be the primary boot device and hard drive to be the secondary boot device. If CD-ROM is selected, it must be the first device. The third and fourth devices are set to *disabled* in the default configuration. The user can add also select *network* as a boot device. The network option allows booting from a network add-in card with a remote boot ROM installed.

⇒ NOTE

A copy of “*El Torito CD-ROM Boot v1.0*” is available on the Phoenix Web page (<http://www.ptltd.com/techs/specs.html>).

3.2.8 Console Redirection

The BIOS supports redirection of both the video and keyboard via a serial port (COM 1 or COM 2). When console redirection is enabled, keyboard input and video output is transferred not only through the normal keyboard and video connections, but also via the serial port (i.e. keyboard inputs from both sources are considered valid and video is displayed to both sources). If you choose, the system can be operated without a keyboard or monitor attached to the system and run entirely via the remote console. Both Setup and the SCU can be used while console redirection is enabled.

When connecting a modem up to the COM port, it should be configured in both auto-answer and the modems reaction to DTR must be to switch to command state.

3.2.8.1 Keystroke Mappings

During console redirection, the **remote** terminal (which may be a dumb terminal or a system with a modem running a package such as ProComm) sends keystrokes to the **local** server, which then passes video back. For keys which have an ASCII mapping (such as A and Ctrl-A), the ASCII

character is sent. For keys which do not have an ASCII mapping (such as F1 and Alt-A), a string of characters as defined in the tables below is sent.

The strings are based on the ANSI BBS and vt100 terminal standards. Since these terminals do not support all the keys on the standard 101 key U.S. keyboard, some additional characters were added (such as F5 - F12, Page Up, and Page Down.) Alt key combinations were created by adding the prefix `^[]` to the character (both `^[]a` and `^[]A` will be interpreted at the local server as alt-a.). In addition, `^{` will be interpreted as a screen refresh.

Since the mappings for non-ASCII keys are done via table lookup, the decision was made not to support unusual combinations such as Ctrl-F1. This saves space in BIOS, as well as a good deal of coding to interpret these sequences.

Table 3.3 Non-ASCII Key Mappings

Key	Normal	Shift	Ctrl	Alt
ESC	<code>^[]</code>	NS	NS	NS
F1	<code>^[]OP</code>	NS	NS	NS
F2	<code>^[]OQ</code>	NS	NS	NS
F3	<code>^[]OR</code>	NS	NS	NS
F4	<code>^[]OS</code>	NS	NS	NS
F5	<code>^[]OT</code>	NS	NS	NS
F6	<code>^[]OU</code>	NS	NS	NS
F7	<code>^[]OV</code>	NS	NS	NS
F8	<code>^[]OW</code>	NS	NS	NS
F9	<code>^[]OX</code>	NS	NS	NS
F10	<code>^[]OY</code>	NS	NS	NS
F11	<code>^[]OZ</code>	NS	NS	NS
F12	<code>^[]O1</code>	NS	NS	NS
Print Screen	NS	NS	NS	NS
Scroll Lock	NS	NS	NS	NS
Pause	NS	NS	NS	NS
Insert	<code>^[]L</code>	NS	NS	NS
Delete	(7Fh)	NS	NS	NS
Home	<code>^[]H</code>	NS	NS	NS
End	<code>^[]K</code>	NS	NS	NS
Pg Up	<code>^[]M</code>	NS	NS	NS
Pg Down	<code>^[]2J</code>	NS	NS	NS
Up Arrow	<code>^[]A</code>	NS	NS	NS
Down Arrow	<code>^[]B</code>	NS	NS	NS
Right Arrow	<code>^[]C</code>	NS	NS	NS
Left Arrow	<code>^[]D</code>	NS	NS	NS
tab	(09h)	NS	NS	NS

NS = Not supported, (xxh) = ASCII character xx

Table 3.4 ASCII Key Mappings

Key	Normal	Shift	Ctrl	Alt
backspace	(08h)	(08h)	(7Fh)	^[(08h)
(accent) `	`	(tilde) ~	NS	^[]`
1	1	!	NS	^[]1
2	2	@	NS	^[]2
3	3	#	NS	^[]3
4	4	\$	NS	^[]4
5	5	%	NS	^[]5
6	6	^	NS	^[]6
7	7	&	NS	^[]7
8	8	*	NS	^[]8
9	9	(NS	^[]9
0	0)	NS	^[]0
(dash) -	-	(under) _	(1Fh)	^[]-
=	=	+	NS	^[]=
a to z	a to z	A to Z	(01h) to (1Ah)	^[]a to ^[]z
[[{	(1Bh)	^[][
]]	}	(1Dh)	^[]]
\	\		(1Ch)	^[]\
(semi-colon) ;	;	(colon) :	NS	^[];
(apostrophe) '	'	(quote) "	NS	^[]'
(comma) ,	,	<	NS	^[],
(period) .	.	>	NS	^[].
/	/	?	NS	^[]/
(space)	(20h)	(20h)	(20h)	^[](20h)

NS = not supported, (xxh) = ASCII character xx

3.2.8.2 Limitations

Console redirection can only be used in “Real Mode”. It will not work in “Protected Mode”. Console redirection only works with text based video, and will not work with graphics based video applications. For keyboard redirection to work, the application on the local server must use the INT 16 keyboard services normally to receive keystrokes. If the program uses INT 9 and INT 15 services instead, the redirection will not work. For example, the DOS edit program cannot be used remotely due to the way it gets keys in the menu code and WordPerfect will not work due to its extensive use of Shift-F1, Ctrl-F1 and other “special” keystrokes.

3.3 BIOS Setup

The Setup utility stores configuration values in flash memory and in the battery-backed memory of the real-time clock (RTC). Values you enter in Setup are overwritten if you change these values in the SCU and save them.

For a number of options, the settings are made by using the SCU, not Setup. The values are simply displayed in the Setup screens. To see the descriptions of such options, refer to the SCU section later in this chapter.

Setup has four major menus and several sub-menus. To move between the major menus, use the ← → keys. To display the sub-menus, press <Enter> when the prompt is displayed beside an option name.

When you see this on the screen:	What it means
On screen, an option is grayed out. In the tables in this chapter, the phrase "Display only" appears in the "Choice" column.	You cannot change or configure the option through Setup. You must use (1) a different Setup screen or (2) the SCU. In some cases, the option may be auto-configured or auto-detected.
On screen, the phrase <Press Enter> appears next to the option, and, in the tables here, in the "Default/next menu" column.	Press <Enter> to display a sub-menu (either a separate full-screen menu or a small pop-up menu with one or several choices).
"Default/next menu" appears as a column header in the tables here.	The column shows either the default option setting, a grayed-out "display only" setting, or a "Press Enter" prompt that leads to a separate menu.

3.3.1 When to Run Setup

... if you get a boot-time prompt that says to do so.

... if you need to enable or properly configure your diskette drive.

... if you do not have access to a diskette drive.

Much of the system configuration is done through the SCU, not Setup. Because the SCU is provided on diskette, a diskette drive needs to be connected and enabled. After configuring the system, you may prefer to secure it against casual or unauthorized access by someone using diskettes. Therefore, you can

- run Setup to enable the diskette drive
- then use Setup or the SCU to configure the system
- run Setup again to disable the diskette drive for security

Refer to the AP450GX MP Server System Installation Guide, Intel Part #642976, for more details on the BIOS Setup utility.

3.4 System Configuration Utility (SCU)

The System Configuration Utility (SCU) is the main tool to configure the system or to check or change the configuration. Most system settings can be entered from either the SCU or BIOS Setup, but the SCU provides conflict resolution as well as access to information about ISA, EISA, and PCI adapters.

⇒ System must have a diskette drive

Your system must have a diskette drive present and enabled to use the SCU, because it is provided on a diskette. If a drive is present but is disabled or improperly configured, use the BIOS Setup utility to enable or configure the diskette drive. Then make a bootable SCU diskette and use the SCU to configure the system.

3.4.1 When to Run the SCU

- ...when you first set up and configure your system
- ...if you get a configuration error message at power-on
- ...each time you add, remove, or move an EISA or ISA add-in board
- ...each time you add or remove a Plug-N-Play or PCI add-in board
- ...each time you add or remove memory

3.4.2 Where the SCU Gets Information

Information comes from	Description
Configuration (.CFG) or overlay (.OVL) files	For the baseboard, we provide these files. For EISA and some ISA add-in boards, each comes with a diskette that contains a .CFG file (and an optional .OVL file) supplied by the device manufacturer. The file describes the board's characteristics and the system resources it requires.
Configuration registers	The configuration registers on PCI boards contain the same type of information that an EISA .CFG file does. The SCU is PCI aware, and it complies with the EISA Specification (version 3.12).
Your option selections	The SCU stores your information by modifying ISA CMOS and EISA nonvolatile RAM (NVRAM). It stores most of the values in the battery-maintained memory of the real-time clock (RTC); it stores the rest of the values in flash memory.

3.4.3 Checking the Configuration at Power-on

At power-on or rebooting, the BIOS POST routines and the Plug-N-Play Auto Configuration Manager check and configure the hardware. POST checks the values that have been stored against the actual hardware configuration; if the values do not agree, you will get an error message. You must then run the SCU to correct the configuration before the system boots.

3.4.4 How to Use the SCU

First make a bootable diskette, and copy the file HIMEM.SYS onto it.

1. Turn on your video display monitor and system.
2. There are three ways to start and run the SCU:
 - From diskette: insert the System Configuration Disk in drive A, and then press the reset button or type <Ctrl+Alt+Del> to reboot the system.
 - From a DOS directory that you have copied onto your hard drive, type SCU. Press <Enter>. If you use this method, you need to load HIMEM.SYS into the AUTOEXEC.BAT and CONFIG.SYS files.
 - From diskette in drive A: change to drive A and type SCU at the MS-DOS prompt. Press <Enter>.

Whether or not you can use the second and third methods depends upon how much conventional memory is available in the system when the SCU is run. The amount of conventional memory available depends on the device drivers that are loaded on the system.

The SCU has four major configuration menus and several sub-menus. From the main menu, select "Step 1: About System Configuration" for information about setting up your computer.

To navigate the screens	Press key	or use mouse
Change between major menus	← or →	
From main menu, press up or down arrow to highlight an item	↑ or ↓	Point to item
Select an item	<Enter>	Double-click left button
Get help	<F1>	Point to help on toolbar
Enter numbers and symbols	numeric keypad keys	
To change options	Enter Administrator password if this is enabled	

⇒ **To run the SCU faster on a DOS-based system**

To run the SCU faster on a DOS-based system, copy to a directory on your hard drive, and run it from there. The SCU may not run properly unless HIMEM.SYS is loaded and there is approximately 600 KB of conventional system memory available.

3.4.5 Configuring the System

There are six steps to configure your system. These steps are accessed from the main menu:

- Step 1: About System Configuration
- Step 2: Add and Remove Boards
- Step 3: Change Configuration Settings
- Step 4: Save Configuration
- Step 5: View Switch/Jumper Settings
- Step 6: Exit

The SCU has three major menus and multiple sub-menus. Follow the screen prompts to move between the major menus, display sub-menus, and make selections.

3.4.5.1 About System Configuration

This step provides basic information for configuring expansion devices. More experienced users can skip this step.

3.4.5.2 Add and Remove Boards

Use this step to add, delete, or move boards. Most boards are automatically detected and added by the SCU once you enter this step. However, if the SCU did not detect a board, you can add a board manually.

Add and Remove Boards

System Board	System Board
PCI Undefined Device	Bus 0 Dev F
PCI SCSI Device	Bus 1 Dev C
PCI SCSI Device	Bus 1 Dev B

- Press INSERT to add a board that was not detected or has not been installed yet.

- Press DEL to remove the selected board.

- Press F7 to move the selected board to a different slot.

- Press ESC when finished with this setup.

[Add = INSERT] [Remove = DEL] [Move = F7] [Done = ESC]
 [Help = F1] [Define ISA = F6]

OM04253

To add a board:

1. Press Insert.
2. From the Select the Board to Add dialog box, select the board's .CFG file and press Enter.

To delete an existing board:

1. Use the arrow keys to select the board that you want to delete.
2. Press Delete.
3. Confirm that you want to delete the board.

To move a board from one slot to another:

1. Use the arrow keys to select the board that you want to move.
2. Press F7.

⇒ **If you add, move, or remove boards**


Manually verify the resource settings of these adapters, and any other adapters that are not locked, before saving your configuration.

To define an ISA board:

Press F6 to display the ISA Board Definition dialog box. Refer to the section below for details.

3.4.5.3 Define an ISA Board

To define an ISA board that has no .CFG file, press F6 while viewing the Add and Remove Boards screen. The ISA Board Definition dialog box will appear. It is necessary to define a board to prevent other boards in the system from using the same IRQ levels, DMA channels, I/O addresses, or memory addresses as that of the ISA board.



OM04254

To define an ISA board:

1. In the Board Name box, type a description of the board.
2. In the Manufacturer box, type the name of the board manufacturer.
3. From the Board Type box, choose the type of board.
4. From the Board Slot box, choose the type of slot.
5. In the DMA box, define up to four DMA channels.
6. In the IRQ box, define up to seven IRQ levels.
7. In the Ports box, define up to eight ranges of I/O ports.
8. In the Memory box, define up to eight memory address ranges.
9. Press F10 to save the ISA board definition.

You can load an existing ISA board in order to modify the board definition.

To load an existing ISA board: Press F9.

To delete an ISA board: Press F9, and confirm that you intend to delete the ISA definition.

3.4.5.4 Change Configuration Settings

Use this step to view or change the configuration settings for any board in the system. You can verify that the baseboard and adapter board resources are set properly.

Change Configuration Settings

System Board	System Board
PCI Undefined Device	Bus 0 Dev F
PCI SCSI Device	Bus 1 Dev C
PCI SCSI Device	Bus 1 Dev B

- This step is optional, you may skip it by pressing ESC and all configuration settings will remain unchanged.
- Press ENTER to view or change a board's configuration settings.
- Press ESC when you are satisfied with the current settings.

[Select = ENTER] [Done = ESC] [Advanced Options = F9]
 [Help = F1] [Lock Toggle = F8]

OM04256

To view or change the settings for a board:

1. Use the arrow keys to select the board.
2. Press Enter.
3. When you are satisfied with the current settings, press ESC to return to the Main Menu.

3.4.5.5 Advanced Options

The Advanced Options menu is intended for advanced users. These are the options available:

Use this option	To see this
Global resource map	A list of allocated resources (DMA, IRQ, ports, and memory)
Board details	Detailed information for individual boards
System details	Information on the entire system and the current configuration
Physical board ID map	IDs of boards present in the system


To view the Advanced Options menu: from the Change Configuration Settings dialog box, press F9.

3.4.5.6 Save Configuration

This step saves the configuration settings to nonvolatile RAM as well as to a backup file (.CMS file). You must save your settings once they have been configured.

3.4.5.7 View Switch/Jumper Settings

Use this step to view manufacturer's instructions about setting dip switches and jumpers, and how to run utilities to ensure correct configuration of each adapter.



OM04255

This feature is not supported for the AP450GX MP Server baseboard.

3.4.5.8 Exit

This step exits to the operating system. If any configuration settings were changed, you will be prompted to restart your system to see the changes.

3.4.6 About the Options

Refer to the AP450GX MP Server Installation Guide, Intel Part #642976, for a list of SCU groups as they are displayed on screen after you select System Board from the Change Configuration Settings screen. These are the groups: Systems Group, Peripheral Configuration Group, LCD Display, Management Subsystem, and System Management.

After each group, some of the option choices are described in the AP450GX MP Server Installation Guide. Not all of them are described because (a) a few are not user-selectable but are displayed for your information, and (b) many of the option choices are relatively self-explanatory.

3.5 SCSISelect Utility

The *SCSISelect* utility detects the number of SCSI AIC-78xx host adapters in your system. Use the utility to start, format, and verify SCSI drives or to explicitly configure the SCSI host adapter to settings other than defaults.

The utility is menu-driven. Follow the screen prompts and information about moving around through the menus and selecting options. Refer to the AP450GX MP Server Installation Guide, Intel Part #642976, for more details on the *SCSISelect* utility.

4 Error Messages and Beep Codes

4.1 BIOS Beep Codes

Table 4.1 Beep Codes

Beep Count	Port 80 Codes	Error Condition
1	71h	Refresh failure
2	72h	Parity cannot be reset
3	73h	First 64 KB memory failure
4	74h	Timer not operational
5	75h	Processor failure
6	76h	8042 Gate A20 is off (v_mode)
7	77h	Exception interrupt error
8	78h	Display memory R/W error
9	79h	ROM checksum error
10	7Ah	Shutdown reg. R/W error
11	7Bh	I ² C Error

4.2 POST Codes and Countdown Codes

At power-on, after the video adapter has been initialized, the BIOS indicates the current testing phase by sending a 2-digit hex code to I/O location 80h. The current countdown code will be displayed on the LCD panel, once the panel is initialized.

4.2.1 Recovery Port-80 Codes and Countdown Codes Displayed

During BIOS recovery, the diskette in drive A is booted, and a BIOS image is automatically installed.

Table 4.2 Recovery Port-80 Codes

Port 80 Code	Countdown Code	Reason
02h		Disable internal cache
08h		Disable DMA controller #1, #2, disable interrupt controller #1, #2, reset video display
13h		Initialize all chip set registers (Enable LCD display here)
15h	900	Initialize system timer
1Bh	800	Real mode base 64 KB test
20h	700	16 KB base RAM test
23h	650	Setup interrupt vectors
40h	600	Test memory in virtual mode
65h	500	Initialize 8237 DMA controller
67h	400	8259 interrupt controller test
80h	300	Unmask diskette, keyboard and timer interrupts
88h	200	Floppy unit initialization
A0h	100	Cache enable
00h	000	Boot OS

4.2.2 Standard Port-80 Codes and Countdown Codes Displayed

Table 4.3 Standard Port-80 Codes

Port 80 Code	Countdown Code	Reason
D0h		Early MP Initialization
D1h		Power On Initialization
D2h		Disable NMI
D3h		Reset video controller
D4h		Enter real mode
D5h		Checksum the 8 KB loader BIOS
D6h		Loader BIOS checksum good
D7h	900	Check if Keyboard Controller (KBC) buffers are free
D8h		Issue BAT (basic assurance test) command to KBC
D9h		Read BAT results
DAh		Check if keyboard controller passed BAT
DBh	820	Keyboard Initialization Passed
DDh		Disable keyboard and auxiliary devices
DFh		Disable both DMA controllers
E0h	780	Preliminary initialization of PICs
E1h		Enter real big mode and initialize chip set, size memory
E2h		Initialize timer 2 for speaker
E3h	760	Initialize timer channel 0 for system timer
E4h		Clear any pending parity errors
E6h	740	Test RAM from 0-640 KB
E7h		Test and initialize 2 MB memory
E8h		RAM failure, remap memory partitions and test again

Continued

Port 80 Code	Countdown Code	Reason
E9h		RAM test complete, passed. Clear parity errors
EAh	730	Set up stack at 30:100, enable cache and shadow BIOS
EBh		Initialize code dispatcher
ECh		Make F000h DRAM R/W Enabled
EDh		Dispatch POST
23h	700	Initializations before setting up vector table
24h		Setup interrupt vector table
0Dh		Check CMOS clear jumper
0Eh	690	Check validity of CMOS
0Fh		Force CMOS defaults if required
10h		CMOS initialization complete
25h		Nothing
28h		Set monochrome mode
29h		Set color display
2ah		Clear parity status if any, initialize warm reset flag
2bh		Video autoconfiguration and initialization
F0h		EISA Slot Initialization
F1h		Enable extended NMI sources
F2h		Test extended NMI sources
2ch	580	Conventional video option ROM search
2dh		Scan user flash
2eh	570	Initialize monochrome display if no other video present
2fh	560	Test buffer memory for monochrome
30h		Check vertical and horizontal retrace

Continued

Port 80 Code	Countdown Code	Reason
31h		Test for color display memory if no external video BIOS found
32h		Check vertical retrace
34h		Sign on message
36h		Initialize Messaging Services and clear screen
37h	500	Custom sign on display
80h	370	Keyboard/mouse port check
81h		Keyboard controller initialization and testing
83h		Check if keyboard is locked
F5h	330	Initialize mouse
39h		Keyboard, mouse and other signons
3bh		Prepare for memory test
43h	290	Decide memory size from chip set
4Fh		Disable cache, test memory and display memory size on screen
52h		Initialize for the other processors in MP system, reset DMA controller
61h	250	DMA register tests
62h		DMA test OK
65h		Initialize 8237 DMA controller
66h		Clear DMA write request register and mask set/reset register
67h	220	8259 Interrupt controller test
F4h		Enable extended NMI sources
8Ch	140	Initialize remaining Plug-N-Play devices (i.e., other than video), initialize IPL, initialize IDE controller

Continued

Port 80 Code	Countdown Code	Reason
8Fh	130	Floppy Initialization
92h		Set printer, RS-232 time-out
96h		Optional ROM scan and initialize above C800h
97h	080	Scan User flash and conventional option ROM scan
98h		Scan User flash area
9Ah		Clear soft reset flag, complete MP Table
9Dh	070	Timer data area initialization
A0h		Printer setup
A1h		RS-232 setup
A2h		Check for stuck key
ABh		Before NPX test and initialization
ACH	060	NPX test and initialization
ADh		Update coprocessor information in CMOS and recalculate checksum
Aeh		Set typematic rate
AFh	050	Keyboard read ID command
B0h		Wait for READ ID response
A3h		Display POST errors
A6h		Before Setup
A7h	030	Call Setup if required, prompt for password if enabled
B1h		Enable Cache for boot
B3h		Setup display mode set
B4H		Jump to pre-OS code
BBh	020	Initialize SMI code, prepare for boot
00h	000	Execute BOOT

4.3 POST Error Codes and Messages

The BIOS indicates errors as follows:

- By writing an error code to the PS/2-standard logging area in the Extended BIOS Data Area.
- By displaying a POST Error Code and message on the screen.

Table 4.4 POST Error Codes

Number	Error message
0002	Primary Boot Device Not Found
0010	Cache Memory Failure, Do Not Enable Cache
0015	Primary Output Device Not Found
0016	Primary Input Device Not Found
0041	EISA ID Mismatch for Slot
0042	ISA Config contains invalid info
0043	EISA Invalid Configuration for Slot
0044	EISA config NOT ASSURED!
0045	EISA Expansion Board Not Ready in Slot
0047	EISA CMOS Configuration Not Set
0048	EISA CMOS Checksum Failure
0049	EISA NVRAM Invalid
0050	PnP Memory Conflict
0051	PnP 32 bit Memory Conflict
0052	PnP IRQ Conflict
0053	PnP DMA Conflict
0054	PnP Error Log is Full
0055	Bad PnP Serial ID Checksum
0056	Bad PnP Resource Data Checksum
0060	Keyboard Is Locked ... Please Unlock It
0070	CMOS Time & Date Not Set
0080	Option ROM has bad checksum
0081	Custom Binary Checksum Failure
0083	Shadow of PCI ROM Failed
0084	Shadow of EISA ROM Failed

Number	Error message	(continued)
0085	Shadow of ISA ROM Failed	
0131	Floppy Drive A:	
0132	Floppy Drive B:	
0135	Floppy Disk Controller Failure	
0140	Shadow of System BIOS Failed	
0162	Unable to apply BIOS Update for Slot 1 Processor #1	
0163	Unable to apply BIOS Update for Slot 1 Processor #2	
0164	Unable to apply BIOS Update for Slot 2 Processor #1	
0165	Unable to apply BIOS Update for Slot 2 Processor #2	
0166	BIOS does not support current stepping of Slot 1 Processor #1	
0167	BIOS does not support current stepping of Slot 1 Processor #2	
0168	BIOS does not support current stepping of Slot 2 Processor #1	
0169	BIOS does not support current stepping of Slot 2 Processor #2	
0170	Disable CPU slot #	
0171	CPU Failure - Slot 1, CPU # 1	
0172	CPU Failure - Slot 1, CPU # 2	
0173	CPU Failure - Slot 2, CPU # 1	
0174	CPU Failure - Slot 2, CPU # 2	
0175	CPU modules are incompatible	
0176	Previous CPU Failure - Slot 1, CPU # 1	
0177	Previous CPU Failure - Slot 1, CPU # 2	
0178	Previous CPU Failure - Slot 2, CPU # 1	
0179	Previous CPU Failure - Slot 2, CPU # 2	
0180	Attempting to boot with failed CPU	
0181	BSP switched, system may not be in uniprocessor mode	
0191	CMOS Battery Failed	
0195	CMOS System Options Not Set	
0198	CMOS Checksum Invalid	
0200	Invalid voltage jumper for processor in Slot 1 Processor #1	
0201	Invalid voltage jumper for processor in Slot 1 Processor #2	
0202	Invalid voltage jumper for processor in Slot 2 Processor #1	
Number	Error message	(continued)

0203	Invalid voltage jumper for processor in Slot 2 Processor #2
0204	CPU Removed - Slot 1, CPU #1
0205	CPU Removed - Slot 1, CPU #2
0206	CPU Removed - Slot 2, CPU #1
0207	CPU Removed - Slot 2, CPU #2
0208	CPU not responding - Slot Slot 1, CPU #1
0209	CPU not responding - Slot Slot 1, CPU #2
0210	CPU not responding - Slot Slot 2, CPU #1
0211	CPU not responding - Slot Slot 2, CPU #2
0220	Fan Failure Slot 1 Processor #1
0221	Fan Failure Slot 1 Processor #2
0222	Fan Failure Slot 2 Processor #1
0223	Fan Failure Slot 2 Processor #2
0230	Invalid processor for module in Slot 1 Processor #1
0231	Invalid processor for module in Slot 1 Processor #2
0232	Invalid processor for module in Slot 2 Processor #1
0233	Invalid processor for module in Slot 2 Processor #2
0289	System Memory Size Mismatch
0295	Address Line Short Detected
0297	Memory Size Decreased
0299	ECC Error Correction failure
0301	ECC Single bit correction failed, Correction Disabled
0302	ECC Double bit Error
0303	ECC SIMMs incompatible
0304	Invalid memory configuration. Caused by either memory failures during POST or invalid combination of SIMM sizes.
0305	PCI-to-PCI bridge found, IO Queue Depth set to 1, setup value overridden
0309	ECC Memory Failure
0310	ECC Memory Size Changed, Bank #1 (2GB memory module)
0311	ECC Memory Size Changed, Bank #2 (2GB memory module)
0312	ECC Memory Size Changed, Bank #3 (2GB memory module)

Number	Error message	(continued)
--------	---------------	-------------

0313	ECC Memory Size Changed, Bank #4 (2GB memory module)
0314	ECC Memory Size Changed, Bank #0 (4GB memory module)
0315	ECC Memory Size Changed, Bank #1 (4GB memory module)
0316	ECC Memory Size Changed, Bank #2 (4GB memory module)
0317	ECC Memory Size Changed, Bank #3 (4GB memory module)
0320	Adding/removing PCI adapters has changed available memory.
0322	An error has caused the memory resizing to fail, insufficient memory to continue.
0370	Keyboard Controller Error
0373	Keyboard Stuck Key Detected
0375	Keyboard and Mouse Swapped
0380	ECC SIMM failure, Board in slot 1 SIMM #
0392	ECC SIMM failure, Board in slot 2 SIMM #
0430	Timer Channel 2 Failure
0440	Gate-A20 Failure
0441	Unexpected Interrupt in Protected Mode
0445	Master Interrupt Controller Error
0446	Slave Interrupt Controller Error
0450	Master DMA Controller Error
0451	Slave DMA Controller Error
0452	DMA Controller Error
0460	Fail-safe Timer NMI Failure
0461	Software Port NMI Failure
0465	Bus Time-out NMI in Slot
0467	Expansion Board NMI in Slot
0510	PCI Parity Error
0511	PCI System Error
0710	System Board Device Resource Conflict
0711	Static Device Resource Conflict
0780	PCI Segment 1 memory request exceeds 998Mb
0781	PCI Segment 1 I/O requests exceeds 12K
0782	PCI I/O request exceeds amount available

Number	Error message	(continued)
--------	---------------	-------------

0783	PCI memory request exceeds amount available
0784	Illegal bus for memory request below 1Mb
0785	Memory request below 1Mb exceeds 1Mb
0800	PCI I/O Port Conflict
0801	PCI Memory Conflict
0802	PCI IRQ Conflict
0803	PCI Error Log is Full
0804	PCI ROM not found, May Be OK For This Card
0805	Insufficient Memory to Shadow PCI ROM
0806	Memory Allocation Failure for Second PCI Segment
0809	PCI Error Log is Full
0810	Floppy Disk Controller Resource Conflict
0811	Primary IDE Controller Resource Conflict
0812	Secondary IDE Controller Resource Conflict
0815	Parallel Port Resource Conflict
0816	Serial Port 1 Resource Conflict
0817	Serial Port 2 Resource Conflict
0900	NVRAM Checksum Error, NVRAM Cleared
0903	NVRAM Data Invalid, NVRAM Cleared
0905	NVRAM Cleared By Jumper
0906	Password Cleared By Jumper
0982	I/O Expansion Board NMI in Slot
0984	Expansion Board Disabled in Slot
0985	Fail-safe Timer NMI
0986	System Reset caused by Watchdog Timer
0987	Bus Time-out NMI in Slot

5 Electrical, Environmental and Mechanical Specifications

This chapter specifies the operational parameters and physical characteristics for the processor, memory, and termination modules and the baseboard. This is a board-level specification only. System specifications are beyond the scope of this document.

5.1 Absolute Maximum Ratings

Operation at conditions beyond those shown in the following table may cause permanent damage to the system (provided for stress testing only). Exposure to absolute maximum rating conditions for extended periods may affect system reliability.

Table 5.1 Absolute Maximum Board Level Ratings

Operating temperature for board set	0°C to +55°C Note: Chassis design must meet the Pentium® Pro processor maximum case temperature as specified in the <i>Pentium Pro Electrical Mechanical and Thermal Specification</i> .
Storage temperature	-55°C to +150°C
Voltage on any signal with respect to VSS	-0.3 to supply voltage + 0.3 V
Supply voltage with respect to VSS	-0.3 to +5.5 V (VCC only)

Further topics in this chapter specify normal operating conditions.

5.2 Electrical Specifications

Below is a summary of the power requirements for the AP450GX MP Server Board Set.

Table 5.2 Voltage and Current Specifications

Voltage	Specification	Min Current	Max Current	Max di/dt	Suggested Bulk Capacitance (in power supply)	Notes
+3.3V	3.3V ± 5%	---	28A	14A/300uS	80,000uF	1,2,3,4,5
+5V	5.0V ± 5%	---	40A	14A/300uS	80,000uF	1,2,3,5
+12V	12.0V ± 5%	---	18.5A	0.2A/uS	10,000uF	1,2,5
-5V	-5.0V ± 5%	---	0.25A	---	---	1,2
-12V	-12.0V ± 10%	---	1A	---	---	1,2

Notes:

- All values are specified at the power supply connector on the baseboard.
- di/dt is the maximum rate of change of current the power supply must be able to supply to the board set while keeping the voltage within tolerance.
- Bulk Capacitance is a suggestion only. The system integrator is looked upon to make the appropriate determination.
- Max values for +3.3V will only be achieved if the 4GB Memory Module is installed, which uses 3.3V DIMMs.
- Remote sense capabilities should be used to ensure proper regulation

Table 5.3 Voltage Sequencing Specifications

Parameter	Description	Specification	Notes
T _{rise}	Voltage Rise Time	100 mS	1
T _{fall}	Voltage Fall Time	None	2
T _{sequence-on}	Voltage Sequencing During Power On	None	3
T _{sequence-off}	Voltage Sequencing	None	3

PwrGood	During Power Off		
	PowerGood Assertion	Min = 100mS Max = 1500mS	4
$T_{\text{powerGood Rise}}$	PowerGood Rise Time	0.5V/ns	Typical value

Notes:

1. Voltage rise time is the time it takes for all voltages input to the baseboard (+3.3V, +5V, +12V, -5V, -12V) to be within their specified value as noted in Table 5.2. This time is measured from the time the voltages begin their rise from ground (0 Volts).
2. Voltage fall time is the time it takes for all voltages input to the baseboard to drop to 0V from the time the power supply is turned off.
3. There are no voltage sequencing requirements during power on or power off. All voltages can come up in any order, but they all must be within their specified value within 50mS as defined by T_{rise} .
4. PwrGood must be asserted no sooner than 100mS, but not longer than 1500mS after all voltages are within their specified values as defined by T_{rise} (the rise time of Power Good).

5.3 Environmental

Table 5.4 Board Set Environmental Specifications

Environmental Condition		Specification
Temperature	nonoperating	-40° to 70°C (-40° to 158°F)
	operating	0° to 55°C (to 131°F)
Temperature, thermal map		Must not exceed maximum IC junction temperature as specified in the component data sheets.
Thermal shock	nonoperating	-40° to 70°C (-40° to 158°F)
Humidity	nonoperating	92% relative humidity (noncondensing) at 55°C (131°F)
	operating	85% relative humidity (noncondensing) at 55°C (131°F)
Vibration	nonoperating	Random input, 0.01 g2/Hz at 5 Hz, sloping to 0.02 g2/Hz at 20 Hz, and maintaining 0.02 g2/Hz from 20 Hz to 500 Hz.
Shock	nonoperating	50 g, 11 ms, 1/2 sine
	operating	Not applicable
Altitude	nonoperating	To 50,000 ft (15,240 m)
	operating	To 10,000 ft (3,048 m)
Electrostatic discharge (ESD)	operating	Tested to 25 kV; no component damage
EMI	operating	Tested as part of system; required to meet EMI emission requirements

5.4 Cooling Requirements

Below are the cooling requirements for the board set, specifically the processors. The first table specifies cooling requirements for the primary processor module. The second table is for the secondary processor module. Both tables assume both processor sockets on each module are populated. Ambient temperature is measured just before it passes over the processor module.

Table 5.5 Primary Processor Module Cooling Requirements

30W Processor		35W Processor		40W Processor	
Air Flow (LFM)	Max Ambient Temp (°C)	Air Flow (LFM)	Max Ambient Temp (°C)	Air Flow (LFM)	Max Ambient Temp (°C)
100	30.7	100	20.3	100	16.3
200	42.9	200	33.7	200	29.9
300	51.2	300	44.2	300	39.6
400	56.2	400	50.8	400	46.7
500	59.6	500	55	500	50.4

Table 5.6 Secondary Processor Module Cooling Requirements

30W Processor		35W Processor		40W Processor	
Air Flow (LFM)	Max Ambient Temp (°C)	Air Flow (LFM)	Max Ambient Temp (°C)	Air Flow (LFM)	Max Ambient Temp (°C)
100	28.3	100	24.3	100	17.3
200	41.5	200	37.5	200	29.9
300	49.3	300	46.1	300	40.6
400	55.6	400	51.6	400	46.8
500	59.2	500	55.2	500	50.9

5.5 Power Budget

All power for the Pentium Pro processors on the processor module is provided by DC-DC converters powered from the +12V supply. There is also a DC-DC converter used for the GTL+ termination voltage reference. The efficiency of the converters is 80%.

I²C components are powered from +5 volts.

All power numbers are given for worst case conditions, not nominal. See the *Pentium Pro Processor Data Sheet* for details of Pentium Pro processor power requirements.

Voltage tolerance is ± 5%.

The numbers below are for the baseboard, processor, and memory modules. The system integrator is looked upon to make cost / performance / market tradeoffs to determine how much power to dedicate for add-in slots.

Table 5.7 Example Power Budget in Watts (Maximum Values)

	-12V	+12V	+3.3V	+5V
Processor Module	0	99.2	0.2*	1.4
Termination Module	0	10.9	0	0.9
Memory Module (1GB)	0	0	3.9	75.3
Baseboard (no add-in cards)	1.2	1.2	7.0	10.0
Total Watts			300.2	

Assumptions:

**two processor modules, four 35W
processors (166/512KB), 1GB of
memory, no add-in cards**

* The Pentium® Pro processor pinout also specifies power at +3.3V. These numbers assume the Pentium Pro processor does not use that voltage. Refer to the *Pentium Pro Processor Data Sheet* for details.

5.6 Mechanical Drawings

The following diagrams show the mechanical specifications of the baseboard, processor module, termination module, and memory module. All dimensions are given in inches, as per ANSI Y15.4M. Maximum primary-side component height is .550" unless otherwise noted. Connectors are dimensioned to pin 1. Refer to "Connector Specifications" after the diagrams for more information.

5.6.1 Processor and Terminator Module Mechanical Specifications




Figure 5.1 Processor and Terminator Module Mechanical Specifications

5.6.3 Baseboard Mechanical Specifications




Figure 5.3 Baseboard Mechanical Specifications

5.6.4 Module Insertion/Extractor Handle Specifications

The card ejection lever shown below is a requirement for the processor and memory modules in the Pentium Pro processor server system. The cards must be seated into the baseboard connector at no more than a 5° deviation from perpendicular to avoid damage to the baseboard. Using the ejection lever ensures that these modules are completely seated, and eases the insertion /extraction force needed to correctly remove and install the modules.

In addition to the ejection levers, card guides and a hold down rail are required to keep the cards from moving around and becoming displaced during shipping or handling.




Figure 5.4 Module Insertion/Extractor Handle

5.7 Connector Specifications

The following table shows reference designators, quantity, and the manufacturer's part numbers for connectors on the baseboard and processor module. Item numbers reference the circled numbers on the baseboard mechanical drawing. Refer to manufacturers' documentation for more information.

Table 5.8 Connector Specifications

Item	Ref. Designator(s)	Qty	Mfr(s) and Part #	Description
1	J1A1, J1A2, J2A1, J2A2	4	Burndy CB2E188SC-13Z14	EISA bus add-in card connector
2	J5A2, J5A3, J4A2, J4A1, J3A2, J3A1	6	AMP 646255-1	PCI add-in card connector
3	J1F1, J1G1	2	AMP 74931-7	68-pin SCSI connector
4	J6D1, J7D1, J9C1	3	AMP 145264-1	Processor and memory bus connectors
7	J9F1	1	3M 3432-Z00044	LCD front panel display connector
8	J9E1	1	3M 2450-60Y2UB or G	IDE connector
9	J9E2	1	3M 2534-60V2UG	Floppy connector
10	J9A2	1	Molex 39-29-9144	Power control connector (PS3)
11	J9D1, J9B1	2	Molex 39-29-9202	20-pin power connector (PS1 & PS2)
14	J3G1	1	Fox Conn/Hon Haj HC11131-KD6	Server Management feature connector
16	J7A1	1	AMP 750433-2	VGA and Parallel port connector
17	J8A1	1	Fox Conn/Hon Haj DM10156-73	Dual serial port connector
18	J9A1	1	Fox Conn/Hon Haj MH11063-D0	Keyboard and mouse connector
	J5G3, J2G4, J2G3, J5G2, J107, J102	6	AMP640456-3	System & CPU Fan Connector (3 pin) (J107 & J102 on processor module)
	J2G1, J5G1	2	AMP 640456-4	Hard Disk LED Connector (4 pin)

Appendix A -- Supported Environments

The AP450GX MP Server has been validated with the leading network operating systems, adapter cards, video DRAM and SIMM/DIMM combinations. Not all configurations have been validated and there may be limitations to their interoperability. Contact your Intel representative for the latest interoperability information.

A.1 Certified Operating Systems

The table below lists the operating system certifications for the AP450GX MP Server System.

- Level 1 - Heavy testing done in Intel's Server Validation Lab
- Level 2 - Minimal testing done in Intel's Compatibility Engineering Lab

Level	Operating System	Version	Certification Status
1	Windows NT	3.51 & 4.0	OEM must certify with Microsoft
1	Novell NetWare	3.12 & 4.11	Completed at Novell facility
1	IBM OS/2	LANServer 4.0 Advanced	Completed at IBM facility
1	SCO UnixWare	2.1	OEM must certify with SCO
2	Banyan	6.0	Completed at Banyan facility
2	IBM OS/2	3.0 WARP	Completed in Intel's Compatibility Engineering Lab
2	SCO UNIX	OpenServer 5.0 & 5.0MPX	OEM must certify W/SCO
2	Solaris	2.5	Completed in Intel's Compatibility Engineering Lab

A.2 Tested Adapter Cards

Contact your Intel representative for an updated list of adapter cards that have been tested with the AP450GX MP Server System.

A.3 Qualified SIMM/DIMMs

Only use SIMMs and DIMMs approved for use in this system. Contact your Intel representative for an updated list of qualified SIMMs and DIMMs.

A.4 Qualified Video DRAM

Only use video DRAM approved for use in this system. Contact your Intel representative for an updated list of qualified Video DRAM.

Appendix B -- Product Codes

Contact your Intel representative for the current product codes, availability, and pricing.

Appendix C -- Connector Pinouts

Below is the pinout for each connector on the AP450GX MP Server Board Set.

C.1 Power Connectors PS1 and PS2, Baseboard

The baseboard receives power at PS1 and PS2 from connectors J6 and J7 on the power distribution board. PS1 and PS2 are identical; J6 and J7 are identical.

Table C.1 Power Connectors

Pin	Signal	Pin	Signal
1	+5 VDC	11	+12 VDC
2	GND	12	GND
3	+5 VDC	13	+12 VDC
4	GND	14	GND
5	+5 VDC	15	+3.3 VDC
6	GND	16	GND
7	+5 VDC	17	+3.3 VDC
8	GND	18	GND
9	+5 VDC	19	+3.3 VDC
10	GND	20	GND

C.2 Power Status/Control Signal Connector PS3, Baseboard

The baseboard receives power status and control signals at PS3 from connector J11 on the power distribution board.

Table C.2 Power Status/Control Signal Connector

Pin	Signal	Pin	Signal
1	-12 VDC	8	+5 V standby
2	-5 VDC	9	GND
3	PWR_ON	10	PWRGOOD
4	I ² C-SDA (Data)	11	GND
5	I ² C-SCL (Clock)	12	I ² C_PRESENT
6	+5V remote sense (+)	13	+3.3V remote sense (+)
7	+12V remote sense (+)	14	Ground remote sense (-)

C.3 Diskette Drive Connector, Baseboard

Table C.3 Diskette Drive Connector

Pin	Signal	Pin	Signal
1	GND	18	Head direction
2	Density select	19	GND
3	GND	20	Step
4	Not connected	21	GND
5	Key (pin missing)	22	Write data
6	Extended density in	23	GND
7	GND	24	Write enable
8	Index	25	GND
9	GND	26	Track 0
10	Motor A on	27	GND
11	GND	28	Write protect
12	Drive B select	29	Extended density out
13	GND	30	Read data
14	Drive A select	31	GND
15	GND	32	Head select side 1
16	Motor B on	33	High density out
17	GND	34	Disk change

C.4 Front Panel Connector, Baseboard

Table C.4 Front Panel Connector

Pin	Signal name	Type	Function
1	SPKRDAT	Out	Drives standard PC-AT speaker
2	VCC5	Out	5 V power supply
3	5VSTANDBY	Out	5 V power supply standby
4	PS_ON	I/O	Power supply on/off switch connection
5	FP_RESET #	In	Active-low front panel reset switch connection
6	GND		Ground
7	FP_NMI #	In	Connects to FP_NMI driver
8	GND		Ground
9	HD1_LED_VCC		Hard Drive #1 LED Activity indicator return
10	HD1_LED_ACT#		Hard Drive #1 LED Activity indicator
11	HD2_LED_ACT#		Hard Drive #2 LED Activity indicator
12	HD2_LED_VCC		Hard Drive #2 LED Activity indicator return
13	KEYLOCK#		Keyboard lock signal
14	GND		Ground
15	SECURE	Out	Secure mode indicator
16	VCC5	Out	LCD Display controller power
17	KEY		Not connected
18	VCC5	Out	5 V power supply
19	I ² C-SDA	I/O	I ² C interface data signal
20	CHASIS_SWT_RET	In	Chassis intrusion detection switch return
21	LCD_SD	I/O	Serial I/O data to LCD controller
22	H_PWROFF#	Out	Host power control (from Server Management board)

Continued

Front Panel Connector, Baseboard, continued

Pin	Signal name	Type	Function
23	LCD_SCLK	Out	Clock for LCD serial I/O
24	I2C_SCL	I/O	I ² C interface clock signal
25	LCD_PCLK	Out	LCD controller processor clock
26	GND		Ground
27	EN	Out	LCD enable
28	GND		Ground
29	RW	Out	LCD Read/Write strobe
30	VCC3		3.3 V power supply
31	RS	Out	LCD reset
32	PWR#	Out	RTC power control indication
33	LCD_GND	Out	LCD display ground connection
34	GND		Ground
35	FAN_FAIL#	Out	Indicates failure of at least one cooling fan
36	GND		Ground
37	I2C_PRES		I ² C control signal
38	RESERVED		Reserved
39	Vcc		Vcc
40	RESERVED		Reserved

- Out: driven by system baseboard. In: driven by front panel.
- # at the end of a signal name indicates an active low signal

C.5 IDE Drive Connector, Baseboard

Table C.5 IDE Drive Connector

Pin	Signal	Pin	Signal
1	IDERST#	2	GND
3	ID7 (data bit 7)	4	ID8 (data bit 8)
5	ID6 (data bit 6)	6	ID9 (data bit 9)
7	ID5 (data bit 5)	8	ID10 (data bit 10)
9	ID4 (data bit 4)	10	ID11 (data bit 11)
11	ID3 (data bit 3)	12	ID12 (data bit 12)
13	ID2 (data bit 2)	14	ID13 (data bit 13)
15	ID1 (data bit 1)	16	ID14 (data bit 14)
17	ID0 (data bit 0)	18	ID15 (data bit 15)
19	GND	20	Keyed (pin missing)
21	IDEDRQ (DMA request 3)	22	GND
23	IDEIOW# (I/O write)	24	GND
25	IDEIOR# (I/O read)	26	GND
27	CHRDY (I/O channel ready)	28	SPSYNC (address latch enable)
29	IDEDAK# (DMA acknowledge 3)	30	GND
31	IDEIRQ14 (interrupt request 14)	32	IDEIO16 # (I/O channel size 16)
33	IDESA1 (address bit 1)	34	PDIAG #
35	IDESA0 (address bit 0)	36	IDESA2 (address bit 2)
37	IDECS0# (host chip select 0)	38	IDECS1# (host chip select 1)
39	IDEHDACT#/DRVPRES# disk activity/drive present)	40	GND

C.6 Fan Connector, Baseboard & Processor Module

Table C.6 Fan Connectors

Pin	Function
1	GND
2	+12V
3	Fan fail sensor

C.7 Hard Drive LED Connectors, Baseboard

Table C.7 Hard Drive LED Connectors

Pin	Function
1	not connected
2	HD1_ACTIVE#
3	HD2_ACTIVE#
4	not connected

C.8 I2C Connector, Baseboard

Table C.8 I2C Connector

Pin	Function
1	I2C_SDA (Data)
2	GND
3	I2C_SCL (Clock)

C.9 3.3V PCI Power Connector, Baseboard

Table C.9 +3.3 Volt PCI Power Connector

Pin	Function
1	GND
2	GND
3	GND
4	+3.3V PCI
5	+3.3V PCI
6	+3.3V PCI

C.10 Server Monitor Module Connector, Baseboard

Table C.10 Server Monitor Module Connector

Pin	Signal	Type	Description
1	SMI#	Input	System management interrupt
2	I2C_CLK	Output	I ² C clock (8 MHz)
3	GND	Power	Ground
4	Reserved		No connection
5	PWROFF#	Output	Power supply off (active low)
6	I2CDATA	I/O	I ² C data signal
7	LPOK	Input	Host line power okay
8	KEYUNLK#	Input	Keyboard unlock
9	NMI	Input	Nonmaskable interrupt
10	3.3 V	Input	3.3 V power
11	RESET#	Output	Reset system board
12	GND	Power	Ground
13	GND	Power	Ground
14	Reserved		No connection
15	SECURE	Input	Host in secure mode
16	GND	Power	Ground
17	INTRUD	Input	Chassis is open
18	Reserved		No connection (reserved for future use)
19	Reserved		No connection
20	GND	Power	Ground
21	Reserved		No connection
22	Reserved		No connection
23	POWERGD		Power to system is within specification
24	Reserved		No connection
25	Reserved		No connection, pin missing
26	Reserved		No connection

C.11 SCSI Channel A and B Connectors, Baseboard




Table C.11 68-pin Wide SCSI Connector

Signal name	Connector contact	SCSI bus conductor	SCSI bus conductor	Connector contact	Signal name
GND	1	1	2	35	DB(12) #
GND	2	3	4	36	DB(13) #
GND	3	5	6	37	DB(14) #
GND	4	7	8	38	DB(15) #
GND	5	9	10	39	DB(P1) #
GND	6	11	12	40	DB(0) #
GND	7	13	14	41	DB(1) #
GND	8	15	16	42	DB(2) #
GND	9	17	18	43	DB(3) #
GND	10	19	20	44	DB(4) #
GND	11	21	22	45	DB(5) #
GND	12	23	24	46	DB(6) #
GND	13	25	26	47	DB(7) #
GND	14	27	28	48	DB(P) #
GND	15	29	30	49	GND
GND	16	31	32	50	GND
TERMPWR	17	33	34	51	TERMPWR
TERMPWR	18	35	36	52	TERMPWR
Reserved	19	37	38	53	Reserved
GND	20	39	40	54	GND
GND	21	41	42	55	ATN #
GND	22	43	44	56	GND
GND	23	45	46	57	BSY #
GND	24	47	48	58	ACK #
GND	25	49	50	59	RST #
GND	26	51	52	60	MSG #
GND	27	53	54	61	SEL #
GND	28	55	56	62	CD #
GND	29	57	58	63	REQ #
GND	30	59	60	64	I/O #
GND	31	61	62	65	DB(8) #
GND	32	63	64	66	DB(9) #
GND	33	65	66	67	DB(10) #
GND	34	67	68	68	DB(11) #

C.12 PCI Connectors, Baseboard

The baseboard PCI connectors adhere to the requirements in the PCI Specification 2.0.

C.13 VGA Video Port, Baseboard




Table C.12 VGA Video Port

Pin	Signal	Pin	Signal
1	Red	9	Not connected
2	Green	10	GND
3	Blue	11	Not connected
4	Not connected	12	Not connected
5	GND	13	HSYNC (horizontal sync)
6	GND	14	VSYNC (vertical sync)
7	GND	15	Not connected
8	GND		

C.14 Parallel Port Connector, Baseboard




Table C.13 Parallel Port Connector

Pin	Signal	Pin	Signal
1	Strobe #	10	ACK (acknowledge) #
2	Data bit 0	11	Busy
3	Data bit 1	12	PE (paper end)
4	Data bit 2	13	SLCT (select)
5	Data bit 3	14	AUFDXT (auto feed) #
6	Data bit 4	15	Error #
7	Data bit 5	16	INIT (initialize printer)
8	Data bit 6	17	SLCTIN (select input) #
9	Data bit 7	18–25	GND

C.15 Serial Port Connectors 1 and 2, Baseboard





Table C.14 Serial Port Connectors

Pin	Signal
1	DCD (data carrier detect)
2	RXD (receive data)
3	TXD (transmit data)
4	DTR (data terminal ready)
5	GND
6	DSR (data set ready)
7	RTS (request to send)
8	CTS (clear to send)
9	RI (ring indicator)

C.16 Keyboard and Mouse Connectors, Baseboard



OM04418 These identical PS/2-compatible connectors share a common housing.

Table C.15 Keyboard and Mouse Connectors

Pin	Keyboard signal	Pin	Mouse signal
1	KEYDAT (keyboard data)	1	MSEDAT (mouse data)
2	Not connected	2	Not connected
3	GND	3	GND
4	FUSED_VCC (+5 V)	4	FUSED_VCC (+5 V)
5	KEYCLK (keyboard clock)	5	MSECLK (mouse clock)
6	Not connected	6	Not connected

Appendix D - 450GX PCIset Register Changes

The following register changes have occurred in the 450GX PCIset as a result of going from the B0 stepping to the C0 stepping of the chipset. For a more detailed description of each register change, please refer to the Specification Update for the Intel 450GX PCIset.

- ◆ Register 48h, bit 3 - Alias GAT mode sideband request to non-GAT mode

This bit allows the PCEB to be operated in GAT mode (so that EISA tenure is limited) while the OPB operates in nonGAT mode (so that BPRI is deasserted between requests).

- ◆ Register 48h, bit 4 - Use slow BPRI deassertion

This bit forces serialization of inbound requests. This is necessary in systems where inbound read prefetching can occur to a device that can issue a hard fail response.

- ◆ Register 48h, bit 5 - Disable Livelock Workaround

If this bit is zero (default), then nonGAT mode is entered for 64 clocks after an outbound request is retried. Setting bit 5 to one disables this new feature.

- ◆ Register 48h, bit 6 - Disable Outbound Traffic Priority

This bit can be asserted to effectively override the priority normally given to outbound requests. If this bit is zero (default), then nonGAT mode is entered for 64 clocks after an inbound request is retried eight times. Setting bit 6 to one disables this new feature.

- ◆ Register B0[8] is now reserved

This bit was the AERR input enable bit for the Driven on Reset register. The AERR input is now always on. Register B0[8] must be set to 0 so that no other Pentium Pro processor devices will observe AERR.

- ◆ Register C0[1] - AERR# to BERR#

This bit was added as another method of reporting AERRs. BERR# can optionally be elevated to BINIT#.

- ◆ Register C8[31:16] - Pentium Pro processor Retry Counter

This is not a new register, but its optimum value has changed since the B0 stepping. For optimum performance this counter should be left at its default value of 0 (in B0 systems the recommendation was to set it to a small, non-zero value).

- ◆ Register CC[15:0] - Unused Agent ID

These bits represent the Pentium Pro processor agent IDs that are not in use on the Pentium Pro processor bus. Bits 15 to 0 translate to agent IDs 31 to 16 respectively. A “1” in a bit location means the ID is not used by a Pentium Pro processor bus agent.

Appendix E -- Errata

This appendix lists the errata which apply to the AP450GX MP Server Board Set. Intel intends to fix some of the errata in the future, and to account for the other outstanding issues through documentation or specification changes as noted. Refer to the *AP450GX MP Server Board Set Specification Update* (Order Number 282963) for additional specification updates concerning the AP450GX MP Server Board Set.

Refer to the *Pentium Pro Processor Specification Update* (Order Number 242689) for specification updates concerning the PentiumPro processor. Items contained in the *Pentium Pro Processor Specification Update* that either do not apply to the AP450GX MP Server Board Set or have been worked around are noted. Otherwise, it should be assumed that any processor errata for a given stepping are applicable to the Printed Board Assembly (PBA) revisions(s) associated with that stepping.

Refer to the *Intel 450KX/GX PCIset Specification Update* (Order Number 243109) for specification updates concerning the Intel 450GX PCIset. Items contained in the *Intel 450KX/GX PCIset Specification Update* that either do not apply to the AP450GX MP Server Board Set or have been worked around are noted. Otherwise, it should be assumed that any PCIset errata for a given stepping are applicable to the Printed Board Assembly (PBA) revisions(s) associated with that stepping.

Certain Pentium Pro processor and Intel 450GX PCIset errata are also included as board set errata. These errata are included here because of their implications and/or significance to the operation of the AP450GX MP Server Board Set. Errata #10, 11, 20, 32, and 33 fall into this category.

E.1 Summary Table of Changes

The following table indicates the errata which apply to the AP450GX MP Server Board Set. Intel intends to fix some of the errata in the future, and to account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

Codes Used in Summary Table

Fix:	This erratum is intended to be fixed in a future revision of the hardware or software associated with the AP450GX MP Server Board Set.
Fixed:	This erratum has been previously fixed.
No Fix:	There are no plans to fix this erratum.

Table E-1. Summary Table of Changes

NO.	PLANS	ERRATA
1	Fixed	Board level shock and vibration testing may cause processor module capacitor fatigue
2	Fixed	IDE CD-ROM as master may cause server hang
3	NoFix	Flash boot block protect jumper in unprotected mode may cause flash corruption during a warm reset
4	Fixed	Power distribution board scan via the I ² C bus may cause possible incorrect chip set register settings
5	Fixed	BIOS does not remap bad SIMMs correctly during a system reset
6	Fixed	The Fab 3.x processor module does not support the 200-MHz Pentium® Pro Processor with 512-Kbyte L2 cache
7	Fixed	EISA read performance is below expectations
8	NoFix	Incorrectly inserted memory module may cause baseboard damage
9	NoFix	If address bit permuting is enabled memory resizing can not be performed
10	Fixed	BIOS setting IOQ=8 may cause SMM handler to hang the operating system
11	Fixed	If incompatible SIMMs are installed the system may hang during reset
12	Fixed	Fan failure causes intrusion switch detection to be disabled
13	Fixed	BIOS record type 13H indicates incorrect hard drive information
14	Fixed	Memory resizing error causes BIOS to report wrong memory bank
15	Fixed	Pentium® Pro processor data bus single bit ECC errors may cause excessive SMI generation
16	Fixed	Incorrectly entering administrator password may hang SCU 3.40/OVL 1.31
17	Fixed	Entering a valid password to exit BIOS "secure mode" leaves keyboard lights enabled
18	Fixed	Greater than 1.5 GB of memory installed may cause system hang
19	Fixed	BIOS does not log bad SIMM location during POST memory testing
20	Fixed	Spurious interrupts may cause virtual wire mode APIC operation to fail
21	Fixed	The SCU cannot change the state of the PCI system error option
22	Fixed	The SCU incorrectly sets the baud rates for serial redirection
23	Fixed	Power and reset security switches in the BIOS setup are not available in the SCU
24	Fixed	Incorrectly initialized real time clock registers may hang operating system on the tenth of each month
25	Fixed	BIOS setting IOQ=Autodetect causes BIOS to set IOQ=8
26	Fixed	If the system temperature reaches a warning threshold temperature monitoring is disabled
27	Fixed	Using 60ns 64MB SIMMs and 2-way memory interleave may cause system hang during reset
28	Fixed	Location of password prompts in POST sequence may cause system security violation
29	Fixed	Clearing NVRAM (CMOS) and installing an operating system may cause a system hang
30	Fix	Excessive single-bit ECC errors incorrectly disables single-bit error logging for memory bus and processor data bus
31	Fixed	Saving BIOS configuration after date change may cause date to be set incorrectly
32	Fixed	BIOS setting IOQ = 8 may corrupt PCI configuration cycles
33	Fixed	PCI-to-PCI bridges may cause the system to hang
34	Fixed	Board set TAP reset circuit may cause incorrect system power on
35	Fixed	INCA anomaly at power up may cause PCI bus clocks to run at 66MHz on baseboards with the C0 stepping of Intel 450GX PCIsset

E.2 Errata

1. Board Level Shock and Vibration Testing May Cause Processor Module Capacitor Fatigue

PROBLEM: Fatigues and broken leads have occurred on the capacitors of the processor module during board level shock and vibration testing.

IMPLICATION: Fatigues and broken leads can occur on the processor module in certain chassis configurations.

WORKAROUND: None Identified.

STATUS: This erratum was fixed with the Fab 4.2 processor module (PBA# 659506-213).

2. IDE CD-ROM as Master May Cause Server Hang

PROBLEM: During a system reboot, if an AP450GX MP Server is configured with an IDE CD-ROM as a master boot device in boot floppy emulation mode, the power on self test (POST) completes but the server will hang if a bootable CD-ROM is in the drive.

IMPLICATION: The server may hang while booting from a CD-ROM.

WORKAROUND: None Identified.

STATUS: This erratum was fixed in BIOS 1.00.07 CD0.

3. Flash Boot Block Protect Jumper in Unprotected Mode May Cause Flash Corruption During a Warm Reset

PROBLEM: If the boot block protect jumper is moved from its default location, the flash boot area may be corrupted by a warm reset. If the flash boot block protect jumper is left in the unprotected mode and a warm reset occurs then the data in the flash can be corrupted, including the boot block.

IMPLICATION: If the boot block protect jumper is moved from its default location, the flash boot area may be corrupted by a warm reset. Once corrupted, the baseboard would require reprogramming at the factory and thus need to be replaced.

WORKAROUND: The boot block protect jumper should only be placed in the unprotected position by Intel BIOS developers (i.e., it is for Intel use only). Do not move this jumper from its default location.

STATUS: There are no plans to fix this erratum.

4. Power Distribution Board Scan via the I²C Bus May Cause Possible Incorrect Chip Set Register Settings

PROBLEM: The AP450GX MP Server chassis SCSI Backplane periodically scans the power distribution board via the I²C bus. If the BIOS is reading the baseboard ID at the same time this

scan is occurring, then the chip set registers may be set incorrectly by the BIOS as a result of this scan.

IMPLICATION: There are a variety of implications for this erratum. The processor speeds may be reported incorrectly. If more than one processor is in the system, the BIOS will write a warning message to the console indicating the CPUs are incompatible. The system will function correctly under these conditions. The memory SIMM speed may be reported incorrectly. 60ns and 70ns SIMM timings are supported. If 60ns SIMMs are given 70ns timings, then silent system performance degradation will result. If 70ns SIMMs are given 60ns timings, then ECC errors may occur and silent data corruption is possible if the user does not monitor the ECC errors with appropriate software alarms or server management software.

WORKAROUND: Reboot the server.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

5. BIOS Does Not Remap Bad SIMMs Correctly During a System Reset

PROBLEM: When bad SIMMs are detected in the system, the BIOS may not remap the bad SIMMs correctly during a system reset.

IMPLICATION: Memory may be mapped to an incompatible memory range causing an error message to be displayed and the server to immediately halt or too much memory may be mapped out and the server will run with less memory.

WORKAROUND: The user must find and replace the bad SIMM(s) by trial and error until the problem ceases to exist.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

6. The Fab 3.x Processor Module Does Not Support the 200-MHz Pentium Pro Processor with 512-Kbyte L2 Cache

PROBLEM: The upper bound of the current requirements for the 200-MHz Pentium Pro processor with 512-Kbyte L2 cache is greater than the current provided by the DC-DC converters on the Fab 3.x processor module. The processor module currently supports the 166-MHz version of the Pentium Pro processor with 512-Kbyte L2 cache. This applies to all processor modules up through and including the Fab 3.2.

IMPLICATION: If the 200-MHz Pentium Pro processor with 512-Kbyte L2 cache is installed on a Fab 3.x processor module, intermittent errors may arise because of the DC-DC converter limitations and unpredictable system failures may result.

WORKAROUND: None Identified.

STATUS: This erratum was fixed with the Fab 4.2 processor module (PBA# 659506-212).

7. EISA Read Performance is Below Expectations

PROBLEM: The B0 stepping of the Intel 450GX PCIset will not perform greater than Dword transfers if the read transfer requested by the PCI master is not 32 byte (cache line) aligned. This

causes EISA read performance to be lower than expected. Because the PCEB always performs a 16 byte read when beginning a transfer, the first read has a dword transfer rate of 4-1-1-1-1..., where the count indicates the dwords transferred per PCI transaction. The Intel 450GX PCIset has a long initial latency for reads (approximately 24 PCI clocks from FRAME# asserted to the first TRDY#), therefore, by the time the EISA master reads the first cache line, it must surrender the EISA bus.

IMPLICATION: The EISA master read rate never exceeds approximately 6.5 MB per second in the best case. This causes EISA read performance to be lower than expected.

WORKAROUND: None identified.

STATUS: This erratum was fixed with the Fab 3.5 baseboard module (PBA# 666107-001).

8. Incorrectly Inserted Memory Module May Cause Baseboard Damage

PROBLEM: If the memory module is inserted at an angle or is not fully inserted, and power is applied to the baseboard, the baseboard may be damaged. When the memory module is incorrectly inserted, the 3.3V power rail is shorted to the memory interface signal lines of the Intel 450GX PCIset. If the system is powered on in this condition, the chip set may be damaged within 10-30 seconds. This is not an issue with the processor or terminator modules.

IMPLICATION: The baseboard may be damaged if the memory module is not correctly inserted.

WORKAROUND: Insure the memory module is fully seated and straight before applying power to the baseboard. If the board set is installed in an AP450GX MP Server Chassis, make sure the module cover plate is installed before powering on the system. Correctly installing the cover plate will insure the memory module is fully inserted.

STATUS: There are no plans to fix this erratum.

9. If Address Bit Permuting is Enabled Memory Resizing Can Not Be Performed

PROBLEM: If address bit permuting is enabled on an AP450GX MP Server and a single bit or double bit memory error occurs which requires a reduction in memory size, the system may hang. It is not possible for memory downsizing to occur if address bit permuting is enabled. Furthermore, the error log will not correctly identify the SIMM where the memory error has occurred.

IMPLICATION: If a bad SIMM exists in the system and address bit permuting is enabled, then the system may hang, and the error log will not correctly identify the SIMM where the memory error has occurred.

WORKAROUND: Disable address bit permuting in the BIOS setup, clear the error log after address bit permuting has been disabled, and then find and replace the bad SIMM(s).

STATUS: There are no plans to fix this erratum.

10. BIOS Setting IOQ=8 May Cause SMM Handler to Hang the Operating System

PROBLEM: An AP450GX MP Server system with two or more processors is configured with BIOS setting IOQ=8. If the stress test, iSTRESS, is run for approximately 8 hours, and if the SMI rate is greater than two interrupts per second, then the SMM handler may hang the operating system. Data corruption is also a possibility when using this configuration. (see Intel 450GX PCIset erratum number 1 for further details.)

IMPLICATION: Setting IOQ=8 may cause silent data corruption and server hangs. This problem was seen using Microsoft Windows NT 3.51.

WORKAROUND: The BIOS sets IOQ=1 if the default settings are selected in the BIOS setup. Manually set IOQ=1 in the BIOS setup if the default IOQ setting has been changed. Intel recommends only running with the default BIOS settings.

STATUS: This erratum was fixed with the Fab 3.5 baseboard module (PBA# 666107-001).

11. If Incompatible SIMMs are Installed the System May Hang During Reset

PROBLEM: Due to an anomaly in the B0 stepping of the Intel 450GX PCIset memory controller there are limitations on which sizes of SIMMs can be mixed within a system using the 1GB Memory Module. (see Intel 450GX PCIset erratum number 4 for further details.)

IMPLICATION: Use of any unsupported SIMM combinations may result in server hangs. The BIOS will detect an unsupported SIMM configuration, display an error message and prevent the system from booting.

WORKAROUND: Only use supported SIMM combinations. Not all combinations of SIMMs can be mixed. Below is a matrix of supported SIMM combinations for the 1GB memory module.

		BANK 1				
		1 6 M B	3 2 M B	6 4 M B	12 8 M B	N o t e s
B A N K 0	16 MB	Y e s	Y e s	N o	N o	1
	32 MB	Y e s	Y e s	N o	N o	2, 3
	64 MB	N o	N o	Y e s	Y e s	
	128 MB	N o	N o	Y e s	Y e s	

Notes:

16MB single sided SIMMs only

32MB double sided SIMMs only.

32MB single sided SIMMs may be used but may not be mixed with any other type of SIMM.

STATUS: This erratum was fixed with the Fab 3.5 baseboard module (PBA# 666107-001).

12. Fan Failure Causes Intrusion Switch Detection to be Disabled

PROBLEM: The intrusion switch and the fan fail alert share the same A/D channel for reporting chassis intrusions and system fan failures. If a fan failure occurs, the BIOS disables the A/D channel.

IMPLICATION: A chassis intrusion will not be detected and logged if the intrusion switch is opened after a fan failure occurs.

WORKAROUND: None Identified.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

13. BIOS Record Type 13H Indicates Incorrect Hard Drive Information

PROBLEM: The BIOS does not record the hard drive information into the flash Memory Device under record type 13H. This field is an information only field that contains data related to the first four hard drives in the system. The record type 13H exists but no data exists in the record fields.

IMPLICATION: Applications referencing this record may display incorrect information for the first four hard drives in the system.

WORKAROUND: None Identified.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

14. Memory Resizing Error Causes BIOS to Report Wrong Memory Bank

PROBLEM: If a bad memory location is detected during the memory test at boot time, the BIOS correctly resizes the memory and incorrectly reports to the user the bank number that was just resized.

IMPLICATION: An incorrect location of the bad SIMM is reported. The user must find and replace the bad SIMM(s) by trial and error until the problem ceases to exist.

WORKAROUND: None Identified.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

15. Pentium Pro Processor Data Bus Single Bit ECC Errors May Cause Excessive SMI Generation

PROBLEM: The BIOS SMI handler currently does not check and log single bit ECC errors for the Pentium Pro Processor data bus. The BIOS does not disable the bit that caused the error which results in the continual generation of the SMI for the error.

IMPLICATION: If a system continuously encounters single bit ECC errors, system performance may decrease due to an increase in the number of times the SMI handler needs to be executed.

WORKAROUND: Disable SMM mode in the BIOS setup.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

16. Incorrectly Entering Administrator Password May Hang SCU 3.40/OVL 1.31

PROBLEM: With the administrator password enabled and set, the SCU will hang after an incorrect password is entered three consecutive times and then a correct password is entered.

IMPLICATION: The SCU and the system will hang as soon as it starts to process the CFG files. A reset is required.

WORKAROUND: None Identified.

STATUS: This erratum was fixed in SCU 3.50/OVL 1.40.

17. Entering a Valid Password to Exit BIOS "Secure Mode" Leaves Keyboard Lights Enabled

PROBLEM: When exiting BIOS secure mode by entering the appropriate user or administrator password both the caps lock and scroll lock keyboard lights are enabled. This only happens when pressing the caps lock key two times before putting the system into secure mode (characterized by the keyboard lights flashing in sequence) and not when it is waiting at a password prompt. The lights left enabled are always the same and are not dependent upon where the "pulsing" light was when the password was entered.

IMPLICATION: The keyboard lights display the incorrect state for the caps lock key and the scroll lock key, and the caps lock and scroll lock are not really enabled.

WORKAROUND: Pressing the caps lock key twice and the scroll lock key twice will reset the lights properly.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

18. Greater Than 1.5 GB of Memory Installed May Cause System Hang

PROBLEM: If a Writeback Invalidate to page 0x7000000 - 0x7003fff is performed, the system will hang. This is a valid address when greater than 1.5GB of memory is installed. System hangs have only been seen while executing focused tests during problem isolation. (see Pentium® Pro processor erratum numbers 29 and 50 for further details.)

IMPLICATION: If the memory module uses greater than 1.5 GB of memory, then the server may hang.

WORKAROUND: Use less than 1.5 GB of memory.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

19. BIOS Does Not Log Bad SIMM Location During POST Memory Testing

PROBLEM: If there is a memory downsizing during POST memory testing, the BIOS does not log the bad SIMM(s) location into the event log; and the bad SIMM(s) can not be easily located.

IMPLICATION: Memory downsizing occurs as a result of one or more bad SIMMs. It will be difficult to find the bad SIMM(s). The user must find and replace the bad SIMM(s) by trial and error until the problem ceases to exist.

WORKAROUND: None Identified.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

20. Spurious Interrupts May Cause Virtual Wire Mode APIC Operation to Fail

PROBLEM: In the local APIC design in the Pentium Pro Processor, if interrupts are configured for "virtual wire operation" with interrupt delivery via the INTR signal, then certain spurious interrupts can cause the spurious interrupt vector to be supplied by the local APIC and not the 8259 in the ESC.

IMPLICATION: An operating system can crash if no interrupt handler is available for the spurious interrupt vector supplied by the local APIC (see Pentium Pro processor erratum number 5AP for further details). In addition, the spurious interrupt is sometimes seen as a division by zero error by the Pentium Pro processor (see Pentium Pro processor erratum number 6AP for further details).

WORKAROUND: Use Virtual Wire Mode B option with BIOS 1.00.05 CD0.

STATUS: This erratum was fixed in BIOS 1.00.06 CD0.

21. The SCU Cannot Change the State of the PCI System Error Option

PROBLEM: The PCI System Error option is available in the SCU but is not functional. Choosing enable or disable within the SCU has no effect on the actual state of this option.

IMPLICATION: Depending on the initial state of the PCI System Error option, either the error logging associated with this option will not occur, or the error logging associated with this option will not be disabled.

WORKAROUND: The PCI System Error option can be properly set via BIOS Setup.

STATUS: This erratum was fixed in SCU 3.50/OVL 1.40.

22. The SCU Incorrectly Sets the Baud Rates For Serial Redirection

PROBLEM: The baud rates shown in the SCU are different from the actual baud rate set by the SCU. Currently, the SCU will display and set the baud rates as follows:

<u>Baud Rate Shown in SCU</u>	<u>Actual Baud Rate Set</u>
9600	2400
19200	9600
38400	19200
115200	115200

IMPLICATION: If the baud rate is set using the SCU, a slower than expected serial redirection baud rate will be realized.

WORKAROUND: The BIOS setup displays and sets the serial redirection baud rates properly.

STATUS: This erratum was fixed in SCU 3.50/OVL 1.40.

23. Power and Reset Security Switches In The BIOS Setup Are Not Available In The SCU

PROBLEM: The option to enable or disable the power and reset switches is accessible in the BIOS setup security section, but is not available in the security section of the SCU.

IMPLICATION: The power and reset security switches cannot be enabled or disabled using the SCU.

WORKAROUND: Use the BIOS setup to enable or disable these options.

STATUS: This erratum was fixed in SCU 3.50/OVL 1.40.

24. Incorrectly Initialized Real Time Clock Registers May Hang Operating System On The Tenth Of Each Month

PROBLEM: Incorrectly initialized registers in the Dallas 1587 real time clock may hang the operating system on Intel server products. The operating system may fail to boot, or a currently running system may hang. This symptom will only happen on the tenth of the month. After rebooting the system it will work properly until the tenth of the next month. The root cause is Testview, Intel's manufacturing test and diagnostic software. Testview improperly initializes the alarm registers in the Dallas Real Time Clock which results in an alarm interrupt.

IMPLICATION: All systems manufactured between November 1995 and April 1996, or systems that have had Testview (PCDIAGS) versions 3.31 through 3.36 run on them may hang on the tenth of the month. This issue was seen initially on servers running Microsoft Windows NT 3.51.

WORKAROUND: A special utility has been developed to properly initialize the real time clock registers. This utility is called RTC.EXE and is available from the Intel Applications support BBS, or by contacting an Intel Field representative.

STATUS: This erratum was fixed in Testview (PCDIAGS) version 3.37a.

25. BIOS Setting IOQ=Autodetect Causes BIOS To Set IOQ=8

PROBLEM: If the Autodetect option for the bus performance setting in the BIOS setup is selected, the IOQ depth will be set to IOQ=8 on an AP450GX MP server containing the B0 stepping of the Intel 450GX PCIsset. (see Intel 450GX PCIsset erratum numbers 1, 6, and 19 for further details.)

IMPLICATION: Setting IOQ=8 may cause silent data corruption and server hangs.

WORKAROUND: The BIOS sets IOQ=1 if the default settings are selected in the BIOS setup. Manually set IOQ=1 in the BIOS setup if the default IOQ setting has been changed. Intel recommends only running with the default BIOS settings.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

26. If The System Temperature Reaches A Warning Threshold Temperature Monitoring Is Disabled

PROBLEM: The system temperature monitoring is disabled after the system either reaches the upper or the lower warning threshold temperature.

IMPLICATION: After temperature monitoring is disabled, all temperature events will not be logged.

WORKAROUND: None Identified.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

27. Using 60ns 64MB SIMMs and 2-Way Memory Interleave May Cause System Hang During Reset

PROBLEM: If 60ns 64MB SIMMs are installed and the system is configured as 2-way interleave (i.e. 4 SIMMs are installed) , the system will hang after finishing the memory test during a reset.

IMPLICATION: The system will hang after finishing the memory test during a reset.

WORKAROUND: Do not install 60ns SIMMs in a 2-way interleave configuration.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

28. Location of Password Prompts in POST Sequence May Cause System Security Violation

PROBLEM: The BIOS system administrator and user passwords must be verified before the option ROMs from adapter cards are scanned, otherwise the SCSI option ROMs would allow the user to reformat the hard drives, and do other actions which violate security.

IMPLICATION: The SCSI option ROM utilities are executed early in the system boot sequence, before the password prompt, and hence are available to anyone with access to the system. Access to the SCSI option ROM utilities allow the ability to format hard drives and could be a serious security violation if accessed by unauthorized users.

WORKAROUND: None Identified.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

29. Clearing NVRAM (CMOS) and Installing an Operating System May Cause a System Hang

PROBLEM: NVRAM (CMOS) was cleared on an AP450GX MP Server and the system was reset. During the final stages of an operating system installation, when the system was restarted for the second time, the BIOS string was displayed on the LED display of the system for about a second and then the system failed to startup. The video never came up and the LED display went blank.

IMPLICATION: The server may hang during the final stages of an operating system installation. This issue was seen during a Microsoft Windows95 installation.

WORKAROUND: Clear the NVRAM (CMOS) and reset the system.

STATUS: This erratum was fixed in BIOS 1.00.05 CD0.

30. Excessive Single-Bit ECC Errors Incorrectly Disables Single-Bit Error Logging for Memory Bus and Processor Data Bus

PROBLEM: The BIOS will disable single bit error logging after ten single-bit errors occur on the Pentium Pro processor data bus or on the memory bus. This is done to avoid filling the error logs with repeated errors of the same type (i.e. a SIMM is bad and always has the same single bit error). However, if the errors were on the memory bus, the BIOS simultaneously disables error

logging for both the memory bus and the processor data bus. The same is true if the errors occur on the processor data bus.

IMPLICATION: If single bit error logging is disabled due to errors on the memory bus, single bit errors on the processor data bus will not be logged. Conversely, if single bit error logging is disabled due to errors on the processor data bus, single bit errors on the memory bus will not be logged.

WORKAROUND: None Identified.

STATUS: This erratum is targeted to be fixed in a future release of the BIOS.

31. Saving BIOS Configuration After Date Change May Cause Date to be Set Incorrectly

PROBLEM: If a user opens the BIOS setup menu a few minutes before 24:00, makes some BIOS changes, allows time to elapse such that a new day begins (i.e. 00:01), saves the configuration and resets the system, the BIOS setup will then record the previous date as the current date.

IMPLICATION: Saving BIOS setup configurations across date changes will cause the server to incorrectly set the date.

WORKAROUND: Do not execute and save BIOS setup configurations across date changes.

STATUS: This erratum was fixed in BIOS 1.00.06 CD0.

32. BIOS Setting IOQ = 8 May Corrupt PCI Configuration Cycles

PROBLEM: When PCI configuration cycles interact with an inbound posted write in the non-compatibility PCI bridge, the system may hang or the configuration cycle data may become corrupted. (See Intel 450GX PCIset erratum number 6 for more details).

IMPLICATION: The configuration space of bridges or PCI devices may be corrupted. PCI configuration cycles can occur any time an O/S boots or loads a driver. This erratum could occur under any O/S and any driver.

WORKAROUND: The BIOS sets IOQ=1 if the default settings are selected in the BIOS setup. Manually set IOQ=1 in the BIOS setup if the default IOQ setting has been changed. Intel recommends only running with the default BIOS settings.

STATUS: This erratum was fixed with the Fab 3.5 baseboard module (PBA# 666107-001).

33. PCI-to-PCI Bridges May Cause The System To Hang

PROBLEM: A livelock condition may result if adapter cards with a PCI-to-PCI bridge are installed in the system. (See Intel 450GX PCIset erratum number 7 for more details).

IMPLICATION: The system may hang if a PCI-to-PCI bridge is installed in the system.

WORKAROUND: Do not install PCI-to-PCI bridges in the system.

STATUS: This erratum was fixed with the Fab 3.5 baseboard module (PBA# 666107-001).

34. Board Set TAP Reset Circuit May Cause Incorrect System Power On

PROBLEM: The AP450GX MP Server Board Set asserts the "pwrgood" signal which resets the processors Test Access Port (TAP) during a power on. The sB1 stepping of the Pentium Pro processor implemented a change to the TAP reset circuitry (See Pentium® Pro erratum number 27 for more details). This change does not allow "pwrgood" to reset the TAP circuitry, but does allow other reset methods. If an sB1 stepping of the Pentium Pro processor is installed, the system may not power on correctly. Note that while this could occur on any given system power cycle, Intel has only seen this occur on systems during rapid (less than 25 seconds) power cycle stress tests.

IMPLICATION: If an sB1 stepping of the Pentium Pro processor is installed, the system may not power on correctly, one or more installed processors may not come online, and the system may hang. Once the system has powered on correctly, no other side effects occur as a result of this erratum. Note that while this could occur on any given system power cycle, Intel has only seen this occur on systems during rapid (less than 25 seconds) power cycle stress tests.

WORKAROUND: There are three workarounds possible:

Add a Power Up TAP Reset (PUTR) module to the baseboard. A PUTR is a ~2" x 2" printed circuit board that plugs into the ITP connector on the baseboard. Installing the PUTR insures the system will power on correctly with the sA1 and/or sB1 stepping of the Pentium Pro processor installed. The PUTR is a field upgrade item only and should not be installed prior to product shipment because it may unseat from the ITP connector during shipment. The PUTR is available from Intel at no cost. Please contact your Intel representative for ordering information.

Perform rework to the processor module. (For rework details see the Intel Action Alert *AP450GX Power UP Issue with the sB1 Stepping of the Pentium Pro processor*, Serial Number: AA-0001, released 12/31/96.)

Wait at least 60 seconds after the system has been powered off before powering up the system. This option is not guaranteed to work all the time and should only be considered a temporary workaround.

STATUS: This erratum was fixed with the Fab 4.3 processor module (PBA# 659506-316).

35. INCA Anomaly at Power Up May Cause PCI Bus Clocks to Run at 66MHz on Baseboards with the C0 Stepping of Intel 450GX PCIset

PROBLEM: The AP450GX MP Server Board Set containing the C0 stepping of the Intel 450GX PCIset may power up with the PCI bus clocks incorrectly running at 66 MHz rather than at 33 MHz. Upon power up, the clock detection circuit in the INCA component samples the PCLK outputs (OPB1_PCLK, OPB2_PCLK) from OPB1 and OPB2 to determine if Source B or Source C clock inputs to the INCA are to be used for the PCI clocks. A timing change to the reset logic in the C0 stepping of OPB has resulted in a possibility that the INCA component selects the wrong clock(s) for the PCI bus(es). INCA clock selection occurs only at power-up. The INCA component samples the OPB PCLK (OPB1_PCLK, OPB2_PCLK) signals after the rising edge of the PS_PWR_GOOD signal (power supply good indicator) and with the qualifying assertion of the IRST_L signal (derived from the OPB PCIRST_L signals). The clock source detection circuitry within the INCA component requires that the sampled clock source information remain

stable during the first 45nS following the rising edge of the PS_PWR_GOOD signal, when the IRST_L signal is asserted. Source B or Source C clock inputs to INCA must not transition low to high during this time, or a possibility of incorrect PCI clock frequency selection exists. Specifically the Source B and Source C clock inputs to INCA are PCLK outputs from OPB1 (OPB1_PCLK) and OPB2 (OPB2_PCLK). The C0 stepping of the OPB issues the PCIRST_L signal significantly earlier than the B0 stepping and the new timing results in the assertion of IRST_L to the INCA chip during the first 45nS following the rising edge of the PS_PWR_GOOD signal. The OPB PCLK output signals (OPB1_PCLK, OPB2_PCLK) may generate low to high pulses during the sampling window opened up by the earlier IRST_L timing. The PCLK output signal (OPB1_PCLK, OPB2_PCLK) glitching is believed to be caused by internal OPB flip-flop state changes during the system 3.3 volt power supply initial power ramp, and is of a very short duration.

IMPLICATION: This anomaly is believed to be limited to the unique implementation and interaction between the (C0 stepping) 82454GX PB (OPB component) of the Intel 450GX PCIset and the INCA component of the AP450GX MP Server Board Set. This anomaly has not been observed on systems with baseboards containing the B0 stepping of the Intel 450GX PCIset and Intel has not been able to reproduce this anomaly on systems with baseboards containing the B0 stepping of the Intel 450GX PCIset. The system may exhibit various symptoms when the PCI bus clocks are running at the incorrect speed. Should the failure occur, the symptoms are believed to be highly visible and immediate, as indicated in observed scenarios 1 through 3 below. Scenario 4 results in the system running without any apparent failures. However, prolonged operation at 66MHz may damage the onboard SCSI controllers, and/or INCA component.

OPB1 PCI bus clock running at 66 MHz - System hangs with no post code (blank LCD).

OPB2 PCI bus clock running at 66 MHz - Device failures on PCI bus 2, various post codes, or MTA diagnostic failures.

OPB1, OPB2 PCI bus clocks running at 66 MHz - System hangs during POST with a NMI error.

OPB2 PCI bus clock running at 66 MHz - No adapters installed in PCI bus 2 and system appears to run correctly without the onboard SCSI controllers active.

WORKAROUND: None identified for Fab 3.5 baseboard modules with PBA# 666107-001 or PBA# 666107-002. See fix information in status section below.

STATUS: Intel has implemented a programming change to a PLD (Programmable Logic Device) on the AP450GX MP Server baseboard. This PLD change ensures that IRST_L remains inactive during the first 45nS following the rising edge of the PS_PWR_GOOD signal. This erratum was fixed with the Fab 3.5 baseboard module (PBA# 666107-004, PBA# 666107-005, or PBA# 666107-006).

Order Number 282964-002