

intel® Technical Advisory

TA-507

5200 NE Elam Young Parkway
Hillsboro, OR 97124

January 8, 2002

Intel® & ICP Vortex* RAID Controllers will cause the Intel® Server Board SDS2 to halt during POST when the BIOS Logo screen is enabled

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. **The Intel® RAID Controller SRCMR, Intel® RAID Controller SRCU32, Intel® RAID Controller U3-1, Intel® RAID Controller U3-1L and Intel® Server Board SDS2 may contain design defects or errors known as errata that may cause the product to deviate from published specifications. Current characterized errata are available on request.**

Products Affected

| Product Code | Description |
|--------------------------|--|
| SRCMR | Intel® RAID Controller SRCMR |
| SRCU32 | Intel® RAID Controller SRCU32 |
| BOXSRCU31 | Intel® RAID Controller U3-1 (SRCU31 version 6.1.2.6i firmware) |
| BOXSRCU31L | Intel® RAID Controller U3-1L (SRCU31L version 6.1.2.6i firmware) |
| SDS2 | Intel® Server Board SDS2 (boxed 5-pack) |
| BDSBB | Intel® Server Board SDS2 (bulk 10-pack) |
| ICP Vortex* GDT7628RN | ICP Vortex* RAID Controller |
| ICP Vortex* GDT8623RZ | ICP Vortex* RAID Controller |
| ICP Vortex* GDT6523RS | ICP Vortex* RAID Controller |

intel® Technical Advisory

TA-507

5200 NE Elam Young Parkway
Hillsboro, OR 97124

January 8, 2002

Description

When booting the Intel® Server Board SDS2 with an Intel or ICP Vortex* RAID controller installed, the system will halt during POST when the SDS2 BIOS Logo screen is enabled. This issue occurs with Intel® RAID Controller SRCMR, SRCU32, SRCU31 and SRCU31L (with version 6.1.2.6i firmware), and also with ICP Vortex* GDT7628RN, GDT8623RZ, and GDT6523RS RAID controllers.

Root Cause

Engineering has found the root cause of this issue to be an INT 10 BIOS video interrupt call during RAID POST.

Corrective Action / Resolution

Intel is currently investigating a solution for this issue. A workaround for this issue is to press the ESC key when the Intel BIOS logo screen appears. Alternately, the Intel BIOS logo screen can be disabled. To disable the Intel BIOS logo screen, Access the SDS2 BIOS Setup (by pressing F2 when the Intel BIOS logo screen appears). In BIOS Setup, change the Advanced → Boot-Time Diagnostic Screen option to "Enabled".

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms and Services Division
Enterprise Platforms Group
Intel Corporation