Russ Winslow's

١.	IDENTIFICATION	(7-54-m)
1.1	MAINDEC 701 Digital - 7- 54-M	•
1.2	PDP-7 Instruction Test	
1.3	3/11/66	•

To check program operation from upper 9K bank =

- 1. Set 7-9 mem. sw. to 7, extend sw. off, TRAP OFF.
- 2. READ IN "UPPER CORE INTERRUPT LINK" AT LOC. Q.
- 3. READ IN RIM COADER IN UPPER 8K
- 4. PUT MAINDER TOI IN READER, START AT 37777 WITH EXT. SW. DOWN,
- 5. STAKT POM AT 20170 -

AC = \$20000 - THIS IS NORMAL
ANY OTHER HALT IS ABNORMAL -

2. ABSTRACT

Instruction test is a sequence of fourteen programs which tests the operation of all PDP-7 instructions except the IOT group. Indirect addressing and automatic indexing are also checked. ADD, TAD, ISZ are checked with random numbers as well as noise patterns.

RIM Formal.

The program tape is supplied in Hardware Read-in format and should be loaded via the Read-in key. Hardware read-in is employed so that no reliance need be placed in untested instructions.

- 3. REQUIREMENTS
- 3.1 Storage

The program occupies _____ locations of core storage.

3.2 Subprograms and/or Subroutines

The entire instruction test consists of 14 individual tests which are described fully in the following sections.

3.3 Equipment

Standard PDP-7

High Speed Reader and/or Teletype 33/35.

4. USAGE

4.1 Loading

- 1) Load MAINDEC 701 program tape into reader.
- 2) Set all ADDRESS REGISTER switches (ADS) to the zero (down) state. KIM LOADE
- -3) Depress and release the READ-IN key:
 - 4) Program will read into core and computer will hait.

4.2 Calling Sequence

(Not Applicable)

4.3 Switch Settings

Switch	Setting	Function	
ACSØ-17	non-zero	. A non-zero AC is essential in the second test (PR2) ta	
t	•	the testing of the OAS instruction.	
ACSØ	1	Causes current program to iterate.	
	ø	Causes program to give way to the next in sequence.	
ACS17	1	Causes series of test programs to be repeated from the	
		beginning automatically.	
	Ø	Causes a halt to be executed at 2623 signifying	
		the end of the test series. Pressing CONTINUE causes	
		the series to be repeated from the beginning.	
4.			

- 4.4 Start Up and/ or Entry
- 1. Set the AGCUMULATOR SWITCH REGISTER (ACS) to some non-zero state.
- 2. Set ACSØ and ACS I7 as desired (see para. 4.3)
- 3. Set ADDRESS SWITCH REGISTER (ADS) to 178. Press START.
- 4. Normally, four HLT instructions will be encountered in succession requiring that the operator press CONTINUE after examining the contents of the AC and LINK, subsequent to each HLT. Pressing CONTINUE after execution of the fourth HLT causes the computer to begin cycling through the first test in the series.

The code involved in this series of HLT's is as follows:

ib a lafter CML 170 HLT /Test of HLT instruction. AC should = Ø. terres 171 CMA!CML /Change state of AC and LINK. /AC should = 777777. LINK should = 1. 172 HLT 173 SPA 174 CLA:CLL 175 HLT /AC and LINK should = Ø. If AC=777777, SPA folled. 176 SPA 177 /SPA failed_ HLT 20% **OAS'HLT** /AC should = C(ACS).

4.5 Errors in Usega

	C.(MA)	Cours and Renedial Action
PR 12	96733	Trap Mode Switch is on. Turn Trap Mode Switch oil and
		press CONTINUE.
General	BAX5	A non-programmed interrupt has accurred. Press CONTINUE
PR 13	1987S	CAL instruction jumped to 20. Restort at loc. 2546 (PR (3).
General	<i>3</i> 5021	A non-programmed CAL has occurred from the location
		addressed in register 20 less one. Re-examine your
		operating procedure and/or reload program.
MI3	\$\$\$\$22- \$ \$\$77	CAL instruction forced incorrect address to PC. Restart
		er loc 2546 (PR13).
PR 13	W33	Execution of CAL follow to preserve the LINK. Press
		CONTINUE to ignore error. Restart at loc 2546 (PK 13)
		to repeat the CAL.
PR13	<i>j</i> ysio	Execution of CAL failed to save the PC. Press CONTINUE
		to ignore error. Restart at loc 2546 (PR 13) to repeat the CAL
PR13	ØØ42	Execution of CAL Miled to clear bits 1-4 of loc. 20. Press
		CONTINUE to ignore error. Restort at Loc 2546 (PR 13) to
		repeat the CAL.
PRØ	\$17\$	This is the test for HLT. AC and LINK should = Ø. I not,
		pressing START has failed to clear AC and LINK. Press
		CONTINUE IF AC and LINK = B.

Program	C(MA)	Cause and Remedial Action
PRØ	172	This is a preliminary test of CMA and CML. If AC + 77777
	and the second s	CMA failed. If LINK \$\neq 1, CML failed. In either case,
		restart at \$17\$. If AC = 777777 and LINK = 1, press
•		CONTINUE.
PRØ	175	If AC and LINK = Ø, press CONTINUE. If AC = 777777,
		SPA failed; restart at 170.
PRO'	177	SPA failed. Restart at 179.
PRØ	200	Test for OAS. If AC = C(SR), press CONTINUE. If not, restart at 170.
PRØ	204	JMP failed to jump. Restart at 203.
PRØ	215	ISZ skipped on negative result. Restart at 21%.
PRØ	216-223	ISZ forced 2,3,4,5,6 or 7 to the PC. Restart at 21%.
PRØ	225	ISZ failed to skip on \$ result. Restart at 21\$.
PRØ	227-234	ISZ forced 2,3,4,5,6, or 7 to the PC. Restart at 210.
PRØ	237	ISZ skipped on non-zero positive result. Restart at 21%.
PRØ	24 %-24 5	ISZ forced 2,3,4,5,6 or 7 to the PC. Restart or 210.
PRI	257	NOP skipped. Restart at 253.
PR1	260-265	NOP forced 2,3,4,5,6, or 7 to the PC. Restart at 253.
RI	207	SKP failed to skip. Restart at 253.
RI	27 1-276	SKP forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
RI	302	If LINK = 1, CLL failed. If LINK = Ø, SNL failed.
		Restart at 253.
RI	303 - 310	SNL forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
RI	312	SZL failed to skip. Restart at 253.
ŔĬ	314 - 321	SZL forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
RI	324	If LINK = 1, SNL folled. If LINK = 0, CML failed.

Marie and the second se	and the second s	
Program	C(MA)	Cause and Remedial Action
PRI	326-333	SNL forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
PRI	336	NOPskipped. Restart at 253.
PRI	337-344	NOP forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
PRI	347	If LINK = 1, CLL failed. If LINK = Ø, SZL failed.
		Restort at 253.
PRI	351 - 356	SZL forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
PR)	362	If LINK = 1, SZL failed. If LINK = \$, CML failed.
	معدمات معدما	Restall of 253.
PRI	363 - 37%	SZL forced 2,3,4,5,6, or 7 to the PC. Restart at 253.
PRI	373	If LINK = 1, SNL failed. If LINK = \$, STL failed.
		Restart at 253.
PRI	375 - 402	SNL forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
PRI	45%	If AC #8, SZA failed. Otherwise, CLA failed. Restart at 233
PR 1	418 - 415	SZA forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
PRI	420	NOP skipped. Restart at 253.
PR1 ·	421 - 426	NOP forced. 2, 3, 4, 5, 6 or 7 to the PC. Restart at 253.
PRI	432	If AC = Ø, CMA failed, Otherwise, SZA failed.
		Restart at 253.
PRI	433 - 44ø	SZA forced 2,3,4,5 6 or 7 to the PC. Restart at 253.
PRI	444	If AC = Ø, SZA failed. Otherwise CLC and/or CMA failed.
		Restart at 253.
PRI	446 - 453	SZA forced 1,2,3,4,5,6 or 7 to the PC. Restart at 253.
PRI	457	IF AC = Ø, SZA failed. Otherwise CLA failed.
		Restart at 253.
PRI	461 - 466	SZA forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
PRI	471	If AC = Ø, CMA failed. Otherwise SMA failed.
		Restort at 253.
PRI	473 - 566	SMA forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
የ ጸ1	503	NOP skipped. Restart at 253.
PR1	504 - 511	NOPforced 2,3,4,5,6 or 7 to the PC. Restart at 253.
	Programme and the second	

4.5 Errors in Usage

(continued)

Control of the contro	C(MA)	Cause and Remedial Action
PRI	515	If AC = \$1, SMA failed. Otherwise CMA failed.
PR I	51ø - 523	Restart at 253. SMA forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
PRI	525	SPA failed. Restart at 253.
PRI	527 - 534	SPA forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
PRI	540	If AC = Ø, CMA falled. Otherwise, SPA falled.
		Restart at 253.
PRI	541 - 546	SPA forced 2,3,4,5,6 or 7 to the PC. Restort at 253.
PRI	5 51	If AC = \$, SZA failed. Otherwise CLA failed.
		Restart at 253.
PRI	553 - 560	SZA forced 2,3,4,5,6 or 7 to the PC.
		Restart at 253.
PR1 564	564	If AC = Ø, OAS failed. Otherwise SNA failed.
		(be sure that ACS hold non-zero number)
		Restart at 253
PRI	566-573	SNA forced 2,3,4,5,6 or 7 to the PC. Restart at 253.
PR2	631	JMS at 627 failed to jump. Restart at 621.
PR2	64Ø	JMS at 3673 failed to increment operand address (Y) in PC.
•		Restart at 621.
PR2	642 - 647	JMS at 3673 incremented operand address (Y) 2,3,4,5,6 or
		7 times. Restart at 621.
PR2		JMS at 3673 failed to preserve LINK. Restart at 621.
PR2	554	JMP I at 653 failed to jump. Restart at 652.

4.5	Enons	177	Usage
-----	-------	-----	-------

(continued)

	C(MA)	Cause and Remedial Action
- Andrew States - Commission of States - Land States -	662	XOR of 777777 into 777777 failed. AC indicates bits in arror. Restart at 657.
PR3	666	XOR of photos into photos failed. AC Indicates bits in error. Restart at 663.
PK3	673	XOR of 777777 into \$60000 failed. AC indicates bits in error. Restart at 667.
PR3	766	XOR of \$60,000 into 777777 failed. AC indicates bits in error. Restart at 674.
PR3	766	XOR of \$7\$7\$7 into \$35555 Into 7\$7\$7\$ failed. AC indi- cates bits in error. Restart at 7\$1.
PR3	714	XOR of 7,07,07,0 into 0,00,000 into 0,7,07,07 failed. AC indi-
% 3	722	XOR of 333333 into \$55550 into 444444 failed. AC indi- cates bits in error. Restart at 715.
PRO	73ø	XOR of 444444 into 000000 into 333333 failed. AC indi- cates bits in error. Restart at 723.
PR3	736	XOR of 525252 into \$66666 into 252525 failed. AC indi- cates bits in error. Restart at 731.
° 83	744	XOR of 252525 into 800000 into 525252 failed. AC Indi-
? R4	757	SAD failed to skip when comparing \$66666 and 777777. Restart at 755.
⁾	761	SAD failed to replace C(AC) which initially contained

Program	C(MA)	Cause and Remedial Action
PR4	765	SAD skipped when comparing equal numbers (777777). Restart at 762.
PR4	77¢	SAD failed to replace C(AC) which initially contained 777777. Restart at 762.
PR4	774	SAD failed to skip when comparing 525252 and 252525. Restart at 771.
PR4	1,886	SAD failed to replace C(AC) which initially contained 525252. Restart at 771.
PR4	1865	SAD skipped when comparing equal numbers (525252). Restart at 1881.
PR4	1811	SAD failed to replace C(AC) which initially contained 525252.
PR5	1ø25	SNA failed on AC = \$66666.
PR5	1Ø3Ø	SNA failed with AC17 set. Restart at 1,022.
PR5	1ø33	SNA failed with AC16 set. Restart at 1822.
PR5	1,036	SNA failed with AC15 set. Restart at 1,022.
PR5	1,041	SNA failed with AC14 set. Restart at 1822
PR5	1ø44	5NA failed with AC 13 set. Restart at 1822
PR5	1047	SNA failed with AC 12 set. Restart at 1022
PR5	1Ø52	SNA failed with AC 11 set. Restart at 1,022.
PR5	1Ø55	SNA failed with AC 10 set. Restart at 1,022
PR5	1,06,0	SNA failed with AC 9 set. Restart at 1,022
PR5	1,063	SNA foiled with AC8 set. Restart at 1022
PR5	1,066	SNA failed with AC 7 set. Restart at 1022
PR5	1,071	SNA failed with AC6 set. Restart at 12/122
PR5	1,074	SNA failed with AC 5 set. Restart at 1022
PR5	1077	SNA failed with AC 4 set. Restart at 1022
PR5	1102	SNA failed with AC 3 set. Restart at 1022
PR5	1105	SNA failed with AC 2 set. Restart at 1822
PR5	1110	SNA failed with AC 1 set. Restart at 1022
PR5	1113	SNA failed with AC Ø set. Restart at 1022

Program	C(MA)	Cause and Remedial- Action
PR6	1127	LAC of popper into popper falled. Restort of 1124.
PRó	1134	LAC of 777777 into 300000 failed. Restort at 1130.
PRS	1141	LAC of 777777 into 777777 failed. Restart at 1135.
PR6	1145	LAC of \$60000 Into 777777 falled. Restart at 1142.
Pro ·	1153	LAC of 252525 into 525252 failed. Restart at 1146.
PRO	1161	LAC of 525252 into 252525 failed. Restart at 1154.
Pró ·	1167	LAC of \$7,57,57 into 7,57,57\$ failed. Restart at 1162.
PRS	1175	LAC of 7,67,67,6 into 57,67,67 failed. Restart at 117,6.
PR6	1293	LAC of 444444 into 333333 falled. Restart at 1176.
PR6	1211	LAC of 333333 into 444444 failed. Restart at 1264.
™R6	1216	DAC of ØØØØØ failed. Restart at 1212.
PR6	1223	DAC of 777777 into BBBBBB failed. Restart at 1217.
≥86	123¢	DAC of 777777 into 777777 failed. Restart at 1224.
PR6	1235	DAC of \$66666 into 777777 foiled. Restart at 1231.
PR6	1242	DAC of \$60000 into \$600000 failed. Restart at 1236.
PR6	1250	DAC of 525252 into \$66666 failed. Restart at 1243.
PR6	1256	DAC of 252525 Into 525252 failed. Restart at 1251.
PR6	1264	DAC of 525252 into 252525 failed. Restart at 1257.
PR6	1272	DAC of 707070 into 525252 failed. Restart at 1265.
PR6	13.09	DAC of \$7,57,67 Into 7,67,67,6 failed. Restart at 1273.
PR6	1386	DAC of 7,07,07% into 107,07,07 failed. Restart at 13,01.
PR6	1314	DAC of 333333 into 7,07,67,0 failed. Restart at 13,67.
PR6	1322	DAC of 444444 into 333333 failed. Restart at 1315.
286	133ø	DAC of 333333 into 444444 failed. Restart at 1323.

(continued)

4.5

Program	C(MA)	Couse and Remedial Action
PR7	1345	DZM falled to clear the bits indicated in the AC. Restart at 1340.
PRO	1351	DZM set the bits indicated in the AC. Restart at 1346.
PRZ	136Ø	LAW entered defer cycle. Restart at 1352.
PR7	1364	LAW 8 failed. AC = result. Restart at 1352.
PRY	1373	LAW entered defer cycle. Restart at 1365.
PRZ	377	LAW & failed. AC = result. Restart at 1365.
PRT	14/66	LAW entered defer cycle. Restart at 1400.
PRT	1412	LAW 17777 failed. AC = results. Restart at 1400.
PR7	1421	LAW entered defer cycle. Restort at 1413.
PR7	1425	LAW 17777 failed. AC = result. Restart at 1413.
PR7	1436	LAC of 777777 into BBBBBB failed. AC = result. Restart at 1426
PK7	1446	DAC Lof 777777 into 80000 failed. AC = result. Restart at 1437
PR7	1452	DAC I altered operand register. Restart at 1437.
PR8	1512	XCT failed to execute the one cycle CML. Restart at 1507.
PR8	1514	XCT failed to execute the two cycle JMP. Restart at 1513.
PRB	1516	XCT failed to execute JMP correctly. Restart at 1513.
PR8	1522	XCT failed to execute the three cycle JMP 1. Restart at 1517.
PR8	1524	XCT failed to execute JMP correctly, Restart at 1517.
PRB	153Ø	XCT failed to execute an XCT. Restart at 1525.
PR8	1532	XCT failed to execute XCT correctly. Restart at 1525.
PR8	1547	LAC I via Auto Index 10 failed. Restart at 1544.
PR8	1553	LACT via Auto Index 11 failed. Restart at 1550.
PR8	1557	LACT via Auto Index 12 failed. Restart at 1554.
PR8	1563	LACT via Auto Index 13 failed. Restart at 1560.
PR8 PR8	1567	LAC I via Auto Index 14 failed. Restort at 1564. LAC I via Auto Index 15 failed. Restart at 1570.
PR8.	1 <i>57</i> 3 1 <i>57</i> 7	LAC I via Auto Index 15 failed. Restart at 1570.
PRB	16ø3	LACT via Auto Index 17 failed. Restart at 15/9.

Errors in Usage

Program	C(MA)	Cause and Remedial Action
PRP	1654	AND of 777777 and 777777 falled. AC = result. Restant at 1658.
PRP	1668	AND of 777777 and MANO failed. AC = result. Restort at 1655.
PR9	167 ø	AND of two Identical numbers failed. Number concerned found at 4187. AC = result. Press CONTINUE or restart at 1671.
PRID	2574	Rotate failed. Rotate instruction concerned in AC. Press CONTINUE for further data.
PRIØ	2677	Rotate failed. AC and LINK display their conditions before the rotate. Press CONTINUE for further data.
Priø	2164	Rotate falled, AC and LINK display their conditions after
P8) Ø	2135	the rotate. Press CONTINUE to resume testing. RAR followed by RAL left LINK altered. Number rotated in 41,67. LINK was initially \$\beta\$. Press CONTINUE or
PR 1ø	214Ø	The number in 41,67 did not survive a RAR, RAL. Result in AC. Press CONTINUE or restart at 2127.
PR 1Ø	2146	RAR followed by RAL left LINK altered. Number rotated in 4107. LINK was initially 1. Press CONTINUE or
PR1 #	2151	The number in 4107 did not survive a RAR, RAL. Result in AC. Press CONTINUE or restart at 2127.
PRIØ	215%	RAR failed to move AC light. Press CONTINUE.
PRIM	2163	RAL failed to move AC left. Press CONTINUE.

Program	C(MA)	Cause and Kemedial Action		
PRII		ADD falled on XOR function (7,57,57,5 + 57,57,57).		
•		Restort at 2174 or press CONTINUE.		
PRII	22\$7	<u>ADD</u> falled an XOR function (\$7,57,57 + 7,57,57,5).		
		Restart at 2262 or press CONTINUE.		
PRII	2215	ADD failed an XO1 function (444444 + 333333).		
•		Restart at 221% or press CONTINUE.		
PRII	2223	ADD failed an XOR function. (333333 + 444444).		
		Restart at 2216 or press CONTINUE.		
PRII	2231	ADD failed on XOR function (525252 + 252525).		
• •		Restart 2224 or press CONTINUE.		
PRII	2235	ADD failed on XOR function (252525 + 525252).		
		Restort at 2232 or press CONTINUE.		
PRII	: 2244	ADD failed a carry function (525252 + 525252).		
		Restart at 2237 or press CONTINUE.		
PRII	2252	ADD failed a carry function (333333 + 333333).		
		Restart at 2245 or press CONTINUE.		
PRII	2266	ADD failed a carry function (673567 + 673567).		
		Restart at 2253 or press CONTINUE.		
PRII	2266	TAD a carry function (525252 + 525252).		
•	·	Restart at 2261 or press CONTINUE.		
PRII	2274	TAD failed a carry function (333333 + 333333).		
•		Restart at 2267 or press CONTINUE.		
PRIII. I	23,62	TAD failed a carry function (673567 + 673567).		
•		Restart at 2275 or press CONTINUE.		
PRII	2210	ADD failed attempting 671671 + 257257.		
		Restart at 23,63 or press CONTINUE.		
PRII	2312	ADD of 671671 + 257257 set an initially zeroed LINK.		
	•	Restart at 23,03 and press CONTINUE.		
PRTT .	2465	ADD of random numbers failed. First halt in this		
·		address displays AUGEND in AC. Press CONTINUE.		
		Second hold displays ADDEND., Press CONTINUE to try		
		another random set.		
9877	2463	TAD of medom number failed Demond on too half in 2466		

Page 15

rogion	C(MA)	Cause and Remedial Action
	2 # 2	ISZ falled. If AC = \$, ISZ falled to skip. Otherwise, ISZ
		lost a count (compare C(AC) withC(41,67). Restart of 2511.
P212	2524	ISZ skipped on non-zero result. Restart et 2511.
PR12	2536	152 failed with random number. Expected result in AC.
		Press CONTINUE to obtain actual result.
PRIZ	254#	ISZ failed with random number (in 1483). Result in AC.
		Press CONTINUE or restart at 2541.
PR 13	2556	JMS falled to preserve a previously set LINK. Restart at
	upoja A Miliando	25.91. 1 1/1 here if re
PR13	2561	JMS falled to clear YI-4. Restart at 255%. Halt, here is my pair 9 K
PR 13	257%	JMS failed to preserve a previously cleared LINK. Restart at 2562.
PR 13	2573	JMS failed to clear Y1-4. Restart at 2502.
PR13	26 % 6	CAL failed to jump. Restart at 2574.
General	2623	Not on Error Halt: Program halts here when test series complete.
		AC17=1 prevents this halt. Press CONTINUE to repeat test series.
PR2	366\$ - 3662	JMS at 3732 altered PC incorrectly. Restart at 3732.
PR2	3663	JMS at 3732 failed to increment operand address Y.
		Restart at 3732.
PR2	3665 - 3672	JMS at 3732 incremented operand address (Y)-2,3,4,5,6 or 7
		times. Restart at 3732.
PR2	3786	JMS at 4001 altered PC incorrectly. Restart at 4061.
PR2	37Ø1	JMS at 4061 failed to increment operand address Y.
		Restart at 4561.
PR2	37/03 - 37 1/d	JMS at 4061 incremented operand address (Y)2,3,4,5,6 of 7
		times. Restart at 4861.
×R2	3715	JMS at 3713 falled to jump. Restart at 3713.

5.

RESTRICTIONS

None.

6. DESCRIPTION

6.1 DISCUSSION

General

MAINDEC 701 is a set of fourteen programs (numbered PR# through PR13) designed to test the operation of PDP-7 instructions. The following instructions are tested:

law, all the operate group (except oas which is only partially tested.), and the memory reference instructions.

add and tad are the only arithmetic instructions tested.) Indirect addressing is checked as is the operation of the auto-index registers. Random numbers are employed in testing the rotate group, is and the arithmetic instructions add and tad.

Maindec 701 is designed so that it is not necessary to assume that any instruction is working. In order to facilitate usage, an exception is made to this rule. The final five or six instructions of each program comprise a sequence which is responsible for reiterating the current test a set number of times and then sensing AC switch zero to determine if the operator desires that the next program be entered. Some of these instructions are not fully tested until a later program is entered. These sequences are not, however, inherent to the testing purpose and may be replaced by a single jmp addressed to the beginning of the following test or the current test. Maindec 701 is loaded by the hardware read-in facility, to abvious dependance on an instruction artented leading system.

6.2 Examples and/or Applications

6.2.1 Program Zero (PRØ)

Program zero provides a complete test for hit and [mp and preliminary tests for isz, spa, cml, cma, and cla. When first entered at lac. 175, a sequence of nine instructions is encountered involving from normal hats. This sequence is designed to provide a test for hit, a check-out of the ability to clear the AC and Link by pressing START, and preliminary tests of the instructions cma, cml, spa, cla, all and oas. The last mentioned preliminary tests made here and in this manner are intended to give a sufficient degree of confidence in the operation of these instructions so that they may be safely employed as elements of "housekeeping" functions such as loop counters and switch sensors.

The imp is tested by requiring jumps, \$253 to 3777, 3775, 3766, 4616, 4617 and 6216. These addresses were chosen so that every PC bit is forced to transition from 6 to 1, 1 to 6, 6 to 6, and 1 to 1. Each jump is protected by error hits from any incorrect alteration of PC bits 15 - 17.

Upon completion of the jump sequence, the number 777776 is successively indexed to \$66661 to check isz's ability to react to negative, zero, and positive results.

The sequences described above, exclusive of the initial nine Instructions are arbitrarily iterated 100_{10} times. After the 100th iteration the AC Switch Register is checked. If ACSØ = 1, 100 more iterations are performed. If ACSØ = β , Program 1 is entered.

6.2.2 Program One (PR1)

Program One checks operate instructions cla, clc, cll, nop, skp, smo, snl, stl, sza, and szl and partially tests cma, cml, oas, sna, and spa.

Since only hit and jmp have been completely tested prior to this time, the operate instructions are tested for the most part in pairs. This requires that failures be determined manually by examination of the AC and Link states at error halt time. All skip instructions are "protected" to a depth of seven against excessive increments of the PC.

The last test performed is of oas, and requires that the AC switches be in a non-zero state.

Program One is arbitrarily iterated 100_{10} times. Following the 100th iteration, the AC Switch Register is checked. If ACSØ = 1, Program One is iterated 100 additional times. If ACSØ = Ø, Program Two is entered.

4.3.3 Program Yes (PRO)

Program Two tests Jmp! and partially tests Jms. The Link preservation aspects of JMS are tested by PRIJ. JMS is executed from 6627 to 4027, 4047, 3745, 3746, 3723, 3663, and 6646 thus requiring all PC bits to transition from 6 to 1, 1 to 6, 6 to 6 and 1 to 1. JMS is also tested for ability to temp to the appeared address plus one. JMP! Is tested seen subtral-semiconistant of JMS.

JMS and JMP! executions are accompanied by protection to a depth of seven against exceptive incrementions of the PC.

Program Two is automatically Iterated 100_{10} times. Following the 100th iteration, the AC Switch Register is checked. If ACSE = 1, Program Two is iterated 166 additional times. If ACSE = 6, Program Three is entered.

- 6. DESCRIPTION (continued).
- 6.4 Program Three (PR3)

Program Three tests the XOR Instruction. The exclusive OR is formed sixteen times to include all pertinent combinations. The following combinations are employed; AC = 777777 with 777777, AC = \$66666 with 777777, AC = 777777 with \$66666, AC = \$666666 with 777777, AC = 777777 with \$666666, AC = 777777 with \$666666, AC = \$666666 with 7676767, AC = \$676767 with 767676, AC = \$666666 with 7676767, AC = \$666666 with 7676767, AC = \$666666 with 333333, AC = \$666666 with 525252, AC = 525252 with 252525, AC = \$666666 with 252525, and AC = 252525 with 525252.

Program three is arbitrarily iterated 40% times. Following the 40% times. Following the 40% times. Following the 40% times. If ACSØ = 1, Program Three is iterated an additional 40% times. If ACSØ = Ø, Program Four is entered.

- 6. DESCRIPTION (continued)
- 6.5 Program Four (PR4)

Program Four tests the <u>SAD</u> instruction. <u>SAD</u> is checked to insure that it (1) skips on unequal comparison, (2) does <u>not</u> skip on equal comparison, and (3) replaces the contents of the AC after comparison. Comparisons are made between AC = \$866666 and 777777, AC = 777777 and 777777, AC = 525252 and 2525252, and AC = 525252 and 525252.

Program Four is arbitrarily iterated 100₁₀ times. After the 100th iteration, the AC Switch Register is checked.

If ACSØ = 1, Program Four is iterated an additional 100 times.

If ACSØ = Ø, Program Five is entered.

6.6 Program Five (PR 5)

Program Five tests the operation of SNA (and indirectly, of SZA) with each individual AC bit set. The program also provides a test of the decoder network which generates the AC \neq + β level.

With zeros in all bits SNA is checked to assure that no skip occurs.

With zeros in all bits except AC17, SNA is executed to skip over an error halt. The same procedure is used with only AC16 = 1, then AC15 = 1 etc. and finally with only AC6 = 1.

Program Five is arbitrarily iterated 100₁₀ times. After the 100th iteration, the AC Switch Register is checked.

If ACSØ = 1, Program Five is iterated an additional 100 times.

If ACS# = Ø, Program Six is entered.

5.7 Program Six (PR 6)

Program Six tests Lac and Dac. Lac is tested by loading the AC with a known number using the lac instruction and then checking for a correct transfer. The combinations employed are \$66,000 loaded into \$66,000, 777777 loaded into \$767,000, 100,000

Program Six is arbitrarily iterated 100_{10} times.

After the 100th iteration, the AC10 Switch Register is checked.

If ACSØ = 1, Program Six is iterated an additional 100 times.

If ACSØ = Ø, Program Seven is entered,

6.8 Program Seven

Program Seven tests the operation of Dzm, Law, Lac i, and Dac i.

Dzm is tested to ensure that it clears a location containing all ones
and a location containing all zeros.

Low is checked by loading all zeros into all ones, all zeros into all zeros, all ones into all ones, and all ones into all zeros. The possibility of law causing an entry into the defer cycle is also checked.

Lac i and Dac i are checked by loading all ones into all zeros indirectly via a reference register. The reference register is checked for alteration after performing dac 1.

Program Seven is arbitrarily iterated 100₁₀ times.

After the 100th iteration, the AC Switch Register is checked.

If ACSØ = 1, Program Seven is iterated 100 additional times.

If ACSØ = Ø, Program Eight Is entered.

- 6. DESCRIPTION (continued)
- 6.9 Program Eight (PR 8)

Program Eight tests the operation of Xct and auto-index registers 10 - 17.

Xct is used to execute the one cycle instruction and, the two cycle instruction imp, the three cycle instruction imp i, and another xct instruction.

'The operation of the auto-index registers is checked by using each in turn to retrieve three known numbers via a lac i instruction.

Program Eight is arbitrarily Iterated 10010 times.

After the 100th iteration, the AC Switch Register is checked.

If ACSB = 1, Program Eight is iterated 100 additional times.

If ACSØ = Ø, Program Nine is entered.

6.18 Program Nine (PR 9)

Program Nine tests the and instruction.

All ones are anded with all ones, all ones are anded with all zeros, and each AC bit is anded with itself.

Program Nine is arbitrarily iterated 100₁₀ times.

After the 100th iteration, the AC Switch Register is checked.

If ACSØ = 1, Program Nine is iterated 100 additional times.

If ACSØ = Ø, Program Ten is entered.

6.11 Program Ten (PR16)

Program ten tests rotate instructions rar, rai, rir, and rti.

All four instructions are used in succession to rotate a one through a field of zeros compused of all AC bits and the Link 40% times, checking the state of the AC and link after each individual rotation. The same procedure is repeated, this time rotating a zero through a field of ones.

Ral and Rar are then employed to shift all possible 18 bit numbers one bit left and right. The program checks that an apparent movement of the number in the AC has occurred and that the state of the Link is as it should be after each rotation.

The state of the AC Switch Register is then checked.

If $ACS\beta = 1$, Progresm Ten is re-entered.

If ACSØ = Ø, Program Eleven is entered.

6.12 Program Eleven (PR II)

Program Elevan tests the operation of add and tad. Using various combinations of \$7\$7\$7, 7\$7\$7\$, 444444, 333333, 777777, 525252, and 252525, XOR functions and carry functions of add are checked as well as carry functions of tad.

Add and tad are further checked by using random numbers. Two random numbers are created and added/tadded together. This result is then compared with a simulated result to assure a correct mathematical result. The Link is also checked.

Program Eleven is arbitrarily iterated 40% times

After the 40%th iteration, the AC Switch Register is checked.

If ACSØ = 1, Program Eleven is iterated an additional 40% times.

If ACSØ = Ø, Program Twelve is entered.

6.13 Program Twelve (PR12)

Program Twelve completes the testing of ISZ, and concerns itself with counting accuracy: A memory location is indexed from the zero state to 777777 while a parallel count is maintained in the AC by adding one to the previous contents of the AC. The memory location contents are checked against the number in the AC after each isz to detect a miscount. When the memory location is indexed to zero, the program confirms that isz responded correctly with a skip. This sequence repeats three times before beginning a series of random number tests.

A random number is created and incremented with <u>isz</u>. The program checks the result. This sequence is repeated 262, 143₁₀ times. The state of the AC Switch Register is then checked.

If ACSØ = 1, Program Twelve is entirely repeated.

If $ACS\emptyset = \emptyset$, Program Thirteen is entered.

6.14 Program Thirteen (PR 13)

Program Thirteen checks the Link saving properties of June and the instructions cal and cal i.

Two Jms instructions are executed to a memory location containing alternately 36,000 and 40,000, with the Link equal to one and zero respectively. In each case, the memory location is checked to determine if the link was properly saved in bit 6 and if bits 1-4 were properly cleared.

The <u>cal</u> instruction is tested by an execution of <u>cal</u> ϕ with the link set, lac. 20 containing <u>het</u>, and lac 21 containing a jump to 30. Beginning at lac. 30 a sequence of instruction tests lac 20 for presence of the Link state in bit zero, the address of the location following the <u>cal</u> in bits 5 - 17, and zeros in bits 1 - 4. A return is made to the <u>cal</u> location plus one with a cleared link. The state of the link is immediately checked to rule out the possibility that cal never jumped originally. Lac 20 is indexed and a <u>cal</u> ϕ is executed to transfer control to the original <u>cal</u>, lac, plus two.

Program Thirteen arbitrarily iterates 100₁₀ times.

After the 100th Iteration, the AC Switch Register is checked.

- If ACSØ = 1, Program Thirteen is Iterated an additional 100 times.
- If ACSØ = Ø, the AC Switch Register is checked again.
- If ACS 17 = 1, control is transferred to PRØ at lac. 201.
- If ACS17 = Ø, the program halts in lac 2623 signifying the end of the test series. Pressing CONTINUE at this point will also transfer control to PRØ at lac 201.

6.2

TABLE 6-1 INSTRUCTIONS TESTED SY MAINDEC 701 (Alphabetically Arranged)

nstruction	Program	Instruction	Tested by Program
odd	11 (oas .	ø, 1
and `	9	rai	10
col :	13	rar	iø
class.	1	ntl	18
cle	1	rtr	1,0
cll	1	sad	4
cma	ø, i	skp	
cmi	ø, 1	s ma	્ૄૄંી
dac	6,7	sna	1, 5
dzm	7	sni	1
and the second s	g. g.	spa	ø, 1
6 F W	p, 12	stl	1
imp	¥	sza	1
ims	2, 13	szí .	
lac	6,7	tad	11
law	7	×c†	8
nop	1	xor	3

TABLE 6-2 PROGRAMS IN MAINDEC 701

Program Number	Tests	Program Number	Tests
Ø	cla *		
ß	cma *	1	szl
ø	cml *	2	įms *
ø	hit	3	xor
S	isz *	4	sod
ø	i mp	5	. sna *
, B	oas **	6	dac.*
ø	spia *	8	lac *
•	cla	. 7	dac *
	ele	7	dzm
1	cll	7	iac *
1	cmo *	7	law
1	cml *	8	xcf
1	nop	9	and
	ogs **	1,0	ral
1	skp	1,6	ror
1	sma	1ø	rtl
1	sna *	1,6	rtr
•	snl	11	add
*	spa *-	. 11	tod
1	sti	12	isz *
1	sza	. 13	cal
•		13	įms *

^{*} completely tested, but only partially by this program

^{**} only partially tested