

MSA500 G2 version 1.52 (continued on second page)

This MSA500 G2 firmware will recommend updates for some SCSI disk drive models after the MSA500 G2 firmware has been installed. To avoid notification on the LCD panel, update any applicable hard disk drives before updating the MSA500 G2 firmware.

Disk drive firmware components are available from:

http://h18000.www1.hp.com/support/files/storage/us/locOsCat/99_56.html

If a component is not available for the affected disk drive model, download the following ROMPaq:
<http://h18000.www1.hp.com/support/files/server/us/download/17149.html>

A later version of the disk drive firmware may be available and should be used.

Disk Drive Model	Minimum Firmware	Disk Drive Family
BB009135B4	B021	SCSI 9GB 7200 WU2
BB009235B6	B021	SCSI 9GB 7200 WU2
BB018135B5	B021	SCSI 18GB 7200 WU2
BB018235B7	B021	SCSI 18GB 7200 WU2
BD004153C3	B415	SCSI 4GB 10K WU2
BD004253C4	B415	SCSI 4GB 10K WU2
BD00962A66	B008	SCSI 9GB 10K WU3
BD0096349A	3B12	SCSI 9GB 10K WU3
BD009635C3	B022	SCSI 9GB 10K WU3
BD00965333	B915	SCSI 9GB 10K WU3
BD00972A69	B008	SCSI 9GB 10K WU3
BD009735C6	B022	SCSI 9GB 10K WU3
BD00975334	B915	SCSI 9GB 10K WU3
BD01862A67	B008	SCSI 18GB 10K WU3
BD0186349B	3B12	SCSI 18GB 10K WU3
BD018635C4	B022	SCSI 18GB 10K WU3
BD0186459A	B011	SCSI 18GB 10K WU3
BD01872A6A	B008	SCSI 18GB 10K WU3
BD018735C7	B022	SCSI 18GB 10K WU3
BD018745A3	B011	SCSI 18GB 10K WU3
BD036635C5	B022	SCSI 36GB 10K WU3
BD0366459B	B011	SCSI 36GB 10K WU3
BD036735C8	B022	SCSI 36GB 10K WU3
BD036745A4	B011	SCSI 36GB 10K WU3
BD03685A24	HPB4	SCSI 36GB 10K U320
BD03695A27	HPB4	SCSI 36GB 10K U320
BD0726459C	B011	SCSI 72GB 10K WU3
BD07285A25	HPB4	SCSI 72GB 10K U320
BD07287B4C	HPB5	SCSI 72GB 10K U320
BD07297B57	HPB5	SCSI 72GB 10K U320
BD14685A26	HPB4	SCSI 146GB 10K U320
BD14687B52	HPB5	SCSI 146GB 10K U320
BD14697B58	HPB5	SCSI 146GB 10K U320
BD30087B53	HPB5	SCSI 300GB 10K U320

MSA500 G2 version 1.52 (continued from first page)

This MSA500 G2 firmware will recommend updates for some SCSI disk drive models after the MSA500 G2 firmware has been installed. To avoid notification on the LCD panel, update any applicable hard disk drives before updating the MSA500 G2 firmware.

Disk drive firmware components are available from:

http://h18000.www1.hp.com/support/files/storage/us/locOsCat/99_56.html

If a component is not available for the affected disk drive model, download the following ROMPaq:
<http://h18000.www1.hp.com/support/files/server/us/download/17149.html>

A later version of the disk drive firmware may be available and should be used.

BF01865222	B009	SCSI 18GB 15K WU3
BF01885A34	HPB4	SCSI 18GB 15K U320
BF03665223	B009	SCSI 36GB 15K WU3
BF03685A35	HPB4	SCSI 36GB 15K U320
BF03687B54	HPB1	SCSI 36GB 15K U320
BF03697B5B	HPB1	SCSI 36GB 15K U320
BF07285A36	HPB4	SCSI 72GB 15K U320
BF07287B55	HPB1	SCSI 72GB 15K U320
BF07297B5B	HPB1	SCSI 72GB 15K U320
BF14687B56	HPB1	SCSI 146GB 15K U320
BF14697B5C	HPB1	SCSI 146GB 15K U320