



DATE: May 3, 2002

SUBJECT: EA81520A.86B Standard S815EBM1 BIOS Production 5 Build 15.

About This Release

- EA81520A.86B.0015.P05.0204031942
- 815 Video BIOS 6.2 Production Version 2313
- ICH2 PXE 2.0 Ver. 83

Features/Errata Fixed in This Release

P05-0015

- Fixed the issue where the user is not able to flash the user logo area of the BIOS with SPLASH.exe / lflash.exe.

P04-0012

- Added IOAPIC Support and updated GPIO logic (GP21) to detect IOAPIC.
- Enabled COM port B support.
- Removed the APM choice in BIOS setup menu and force APM configuration to disable by default and power on.

P03-0008

- Reopen G_VIDEO_CFG to fix the issue where add-in PCI Video Adapter is not supported in server environment.
-