



PROCESSOR TYPE PDP-11 Family

G8000-C0001 CODE: F CS: A
AUG-73 - PROBLEM: Capacitor voltage ratings are too low.
CORRECTION: Raise voltage rating of capacitors C1, C2, and C3 from 15*
to 20 volts.
In-plant effectivity -03 * retrofit in test when problem occurs. Phase-in to
production when parts are available.
Field effectivity -Rework all G8000's when symptoms are present.
(Time To Install And Test .5 Hour.) (Kit Contents -F1029 -FCO/Prints
And Parts)