



Product Change Notification

110788 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

| | |
|-------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Change Notification #: | 110788 - 00 |
| Change Title: | Intel PRO/100 M Desktop Adapters, PILA8460M MM#854613, PILA8460MBLK20 MM#847578 (Dayville Retail) PCN 110788-00 Product Discontinuance End of Life |
| Date of Publication: | July 29, 2011 |

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

| | |
|------------------------------------------------------------|--------------|
| Last Product Discontinuance Order Date: | Jul 30, 2012 |
| Orders are Non-Cancelable and Non-Returnable After: | Oct 30, 2012 |
| Last Product Discontinuance Shipment Date: | Dec 31, 2012 |
| Technical Support Service Ends: | Dec 31, 2013 |

Description of Change to the Customer:

The Intel PRO/100 M Desktop Adapters, PILA8460M MM#854613, PILA8460MBLK20 MM#847578 (Dayville Retail) will End of Life.

The Intel silicon controllers used on these Networking Adapters have announced End of Life on PCN#109390-00, dated July 24th, 2009, as follows; "Intel will be discontinuing the production of its legacy Fast Ethernet 10/100 PCI host-interface Silicon Components. This End of Life (EOL) plan is a LAN Access Division (LAD) business decision influenced by declining demand for all parts manufactured on an old process technology (P854) and the potential of increasing costs."

Customer Impact of Change and Recommended Action:

Customers should place their last time orders by July 30th, 2012, and delivery of all orders must be taken no later than December 31st, 2012. Orders are Non-Cancelable and Non-Returnable after October 30th, 2012, with Technical Support Service ending December 31, 2013.

Note on Discontinued Product Returns:

Approval from Intel, documented by an RMA# reference, must be obtained prior to the return of any product. No credit will be given for products returned by a distributor without prior authorization from Intel and unauthorized returns will be returned to the distributor, freight collect. Intel reserves the right to refuse credit if upon receipt of product it establishes that the terms of return, as defined in this policy, have not been met by distributor or if the product returned does not match the product described on the authorized RMA. Credit for returned products will be calculated based on the cost specified in the current Distributor Cost List in effect on the day that the return is authorized by Intel. Products included in the Discontinued Product Return Notification, as described in Product Discontinuance policy #188000, are not eligible for return under any other Intel® RMA program. No returns of any kind will be accepted for shrink-wrap software products if the shrink-wrap is broken. As indicated below, certain types of RMA product must be returned in the original unopened, undamaged, and unadjusted packaging. Where this requirement is not met, Intel reserves the right to return the product to distributor, freight collect, or to charge distributor a 20% administration fee when calculating credit for return. It is the responsibility of the distributor to ensure that RMA product is adequately protected to reasonably ensure that damage in-transit to Intel does not occur.

Intel encourages all customers to upgrade to 10/100/1000 Mbps adapters. Recommended transition products are noted within the affected products table within this PCN notice.

Products Affected / Intel Ordering Codes:

| End of Life Product Name | End of Life Product Code | End of Life MM# | Note |
|-------------------------------------------------------------|--------------------------|-----------------|-----------------|
| Intel® PRO/100 M Desktop Adapter Dayville Retail | PILA8460M | 854613 | 10/100 Mbps PCI |
| Intel® PRO/100 M Desktop Adapter Dayville Retail BLK 20-pak | PILA8460MBLK20 | 847578 | 10/100 Mbps PCI |

| Recommended Replacement Product Name | Replacement Product Code | Replacement MM# | Note |
|---------------------------------------------------------------------------------------|--------------------------|-----------------|------------------------------|
| Intel PRO/1000 GT Desktop Adapter Stebbins 2 LF Retail | PWLA8391GT | 864968 | 10/100/1000 Mbps PCI |
| Intel PRO/1000 GT Desktop Adapter Stebbins 2 LF Retail BLK 20-pak | PWLA8391GTBLK | 865080 | 10/100/1000 Mbps PCI |
| Intel PRO/1000 GT Desktop Adapter Stebbins 2 LF Retail BLK 20-pak Low Profile bracket | PWLA8391GTLBLK | 865088 | 10/100/1000 Mbps PCI |
| OR | | | |
| Intel Gigabit CT Desktop Adapter Shelter Island Retail | EXPI9301CT | 893646 | 10/100/1000 Mbps PCI Express |
| Intel Gigabit CT Desktop Adapter Shelter Island Retail BLK 20-pak | EXPI9301CTBLK | 893647 | 10/100/1000 Mbps PCI Express |

PCN Revision History:

| Date of Revision: | Revision Number: | Reason: |
|-------------------|------------------|--------------------------|
| July 29, 2011 | 00 | Originally Published PCN |