



**HEWLETT-PACKARD COMPANY
LOGIC SYSTEMS DIVISION**

**HP 64000
Logic Development
System**

DOCUMENTATION CATALOG

October 17, 1988

Dear Hewlett-Packard Customer,

Welcome to the new Logic Systems Division Document Catalog! The Catalog lists all of the operating and service documentation currently available for HP 64000 system products. You can order documents listed in this catalog by contacting your local HP Sales & Service office.

How To Use The Catalog

There are five columns listed in the Document Catalog:

Product/Assembly# lists the HP product number of a system component; or the assembly number of a documentation assembly. (A document assembly usually contains more than one document.)

Assembly/Part# lists the HP part numbers of document assemblies and actual documents.

Edition is the current edition code of a particular document. The edition references the date of the last change to the document. Edition codes are of the form EMMYY, where E is the prefix, MM represents months 1-12, and YY represents the year. (For example, an edition code of E0188 represents a document that was introduced or changed in January of 1988.)

Update lists the update code for any change sheets supplied with the document. Update codes are read in the same manner as edition codes. (Note: only updates in the U code system are listed in the main catalog. Updates published in the "A", "B", "C" code system are listed in a special supplement at the end of the main catalog.)

Description is the name of the product, description of a document assembly, or title of the manual.

To find all of the documents for a particular product:

- Look up the product number in the Product/Assembly# column.
- Look at the list of documents & document assemblies shipped with that product in the Assembly/Part# column.
- If document assemblies are listed in the Assembly/Part# column, you can obtain more information on these assemblies by looking for their numbers in the Product/Assembly# column.

For example, if you want to know which documents are shipped with the 64742A 68000 Emulator:

- Look up the 64742A in the Product/Assembly# column. You will see the assembly 64742-99901 in the Assembly/Part# column.

- Look up the 64742-99901 assembly in Product/Assembly# column. You will see two documents: 64740-90912, HP 64000 Support Services, and 64742-90901, MC68000 Emulator User's Guide. In addition, there is a document assembly, 64740-99901.
- Look up the 64740-99901 assembly in the Product/Assembly# column. You will see 8 documents listed for this assembly: 5959-6245, 64306-90901, 64740-90901, 64740-90902, 64740-90903, 64740-90904, 64740-90908, and 64740-90909.

In general:

- Numbers with "99" or "999" in the second part of the part number are document assemblies.
- Numbers with "90" or "909" in the second part of the part number are documents.
- Eight digit part numbers are document supplements, such as operating notices, software notices, compatibility guides, etc.

Not All Parts Are Orderable!

Many document assemblies were set up for internal manufacturing purposes only and are not orderable directly from HP. Other document assemblies may be ordered as a unit. If you want all of the manuals listed on a particular document assembly, contact your HP order coordinator for information on whether or not that particular document assembly may be ordered directly. If not, your HP order coordinator can assist you in ordering the individual components for the document assembly.

Also, updates/change sheets listed in the catalog are not orderable as individual items. You must order the manual to receive all of the current updates/change sheets.

Hewlett-Packard
Logic Systems Division
Technical Publications

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|----------------------------------|--------|---|
| 64020A | 64020-90901 64020-90902 | E1287 E0787 | | 64100A Retrofit Kit Peripheral Package Upgrade Kit |
| 64021A | 64021-90901 64021-90902 | E1186 E0686 | | 64110A Retrofit Kit Peripheral Package Peripheral Package |
| 64032A | 64032-90901 | NOV81 | | 16K Dynamic Memory 16K MEMORY EXPANSION MODULE |
| 64037A | 64037-90901 | E0588 | | RS422 High Speed Interface High Speed Interface Installation Guide |
| 64037AX | 64037-90901 | E0588 | | One-Time Update High Speed Interface Installation Guide |
| 64050A | 64050-90901 | JUL82 | | Screen Printer Interface Screen Printer Interface |
| 64100A | 64100-90910 64980-90929 | DEC83 JUL83 | | Pisces Mainframe 64100A Mainframe Installation and Configuration Reference |
| 64100A/S01 | 64980-90929 | JUL83 | | Operation-Scheduling Installation and Configuration Reference |
| 64100AF | 64980-90912 64980-90922 64980-90930 64980-90933 64980-99901 64980-99934 | FEB82 E0986 MAR85 E1186 | | Disc Operating System System Overview Reference Measurement System Reference Editor Reference HP64000 File Format Reference Documentation Assembly Documentation Assembly |
| 64100AR | 64980-90912 64980-90922 64980-90930 64980-90933 64980-99901 64980-99934 | FEB82 E0986 MAR85 E1186 | | Right to Copy System Overview Reference Measurement System Reference Editor Reference HP64000 File Format Reference Documentation Assembly Documentation Assembly |
| 64100AX | 64980-90912 64980-90922 64980-90930 64980-90933 64980-99901 64980-99934 | FEB82 E0986 MAR85 E1186 | | One-Time Update System Overview Reference Measurement System Reference Editor Reference HP64000 File Format Reference Documentation Assembly Documentation Assembly |
| 64110A | 64110-90907 64941-90906 64980-90929 | E1283 JAN84 JUL83 | U0887 | Orion Mainframe 64110A Mainframe Flexible Disc Drives Installation and Configuration Reference |
| 64120-68710 | 64790-90901 64801-90903 64801-90908 | E0587 E0387 E1186 | U0987 | Student Instructor Kit Softkey Editor User's Guide Measurement System |
| 64120A | | | | Development Station II |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|-----------------|---------|--------|---|
| | 64120-90902 | E1186 | U0887 | Instrumentation Cardcage |
| 64130-99901 | 5959-2118 | E0488 | | BTO Documentation Assembly |
| | 5959-6263 | E0888 | | Box List for 64130-99901 |
| | 5959-6267 | E0888 | | Operating Notice |
| | 5959-6272 | E0888 | | Operating Notice |
| | 64130-90901 | E0788 | | Operating Notice |
| | 64740-90912 | E0688 | | HP 64130S/31S/32S System Bundle |
| | | | | HP 64000 Support Services |
| 64130S | | | | 64000-UX MDE |
| | 5959-2105 | E0287 | | 64130S System Bundle Box List |
| | 64130-99901 | | | BTO Documentation Assembly |
| | 64130S/005 | | | 8085 Development Environment Bundle |
| | 64130S/006 | | | 6809 Development Environment Bundle |
| | 64130S/007 | | | 6809E Development Environment Bundle |
| | 64130S/008 | | | 8086/8087 Development Environment Bundle |
| | 64130S/009 | | | 80C86 Development Environment Bundle |
| | 64130S/010 | | | 8088/8087 Development Environment Bundle |
| | 64130S/011 | | | 80C88 Development Environment Bundle |
| | 64130S/012 | | | 80186 Development Environment Bundle |
| | 64130S/013 | | | 80188 Development Environment Bundle |
| | 64130S/014 | | | Z8001 Development Environment Bundle |
| | 64130S/015 | | | Z8002 Development Environment Bundle |
| | 64130S/016 | | | 68000 (DIP) Development Environment Bundle |
| | 64130S/017 | | | 68000 (PGA) Development Environment Bundle |
| | 64130S/018 | | | 68008 Development Environment |
| | 64130S/019 | | | 68010 Development Environment Bundle |
| | 64130S/020 | | | 68010 Development Environment Bundle |
| | 64130S/021 | | | Z80 Development Environment Bundle |
| | 64130S/022 | | | 6801/6803 Development Environment Bundle |
| | 64130S/023 | | | 8051 Development Environment Bundle |
| | 64130S/024 | | | F9450 Development Environment` Bundle |
| | 64130S/025 | | | 68020 Development Environment Bundle |
| 64131S | | | | 64000-UX MDE |
| | 64130-99901 | | | BTO Documentation Assembly |
| | 64131S/002 | | | 6805P Development Environment Bundle |
| | 64131S/003 | | | 46805G2 Development Environment Bundle |
| | 64131S/004 | | | 46805E2 Development Environment Bundle |
| | 64131S/005 | | | 8085 Development Environment Bundle |
| | 64131S/006 | | | 6809 Development Environment Bundle |
| | 64131S/007 | | | 6809E Development Environment Bundle |
| | 64131S/008 | | | 8086/8087 Development Environment Bundle |
| | 64131S/009 | | | 80C86 Development Environment Bundle |
| | 64131S/010 | | | 8088/8087 Development Environment Bundle |
| | 64131S/011 | | | 80C88 Development Environment Bundle |
| | 64131S/012 | | | 80186 Development Environment Bundle |
| | 64131S/014 | | | Z8001 Development Environment Bundle |
| | 64131S/015 | | | Z8002 Development Environment Bundle |
| | 64131S/016 | | | 68000 (DIP) Development Environment Bundle |
| | 64131S/017 | | | 68000 (PGA) Development Environment Bundle |
| | 64131S/018 | | | 68008 Development Environment Bundle |
| | 64131S/021 | | | Z80 Development Environment Bundle |
| | 64131S/023 | | | 8051 Development Environment Bundle |
| | 64131S/024 | | | F9450 Development Environment Bundle |
| | 64131S/025 | | | 68020 Development Environment Bundle |
| | 64131S/026 | | | 6301V Development Environment Bundle |
| | 64131S/027 | | | 6301X Development Environment Bundle |
| | 64131S/028 | | | 6301Y Development Environment Bundle |
| | 64131S/029 | | | V20 (70108) Development Environment Bundle |
| | 64131S/030 | | | V30 (70116) Development Environment Bundle |
| | 64131S/031 | | | UDE Development Environment Bundle |
| | 64131S/032 | | | UDE Development Environment Bundle (No Pod) |
| | 64131S/033 | | | V50 (70216) Emulation Environment Bundle |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|-----------------|---------|--------|---|
| | 64131S/034 | | | V40 (70208) Development Environment Bundle |
| | 64131S/035 | | | 68HC11 Development Environment Bundle |
| | 64131S/036 | | | 64180 SDIP Emulation Environment Bundle |
| | 64131S/037 | | | 64180 PLCC Emulation Environment Bundle |
| | 64131S/038 | | | P1750 Emulation Environment Bundle |
| 64131S/013 | | | | 80188 Development Environment Bundle |
| 64132S | | | | 64000-UX MDE |
| | 64130-99901 | | | BTO Documentation Assembly |
| | 64132S/001 | | | 8085 Development Environment Bundle |
| | 64132S/002 | | | 6805P Development Environment Bundle |
| | 64132S/003 | | | 46805G2 Development Environment Bundle |
| | 64132S/004 | | | 46805E2 Development Environment Bundle |
| | 64132S/005 | | | 8085 Development Environment Bundle |
| | 64132S/006 | | | 6809 Development Environment Bundle |
| | 64132S/007 | | | 6809E Development Environment Bundle |
| | 64132S/008 | | | 8086/8087 Development Environment Bundle |
| | 64132S/009 | | | 80C86 Development Environment Bundle |
| | 64132S/010 | | | 8088/8087 Development Environment Bundle |
| | 64132S/011 | | | 80C88 Development Environment Bundle |
| | 64132S/012 | | | 80186 Development Environment Bundle |
| | 64132S/013 | | | 80188 Development Environment Bundle |
| | 64132S/014 | | | Z8001 Development Environment Bundle |
| | 64132S/015 | | | Z8002 Development Environment Bundle |
| | 64132S/016 | | | 68000 Development Environment Bundle |
| | 64132S/017 | | | 68000 Development Environment PGA Bundle |
| | 64132S/018 | | | 68008 Development Environment Bundle |
| | 64132S/019 | | | 68010 Development Environment Bundle |
| | 64132S/020 | | | 68010 Development Environment Bundle |
| | 64132S/021 | | | Z80 Development Environment Bundle |
| | 64132S/022 | | | 6801/6803 Development Environment Bundle |
| | 64132S/023 | | | 8051 Development Environment Bundle |
| | 64132S/024 | | | F9450 Development Environment Bundle |
| | 64132S/025 | | | 68020 Development Environment Bundle |
| | 64132S/026 | | | 6301V Development Environment Bundle |
| | 64132S/027 | | | 6301X Development Environment Bundle |
| | 64132S/028 | | | 6301Y Development Environment Bundle |
| | 64132S/029 | | | V20 (70108) Development Environment Bundle |
| | 64132S/030 | | | V30 (70116) Development Environment Bundle |
| | 64132S/031 | | | UDE Development Environment Bundle |
| | 64132S/032 | | | UDE Development Environment (No Pod) Bundle |
| | 64132S/033 | | | V50 (70216) Emulation System Bundle |
| | 64132S/034 | | | V40 (70208) Emulation Environment Bundle |
| | 64132S/035 | | | 68HC11 Development Environment Bundle |
| | 64132S/036 | | | 64180 SDIP Emulation Environment Bundle |
| | 64132S/037 | | | 64180 PLCC Emulation Environment Bundle |
| | 64132S/038 | | | P1750 Emulation Environment Bundle |
| 64133S | 64130-99901 | | | 64000-UX MDE |
| | | | | BTO Documentation Assembly |
| 64135-99902 | 64740-90912 | E0688 | | Documentation Assembly HP 64000 Support Services |
| 64135S | 64135-90902 | E0788 | | 64000 PC MDE |
| | 64135-99902 | | | HP 64135 S System Bundle |
| | | | | Documentation Assembly |
| 64151A | 64151-90901 | FEB85 | | RAM Static 200NS |
| | 64151-90902 | E0787 | | Emulation Memory Controller |
| | | | | Emulation Memory Controller |
| 64155A | | | | Wide Address Memory Control |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|---|--------|--|
| | 64155-90901 64155-90903 | E1186 E1186 | | Wide Emulation Memory Controllers Wide Address Memory Controller |
| 64155B | 64155-90901 64155-90903 | E1186 E1186 | | Wide Address Memory Control with 128K Wide Emulation Memory Controllers Wide Address Memory Controller |
| 64161A | 64161-90901 64161-90902 | JAN84 E1187 | | 128K Static Memory 32/64/128K Emulation Memory Emulation Memory |
| 64162A | 64161-90901 64161-90902 | JAN84 E1187 | | 64K Static Memory 32/64/128K Emulation Memory Emulation Memory |
| 64163A | 64161-90901 64161-90902 | JAN84 E1187 | | 32K Static Memory 32/64/128K Emulation Memory Emulation Memory |
| 64180AA | 64180-99901 | | | SDIP Emulator Subsystem Documentation Assembly |
| 64180AA/004 | 64180-99902 | | | 64180 Emulator (DC600) Documentation Assembly |
| 64180AB | 64180-99901 | | | PLCC Emulator Subsystem Documentation Assembly |
| 64180AB/004 | 64180-99902 | | | 64180 Emulator (DC600) Documentation Assembly |
| 64192-99901 | 64192-90906 64200-90912 64801-90906 64801-90908 64801-90909 | E0787 E0187 E1086 E1186 E1186 | U0987 | Documentation Assembly R/U/P/G/E Emulator Operating Manual (300) Emulation /Analysis Reference Option Test Measurement System HP Support Services |
| 64192A | 5957-7326 5957-7358 64192-90901 64192-90903 | E0983 E0684 E0283 MAY84 | | 6805R/U Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors 6805R/U Emulation Pod 6805R/U EMULATION WUTH INTERNAL ANALYSIS |
| 64192A/004 | 64192-99901 | | | 6805U/R Emulation 300 Documentation Assembly |
| 64192AX | 64192-90903 | MAY84 | | One Time Update for 64192A 6805R/U EMULATION WUTH INTERNAL ANALYSIS |
| 64192AX/004 | 64192-99901 | | | One Time Update for 64192A/004 Documentation Assembly |
| 64192S/004 | 64192-99901 | | | 6805U/R Emulation 300 Documentation Assembly |
| 64193A | 5957-7326 5957-7358 64193-90901 64193-90903 | E0983 E0684 E0383 E0483 | | 6805 Emulator Operating Notice Caution for Emulator Pods and Preprocessors 6805P Emulation Pod 6805P Emulation with Internal Analysis |
| 64193A/004 | 64192-99901 | | | 6805P Emulation 300 Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|----------------------------------|--------|--|
| 64193AX | 64193-90903 | E0483 | | One Time Update for 64193A 6805P Emulation with Internal Analysis |
| 64193AX/004 | 64192-99901 | | | One-Time Update Documentation Assembly |
| 64193S/004 | 64192-99901 | | | 6805P Emulator 300 Documentation Assembly |
| 64194A | 5957-7326 5957-7358 64194-90901 64194-90902 | E0983 E0684 E1084 E1084 | U1185 | 146805G Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors 146805G Emulator Pod 146805G Emulator Pod |
| 64194A/004 | 64192-99901 | | | 6805G Emulation 300 Documentation Assembly |
| 64194AX | 64194-90902 | E1084 | | One Time Update for 64194A 146805G Emulator Pod |
| 64194AX/004 | 64192-99901 | | | One Time Update for 64194A/004 Documentation Assembly |
| 64194S/004 | 64192-99901 | | | 6805E Emulation 300 Documentation Assembly |
| 64195A | 5957-7326 64195-90901 64195-90902 | E0983 E0585 E0585 | | 146805E2 Emulator Pod Operating Notice 146805E2 Emulation Subsystem 146805E2 Emulation with Internal Analysis |
| 64195A/004 | 64192-99901 | | | 6805E Emulation 300 Documentation Assembly |
| 64195AX | 64195-90902 | E0585 | | One Time Update for 64195A 146805E2 Emulation with Internal Analysis |
| 64195AX/004 | 64192-99901 | | | One Time Update for 64195A/004 Documentation Assembly |
| 64195S/004 | 64192-99901 | | | 6805E Emulation 300 Documentation Assembly |
| 64197A | 64197-90901 | OCT84 | | 6805 Emulator Control Emulator Control |
| 64200-99901 | 5958-6065 64200-90907 | R2610 E0681 | | Documentation Assembly Software Notice for 64200-90907 8080/8085 Assembler and Linker Supplement |
| 64201A | 64200-90909 | JUL83 | | 8080 Emulator Control 8080/8085 Emulator Control |
| 64202A | 5957-7326 5957-7358 64200-90911 64202-90902 | E0983 E0684 APR84 E0985 | | 8080 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors 8080/8085 Emulation with Internal Analysis 8080 Emulation Pod |
| 64202AX | 64200-90911 | APR84 | | One-Time Update 8080/8085 Emulation with Internal Analysis |
| 64202AX/004 | | | | One-Time Update |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|----------------------------------|--------|--|
| | 64203-90903 64801-90909 | E0687 E1186 | | 8085 Emulation with Internal Analysis HP Support Services |
| 64202S/004 | 64203-90903 64801-90909 | E0687 E1186 | | 8080 Emulator (300) 8085 Emulation with Internal Analysis HP Support Services |
| 64203A | 5957-7326 5957-7358 64200-90911 64203-90902 | E0983 E0684 APR84 E0582 | U1286 | 8085 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors 8080/8085 Emulation with Internal Analysis 8085 Emulation Pod |
| 64203A/004 | 64203-90903 64801-90909 | E0687 E1186 | | 8085 Emulator (300) 8085 Emulation with Internal Analysis HP Support Services |
| 64203AX | 64200-90911 | APR84 | | One-Time Update 8080/8085 Emulation with Internal Analysis |
| 64203AX/004 | 64203-90903 64801-90909 | E0687 E1186 | | One-Time Update 8085 Emulation with Internal Analysis HP Support Services |
| 64203S/004 | 64203-90903 64801-90909 | E0687 E1186 | | 8085 Emulator (300) 8085 Emulation with Internal Analysis HP Support Services |
| 64206A | 64206-99901 | | | 6301 Emulator Documentation Assembly |
| 64206A/004 | 64206-99902 | | | 9000 Host Interface (300) Documentation Assembly |
| 64206S/004 | 64206-99902 | | | 9000 Host Interface (300) Documentation Assembly |
| 64207A | 64207-99901 | | | 6301X Emulation Pod Documentation Assembly |
| 64207A/004 | 64206-99902 | | | 9000 Host Interface (300) Documentation Assembly |
| 64207S/004 | 64206-99902 | | | 9000 Host Interface (300) Documentation Assembly |
| 64208A | 64207-99901 | | | Emulation Pod 6301Y Documentation Assembly |
| 64208A/004 | 64206-99902 | | | 9000 Host Interface (300) Documentation Assembly |
| 64208S/004 | 64206-99902 | | | 9000 Host Interface (300) Documentation Assembly |
| 64211A | 64211-90902 | E0682 | | 6800 Emulator Control 6800/6802 Emulator Control |
| 64212A | 5957-7326 5957-7358 64210-90906 64213-90902 | E0983 E0684 E1282 E1083 | | 6800 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors 6800/6802 Emulation with Internal Analysis 6800 Emulator Pod |
| 64212AX | | | | One-Time Update |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|-----------------|---------|--------|---|
| | 64210-90906 | E1282 | | 6800/6802 Emulation with Internal Analysis |
| 64213A | 5957-7326 | E0983 | | 6802 Emulator Pod Operating Notice |
| | 5957-7358 | E0684 | | Caution for Emulator Pods and Preprocessors |
| | 64210-90906 | E1282 | | 6800/6802 Emulation with Internal Analysis |
| | 64213-90902 | E1083 | | 6800 Emulator Pod |
| 64213AX | 64210-90906 | E1282 | | One-Time Update 6800/6802 Emulation with Internal Analysis |
| 64214-99901 | 64214-90904 | E0587 | | Documentation Assembly 6809/6809E Emulation with Internal Analysis |
| | 64801-90909 | E1186 | | HP Support Services |
| 64214A | 64214-90901 | MAR83 | | 6809 Emulator Control 6809/6809E Emulator Control |
| 64215A | 5957-7326 | E0983 | | 6809 Emulator Pod Operating Notice |
| | 5957-7358 | E0684 | | Caution for Emulator Pods and Preprocessors |
| | 64214-90903 | SEP82 | | 6809/6809E Emulation with Internal Analysis |
| | 64215-90902 | DEC82 | | 6809 Emulator Pod |
| 64215A/004 | 64214-99901 | | | 6809 Emulator (300) Documentation Assembly |
| 64215AX | 64214-90903 | SEP82 | | One-Time Update 6809/6809E Emulation with Internal Analysis |
| 64215AX/004 | 64214-99901 | | | One-Time Update Documentation Assembly |
| 64215S/004 | 64214-99901 | | | 6809 Emulator (300) Documentation Assembly |
| 64216A | 5957-7326 | E0983 | | 6809E Emulator Pod Operating Notice |
| | 5957-7358 | E0684 | | Caution for Emulator Pods and Preprocessors |
| | 64214-90903 | SEP82 | | 6809/6809E Emulation with Internal Analysis |
| | 64216-90901 | JUL83 | | 6809E Emulator Pod |
| 64216A/004 | 64214-99901 | | | 6809E Emulator (300) Documentation Assembly |
| 64216AX | 64214-90903 | SEP82 | | One-Time Update 6809/6809E Emulation with Internal Analysis |
| 64216AX/004 | 64214-99901 | | | One-Time Update Documentation Assembly |
| 64216S/004 | 64214-99901 | | | 6809E Emulator (300) Documentation Assembly |
| 64220AX | 64220-90902 | E0986 | | One-Time Update 8086/8088 Emulation with Internal Analysis |
| 64220AX/004 | 64220-90903 | E0487 | U1087 | One-Time Update 80186/80188 Emulation with Internal Analysis |
| 64220B | 5180-4848 | E0986 | | 8086/8087 Emulator 808X General Hardware |
| | 64220-90902 | | | 8086/8088 Emulation with Internal Analysis |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|----------------------------------|----------------|--|
| 64220B/004 | 64220-90903 | E0487 | U1087 | 8086 Emulator (300) 80186/80188 Emulation with Internal Analysis |
| 64220C | 5180-4848 64220-90902 | E0986 | | 80C86 Emulator 808X General Hardware 8086/8088 Emulation with Internal Analysis |
| 64220C/004 | 64220-90903 | E0487 | U1087 | 8086 Emulator (300) 80186/80188 Emulation with Internal Analysis |
| 64220S/004 | 64220-90903 | E0487 | U1087 | 8086 Emulator (300) 80186/80188 Emulation with Internal Analysis |
| 64221AX | 64220-90902 | E0986 | | One-Time Update 8086/8088 Emulation with Internal Analysis |
| 64221AX/004 | 64220-90903 | E0487 | U1087 | One-Time Update 80186/80188 Emulation with Internal Analysis |
| 64221B | 5180-4848 64220-90902 | E0986 | | 8088/87 Emulator 808X General Hardware 8086/8088 Emulation with Internal Analysis |
| 64221B/004 | 64220-90903 | E0487 | U1087 | 8088 Emulator (300) 80186/80188 Emulation with Internal Analysis |
| 64221C | 5180-4848 64220-90902 | E0986 | | 80C88 Emulator 808X General Hardware 8086/8088 Emulation with Internal Analysis |
| 64221C/004 | 64220-90903 | E0487 | U1087 | 8088 Emulator (300) 80186/80188 Emulation with Internal Analysis |
| 64221S/004 | 64220-90903 | E0487 | U1087 | 8088 Emulator (300) 80186/80188 Emulation with Internal Analysis |
| 64222-99901 | 64222-90903 64801-90906 64801-90909 | E0487 E1086 E1186 | U1087 | Documentation Assembly 8086/8088 Emulation with Internal Analysis Option Test HP Support Services |
| 64222AX | 64980-90931 | SEP83 | | One-Time Update 8086/8088 Emulation with Internal Analysis |
| 64222AX/004 | 64222-99901 | | | One-Time Update Documentation Assembly |
| 64224-99901 | 5957-7326 5957-7358 64224-90903 64225-90902 | E0983 E0684 APR85 OCT84 | U0985 U1285 | Documentation Assembly Operating Notice Caution for Emulator Pods and Preprocessors 80186/188 Emulation with Internal Analysis 80186/80188 Emulation Subsystem |
| 64224A | 64224-99901 | | | 80186 Emulator Documentation Assembly |
| 64224A/004 | 64223-90902 | E0387 | U0388 | 80186 Emulator (300) 80186/80188 Emulation with Internal Analysis |
| 64224AX | 64224-99901 | | | One-Time Update Documentation Assembly |
| 64224AX/004 | 64223-90902 | E0387 | U0388 | One-Time Update 80186/80188 Emulation with Internal Analysis |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|----------------------------------|--------|---|
| 64224S/004 | 64223-90902 | E0387 | U0388 | 80186 Emulator (300) 80186/80188 Emulation with Internal Analysis |
| 64225A | 64224-99901 | | | 80188 Emulator Documentation Assembly |
| 64225A/004 | 64223-90902 | E0387 | U0388 | 80188 Emulator (300) 80186/80188 Emulation with Internal Analysis |
| 64225AX | 64224-99901 | | | One-Time Update Documentation Assembly |
| 64225AX/004 | 64223-90902 | E0387 | U0388 | One-Time Update 80186/80188 Emulation with Internal Analysis |
| 64225S/004 | 64223-90902 | E0387 | U0388 | 80188 Emulator (300) 80186/80188 Emulation with Internal Analysis |
| 64226AX | 64980-90931 | SEP83 | | One-Time Update 8086/8088 Emulation with Internal Analysis |
| 64226AX/004 | 64222-99901 | | | One-Time Update Documentation Assembly |
| 64227AX | 64227-90901 | JAN85 | | One-Time Update 80286 Emulation with Internal Analysis |
| 64227B | 64227-90901 | JAN85 | | 80286 Emulator Pod 80286 Emulation with Internal Analysis |
| 64228S | 5957-7326 64228-90901 | E0983 E0887 | U0388 | 80286 Emulator Operating Notice 80286 Emulation with Internal Analysis |
| 64228SX | 64228-90901 | E0887 | U0388 | One-Time Update 80286 Emulation with Internal Analysis |
| 64232-99901 | 64200-90912 64232-90903 64801-90909 | E0187 E0787 E1186 | U0987 | Documentation Assembly Emulation /Analysis Reference Z8001 Emulation with Internal Analysis HP Support Services |
| 64232A | 5957-7326 5957-7358 64232-90902 64980-90923 | E0983 E0684 AUG82 E0486 | | Z8001 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors Z8001 Emulation Pod Z8001/02 Emulation with Internal Analysis |
| 64232A/004 | 64232-99901 | | | 300 Z8001 Emulation Pod Documentation Assembly |
| 64232AX | 64980-90923 | E0486 | | One-Time Update Z8001/02 Emulation with Internal Analysis |
| 64232AX/004 | 64232-99901 | | | One-Time Update Documentation Assembly |
| 64232S/004 | 64232-99901 | | | 300 Z8001 Emulator Documentation Assembly |
| 64233-99901 | 64200-90912 64233-90903 64801-90909 | E0187 E0687 E1186 | U0987 | Documentation Assembly Emulation /Analysis Reference Z8002 Emulator/Analyzer HP Support Services |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|---|----------------|--|
| 64233A | 5957-7326 5957-7358 64233-90902 64233-99901 64980-90923 | E0983 E0684 SEP83 E0486 | | Z8002 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors Z8002 Emulator Pod Documentation Assembly Z8001/02 Emulation with Internal Analysis |
| 64233A/004 | 64233-99901 | | | Z8002 Emulator (300) Documentation Assembly |
| 64233AX | 64233-99901 64980-90923 | E0486 | | One-Time Update Documentation Assembly Z8001/02 Emulation with Internal Analysis |
| 64233AX/004 | 64233-99901 | | | One-Time Update Documentation Assembly |
| 64233S/004 | 64233-99901 | | | Z8002 Emulator (300) Documentation Assembly |
| 64242AX | 64980-99932 | | | One-Time Update Documentation Assembly |
| 64242AX/004 | 64242-90906 | E0387 | U1087 | One-Time Update 68000/10 Emulation with Internal Analysis |
| 64243-99901 | 5958-8896 64243-90901 | R2701 E0486 | | Documentation Assembly Software Notice 68000/08 Emulation with Internal Analysis |
| 64243-99902 | 5959-2128 64200-90912 64243-90903 64801-90908 64801-90909 | R2707 E0187 E0187 E1186 E1186 | U0987 U0387 | Documentation Assembly Operating Notice Emulation /Analysis Reference 68000/08 Emulation with Internal Analysis Measurement System HP Support Services |
| 64243-99903 | 64740-90912 | E0688 | | Documentation Assembly HP 64000 Support Services |
| 64243AA | 5957-7326 5957-7358 64243-99901 | E0983 E0684 | | 68000 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64243AA/004 | 64243-99902 | | | 68000 Emulator (300) Documentation Assembly |
| 64243AB | 5957-7326 5957-7358 64243-99901 | E0983 E0684 | | 68000 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64243AB/004 | 64243-99902 | | | 68000 Emulator (300) Documentation Assembly |
| 64243AX | 64243-99901 | | | One-Time Update Documentation Assembly |
| 64243AX/004 | 64243-99902 | | | One-Time Update Documentation Assembly |
| 64243DM/004 | 64243-99903 | | | Media and Manuals (300) Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|----------------------------------|----------------|--|
| 64244AA | 5957-7326 5957-7358 64243-99901 | E0983 E0684 | | 68008 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64244AA/004 | 64243-99902 | | | 68008 Emulator (300) Documentation Assembly |
| 64244AX | 64243-99901 | | | One-Time Update Documentation Assembly |
| 64244AX/004 | 64243-99902 | | | One-Time Update Documentation Assembly |
| 64245-99901 | 5958-8897 64245-90901 | R2701 E0486 | U0787 | Documentation Assembly Software Notice 68010 Emulation with Internal Analysis |
| 64245-99902 | 64200-90912 64245-90903 64801-90908 64801-90909 | E0187 E0287 E1186 E1186 | U0987 U0987 | Documentation Assembly Emulation /Analysis Reference 68010 Emulator/Analyzer Measurement System HP Support Services |
| 64245AA | 5957-7326 5957-7358 64245-99901 | E0983 E0684 | | 68010 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64245AA/004 | 64245-99902 | | | 68010 Emulator (300) Documentation Assembly |
| 64245AB | 5957-7326 5957-7358 64245-99901 | E0983 E0684 | | 68010 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64245AB/004 | 64245-99902 | | | 68010 Emulator (300) Documentation Assembly |
| 64245AX | 64245-99901 | | | One-Time Update Documentation Assembly |
| 64245AX/004 | 64245-99902 | | | One-Time Update Documentation Assembly |
| 64249AX | 64980-99932 | | | One-Time Update Documentation Assembly |
| 64249AX/004 | 64242-90906 | E0387 | U1087 | One-Time Update 68000/10 Emulation with Internal Analysis |
| 64252-99901 | 64200-90912 64252-90905 64801-90908 64801-90909 | E0187 E0187 E1186 E1186 | U0987 U0287 | Documentation Assembly Emulation /Analysis Reference Z80 Emulation with Internal Analysis Measurement System HP Support Services |
| 64252AX | 64252-90903 | APR83 | | One-Time Update Z80 Emulation with Internal Analysis |
| 64252AX/004 | 64252-99901 | | | One-Time Update Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|----------------------------------|--------|--|
| 64253A | 5957-7326 64253-90901 64253-90902 | E0983 APR85 E1085 | | Z80 Emulator Pod Operating Notice Z80 Emulator Pod Z80 Emulation with Internal Analysis |
| 64253A/004 | 64253-90903 | E0287 | U1087 | Z80 Emulator (300) Z80 Emulation with Internal Analysis |
| 64253AX | 64253-90902 | E1085 | | One-Time Update Z80 Emulation with Internal Analysis |
| 64253S/004 | 64253-90901 64253-90902 64253-90903 | APR85 E1085 E0287 | U1087 | Z80 Emulator (300) Z80 Emulator Pod Z80 Emulation with Internal Analysis Z80 Emulation with Internal Analysis |
| 64255-68701 | 64255-90906 | JUN84 | | 6801 Retrofit Installation Instructions |
| 64255-99901 | 5958-6066 64255-90903 | R2604 E1285 | | Documentation Assembly Software Notice for 64255-90903 6801/6803 Emulation with Internal Analysis |
| 64255A | 64255-90905 | JAN84 | | Control Emulator 6801/6803 Emulation Control |
| 64256A | 5957-7326 5957-7358 64255-99901 64256-90903 | E0983 E0684 JAN84 | | 6801 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly 6801/6803 Emulator Pod |
| 64256A/004 | 64255-90907 | E0387 | | 300 6801/03 Emulation 6801/6803 Emulation with Internal Analysis |
| 64256AX | 64255-99901 | | | One-Time Update Documentation Assembly |
| 64256AX/004 | 64255-90907 | E0387 | | One-Time Update 6801/6803 Emulation with Internal Analysis |
| 64256S/004 | 64255-90907 | E0387 | | 300 6801/6803 Emulator 6801/6803 Emulation with Internal Analysis |
| 64261A | 64261-90901 | AUG82 | | 8048 Emulator Control 8048 Series Emulator Control |
| 64262A | 5957-7326 5957-7358 64261-90903 64262-90901 | E0983 E0684 JUL83 DEC81 | | 8048 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors 8048 Series Emulation with Internal Analysis 8048 Series Emulator Pod |
| 64262AX | 64261-90903 | JUL83 | | One-Time Update 8048 Series Emulation with Internal Analysis |
| 64262AX/004 | 64261-90903 | JUL83 | | One-Time Update 8048 Series Emulation with Internal Analysis |
| 64262S/004 | 64261-90903 | JUL83 | | 8048 Emulator (300) 8048 Series Emulation with Internal Analysis |
| 64263A | 64263-90901 | APR84 | | 8051 Emulator Pod 8051 Emulator Control |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|----------------------------------|--------|--|
| 64264-99901 | 64264-90903 64801-90909 | E0387 E1186 | | Documentation Assembly 8031, 8051, 8751 Emulation with Internal Analysis HP Support Services |
| 64264A | 5957-7326 5957-7358 64264-90901 64264-90902 | E0983 E0684 MAR85 APR84 | U1285 | 8051 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors 8051 Emulation with Internal Analysis 8051 Emulator Pod |
| 64264A/004 | 64264-99901 | | | 8051 Emulator (300) Documentation Assembly |
| 64264AX | 64264-90901 | MAR85 | U1285 | One-Time Update 8051 Emulation with Internal Analysis |
| 64264AX/004 | 64264-99901 | | | One-Time Update Documentation Assembly |
| 64264S/004 | 64264-99901 | | | 8051 Emulator (300) Documentation Assembly |
| 64265-99901 | 64265-90902 64801-90909 | E1087 E1186 | U1088 | Documentation Assembly 68HC11 Emulator Operating Manual HP Support Services |
| 64265A | 64265-90901 | E0487 | U1088 | 68HC11A Emulator 68HC11 Emulator with Internal Analysis |
| 64265A/004 | 64265-99901 | | | 68HC11A Emulator (300) Documentation Assembly |
| 64265AX | 64265-90901 | E0487 | U1088 | One-Time Update 68HC11 Emulator with Internal Analysis |
| 64265AX/004 | 64265-99901 | | | One-Time Update Documentation Assembly |
| 64266A | 64265-90901 | E0487 | U1088 | 68HC11D4 Emulator 68HC11 Emulator with Internal Analysis |
| 64267A | 64265-90901 | E0487 | U1088 | 68HC11E2 Emulator 68HC11 Emulator with Internal Analysis |
| 64268B | 5959-2122 | R2706 | | Cable - 52 pin PLCC Operating Notice |
| 64271B | 64271-90902 | NOV83 | | General Purpose Emulator Control General Purpose Emulator Control |
| 64272A | 5957-7326 5957-7358 64272-90901 64272-90902 | E0983 E0684 OCT82 OCT82 | | General Purpose ROM Pod Operating Notice Caution for Emulator Pods and Preprocessors ROM Emulator Pod ROM Emulator |
| 64272AX | 64272-90901 | OCT82 | | One-Time UPdate ROM Emulator Pod |
| 64274-99901 | 64274-90903 64801-90909 | E0387 E1186 | | Documentation Assembly User-Definable Emulator HP Support Services |
| 64274A | | | | General Purpose Emulator Control |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|----------------------------------|--------|--|
| | 5957-7358 64274-90901 | E0684 MAR82 | | Caution for Emulator Pods and Preprocessors User Definable Emulation with Internal Analysis |
| 64274B | 64274-90902 | OCT82 | | UDE Kit User-Definable Emulation with Internal Analysis |
| 64274B/004 | 64274-99901 | | | 300 UDE Kit Documentation Assembly |
| 64274BU/099 | 64274-90902 | OCT82 | | One-Time Update User-Definable Emulation with Internal Analysis |
| 64274BX | 64274-90902 | OCT82 | | One-Time Update User-Definable Emulation with Internal Analysis |
| 64274BX/004 | 64274-99901 | | | One-Time Update Documentation Assembly |
| 64274C/004 | 64274-99901 | | | UDE Emulator (300) Documentation Assembly |
| 64274S/004 | 64274-99901 | | | UDE Emulator (300) Documentation Assembly |
| 64274SF | 64274-90902 | OCT82 | | Emulator Disc Ude User-Definable Emulation with Internal Analysis |
| 64274ST | 64274-90902 | OCT82 | | Emulator Ude User-Definable Emulation with Internal Analysis |
| 64274UT/099 | 64274-90902 | OCT82 | | One-Time Update User-Definable Emulation with Internal Analysis |
| 64276A | 64276-90901 | E1185 | | Run Control Pod Microprogrammable Development Subsystem |
| 64276AX | 64276-90901 | E1185 | | One-Time Update Microprogrammable Development Subsystem |
| 64276B | 64276-90901 | E1185 | | Run Control - 1 WCS Microprogrammable Development Subsystem |
| 64276C | 64276-90901 | E1185 | | Run Control - 2 WCS Microprogrammable Development Subsystem |
| 64285A | 5957-7326 5957-7358 64285-90901 64285-90902 | E0983 E0684 MAY85 MAY85 | | 32010 Emulator Operating Notice Caution for Emulator Pods and Preprocessors TMS32010 Emulator/Analyzer System TMS32010 Emulation Subsystem |
| 64285AX | 64285-90901 | MAY85 | | One-Time Update TMS32010 Emulator/Analyzer System |
| 64286-99901 | 64286-90903 | | | Documentation Assembly |
| 64286-99902 | 64740-90912 | E0688 | | Documentation Assembly HP 64000 Support Services |
| 64286AB | 5957-7326 64286-90902 | E0983 | | 9450 15MHZ Emulator Pod Operating Notice |
| 64286AB/004 | | | | 9450 Emulator (300) |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|----------------------------------|--------|--|
| | 64286-99901 | | | Documentation Assembly |
| 64286AX | 64286-99901 | | | One-Time Update Documentation Assembly |
| 64286AX/004 | 64286-99901 | | | One-Time Update Documentation Assembly |
| 64286DM/004 | 64286-99902 | | | Media and Manuals (300) Documentation Assembly |
| 64286SB/004 | 64286-99901 | | | 9450 Emulator (300) Documentation Assembly |
| 64288-99901 | 64288-90901 64801-90909 | E0288 E1186 | | Documentation Assembly P1750 Emulator Operating Manual HP Support Services |
| 64288-99902 | 64288-90902 64801-90909 | E0288 E1186 | | Documentation Assembly P1750 Emulator Operating Manual (300) HP Support Services |
| 64288-99903 | 64740-90912 | E0688 | | Documentation Assembly HP 64000 Support Services |
| 64288A | 5957-7326 64288-99901 64288-99902 | E0983 | | 1750 Emulator Operating Notice Documentation Assembly Documentation Assembly |
| 64288A/004 | 64288-99902 | | | P1750 Emulator (300) Documentation Assembly |
| 64288AX | 64288-99901 | | | One-Time Update Documentation Assembly |
| 64288AX/004 | 64288-99902 | | | One-Time Update Documentation Assembly |
| 64288DM/004 | 64288-99903 | | | Media and Manuals (300) Documentation Assembly |
| 64288S/004 | 64288-99902 | | | P1750 Emulator (300) Documentation Assembly |
| 64291A | 64291-90901 | JUL83 | | NSC800 Emulator Control NSC800 Emulator Control |
| 64292A | 5957-7326 5957-7358 64292-90902 64292-90903 | E0983 E0684 JUL83 JUN83 | | NSC800 Emulator Pod Operating Notice Caution for Emulator Pods and Preprocessors NSC800 Emulator Pod NSC800 Emulation with Internal Analysis |
| 64292AX | 64292-90903 | JUN83 | | One-Time Update NSC800 Emulation with Internal Analysis |
| 64294A | 64294-99901 | | | V30 Emulation Pod Documentation Assembly |
| 64294A/004 | 64294-99901 | | | 9000 Host Interface (300) Documentation Assembly |
| 64294S/004 | | | | 9000 Host Interface (300) |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|----------------------------|----------------|--------|--|
| | 64294-99901 | | | Documentation Assembly |
| 64295A | 64294-99901 | | | V20 Emulation Pod Documentation Assembly |
| 64295A/004 | 64294-99901 | | | 9000 Host Interface (300) Documentation Assembly |
| 64295S/004 | 64294-99901 | | | 9000 Host Interface (300) Documentation Assembly |
| 64296A | 64294-99901 | | | 70216 Emulation Pod Documentation Assembly |
| 64296A/004 | 64294-99901 | | | 9000 Host Interface (300) Documentation Assembly |
| 64296S/004 | 64294-99901 | | | 9000 Host Interface (300) Documentation Assembly |
| 64297A | 64294-99901 | | | 70208 Emulation Pod Documentation Assembly |
| 64297A/004 | 64294-99901 | | | 9000 Host Interface (300) Documentation Assembly |
| 64297S/004 | 64294-99901 | | | 9000 Host Interface (300) Documentation Assembly |
| 64302A | 64302-90902 | E0986 | | 48 Channel Internal Analysis Wide Logic Analyzer |
| 64303A | 64303-90901 64303-90902 | JAN84 DEC83 | | IMB Extender IMB Extender IMB Extender |
| 64303AX | 64303-90901 | JAN84 | | One-Time Update IMB Extender |
| 64304A | 64304-90901 64304-90902 | JUL83 OCT83 | | Emulation Buss Preprocessor Emulation Bus Preprocessor Emulation Bus Preprocessor |
| 64304A/004 | 64304-90903 | E1086 | | 300 Emulation Bus Preprocessor Emulation Bus Preprocessor |
| 64304AX | 64304-90902 | OCT83 | | One-Time Update Emulation Bus Preprocessor |
| 64304AX/004 | 64304-90902 64304-90903 | OCT83 E1086 | | One-Time Update Emulation Bus Preprocessor Emulation Bus Preprocessor |
| 64306A | 5959-2194 | E0388 | | IMB/CMB Interface Instrument Notice |
| 64310-99901 | 5958-6067 64310-90902 | R2604 APR83 | | Documentation Assembly Software Notice for 64310-90902 Software Performance Analyzer |
| 64310A | 64310-90901 64310-99901 | MAR83 | | Software Performance Analyzer Software Performance Analyzer Documentation Assembly |
| 64310A/004 | | | | 300 SPA |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|----------------------------|---------|--------|--|
| | 64310-90903 | E0986 | U0287 | Software Performance Analyzer |
| 64310AX | 64310-99901 | | | One-Time Update Documentation Assembly |
| 64310AX/004 | 64310-90903 64310-99901 | E0986 | U0287 | One-Time Update Software Performance Analyzer Documentation Assembly |
| 64321A | 64320-90901 | E0386 | | 25 MHz Control 25 MHZ Logic State/Software Analyzer |
| 64321AX | 64320-90901 | E0386 | | One-Time Update 25 MHZ Logic State/Software Analyzer |
| 64331-99901 | 64331-90903 | E0985 | | Documentation Assembly 68000/08/10 High Level Analyzer |
| 64331A | 64331-99901 | | | 68000 Software Analysis Documentation Assembly |
| 64331AR | 64331-99901 | | | Right to Copy Documentation Assembly |
| 64331AX | 64331-99901 | | | One-Time Update Documentation Assembly |
| 64331B | 64331-99901 | | | 68000 Spider DEQ Documentation Assembly |
| 64331BR | 64331-99901 | | | Right to Copy Documentation Assembly |
| 64331BX | 64331-99901 | | | One-Time Update Documentation Assembly |
| 64332-99901 | 64332-90902 | E0785 | | Documentation Assembly 8086 High Level Analyzer |
| 64332A | 64332-99901 | | | 8086 Software Analysis Documentation Assembly |
| 64332AR | 64332-99901 | | | Right to Copy Documentation Assembly |
| 64332AX | 64332-99901 | | | One-Time Update Documentation Assembly |
| 64332B | 64332-99901 | | | 8086 Spider DEQ Documentation Assembly |
| 64332BR | 64332-99901 | | | Right to Copy Documentation Assembly |
| 64332BX | 64332-99901 | | | One-Time Update Documentation Assembly |
| 64333A | 64332-99901 | | | 8088 Software Analysis Documentation Assembly |
| 64333AR | 64332-99901 | | | Right to Copy Documentation Assembly |
| 64333AX | | | | One-Time Update |

| Product/Assembly # | Assembly/Part #: | Edition | Update | Description |
|--------------------|------------------|---------|--------|--|
| | 64332-99901 | | | Documentation Assembly |
| 64333B | 64332-99901 | | | 8088 Spider DEQ Documentation Assembly |
| 64333BR | 64332-99901 | | | Right to Copy Documentation Assembly |
| 64333BX | 64332-99901 | | | One-Time Update Documentation Assembly |
| 64334A | 64331-99901 | | | 68010 Software Analysis Documentation Assembly |
| 64334AR | 64331-99901 | | | Right to Copy Documentation Assembly |
| 64334AX | 64331-99901 | | | One-Time Update Documentation Assembly |
| 64334B | 64331-99901 | | | 68010 Spider DEQ Documentation Assembly |
| 64334BR | 64331-99901 | | | Right to Copy Documentation Assembly |
| 64334BX | 64331-99901 | | | 64334B OTU Documentation Assembly |
| 64335A | 64332-99901 | | | 80186 Software Analysis Documentation Assembly |
| 64335AR | 64332-99901 | | | Right to Copy Documentation Assembly |
| 64335AX | 64332-99901 | | | One-Time Update Documentation Assembly |
| 64336A | 64332-99901 | | | 80188 Software Analysis Documentation Assembly |
| 64336AR | 64332-99901 | | | Right to Copy Documentation Assembly |
| 64336AX | 64332-99901 | | | One-Time Update Documentation Assembly |
| 64337A | 64331-99901 | | | 68008 Spider DEQ Documentation Assembly |
| 64337AR | 64331-99901 | | | Right to Copy Documentation Assembly |
| 64337AX | 64331-99901 | | | One-Time Update Documentation Assembly |
| 64340A | 64340-90901 | E1286 | | Language Analyzer Real-Time High Level Software Analyzer |
| 64341-99901 | 64341-90903 | E0985 | | Documentation Assembly 68000/10 Real-Time High Level Software Analyzer |
| 64341-99902 | 64341-90904 | E0785 | | Documentation Assembly 80186/80188 Real-Time High Level Software Analyzer |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|-----------------|---------|--------|--|
| 64341AA | 64341-99902 | | | 8086 Soda DEQUE Documentation Assembly |
| 64341AR | 64341-99902 | | | Right to Copy Documentation Assembly |
| 64341AX | 64341-99902 | | | One-Time Update Documentation Assembly |
| 64341BA | 64341-99901 | | | 68000 Language Analyzer Documentation Assembly |
| 64341BR | 64341-99901 | | | Right to Copy Documentation Assembly |
| 64341BX | 64341-99901 | | | One-Time Update Documentation Assembly |
| 64341CA | 64341-99902 | | | 8088 Soda DEQUE Documentation Assembly |
| 64341CR | 64341-99902 | | | Right to Copy Documentation Assembly |
| 64341CX | 64341-99902 | | | One-Time Update Documentation Assembly |
| 64341DA | 64341-99901 | | | 68010 Language Analyzer Documentation Assembly |
| 64341DR | 64341-99901 | | | Right to Copy Documentation Assembly |
| 64341DX | 64341-99901 | | | One-Time Update Documentation Assembly |
| 64341EA | 64341-99902 | | | 80186 Language Analyzer Documentation Assembly |
| 64341ER | 64341-99902 | | | Right to Copy Documentation Assembly |
| 64341EX | 64341-99902 | | | One-Time Update Documentation Assembly |
| 64341FA | 64341-99902 | | | 80188 Language Analyzer Documentation Assembly |
| 64341FR | 64341-99902 | | | Right to Copy Documentation Assembly |
| 64341FX | 64341-99902 | | | One-Time Update Documentation Assembly |
| 64341GA | 64341-99901 | | | 68000 Soda DEQUE Documentation Assembly |
| 64341GR | 64341-99901 | | | Right to Copy Documentation Assembly |
| 64341GX | 64341-99901 | | | One-Time Update Documentation Assembly |
| 64341IA | | | | 68010 Soda DEQUE |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|--|--------|--|
| | 64341-99901 | | | Documentation Assembly |
| 64341IR | 64341-99901 | | | Right to Copy Documentation Assembly |
| 64341IX | 64341-99901 | | | One-Time Copy Documentation Assembly |
| 64360-99901 | 5959-2184 64740-90912 | E0288 E0688 | | Documentation Assembly Map Unix HP 64000 Support Services |
| 64380-99901 | 64380-90901 64740-90912 64800-90910 | E0788 E0688 E0488 | | Documentation Assembly HP-UX 68000 Series Basis Branch Analyzer HP 64000 Support Services BTO-MNOP |
| 64380M/004 | 64380-99901 | | | Media and Manual (300) Documentation Assembly |
| 64380M/005 | 64380-99901 | | | Media and Manual (800) Documentation Assembly |
| 64380S/004 | 64380-99901 | | | 68000 BBA (300) Documentation Assembly |
| 64380SR/004 | 64380-99901 | | | Right to Copy Documentation Assembly |
| 64380SX/004 | 64380-99901 | | | One-Time Update Documentation Assembly |
| 64381-99902 | 64381-90901 64801-90909 | E0488 E1186 | U0288 | Documentation Assembly 68020 Basis Branch Analyzer Operating Manual (300/800) HP Support Services |
| 64381M/004 | 64381-99902 | | | Media and Manual (300) Documentation Assembly |
| 64381M/005 | 64381-99902 | | | Media and Manual (800) Documentation Assembly |
| 64381S/004 | 64381-99902 | | | 68020 BBA (300) Documentation Assembly |
| 64381SR/004 | 64381-99902 | | | Right to Copy Documentation Assembly |
| 64381SX/004 | 64381-99902 | | | One-Time Update Documentation Assembly |
| 64410-99901 | 64401-90901 64404-90901 64410-90901 64411-90901 64801-90909 | E1187 E0188 E0188 E0188 E1186 | U0788 | Documentation Assembly Emulator Memory Subsystem 16/32-Bit Analysis Reference 68020 Emulation Specifics 68020 Analysis Specifics HP Support Services |
| 64410-99902 | 5959-2184 64400-90901 64410-90902 64410-90903 64410-99902 64740-90912 | E0288 E0488 E0688 E0688 E0688 E0688 | | Documentation Assembly Map Unix 32-Bit Emulator Reference 68020 Emulation Pod 68020 Emulation Pod Documentation Assembly HP 64000 Support Services |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|----------------------------------|--------|--|
| 64410-99904 | 64401-90901 64404-90901 64801-90909 | E1187 E0188 E1186 | U0788 | Documentation Assembly Emulator Memory Subsystem 16/32-Bit Analysis Reference HP Support Services |
| 64410-99905 | 5959-2184 64400-90901 64410-90904 64740-90912 | E0288 E0488 E0488 E0688 | | BTO-Documentation Assembly Map Unix 32-Bit Emulator Reference 68020 Emulation Operating Manual HP 64000 Support Services |
| 64410-99906 | 64410-90905 64410-99902 | E0688 | | Documentation Assembly 64410E Emulator Upgrade Kit Documentation Assembly |
| 64410A | 64410-99901 64410-99905 | | | 68020 Emulation Pod (256K Memory) Documentation Assembly BTO-Documentation Assembly |
| 64410B | 64410-99901 64410-99905 | | | 20 Emulation Pod (512K Memory) Documentation Assembly BTO-Documentation Assembly |
| 64410C | 64410-99902 64410-99904 | | | 68020 Emulator Pod (256K Memory) Documentation Assembly Documentation Assembly |
| 64410D | 64410-99902 64410-99904 | | | 68020 Emulator Pod (512K Memory) Documentation Assembly Documentation Assembly |
| 64410E | 64410-99906 | | | 68020 Conversion Kit Documentation Assembly |
| 64410SX/004 | 64410-99901 64410-99905 | | | One-Time Update Documentation Assembly BTO-Documentation Assembly |
| 64411-99902 | 64404-90902 64740-90912 | E0888 E0688 | | Documentation Assembly 16/32 Bit Internal Analysis Reference Manual HP 64000 Support Services |
| 64416A | 64410-99901 64410-99905 | | | 68020 Emulator (256K Memory) Documentation Assembly BTO-Documentation Assembly |
| 64416B | 64410-99901 64410-99905 | | | 68020 Emulator (512K Memory) Documentation Assembly BTO-Documentation Assembly |
| 64420-99901 | 64404-90902 64420-90901 64420-90902 64740-90912 | E0888 E0588 E0688 | | Documentation Assembly 16/32 Bit Internal Analysis Reference Manual BTO-OPSV HP 64000 Support Services |
| 64420-99902 | 64404-90901 64801-90909 | E0188 E1186 | U0788 | Documentation Assembly 16/32-Bit Analysis Reference HP Support Services |
| 64420A | 64420-99901 64420-99902 | | | 80386 Emulator Documentation Assembly Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|----------------------------|----------------|--------|--|
| 64420B | 64420-99901 64420-99902 | | | 80386 Emulator Documentation Assembly Documentation Assembly |
| 64420SX/004 | 64420-99901 64420-99902 | | | One-Time Update Documentation Assembly Documentation Assembly |
| 64421A | 64420-99901 64420-99902 | | | 80386 Conversion Kit Documentation Assembly Documentation Assembly |
| 64501A | 64500-90911 64500-90912 | E0184 E0386 | U0787 | Positive PROM Programmer Positive PROM Programmer PROM Programmer Subsystem |
| 64501A/004 | 64550-90901 | E1187 | | Positive PROM Programmer PROM Programmer |
| 64501AX | 64500-90912 | E0386 | U0787 | One-Time Update PROM Programmer Subsystem |
| 64501AX/004 | 64550-90901 | E1187 | | One-Time Update PROM Programmer |
| 64502A | 64502-90903 | E0982 | | 2716 Intel PROM Programmer Module PROM Programmer Module (2716)) |
| 64504A | 64504-90901 | E0180 | | 4X-8X-08 HA PROM Programmer Module PROM Programmer Module (Harris) |
| 64505A | 64505-90901 | E0685 | | 4X-8X-9X SI PROM Programmer Module PROM Programmer Module (Signetics) |
| 64507A | 64507-90901 | E1279 | | 2708-04 ALL PROM Programmer Module PROM Programmer Module (2704/2708) |
| 64509A | 64509-90901 | E0382 | | 2732 Intel PROM Programmer PROM Programmer (2731) |
| 64510B | 64510-90903 | E0183 | | 8748H Intel PROM Programmer Module PROM Programmer Module (8748) |
| 64513A | 64513-90901 | E0782 | | 8755 Intel PROM Programmer Module PROM Programmer Module (8755A) |
| 64514A | 64514-90901 | E0981 | | 68764 MOT PROM Programmer Module PROM Programmer Module (68764/766) |
| 64515C | 64515-90903 | E1183 | | 27256 PROM Programmer Module PROM Programmer |
| 64516A | 64516-90901 | E0585 | | 27512 PROM Programmer Module PROM Programmer |
| 64517B | 64517-90902 | E1285 | | 68701 MOT PROM Programmer Module PROM Programmer |
| 64520A | 64520-90901 | E0283 | | 8751 PROM Programmer Module PROM Programmer (8751A) |
| 64552-99901 | 64552-90901 64801-90909 | E0887 E1186 | | Documentation Assembly 68HC11 Prom Programmer Operating Manual HP Support Services |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|----------------------------|----------------|--------|--|
| 64552A | 64552-99901 | | | 68HC11 PROM Programmer Documentation Assembly |
| 64553-99901 | 64801-90909 | E1186 | | Documentation Assembly HP Support Services |
| 64553A | 64553-99901 | | | 32 Pin PROM Programmer Documentation Assembly |
| 64554-99901 | 64801-90909 | E1186 | | Documentation Assembly HP Support Services |
| 64554A | 64554-99901 | | | 40 Pin Prom Prog Documentation Assembly |
| 64601B | 64610-90901 64610-90902 | E0185 E1084 | | State/Timing Control Board High Speed Analyzer High Speed Analyzer |
| 64601B/004 | 64610-90903 | E0587 | U1087 | 300 Timing Control High Speed State/Timing Analyzer |
| 64601BX | 64610-90901 | E0185 | | One-Time Update High Speed Analyzer |
| 64601BX/004 | 64610-90903 | E0587 | U1087 | One-Time Update High Speed State/Timing Analyzer |
| 64610S/040 | 64610-90903 64801-90909 | E0587 E1186 | U1087 | 300 Timing High Speed State/Timing Analyzer HP Support Services |
| 64620-99901 | 64620-90906 64801-90909 | E0487 E1186 | | Documentation Assembly Logic State/Software Analyzer HP Support Services |
| 64620S/004 | 64620-99901 | | | 10MHz State (300) Documentation Assembly |
| 64621A | 64620-90905 64621-90903 | E0386 E1286 | | State Control Logic State/Software Analyzer State/Software Control |
| 64621A/004 | 64620-99901 | | | State Control (300) Documentation Assembly |
| 64621AX | 64620-90905 | E0386 | | One-Time Update Logic State/Software Analyzer |
| 64621AX/004 | 64620-99901 | | | One-Time Update Documentation Assembly |
| 64622A | 64622-90902 | AUG83 | | 40 Channel Data Acquistion 40 Channel State Acquisition |
| 64623A | 64623-90902 | SEP83 | | 20 Channel Data Acquistion 20 Channel State Acquisition |
| 64635A | 64635-90901 | JUL82 | | State Probe 20 Channel Data Probe |
| 64636A | 64636-90901 | E1187 | | Clock Probe 8 Channel Clock Probe |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|---|--------|---|
| 64650A | 5957-7326 5957-7358 64650-90902 64650-90905 64650-90906 | E0983 E0684 E0885 JUL83 E0986 | | General Purpose Preprocessor Operating Notice Caution for Emulator Pods and Preprocessors General Purpose Preprocessor General Purpose Preprocessor General Purpose Preprocessor |
| 64651B | 64651-90906 | E1187 | | User Definable Interface Wire Wrap Interface |
| 64653-99901 | 64653-90905 64801-90909 | E0786 E1186 | | Documentation Assembly 8086/8088 Interface Module HP Support Services |
| 64653A | 5957-7326 5957-7358 64653-99901 | E0983 E0684 | | 8086/8088 Interface Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64653AX | 64653-99901 | | | One-Time Update Documentation Assembly |
| 64655-99901 | 64655-90904 64801-90909 | E0987 E1186 | | Documentation Assembly 8085 Interface Module HP Support Services |
| 64655A | 5957-7326 5957-7358 64655-99901 | E0983 E0684 | | 8085 Interface Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64655AX | 64655-99901 | | | One-Time Update Documentation Assembly |
| 64657-99901 | 64657-90903 64801-90909 | E0787 E1186 | | Documentation Assembly 80286 Interface Module HP Support Services |
| 64657-99902 | 64657-90904 64801-90909 | E0787 E1186 | | Documentation Assembly 80286 Interface Module HP Support Services |
| 64657A | 64657-99901 64657-99902 | | | 80286 Interface Documentation Assembly Documentation Assembly |
| 64657A/004 | 64657-99901 | | | 300 80286 Interface Documentation Assembly |
| 64657AX | 64657-99901 64657-99902 | | | One-Time Update Documentation Assembly Documentation Assembly |
| 64657AX/004 | 64657-90903 | E0787 | | One-Time Update 80286 Interface Module |
| 64657B | 5957-7326 5957-7358 64657-99902 | E0983 E0684 | | 80286 Interface Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64658-99901 | 64658-90903 64801-90909 | E0687 E1186 | | Documentation Assembly 80186/80188 Interface Module HP Support Services |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|-------------------------|--------|--|
| 64658A | 5957-7326 5957-7358 64658-99901 | E0983 E0684 | | 8018X Interface Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64658AX | 64658-99901 | | | One-Time Update Documentation Assembly |
| 64659-99901 | 5957-7326 64659-90901 64801-90909 | E0983 E0887 E1186 | | Documentation Assembly Operating Notice 80386 Interface Module HP Support Services |
| 64659A | 5957-7358 64659-99901 | E0684 | | 80386 Preprocessor Interface Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64659AX | 64659-99901 | | | One-Time Update Documentation Assembly |
| 64671-99901 | 64671-90903 64801-90909 | E0887 E1186 | | Documentation Assembly 6809/6809E Preprocessor Interface HP Support Services |
| 64671A | 5957-7326 5957-7358 64671-99901 | E0983 E0684 | | 6809 Interface Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64671AX | 64671-99901 | | | One-Time Update Documentation Assembly |
| 64672-99901 | 64672-90905 64801-90909 | E0887 E1186 | | Documentation Assembly 6800/6802 Preprocessor Interface HP Support Services |
| 64672B | 5957-7326 5957-7358 64672-99901 | E0983 E0684 | | 6800/6802 Interface Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64672BX | 64672-99901 | | | One-Time Update Documentation Assembly |
| 64673-99901 | 64673-90903 64801-90909 | E0987 E1186 | | Documentation Assembly 68008 Preprocessor Interface HP Support Services |
| 64673A | 5957-7326 5957-7358 64673-99901 | E0983 E0684 | | 68008 Interface Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64673AX | 64673-99901 | | | One-Time Update Documentation Assembly |
| 64674-99901 | 64674-90903 64801-90909 | E0987 E1186 | | Documentation Assembly 68000/68010 Interface Card HP Support Services |
| 64674A | 5957-7326 5957-7358 64674-99901 | E0983 E0684 | | 68000 Interface Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---------------------------------------|-------------------------|--------|--|
| 64674A/004 | 64674-99901 | | | 300 68000/68010 Interface Documentation Assembly |
| 64674A/S01 | 64674-99901 | | | Operation Scheduling Documentation Assembly |
| 64674AX | 64674-90903 | E0987 | | One-Time Update 68000/68010 Interface Card |
| 64674AX/004 | 64674-99901 | | | One-Time Update Documentation Assembly |
| 64675-99901 | 64675-90902 64801-90909 | E0887 E1186 | | Documentation Assembly 68020 Interface Operating Manual HP Support Services |
| 64675A | 5957-7326 5957-7358 64675-99901 | E0983 E0684 | | 68020 Interface Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64675A/004 | 64675-99901 | | | 68020 Interface (300) Documentation Assembly |
| 64675AX/004 | 64675-99901 | | | One-Time Update Documentation Assembly |
| 64675B | 5957-7326 5957-7358 64675-90902 | E0983 E0684 E0887 | | 68020 Interface Operating Notice Caution for Emulator Pods and Preprocessors 68020 Interface Operating Manual |
| 64675B/004 | 64675-99901 | | | 68851 Interface (300) Documentation Assembly |
| 64680-99901 | 64680-90904 64801-90909 | E0987 E1186 | | Documentation Assembly Z8001/Z8002 Preprocessor Interface HP Support Services |
| 64680A | 5957-7326 5957-7358 64680-99901 | E0983 E0684 | | Z8001 Interface Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64680AX | 64680-99901 | | | One-Time Update Documentation Assembly |
| 64681-99901 | 64681-90904 64801-90909 | E0987 E1186 | | Documentation Assembly Z8002 Preprocessor Interface HP Support Services |
| 64681A | 5957-7326 5957-7358 64681-99901 | E0983 E0684 | | Z8002 Interface Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64681AX | 64681-99901 | | | One-Time Update Documentation Assembly |
| 64683-99901 | 64683-90903 64801-90909 | E1187 E1186 | | Documentation Assembly Z80 Preprocessor Interface HP Support Services |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|--|
| 64683A | 5957-7326 5957-7358 64683-90901 64683-99901 | E0983 E0684 E0785 | | Z80 Interface Operating Notice Caution for Emulator Pods and Preprocessors Z80 Preprocessor Interface Documentation Assembly |
| 64683AR | 64683-90901 | E0785 | | Right to Copy Z80 Preprocessor Interface |
| 64683AX | 64683-90901 64683-99901 | E0785 | | One Time Update Z80 Preprocessor Interface Documentation Assembly |
| 64683S/001 | 64683-90901 | E0785 | | 68020 Assembler (500) Z80 Preprocessor Interface |
| 64683S/003 | 64683-90901 | E0785 | | VAX 68020 Assembler Z80 Preprocessor Interface |
| 64683SR/001 | 64683-90901 | E0785 | | Right to Copy Z80 Preprocessor Interface |
| 64683SR/003 | 64683-90901 | E0785 | | Right to Copy Z80 Preprocessor Interface |
| 64690-99901 | 64690-90903 64801-90909 | E0786 E1186 | | Documentation Assembly NSC800 Interface Module HP Support Services |
| 64690A | 5957-7326 5957-7358 64690-99901 | E0983 E0684 | | NSC800 Interface Operating Notice Caution for Emulator Pods and Preprocessors Documentation Assembly |
| 64690AX | 64690-99901 | | | One-Time Update Documentation Assembly |
| 64695-99901 | 64695-90902 64801-90909 | E0887 E1186 | | Documentation Assembly HP-IB RS232 Interface HP Support Services |
| 64695A | 64695-90902 64695-99901 | E0887 | | Bus Preprocessor HP-IB RS232 Interface Documentation Assembly |
| 64695A/004 | 64695-99901 | | | HPIB/RS INT (300) Documentation Assembly |
| 64695AX | 64695-90902 | E0887 | | One-Time Update HP-IB RS232 Interface |
| 64695AX/004 | 64695-99901 | | | One-Time Update Documentation Assembly |
| 64702-99901 | 64702-90901 64801-90909 | E0288 E1186 | | Documentation Assembly HP Teamwork / Access HP Support Services |
| 64702S/004 | 64702-99901 | | | HP Teamwork/Access Documentation Assembly |
| 64702SR/004 | 64702-99901 | | | Right to Copy Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|---|---|---|
| 64702SX/004 | 64702-99901 | | | One-Time Update Documentation Assembly |
| 64710-99901 | 64710-90903 64711-90903 64711-99901 64801-90909 | E0288 E0288 E1186 | U0588 | Documentation Assembly HP Teamwork Teamwork Users Manual Documentation Assembly HP Support Services |
| 64710S/004 | 64710-99901 | | | Structured Analysis System Documentation Assembly |
| 64710SR/004 | 64710-99901 | | | Right to Copy Documentation Assembly |
| 64710SX/004 | 64710-99901 | | | One-Time Update Documentation Assembly |
| 64711-99901 | 64702-90901 64710-90903 64711-90903 64715-90901 64716-90901 64720-90901 64801-90909 | E0288 E0288 E0288 E0287 E1087 E0288 E1186 | U0588 U0288 U0288 U0288 U0288 U0288 U0288 | Documentation Assembly HP Teamwork / Access HP Teamwork Teamwork Users Manual HP Teamwork / RT HP Teamwork / IM HP Teamwork / SD HP Support Services |
| 64711-99902 | 64740-90912 | E0688 | | Documentation Assembly HP 64000 Support Services |
| 64712-99901 | 64720-90901 64801-90909 | E0288 E1186 | | Documentation Assembly HP Teamwork / SD HP Support Services |
| 64712S/004 | 64712-99901 | | | Structured Analysis (300) Documentation Assembly |
| 64712SR/004 | 64712-99901 | | | Right to Copy Documentation Assembly |
| 64713S/004 | 64711-99901 | | | SE Consulting Kit (300) Documentation Assembly |
| 64714-99901 | 64716-90901 64801-90909 | E1087 E1186 | U0288 | Documentation Assembly HP Teamwork / IM HP Support Services |
| 64714S/004 | 64714-99901 | | | HP Teamwork/MI Documentation Assembly |
| 64714SR/004 | 64714-99901 | | | Right to Copy Documentation Assembly |
| 64715-99901 | 64715-90901 64801-90909 | E0287 E1186 | U0288 | Documentation Assembly HP Teamwork / RT HP Support Services |
| 64715S/004 | 64715-99901 | | | Add Realtime (300) Documentation Assembly |
| 64715SR/004 | 64715-99901 | | | Right to Copy Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|-------------------------|--------|--|
| 64715SX/004 | 64715-99901 | | | One-Time Update Documentation Assembly |
| 64716-99901 | 64711-90903 64716-90901 64801-90909 | E0288 E1087 E1186 | U0288 | Documentation Assembly Teamwork Users Manual HP Teamwork / IM HP Support Services |
| 64716S/004 | 64716-99901 | | | HP Teamwork/IM Documentation Assembly |
| 64716SR/004 | 64716-99901 | | | Right to Copy Documentation Assembly |
| 64716SX/004 | 64716-99901 | | | One-Time Update Documentation Assembly |
| 64717-99901 | 64710-90903 64801-90909 | E0288 E1186 | U0588 | Documentation Assembly HP Teamwork HP Support Services |
| 64717S/004 | 64717-99901 | | | Structured Analysis (300) Documentation Assembly |
| 64717SR/004 | 64717-99901 | | | Right to Copy Documentation Assembly |
| 64718S/004 | 64711-99901 | | | Structured Analysis Demo (300) Documentation Assembly |
| 64720-99901 | 64711-90903 64720-90901 64801-90909 | E0288 E0288 E1186 | | Documentation Assembly Teamwork Users Manual HP Teamwork / SD HP Support Services |
| 64720S/004 | 64720-99901 | | | Structure Design (300) Documentation Assembly |
| 64720SR/004 | 64720-99901 | | | Right to Copy Documentation Assembly |
| 64720SX/004 | 64720-99901 | | | One-Time Update Documentation Assembly |
| 64722S/004 | 64711-99901 | | | HP Teamwork Project Environment Documentation Assembly |
| 64723-99901 | 64740-90912 | E0688 | | Documentation Assembly HP 64000 Support Services |
| 64723S/004 | 64723-99901 | | | Teamwork ADA (300) Documentation Assembly |
| 64723SR/004 | 64723-99901 | | | Right to Copy Documentation Assembly |
| 64723SX/004 | 64723-99901 | | | One-Time Update Documentation Assembly |
| 64724S/004 | 64723-99901 | | | Add Teamwork / ADA Documentation Assembly |
| 64724SR/004 | | | | Right to Copy |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|---|--------|--|
| | 64723-99901 | | | Documentation Assembly |
| 64740-99901 | 5959-2187 5959-6245 64306-90901 64740-90901 64740-90902 64740-90903 64740-90904 64740-90908 64740-90909 | E0188 E0788 E0388 E0188 E0188 E1187 E1187 E1187 E1187 | | HP 64000 Emulation Terminal Interface HP 64700 Emulators Documentation Map HP 64700 Firmware/Software Compatibility Note Terminal Interface: CMB User's Guide Terminal Interface: User's Reference Terminal Interface: System Overview Terminal Interface: Hardware Installation & Configuration Terminal Interface: Support Services HP 64700 Master Glossary of Terms Terminal Interface: Analyzer User's Guide |
| 64740-99902 | 5959-2187 5959-6238 5959-6245 64740-90904 64740-90905 64740-90908 64740-90910 | E0188 E0988 E0788 E1187 E0588 E1187 E0588 | | 64700 Overview Instrument Support HP 64700 Emulators Documentation Map Instrument Notice HP 64700 Firmware/Software Compatibility Note Terminal Interface: Support Services Softkey Interface: Emulation Reference HP 64700 Master Glossary of Terms Softkey Interface: Analyzer User's Guide |
| 64740-99903 | 5959-2187 5959-6245 5959-6283 64740-90904 64740-90906 64740-90907 64740-90908 64740-90911 | E0188 E0788 E0988 E1187 E1187 E1187 E1187 E0988 | | 64700 Emulator HP 64700 Emulators Documentation Map HP 64700 Firmware/Software Compatibility Note Operating Notice Terminal Interface: Support Services PC Interface: User's Reference PC Interface: MS-DOS Application Installation HP 64700 Master Glossary of Terms PC Interface: Analyzer User's Guide |
| 64742-99901 | 64740-90912 64740-99901 64742-90901 | E0688 E1187 E1088 | | 68000/10 Emulation Terminal Interface HP 64000 Support Services HP 64000 Emulation Terminal Interface MC68000 Emulator User's Guide |
| 64742-99902 | 64740-99902 64742-90902 | E1187 E0388 | | Documentation Assembly 64700 Overview Instrument Support Softkey Interface: 68000/68010 User's Guide |
| 64742-99903 | 64740-99903 64742-90903 | E1187 E1088 | | Documentation Assembly 64700 Emulator PC Interface: MC68000 Emulator User's Guide |
| 64742A | 64742-99901 | E0388 | | 68000 Emulator 68000/10 Emulation Terminal Interface |
| 64742A/004 | 64742-99902 | | | Host Interface on Series 300 Documentation Assembly |
| 64742A/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64742AL | 64742-99901 64742-99902 | E0388 | | 68000 Emulator + External Analyzer 68000/10 Emulation Terminal Interface Documentation Assembly |
| 64742AL/004 | 64742-99902 | | | Host Interface on Series 300 Documentation Assembly |
| 64742AL/006 | 64742-99903 | | | Host Interface on PC & Assembler/Linker Documentation Assembly |
| 64742AX/004 | | | | 68K Host 300 |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|----------------------------|---------|--------|---|
| | 64742-99902 | | | Documentation Assembly |
| 64742AX/006 | 64742-99903 | | | 68K Host PC Documentation Assembly |
| 64742B | 64742-99901 64742-99903 | E0388 | | 68000 Emulator 68000/10 Emulation Terminal Interface Documentation Assembly |
| 64742B/004 | 64742-99902 | | | Host Interface on Series 300 Documentation Assembly |
| 64742B/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64742BL | 64742-99901 | E0388 | | 68000 Emulator 68000/10 Emulation Terminal Interface |
| 64742BL/004 | 64742-99902 | | | Host Interface on Series 300 Documentation Assembly |
| 64742BL/006 | 64742-99903 | | | Host Interface on PC & Assembler/Linker Documentation Assembly |
| 64742C | 64742-99901 | E0388 | | 68000 (12.5mHz) Dip Cable (512K) 68000/10 Emulation Terminal Interface |
| 64742C/004 | 64742-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64742C/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64742CL | 64742-99901 | E0388 | | 68000 (12.5) Dip Cable (512K) 68000/10 Emulation Terminal Interface |
| 64742CL/004 | 64742-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64742CL/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64742D | 64742-99901 | E0388 | | 68000 Emulator 68000/10 Emulation Terminal Interface |
| 64742D/004 | 64742-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64742D/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64742DL | 64742-99901 | E0388 | | 68000 Emulator+Bits 68000/10 Emulation Terminal Interface |
| 64742DL/004 | 64742-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64742DL/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64742S/004 | 64742-99902 | | | 68K Host Interface on Series 300 Documentation Assembly |
| 64742S/006 | 64742-99903 | | | 68K Host Interface on PC Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|----------------------------|---------|--------|--|
| 64742SX/004 | 64742-99902 | | | One Time Update for 64742S/004 Documentation Assembly |
| 64742SX/006 | 64742-99903 | | | One Time Update for 64742S/006 Documentation Assembly |
| 64743A | 64742-99901 64742-99903 | E0388 | | 68000 Emulator 68000/10 Emulation Terminal Interface Documentation Assembly |
| 64743A/004 | 64742-99902 | | | Host Interface on Series 300 Documentation Assembly |
| 64743A/006 | 64742-99903 | | | Host Interface on Series 300 Documentation Assembly |
| 64743AL | 64742-99901 | E0388 | | Host Discount Option 68000/10 Emulation Terminal Interface |
| 64743AL/004 | 64742-99902 | | | Host Interface on Series 300 Documentation Assembly |
| 64743AL/006 | 64742-99903 | | | Host Interface on PC & Assembler/Linker Documentation Assembly |
| 64743AX | 64742-99901 | E0388 | | One Time Update for 64743A 68000/10 Emulation Terminal Interface |
| 64743AX/004 | 64742-99902 | | | Series 300 Hosted Documentation Assembly |
| 64743AX/006 | 64742-99903 | | | PC Hosted Documentation Assembly |
| 64743B | 64742-99901 | E0388 | | 68000 Emulator 68000/10 Emulation Terminal Interface |
| 64743B/004 | 64742-99902 | | | Host Interface on Series 300 Documentation Assembly |
| 64743B/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64743BL | 64742-99901 | E0388 | | 68000 Emulator 68000/10 Emulation Terminal Interface |
| 64743BL/004 | 64742-99902 | | | Host Interface on Series 300 Documentation Assembly |
| 64743BL/006 | 64742-99903 | | | Host Interface on PC & Assembler/Linker Documentation Assembly |
| 64743C | 64742-99901 | E0388 | | 68000 (16MHz) Dip Cable (512K) 68000/10 Emulation Terminal Interface |
| 64743CL | 64742-99901 | E0388 | | 68000 (16MHz) Dip Cable+Bits 68000/10 Emulation Terminal Interface |
| 64745A | 64742-99901 | E0388 | | 68010 Emulator 68000/10 Emulation Terminal Interface |
| 64745A/004 | 64742-99902 | | | Host Interface on Series 300 Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|-----------------|---------|--------|--|
| 64745A/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64745AL | 64742-99901 | E0388 | | 68010 Emulator + Bits 68000/10 Emulation Terminal Interface |
| 64745AL/004 | 64742-99902 | | | Host Interface on Series 300 Documentation Assembly |
| 64745AL/006 | 64742-99903 | | | Host Interface on PC & Assembler/Linker Documentation Assembly |
| 64745AX/004 | 64742-99902 | | | Series 300 Hosted Documentation Assembly |
| 64745AX/006 | 64742-99903 | | | PC Hosted Documentation Assembly |
| 64745B | 64742-99901 | E0388 | | 68010 Emulator 68000/10 Emulation Terminal Interface |
| 64745B/004 | 64742-99902 | | | Host Interface on Series 300 Documentation Assembly |
| 64745B/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64745BL | 64742-99901 | E0388 | | 68010 Emulator + Bits 68000/10 Emulation Terminal Interface |
| 64745BL/004 | 64742-99902 | | | Host Interface on Series 300 Documentation Assembly |
| 64745BL/006 | 64742-99903 | | | Host Interface on PC & Assembler/Linker Documentation Assembly |
| 64745C | 64742-99901 | E0388 | | 68010 Dip Cable (512K) 68000/10 Emulation Terminal Interface |
| 64745C/004 | 64742-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64745C/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64745CL | 64742-99901 | E0388 | | 68010 Dip Cable+Bits (512K) 68000/10 Emulation Terminal Interface |
| 64745CL/004 | 64742-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64745CL/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64745D | 64742-99901 | E0388 | | 68010 PGA Cable (512K Memory) 68000/10 Emulation Terminal Interface |
| 64745D/004 | 64742-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64745D/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64745DL | | | | 68010 PGA Cable+Bits (512K Memory) |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|----------------------------|----------------|--------|---|
| | 64742-99901 | E0388 | | 68000/10 Emulation Terminal Interface |
| 64745DL/004 | 64742-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64745DL/006 | 64742-99903 | | | Host Interface on PC Documentation Assembly |
| 64745S/004 | 64742-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64745S/006 | 64742-99903 | | | 68010 Host Interface on PC Documentation Assembly |
| 64745SX/006 | 64742-99903 | | | One-Time Update Documentation Assembly |
| 64753-99901 | 64740-99901 64753-90901 | E1187 E1187 | | Z80 Emulator Documentation Assembly HP 64000 Emulation Terminal Interface Terminal Interface: Z80 Emulator User's Guide |
| 64753-99902 | 64740-99902 64753-90902 | E1187 E1187 | | Documentation Assembly 64700 Overview Instrument Support BTO-MNOP |
| 64753-99903 | 64740-99903 64753-90903 | E1187 E0688 | | Documentation Assembly 64700 Emulator PC Interface: Z80 Emulator User's Guide |
| 64753A | 64753-99901 | | | Z80 Emulator Z80 Emulator Documentation Assembly |
| 64753A/004 | 64753-99902 | | | Z80 Emulator/PC Interface Option Documentation Assembly |
| 64753A/006 | 64753-99903 | | | Z80 Emulator/Softkey Interface Documentation Assembly |
| 64753AL | 64753-99901 | | | Z80 Emulator + Bits Z80 Emulator Documentation Assembly |
| 64753AL/004 | 64753-99902 | | | Z80 Host Interface on Series (300) Documentation Assembly |
| 64753AL/006 | 64753-99903 | | | Z80 Host Interface on PC & ASM/LKR Documentation Assembly |
| 64753AX/004 | 64753-99902 | | | One-Time Update Documentation Assembly |
| 64753AX/006 | 64753-99903 | | | One-Time Update Documentation Assembly |
| 64753S/004 | 64753-99902 | | | Z80 Host Interface on PC Documentation Assembly |
| 64753S/006 | 64753-99903 | | | Z80 Host Interface on PC Documentation Assembly |
| 64753SX/004 | 64753-99902 | | | One-Time Update Documentation Assembly |
| 64753SX/006 | 64753-99903 | | | One-Time Update Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|----------------------------|----------------|--------|---|
| 64762-99901 | 64740-99901 64762-90901 | E1187 E0788 | | Documentation Assembly HP 64000 Emulation Terminal Interface 8086/8088 Emulators Terminal Interface |
| 64762-99902 | 64740-99902 64762-90902 | E1187 E0188 | | Documentation Assembly 64700 Overview Instrument Support BTO-MNOP |
| 64762-99903 | 64740-99903 64762-90903 | E1187 E0788 | | Documentation Assembly 64700 Emulator PC Interface: 8086/8088 Emulators User's Guide |
| 64762A | 64762-99901 | | | 8086 Emulator Documentation Assembly |
| 64762A/004 | 64762-90902 64762-99902 | E0188 | | Host Interface on Series (300) BTO-MNOP Documentation Assembly |
| 64762A/006 | 64762-99903 | | | Host Interface on PC Documentation Assembly |
| 64762AL | 64762-99901 | | | 8086 Emulator + Bits Documentation Assembly |
| 64762AL/004 | 64762-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64762AL/006 | 64762-99903 | | | Host Interface on PC Documentation Assembly |
| 64762AX | 64762-99901 | | | One-Time Update Documentation Assembly |
| 64762AX/004 | 64762-99902 | | | One-Time Update Documentation Assembly |
| 64762AX/006 | 64762-99903 | | | Host Interface on PC Documentation Assembly |
| 64762S/004 | 64762-99902 | | | 8086 Host Interface (S300) Documentation Assembly |
| 64762S/006 | 64762-99903 | | | 8086 Host Interface on PC Documentation Assembly |
| 64763A | 64762-99901 | | | 8088 Emulator Documentation Assembly |
| 64763A/004 | 64762-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64763A/006 | 64762-99903 | | | Host Interface on PC Documentation Assembly |
| 64763AL | 64762-99901 | | | 8088 Emulator + Bits Documentation Assembly |
| 64763AL/004 | 64762-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64763AL/006 | 64762-99903 64763AL/006 | | | Host Interface on PC Documentation Assembly Host Interface on PC |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|-------------------------|--------|---|
| 64763AX | 64762-99901 | | | One-Time Update Documentation Assembly |
| 64763AX/004 | 64762-99902 | | | One-Time Update Documentation Assembly |
| 64763AX/006 | 64762-99903 | | | One-Time Update Documentation Assembly |
| 64763S/004 | 64762-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64763S/006 | 64762-99903 | | | 8088 Host Interface on PC Documentation Assembly |
| 64764-99901 | 5959-6287 64740-99901 64764-90901 | E1088 E1187 E0988 | | 80186/188 Emulator Document Assembly Operating Notice for HP 64764/5 Emulators HP 64000 Emulation Terminal Interface Terminal Interface: 80186/188 Emulator User's Guide |
| 64764-99902 | 64740-99902 64764-90902 | E1187 E1187 | | Documentation Assembly 64700 Overview Instrument Support BTO-MNOP |
| 64764-99903 | 5959-6287 64740-99903 64764-90903 | E1088 E1187 E0988 | | Documentation Assembly Operating Notice for HP 64764/5 Emulators 64700 Emulator Emulator PC Interface: 80186/188 Emulator User's Guide |
| 64764A | 64764-99901 | | | 80186 Emulator 80186/188 Emulator Document Assembly |
| 64764A/004 | 64764-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64764A/006 | 64764-99903 | | | Host Interface on PC Documentation Assembly |
| 64764AL | 64764-99901 | | | 80816 Emulator + Bits 80186/188 Emulator Document Assembly |
| 64764AL/004 | 64764-99902 | | | Host Interface (300) Documentation Assembly |
| 64764AL/006 | 64764-99903 | | | Host Interface on PC&ASM/LKR Documentation Assembly |
| 64764AX/004 | 64764-99902 | | | One-Time Update Documentation Assembly |
| 64764AX/006 | 64764-99903 | | | One-Time Update Documentation Assembly |
| 64764C | 64764-99901 | | | 80186 Emulator 80186/188 Emulator Document Assembly |
| 64764C/004 | 64764-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64764C/006 | 64764-99903 | | | Host Interface on PC Documentation Assembly |
| 64764CL | | | | 80186 Emulator+Bits |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|----------------------------|---------|--------|--|
| | 64764-99901 | | | 80186/188 Emulator Document Assembly |
| 64764CL/004 | 64764-99902 | | | Host Interface on PC Documentation Assembly |
| 64764CL/006 | 64764-99903 | | | Host Interface on PC Documentation Assembly |
| 64764D | 64764-99901 | | | 80186 Emulator 80186/188 Emulator Document Assembly |
| 64764D/004 | 64764-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64764D/006 | 64764-99903 | | | Host Interface on PC Documentation Assembly |
| 64764DL | 64764-99901 | | | 80186 Emulator+Bits 80186/188 Emulator Document Assembly |
| 64764DL/004 | 64764-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64764DL/006 | 64764-99903 | | | Host Interface on PC Documentation Assembly |
| 64764DX/006 | 64764-99903 | | | One-Time Update Documentation Assembly |
| 64764S/004 | 64764-99902 | | | 80186 Host Interface on Series (300) Documentation Assembly |
| 64764S/006 | 64764-99903 | | | Host Interface on PC Documentation Assembly |
| 64764SD/006 | 64764-99903 | | | 80188 Host Interface on PC Documentation Assembly |
| 64764SX/004 | 64764-99902 | | | One-Time Update Documentation Assembly |
| 64764SX/006 | 64764-99903 | | | One-Time Update Documentation Assembly |
| 64765A | 64764-99901 | | | 80188 Emulator 80186/188 Emulator Document Assembly |
| 64765A/004 | 64764-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64765A/006 | 64764-99903 | | | Host Interface on PC Documentation Assembly |
| 64765AL | 64764-99901 | | | 80188 Emulator + Bits 80186/188 Emulator Document Assembly |
| 64765AL/004 | 64764-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64765AL/006 | 64764-99903 64765AL/006 | | | Host Interface on PC&ASM/LKR Documentation Assembly Host Interface on PC&ASM/LKR |
| 64765AX/004 | 64764-99902 | | | One-Time Update Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|----------------------------|----------------|--------|---|
| 64765AX/006 | 64764-99903 | | | One-Time Update Documentation Assembly |
| 64765D | 64764-99901 | | | 80188 Emulator 80186/188 Emulator Document Assembly |
| 64765D/004 | 64764-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64765D/006 | 64764-99903 | | | Host Interface on PC Documentation Assembly |
| 64765DL | 64764-99901 | | | 80188 Emulator+Bits 80186/188 Emulator Document Assembly |
| 64765DL/004 | 64764-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64765DL/006 | 64764-99903 | | | Host Interface on PC Documentation Assembly |
| 64765DX/006 | 64764-99903 | | | One-Time Update Documentation Assembly |
| 64765S/004 | 64764-99902 | | | 80188 Host Interface on Series (300) Documentation Assembly |
| 64765S/006 | 64764-99903 | | | 80188 Host Interface on PC Documentation Assembly |
| 64765SD/006 | 64764-99903 | | | 80188 Host Interface on PC Documentation Assembly |
| 64765SX/004 | 64764-99902 | | | One-Time Update Documentation Assembly |
| 64765SX/006 | 64764-99903 | | | One-Time Update Documentation Assembly |
| 64771-99901 | 64740-99901 64771-90901 | E1187 E0988 | | Documentation Assembly HP 64000 Emulation Terminal Interface Emulator Terminal Interface: 80C196 Emul. User's Guide |
| 64771-99902 | 64740-99902 64771-90902 | E1187 E0188 | | Documentation Assembly 64700 Overview Instrument Support BTO-MNOP |
| 64771-99903 | 64740-99903 64771-90903 | E1187 | | Documentation Assembly 64700 Emulator E0788 BTO-MNOP |
| 64771A | 64771-99901 | | | 80C196 Emulator Documentation Assembly |
| 64771A/004 | 64771-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64771A/006 | 64771-99903 | | | Host Interface on PC Documentation Assembly |
| 64771AL | 64771-99901 | | | 80C196 Emulator+Bits Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|-------------------------|--------|--|
| 64771AL/004 | 64771-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64771AL/006 | 64771-99903 | | | Host Interface on PC Documentation Assembly |
| 64771AX/004 | 64771-99902 | | | One-Time Update Documentation Assembly |
| 64771AX/006 | 64771-99903 | | | One-Time Update Documentation Assembly |
| 64771S/006 | 64771-99903 | | | Host Interface on PC Documentation Assembly |
| 64786-99901 | 64740-99901 64786-90901 | E1187 E0388 | | Documentation Assembly HP 64000 Emulation Terminal Interface Emulators Terminal Interface: TMS320/C25 User's Guide |
| 64786-99902 | 64740-99902 64786-90902 | E1187 E0388 | | Documentation Assembly 64700 Overview Instrument Support BTO-MNOP |
| 64786-99903 | 5959-6285 64740-99903 64786-90903 | E0988 E1187 E0388 | | Documentation Assembly TI COFF Operating Notice 64700 Emulator BTO-MNOP |
| 64786A | 64786-99901 | | | TMS 32020 Emulator Documentation Assembly |
| 64786A/004 | 64786-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64786A/006 | 64786-99903 | | | Host Interface on PC Documentation Assembly |
| 64786AL | 64786-99901 | | | TMS 32020 Emulator+Bits Documentation Assembly |
| 64786AL/004 | 64786-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64786AL/006 | 64786-99903 | | | Host Interface on PC Documentation Assembly |
| 64786AX/004 | 64786-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64786AX/006 | 64786-99903 | | | One-Time Update Documentation Assembly |
| 64786S/006 | 64786-99903 | | | 32020 Host Interface on PC Documentation Assembly |
| 64786SX/006 | 64786-99903 | | | One-Time Update Documentation Assembly |
| 64787 | | | | |
| 64787A | 64786-99901 | | | TMS 320C25 Emulator Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|-------------------------|--------|--|
| 64787A/004 | 64786-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64787A/006 | 64786-99903 | | | Host Interface on PC Documentation Assembly |
| 64787AL | 64786-99901 | | | TMS 320C25 Emulator+Bits Documentation Assembly |
| 64787AL/004 | 64786-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64787AL/006 | 64786-99903 | | | Host Interface on PC Documentation Assembly |
| 64787AX/004 | 64786-99902 | | | Host Interface on Series (300) Documentation Assembly |
| 64787AX/006 | 64786-99903 | | | One-Time Update Documentation Assembly |
| 64787S/006 | 64786-99903 | | | 320C25 Host Interface on PC Documentation Assembly |
| 64787SX/006 | 64786-99903 | | | One-Time Update Documentation Assembly |
| 64790-99901 | 64790-90901 64801-90909 64880-90901 | E0587 E1186 E0488 | U0987 | Documentation Assembly Softkey Editor HP Support Services 68000/10/20 AssyLink/Libr Ref |
| 64790-99902 | 64790-90901 64801-90909 | E0587 E1186 | U0987 | Documentation Assembly Softkey Editor HP Support Services |
| 64790M/001 | 64790-99901 | | | Media and Manual (500) Documentation Assembly |
| 64790M/004 | 64790-99902 | | | Media and Manual (300) Documentation Assembly |
| 64790S/001 | 64790-99901 | | | Softkey Editor (500) Documentation Assembly |
| 64790S/004 | 64790-99902 | | | Softkey Editor (300) Documentation Assembly |
| 64790SR/001 | 64790-99901 | | | Right to Copy Documentation Assembly |
| 64790SR/004 | 64790-99902 | | | Right to Copy Documentation Assembly |
| 64790SX/001 | 64790-99901 | | | One-Time Update Documentation Assembly |
| 64790SX/004 | 64790-99902 | | | One-Time Update Documentation Assembly |
| 64800-99901 | 5958-6068 64800-90907 | R2610 E0186 | | Documentation Assembly Software Notice for 64800-90907 C Compiler Reference |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|--|----------------|---|
| 64800-99902 | 5958-6069 64800-90908 | R2606 E0682 | | Documentation Assembly Software Notice for 64800-90908 Pascal Compiler Reference |
| 64800-99903 | 5958-6070 64800-90909 | R2606 E0184 | U1085 | Documentation Assembly Software Notice for 64800-90909 Pascal Compiler Reference |
| 64801-99901 | 64801-90901 64801-90902 64801-90903 64801-90904 64801-90906 64801-90908 64801-90909 64880-90903 | E0287 E0387 E0387 E0187 E1086 E1186 E1186 E0687 | U0788 | Documentation Assembly System Overview Installation and Configuration User's Guide Simulated I/O Option Test Measurement System HP Support Services Development System File Formats |
| 64801M/004 | 64801-99901 | | | Media and Manual (300) Documentation Assembly |
| 64801S/004 | 64801-99901 | | | HPK-UX Option (300) Documentation Assembly |
| 64801SR/004 | 64801-99901 | | | Right to Copy Documentation Assembly |
| 64801SX/004 | 64801-99901 | | | One-Time Update Documentation Assembly |
| 64808M/001 | 64801-90902 64808-90901 | E0387 E1087 | U0788 U1287 | Media and Manuals (500) Installation and Configuration User Interface Software |
| 64808M/004 | 64808-90901 | E1087 | U1287 | Media and Manuals (300) User Interface Software |
| 64808S/001 | 64801-90902 64808-90901 | E0387 E1087 | U0788 U1287 | PMON Interface (500) Installation and Configuration User Interface Software |
| 64808S/004 | 64808-90901 | E1087 | U1287 | PMON Interface (500) User Interface Software |
| 64808SR/001 | 64801-90902 64808-90901 | E0387 E1087 | U0788 U1287 | Right to Copy Installation and Configuration User Interface Software |
| 64808SR/004 | 64808-90901 | E1087 | U1287 | Right to Copy User Interface Software |
| 64808SX/001 | 64801-90902 64808-90901 | E0387 E1087 | U0788 U1287 | One-Time Update Installation and Configuration User Interface Software |
| 64808SX/004 | 64808-90901 | E1087 | U1287 | One-Time Update User Interface Software |
| 64810AR | 5958-6063 64800-99902 64810-90905 | R2604 OCT83 | | Right to Copy Operating Notice Documentation Assembly 8085 Pascal Compiler Supplement |
| 64810AX | | | | One-Time Update |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|---|
| | 5958-6063 64800-99902 | R2604 | | Operating Notice Documentation Assembly |
| 64811-99901 | 5958-6072 64811-90902 | R2606 E1185 | | Documentation Assembly Software Notice for 64811-90902 6800 Pascal Compiler Supplement |
| 64811-99902 | 5958-6071 64811-90903 | R2604 SEP84 | | Documentation Assembly Software Notice for 64811-90903 (UX) 6800/01/02/03 Pascal Cross Compiler |
| 64811-99903 | 5958-6073 64811-90904 | R2606 SEP84 | | Documentation Assembly Software Notice for 64811-90904 (VMS) 6800/01/02/03 Pascal Compiler (VMS) |
| 64811AF | 5958-6063 64800-99903 64811-99901 | R2604 | | 6800 Pascal Compiler Operating Notice Documentation Assembly Documentation Assembly |
| 64811AR | 5958-6063 64800-99903 64811-99901 | R2604 | | Right to Copy Operating Notice Documentation Assembly Documentation Assembly |
| 64811AX | 5958-6063 64800-99903 64811-99901 | R2604 | | One-Time Update Operating Notice Documentation Assembly Documentation Assembly |
| 64811M/001 | 5958-6051 5958-8877 5958-8882 64811-99902 | R2510 R2608 R2610 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64811M/003 | 5958-6051 5958-8882 5958-8883 64811-99903 | R2510 R2610 R2610 | | VAX Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64811M/004 | 5958-8860 5958-8877 5958-8882 64811-99902 | R2605 R2608 R2610 | | 300 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64811S/001 | 64811-99902 | | | 500 6800 Pascal Compiler Documentation Assembly |
| 64811S/003 | 64811-99903 | | | VAX 6800 Pascal Compiler Documentation Assembly |
| 64811S/004 | 64811-99902 | | | 300 Pascal Compiler Documentation Assembly |
| 64811SR/001 | 64811-99902 | | | Right to Copy Documentation Assembly |
| 64811SR/003 | 64811-99903 | | | Right to Copy Documentation Assembly |
| 64811SR/004 | 64811-99902 | | | Right to Copy Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|--|
| 64811SX/001 | 64811-99902 | | | One-Time Update Documentation Assembly |
| 64811SX/003 | 64811-99903 | | | One-Time Update Documentation Assembly |
| 64811SX/004 | 64811-99902 | | | One-Time Update Documentation Assembly |
| 64812AF | 5958-6063 64800-99902 64812-90903 | R2604 | | Z80 Pascal Compiler Operating Notice Documentation Assembly Z80 Pascal Compiler Supplement |
| 64812AR | 5958-6063 64800-99902 64812-90903 | R2604 | AUG83 | Right to Copy Operating Notice Documentation Assembly Z80 Pascal Compiler Supplement |
| 64812AX | 5958-6063 64800-99902 64812-90903 | R2604 | AUG83 | One-Time Update Operating Notice Documentation Assembly Z80 Pascal Compiler Supplement |
| 64813-99901 | 5958-6074 64813-90903 | R2604 | FEB83 | Documentation Assembly Software Notice for 64813-90903 6809 Pascal Compiler Supplement |
| 64813-99902 | 5958-6075 64813-90904 | R2604 | SEP84 | Documentation Assembly Software Notice for 64813-90904 (UX) 6809/6809E Pascal Compiler Supplement |
| 64813-99903 | 5958-6076 64813-90905 | R2604 | SEP84 | Documentation Assembly Software Notice for 64813-90905 (VMS) 6809/6809E Pascal Compiler Supplement (VMS) |
| 64813AF | 5958-6063 64800-99903 64813-99901 | R2604 | | 6809 Pascal Compiler Operating Notice Documentation Assembly Documentation Assembly |
| 64813AR | 5958-6063 64800-99903 64813-99901 | R2604 | | Right to Copy Operating Notice Documentation Assembly Documentation Assembly |
| 64813AX | 5958-6063 64800-99903 64813-99901 | R2604 | | One-Time Update Operating Notice Documentation Assembly Documentation Assembly |
| 64813M/001 | 5958-6051 5958-8877 5958-8882 64813-99902 | R2510 R2608 R2610 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64813M/003 | 5958-6051 5958-8883 5958-8890 64813-99903 | R2510 R2610 R2608 | | VAX Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64813M/004 | | | | 300 Media and Manuals |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|---|
| | 5958-8860 5958-8877 5958-8882 64813-99902 | R2605 R2608 R2610 | | Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64813S/001 | 64813-99902 | | | 500 6809 Pascal Compiler Documentation Assembly |
| 64813S/003 | 64813-99903 | | | VAX 6809 Pascal Compiler Documentation Assembly |
| 64813S/004 | 64813-99902 | | | 300 6809 Pascal Compiler Documentation Assembly |
| 64813SR/001 | 64813-99902 | | | Right to Copy Documentation Assembly |
| 64813SR/003 | 64813-99903 | | | Right to Copy Documentation Assembly |
| 64813SR/004 | 64813-99902 | | | Right to Copy Documentation Assembly |
| 64813SX/001 | 64813-99902 | | | One-Time Update Documentation Assembly |
| 64813SX/003 | 64813-99903 | | | One-Time Update Documentation Assembly |
| 64813SX/004 | 64813-99902 | | | One-Time Update Documentation Assembly |
| 64814-99901 | 5958-6077 64814-90903 | R2608 MAY85 | U1286 | Documentation Assembly Software Notice for 64814-90903 8086/8088 Pascal Compiler Supplement |
| 64814-99902 | 5958-6078 64814-90904 | R2606 MAY85 | U0685 | Documentation Assembly Software Notice for 64814-90904 (UX) 8086/8088 Pascal Compiler Supplement |
| 64814-99903 | 5958-6079 64814-90905 | R2606 MAY85 | U0386 | Documentation Assembly Software Notice for 64814-90905 (VMS) 8086/8088 Hosted Pascal Compiler (VMS) |
| 64814AF | 5958-6063 64800-99903 64814-99901 | R2604 | | 8086 Pascal Compiler Operating Notice Documentation Assembly Documentation Assembly |
| 64814AR | 5958-6063 64800-99903 64814-99901 | R2604 | | Right to Copy Operating Notice Documentation Assembly Documentation Assembly |
| 64814AX | 5958-6063 64800-99903 64814-99901 | R2604 | | One-Time Update Operating Notice Documentation Assembly Documentation Assembly |
| 64814M/001 | 5958-6051 5958-8877 5958-8882 64814-99902 | R2510 R2608 R2610 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|---|
| 64814M/003 | 5958-6051 5958-8883 5958-8890 64814-99903 | R2510 | | VAX Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64814M/004 | 5958-8860 5958-8877 5958-8882 64814-99902 | R2605 R2608 R2610 | | 300 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64814S/001 | 64814-99902 | | | 500 8086 Pascal Compiler Documentation Assembly |
| 64814S/003 | 64814-99903 | | | VAX 8086 Pascal Compiler Documentation Assembly |
| 64814S/004 | 64814-99902 | | | 300 8086 Pascal Compiler Documentation Assembly |
| 64814SR/001 | 64814-99902 | | | Right to Copy Documentation Assembly |
| 64814SR/003 | 64814-99903 | | | Right to Copy Documentation Assembly |
| 64814SR/004 | 64814-99902 | | | Right to Copy Documentation Assembly |
| 64814SX/001 | 64814-99902 | | | One-Time Update Documentation Assembly |
| 64814SX/003 | 64814-99903 | | | One-Time Update Documentation Assembly |
| 64814SX/004 | 64814-99902 | | | One-Time Update Documentation Assembly |
| 64815-99901 | 5958-6080 64815-90906 | R2701 MAY84 | | Documentation Assembly Software Notice for 64815-90906 68000/08/10 Pascal Compiler Supplement |
| 64815-99902 | 5958-6081 64815-90907 | R2604 SEP84 | U0885 | Documentation Assembly Software Notice for 64815-90907 (UX) 68000/08/10 Pascal Compiler (UX) |
| 64815-99903 | 5958-6082 64815-90908 | R2610 SEP84 | U0885 | Documentation Assembly Software Notice for 64815-90908 (VMS) 68000/08/10 Pascal Cross Compiler (VMS) |
| 64815AF | 5958-6063 64800-99903 64815-99901 | R2604 | | 68000 Pascal Compiler Operating Notice Documentation Assembly Documentation Assembly |
| 64815AR | 5958-6063 64800-99903 | R2604 | | Right to Copy Operating Notice Documentation Assembly |
| 64815AX | 5958-6063 64800-99903 | R2604 | | One-Time Update Operating Notice Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|---|
| 64815M/001 | 5958-6051 5958-8877 5958-8882 64815-99902 | R2510 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64815M/003 | 5958-6051 5958-8883 5958-8890 64815-99903 | R2510 R2610 R2608 | | VAX Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64815M/004 | 5958-8860 5958-8877 5958-8882 64815-99902 | R2605 R2608 R2610 | | 300 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64815S/001 | 64815-99902 | | | 500 68000 Pascal Compiler Documentation Assembly |
| 64815S/003 | 64815-99903 | | | VAX 68000 Pascal Compiler Documentation Assembly |
| 64815S/004 | 64815-99902 | | | 300 68000 Pascal Compiler Documentation Assembly |
| 64815SR/001 | 64815-99902 | | | Right to Copy Documentation Assembly |
| 64815SR/003 | 64815-99903 | | | Right to Copy Documentation Assembly |
| 64815SR/004 | 64815-99902 | | | Right to Copy Documentation Assembly |
| 64815SX/001 | 64815-99902 | | | One-Time Update Documentation Assembly |
| 64815SX/003 | 64815-99903 | | | One-Time Update Documentation Assembly |
| 64815SX/004 | 64815-99902 | | | One-Time Update Documentation Assembly |
| 64816-99901 | 5958-6083 64816-90903 | R2604 SEP82 | | Documentation Assembly Software Notice for 64816-90903 Z8001/Z8002 Pascal Compiler Supplement |
| 64816-99902 | 5958-6084 64816-90904 64819-90904 | R2604 SEP84 SEP84 | U0885 | Documentation Assembly Software Notice for 64816-90904 (UX) Z8001/Z8002 Pascal Cross Compiler (UX) 68000/08/10 Hosted C Compiler (VMS) |
| 64816-99903 | 5958-6085 64816-90905 | R2606 SEP84 | | Documentation Assembly Software Notice for 64816-90905 (VMS) Z8001/Z8002 Pascal Cross Compiler (VMS) |
| 64816AF | 5958-6063 64800-99903 64816-99901 | R2604 | | Z8000 Pascal Compiler Operating Notice Documentation Assembly Documentation Assembly |
| 64816AR | | | | Right to Copy |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|---|
| | 5958-6063 64800-99903 64816-99901 | R2604 | | Operating Notice Documentation Assembly Documentation Assembly |
| 64816AX | 5958-6063 64800-99903 64816-99901 | R2604 | | One-Time Update Operating Notice Documentation Assembly Documentation Assembly |
| 64816M/001 | 5958-6051 5958-8882 64816-99902 | R2510 R2610 | | 500 Media and Manuals Operating Notice Operating Notice Documentation Assembly |
| 64816M/003 | 5958-6051 5958-8883 5958-8890 64816-99903 | R2510 R2610 R2608 | | VAX Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64816M/004 | 5958-8860 5958-8882 64816-99902 | R2605 R2610 | | 300 Media and Manuals Operating Notice Operating Notice Documentation Assembly |
| 64816S/001 | 64816-99902 | | | 500 Z8000 Pascal Compiler Documentation Assembly |
| 64816S/003 | 64816-99903 | | | VAX Z8000 Pascal Compiler Documentation Assembly |
| 64816S/004 | 64816-99902 | | | 300 Z8000 Pascal Compiler Documentation Assembly |
| 64816SR/001 | 64816-99902 | | | Right to Copy Documentation Assembly |
| 64816SR/003 | 64816-99903 64854-99902 | | | Right to Copy Documentation Assembly Documentation Assembly |
| 64816SR/004 | 64816-99902 | | | Right to Copy Documentation Assembly |
| 64816SX/001 | 64816-99902 | | | One-Time Update Documentation Assembly |
| 64816SX/003 | 64816-99903 | | | One-Time Update Documentation Assembly |
| 64816SX/004 | 64816-99902 | | | One-Time Update Documentation Assembly |
| 64817AF | 64817-90904 | DEC83 | | Host Pascal HP64000 Host Pascal Reference |
| 64817AR | 64817-90904 | DEC83 | | Right to Copy HP64000 Host Pascal Reference |
| 64817AX | 64817-90904 | DEC83 | | One-Time Update HP64000 Host Pascal Reference |
| 64818-99901 | 5958-6086 5959-2125 | R2610 R2707 | | Documentation Assembly Software Notice for 64818-90903 Software Notice |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|--|
| | 64818-90903 | SEP84 | U1287 | 8086/8088 C Compiler |
| 64818-99902 | 5958-6087 5959-2125 64818-90904 | R2610 R2707 SEP84 | U1287 | Documentation Assembly Software Notice for 64818-90904 (VMS) Software Notice 8086/8088 C Cross Compiler (VMS) |
| 64818-99903 | 5958-6088 5959-2125 64818-90905 | R2701 R2707 MAY85 | U1287 | Documentation Assembly Software Notice for 64818-90905 Software Notice 8086/8088 C Compiler Supplement |
| 64818AF | 5958-6063 64818-99903 9320-4991 | R2604 | 1978 | 8086 C Compiler Operating Notice Documentation Assembly The C Programming Language |
| 64818AR | 5958-6063 64818-99903 9320-4991 | R2604 | 1978 | Right to Copy Operating Notice Documentation Assembly The C Programming Language |
| 64818AX | 5958-6063 64818-99903 9320-4991 | R2604 | 1978 | One-Time Update Operating Notice Documentation Assembly The C Programming Language |
| 64818M/001 | 5958-6050 5958-8877 5958-8882 64818-99901 | R2510 R2608 R2610 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64818M/003 | 5958-6050 5958-8883 5958-8890 64818-99902 | R2510 R2610 R2608 | | VAX Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64818M/004 | 5958-8860 5958-8877 5958-8882 64818-99901 | R2605 R2608 R2610 | | 300 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64818S/001 | 64818-99901 | | | 500 8086 C Compiler Documentation Assembly |
| 64818S/003 | 64818-99902 | | | VAX 8086 C Compiler Documentation Assembly |
| 64818S/004 | 64818-99901 | | | 300 8086 C Compiler Documentation Assembly |
| 64818SR/001 | 64818-99901 | | | Right to Copy Documentation Assembly |
| 64818SR/003 | 64818-99902 | | | Right to Copy Documentation Assembly |
| 64818SR/004 | 64818-99901 | | | Right to Copy Documentation Assembly |
| 64818SX/001 | 64818-99901 | | | One-Time Update Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|--|
| 64818SX/003 | 64818-99902 | | | One-Time Update Documentation Assembly |
| 64818SX/004 | 64818-99901 | | | One-Time Update Documentation Assembly |
| 64819-99901 | 5958-6089 5959-2125 64819-90902 | R2610 R2707 E1085 | U1287 | Documentation Assembly Software Notice for 64819-90902 Software Notice 68000/08/10 C Compiler |
| 64819-99902 | 5958-6090 5959-2125 64819-90903 | R2707 R2707 E1185 | U1287 | Documentation Assembly Software Notice for 64819-90903 (UX) Software Notice 68000/08/10 C Cross Compiler |
| 64819-99903 | 5958-6091 5959-2125 64819-90903 | R2610 R2707 E1185 | U1287 | Documentation Assembly Software Notice for 64819-90904 (VMS) Software Notice 68000/08/10 C Cross Compiler |
| 64819AF | 5958-6063 64800-99901 64819-99901 9320-4991 | R2604 | | 68000 C Compiler Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64819AR | 5958-6063 64819-99901 9320-4991 | R2604 1978 | | Right to Copy Operating Notice Documentation Assembly The C Programming Language |
| 64819AX | 5958-6063 64800-99901 64819-99901 9320-4991 | R2604 | 1978 | One-Time Update Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64819M/001 | 5958-6050 5958-8877 5958-8882 64819-99902 | R2510 R2608 R2610 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64819M/003 | 5958-6050 5958-8883 5958-8890 64819-99903 | R2510 R2610 R2608 | | VAX Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64819M/004 | 5958-8860 5958-8877 5958-8882 64819-99902 | R2605 R2608 R2610 | | 300 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64819S/001 | 64819-99902 | | | 500 68000 C Compiler Documentation Assembly |
| 64819S/003 | 64819-99903 | | | VAX 68000 C Compiler Documentation Assembly |
| 64819S/004 | 64819-99902 | | | 300 68000 C Compiler Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|--|
| 64819SR/001 | 64819-99902 | | | Right to Copy Documentation Assembly |
| 64819SR/003 | 64819-99903 | | | Right to Copy Documentation Assembly |
| 64819SR/004 | 64819-99902 | | | Right to Copy Documentation Assembly |
| 64819SX/001 | 64819-99902 | | | One-Time Update Documentation Assembly |
| 64819SX/003 | 64819-99903 | | | One-Time Update Documentation Assembly |
| 64819SX/004 | 64819-99902 | | | One-Time Update Documentation Assembly |
| 64820-99901 | 5958-6092 5959-2125 64820-90901 | R2610 R2707 FEB83 | | Documentation Assembly Software notice for 64820-90901 Software Notice Z8001/Z8002 C Compiler Supplement |
| 64820-99902 | 5958-6093 5959-2125 64820-90902 | R2610 R2707 SEP84 | U1287 | Documentation Assembly Software Notice for 64820-90902 (UX) Software Notice Z8001/Z8002 C Cross Compiler (UX) |
| 64820-99903 | 5958-6094 5959-2125 64820-90903 | R2610 R2707 SEP84 | U1185 | Documentation Assembly Software Notice for 64820-90903 (VMS) Software Notice Z8001/Z8002 C Cross Compiler (VMS) |
| 64820AF | 5958-6063 64800-99901 64820-99901 9320-4991 | R2604 | | Z8000 C Compiler Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64820AR | 5958-6063 64800-99901 64820-99901 9320-4991 | R2604 | 1978 | Right to Copy Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64820AX | 5958-6063 64800-99901 64820-99901 | R2604 | | One-Time Update Operating Notice Documentation Assembly Documentation Assembly |
| 64820M/001 | 5958-6050 5958-8877 5958-8882 64820-99902 | R2510 R2608 R2610 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64820M/003 | 5958-6050 5958-8883 5958-8890 64820-99903 | R2510 R2610 R2608 | | VAX Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64820M/004 | 5958-8860 | R2605 | | 300 Media and Manuals Operating Notice |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|--|
| | 5958-8877 5958-8882 64820-99902 | R2608 R2610 | | Operating Notice Operating Notice Documentation Assembly |
| 64820S/003 | 64820-99903 | | | VAX Z8000 C Compiler Documentation Assembly |
| 64820S/004 | 64820-99902 | | | 300 Z8000 C Compiler Documentation Assembly |
| 64820SR/001 | 64820-99902 | | | Right to Copy Documentation Assembly |
| 64820SR/003 | 64820-99903 | | | Right to Copy Documentation Assembly |
| 64820SR/004 | 64820-99902 | | | Right to Copy Documentation Assembly |
| 64820SX/001 | 64820-99902 | | | One-Time Update Documentation Assembly |
| 64820SX/003 | 64820-99903 | | | One-Time Update Documentation Assembly |
| 64820SX/004 | 64820-99902 | | | One-Time Update Documentation Assembly |
| 64821-99901 | 5958-6095 5959-2125 64821-90901 | R2608 R2707 MAR83 | | Documentation Assembly Software Notice for 64821-90901 Software Notice 6800 C Compiler Supplement |
| 64821-99902 | 5958-6096 5959-2125 64821-90902 | R2608 R2707 SEP84 | U1287 | Documentation Assembly Software Notice for 64821-90902 Software Notice 6800/01/02/03 C Cross Compiler (UX) |
| 64821-99903 | 5958-6097 5959-2125 64821-90903 | R2608 R2707 SEP84 | U0987 | Documentation Assembly Software Notice for 64821-90903 (VMS) Software Notice 6800/01/02/03 C Cross Compiler (VMS) |
| 64821AF | 5958-6063 64800-99901 64821-99901 9320-4991 | R2604 | | 6800 C Compiler Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64821AR | 5958-6063 64800-99901 64821-99901 9320-4991 | R2604 | 1978 | Right to Copy Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64821AX | 5958-6063 64800-99901 64821-99901 9320-4991 | R2604 | 1978 | One-Time Update Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64821M/001 | 5958-6050 5958-8877 5958-8882 | R2510 R2608 R2610 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|--|
| | 64821-99902 | | | Documentation Assembly |
| 64821M/003 | 5958-6050 5958-8883 5958-8890 64821-99903 | R2510 R2610 R2608 | | VAX Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64821M/004 | 5958-8860 5958-8882 64821-99902 | R2605 R2610 | | 300 Media and Manuals Operating Notice Operating Notice Documentation Assembly |
| 64821S/001 | 64821-99902 | | | 500 6800 C Compiler Documentation Assembly |
| 64821S/003 | 64821-99903 | | | VAX 6800 C Compiler Documentation Assembly |
| 64821S/004 | 64821-99902 | | | 300 6800 C Compiler Documentation Assembly |
| 64821SR/001 | 64821-99902 | | | Right to Copy Documentation Assembly |
| 64821SR/003 | 64821-99903 | | | Right to Copy Documentation Assembly |
| 64821SR/004 | 64821-99902 | | | Right to Copy Documentation Assembly |
| 64821SX/001 | 64821-99902 | | | One-Time Update Documentation Assembly |
| 64821SX/003 | 64821-99903 | | | One-Time Update Documentation Assembly |
| 64821SX/004 | 64821-99902 | | | One-Time Update Documentation Assembly |
| 64822-99901 | 5958-8853 5959-2125 64822-90901 | R2610 R2707 MAY85 | | Documentation Assembly Software Notice Software Notice 6809 C Compiler Supplement |
| 64822-99902 | 5958-6098 5959-2125 64822-90902 | R2707 R2707 MAR85 | | Documentation Assembly Software Notice for 64822-90902 (UX) Software Notice 6809/6809E C Compiler Supplement (UX) |
| 64822-99903 | 5958-6099 5959-2125 64822-90903 | R2707 R2707 MAR85 | U0885 | Documentation Assembly Software Notice for 64822-90903 (VMS) Software Notice 6809/6809E C Cross Compiler Supplement (VMS) |
| 64822AF | 5958-6063 64800-99901 64822-99901 9320-4991 | R2604 | | 6809 C Compiler Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64822AR | 5958-6063 64800-99901 64822-99901 | R2604 | | Right to Copy Operating Notice Documentation Assembly Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|--|
| | 9320-4991 | 1978 | | The C Programming Language |
| 64822AX | 5958-6063 64800-99901 64822-99901 9320-4991 | R2604 | | One-Time Update Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64822M/001 | 5958-6050 5958-8877 5958-8882 64822-99902 | R2510 R2608 R2610 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64822M/003 | 5958-6050 5958-8883 5958-8890 64822-99903 | R2510 R2610 R2608 | | VAX Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64822M/004 | 5958-8860 5958-8877 5958-8882 64822-99902 | R2605 R2608 R2610 | | 300 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64822S/001 | 64822-99902 | | | 500 6809 C Compiler Documentation Assembly |
| 64822S/003 | 64822-99903 | | | VAX 6809 C Compiler Documentation Assembly |
| 64822S/004 | 64822-99902 | | | 300 6809 C Compiler Documentation Assembly |
| 64822SR/001 | 64822-99902 | | | Right to Copy Documentation Assembly |
| 64822SR/003 | 64822-99903 | | | Right to Copy Documentation Assembly |
| 64822SR/004 | 64822-99902 | | | Right to Copy Documentation Assembly |
| 64822SX/001 | 64822-99902 | | | One-Time Update Documentation Assembly |
| 64822SX/003 | 64822-99903 | | | One-Time Update Documentation Assembly |
| 64822SX/004 | 64822-99902 | | | One-Time Update Documentation Assembly |
| 64823-99901 | 5958-6100 5959-2125 64823-90901 | R2608 R2707 SEP84 | | Documentation Assembly Software Notice for 64823-90901 Software Notice Z80/NSC800 Pascal Compiler |
| 64823-99902 | 5958-8801 5959-2125 64823-90902 | R2608 R2707 SEP84 | | Documentation Assembly Software Notice for 64823-90902 (UX) Software Notice Z80/NSC800 Pascal Cross Compiler (UX) |
| 64823-99903 | 5958-8802 | R2606 | | Documentation Assembly Software Notice for 64823-90903 (VMS) |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|---|
| | 5959-2125 64823-90903 | R2707 SEP84 | | Software Notice Z80/NSC800 Pascal Cross Compiler (VMS) |
| 64823A | 5958-6063 64800-99903 64823-99901 | R2604 | | Z80 Pascal Compiler Operating Notice Documentation Assembly Documentation Assembly |
| 64823AR | 5958-6063 64800-99903 64823-99901 | R2604 | | Right to Copy Operating Notice Documentation Assembly Documentation Assembly |
| 64823AX | 5958-6063 64800-99903 64823-99901 | R2604 | | One-Time Update Operating Notice Documentation Assembly Documentation Assembly |
| 64823M/001 | 5958-6050 5958-8877 5958-8882 64823-99902 | R2510 R2608 R2610 | | Media and Manuals (500) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64823M/003 | 5958-6050 5958-8883 5958-8890 64823-99903 | R2510 R2610 R2608 | | VAX Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64823M/004 | 5958-8860 5958-8877 5958-8882 64823-99902 | R2605 R2608 R2610 | | 300 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64823S/001 | 64823-99902 | | | PSCL Z80 (500) Documentation Assembly |
| 64823S/003 | 64823-99903 | | | VAX Z80 Pascal Compiler Documentation Assembly |
| 64823S/004 | 64823-99902 | | | Z80 Pascal Compiler (300) Documentation Assembly |
| 64823SR/001 | 64823-99902 | | | Right to Copy Documentation Assembly |
| 64823SR/003 | 64823-99903 | | | Right to Copy Documentation Assembly |
| 64823SR/004 | 64823-99902 | | | Right to Copy Documentation Assembly |
| 64823SX/001 | 64823-99902 | | | One-Time Update Documentation Assembly |
| 64823SX/003 | 64823-99903 | | | One-Time Update Documentation Assembly |
| 64823SX/004 | 64823-99902 | | | One-Time Update Documentation Assembly |
| 64824-99901 | 5958-8803 | R2610 | | Documentation Assembly Software Notice for 64824-90901 |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|--|--------|---|
| | 5959-2125 64824-90901 | R2707 SEP84 | | Software Notice Z80/NSC800 C Compiler Supplement |
| 64824-99902 | 5958-8804 5959-2125 64824-90902 | R2610 R2707 SEP84 | U1287 | Documentation Assembly Software Notice for 64824-90902 (UX) Software Notice Z80/NSC800 C Cross Compiler |
| 64824-99903 | 5958-6050 5958-8805 5958-8883 5958-8890 5959-2125 64824-90903 | R2510 R2610 R2610 R2608 R2707 SEP84 | U0987 | Documentation Assembly Operating Notice Software Notice for 64824-90903 (VMS) Operating Notice Operating Notice Software Notice Z80/NSC800 C Cross Compiler (VMS) |
| 64824A | 5958-6063 64800-99901 64824-99901 9320-4991 | R2604 | | Z80 C Compiler Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64824AR | 5958-6063 64800-99901 64824-99901 9320-4991 | R2604 | 1978 | Right to Copy Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64824AX | 5958-6063 64800-99901 64824-99901 9320-4991 | R2604 | 1978 | One-Time Update Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64824M/001 | 5958-6050 5958-8877 5958-8882 64824-99902 | R2510 R2608 R2610 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64824M/003 | 64824-99903 | | | Media and Manual VAX Documentation Assembly |
| 64824M/004 | 5958-8877 5958-8882 64824-99902 | R2608 R2610 | | 300 Media and Manuals Operating Notice Operating Notice Documentation Assembly |
| 64824S/001 | 64824-99902 | | | Z80 C Compiler (500) Documentation Assembly |
| 64824S/003 | 64824-99903 | | | C Z80 VMS Documentation Assembly |
| 64824S/004 | 64824-99902 | | | Z80 C Compiler (300) Documentation Assembly |
| 64824SR/001 | 64824-99902 | | | Right to Copy Documentation Assembly |
| 64824SR/003 | 64824-99903 | | | Right to Copy Documentation Assembly |
| 64824SR/004 | 64824-99902 | | | Right to Copy Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|---|
| 64824SX/001 | 64824-99902 | | | One-Time Update Documentation Assembly |
| 64824SX/003 | 64824-99903 | | | One-Time Update Documentation Assembly |
| 64824SX/004 | 5958-8860 5958-8882 64824-99902 | R2605 R2610 | | One-Time Update Operating Notice Operating Notice Documentation Assembly |
| 64825-99901 | 5958-8806 64825-90901 | R2608 SEP84 | | Documentation Assembly Software Notice for 64825-90901 8085 Pascal Compiler Supplement |
| 64825-99902 | 5958-8807 64825-90902 | R2608 SEP84 | | Documentation Assembly Software Notice for 64825-90902 (UX) 8085 Hosted Pascal Compiler (UX) |
| 64825-99903 | 5958-8808 64825-90903 | R2606 SEP84 | | Documentation Assembly Software Notice for 64825-90903 (VMS) 8085 Pascal Cross Compiler (VMS) |
| 64825A | 5958-6063 64800-99903 64825-99901 | R2604 | | 8085 Pascal Compiler Operating Notice Documentation Assembly Documentation Assembly |
| 64825AR | 5958-6063 64800-99903 64825-99901 | R2604 | | Right to Copy Operating Notice Documentation Assembly Documentation Assembly |
| 64825AX | 5958-6063 64800-99903 64825-99901 | R2604 | | One-Time Update Operating Notice Documentation Assembly Documentation Assembly |
| 64825M/001 | 5958-6051 5958-8877 5958-8882 64825-99902 | R2510 R2608 R2610 | | Media and Manuals (500) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64825M/003 | 5958-6051 5958-8883 5958-8890 64825-99903 | R2510 R2610 R2608 | | Media and Manuals (VAX) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64825M/004 | 5958-8860 5958-8877 5958-8882 64825-99902 | R2605 R2608 R2610 | | Media and Manuals (300) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64825S/001 | 64825-99902 | | | 8085 Pascal Compiler (500) Documentation Assembly |
| 64825S/003 | 64825-99903 | | | 8085 Pascal Compiler (VAX) Documentation Assembly |
| 64825S/004 | 64825-99902 | | | 8085 Pascal Compiler (300) Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|---|
| 64825SR/001 | 64825-99902 | | | Right to Copy Documentation Assembly |
| 64825SR/003 | 64825-99903 | | | Right to Copy Documentation Assembly |
| 64825SR/004 | 64825-99902 | | | Right to Copy Documentation Assembly |
| 64825SX/001 | 64825-99902 | | | One-Time Update Documentation Assembly |
| 64825SX/003 | 64825-99903 | | | One-Time Update Documentation Assembly |
| 64825SX/004 | 64825-99902 | | | One-Time Update Documentation Assembly |
| 64826-99901 | 5958-8809 5959-2125 64826-90901 | R2610 R2707 SEP84 | | Documentation Assembly Software Notice for 64826-90901 Software Notice 8085 C Compiler Supplement |
| 64826-99902 | 5958-8810 5959-2125 64826-90902 | R2610 R2707 SEP84 | U1287 | Documentation Assembly Software Notice for 64826-90902 (UX) Software Notice 8085 C Cross Compiler (UX) |
| 64826-99903 | 5958-8811 5959-2125 64826-90903 | R2610 R2707 SEP84 | U0987 | Documentation Assembly Software Notice for 64826-90903 (VMS) Software Notice 8085 Hosted C Cross Compiler |
| 64826A | 5958-6063 64800-99901 64826-99901 | R2604 | | 8085 C Compiler Operating Notice Documentation Assembly Documentation Assembly |
| 64826AR | 5958-6063 64800-99901 64826-99901 9320-4991 | R2604 1978 | | Right to Copy Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64826AX | 5958-6063 64800-99901 64826-99901 9320-4991 | R2604 1978 | | One-Time Update Operating Notice Documentation Assembly Documentation Assembly The C Programming Language |
| 64826M/001 | 5958-6050 5958-8877 64826-99902 | R2510 R2608 | | Media and Manuals (500) Operating Notice Operating Notice Documentation Assembly |
| 64826M/003 | 5958-6050 5958-8883 5958-8890 64826-99903 | R2510 R2610 R2608 | | Media and Manuals (VAX) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64826M/004 | 5958-8860 5958-8877 | R2605 R2608 | | Media and Manuals (300) Operating Notice Operating Notice |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|---|
| | 5958-8882 64826-99902 | R2610 | | Operating Notice Documentation Assembly |
| 64826S/001 | 64826-99902 | | | 8080 C Compiler (500) Documentation Assembly |
| 64826S/003 | 64826-99903 | | | 8080 C Compiler (VAX) Documentation Assembly |
| 64826S/004 | 64826-99902 | | | 8080 C Compiler (300) Documentation Assembly |
| 64826SR/001 | 64826-99902 | | | Right to Copy Documentation Assembly |
| 64826SR/003 | 64826-99903 | | | Right to Copy Documentation Assembly |
| 64826SR/004 | 64826-99902 | | | Right to Copy Documentation Assembly |
| 64826SX/001 | 64826-99902 | | | One-Time Update Documentation Assembly |
| 64826SX/003 | 64826-99903 | | | One-Time Update Documentation Assembly |
| 64826SX/004 | 64826-99902 | | | One-Time Update Documentation Assembly |
| 64840-99901 | 5958-8812 64840-90902 | R2610 SEP84 | | Documentation Assembly Software Notice for 64840-90902 (UX) 8080/8085 Cross Assembler/Linker |
| 64840-99902 | 5958-8813 64840-90903 | R2610 SEP84 | | Documentation Assembly Software Notice for 64840-90903 (VMS) 8080/8085 Cross Assembler/Linker (VMS) |
| 64840AF | 5958-6046 5958-6063 64200-99901 64980-99902 | R2510 R2604 | | 8080/8085 Assembler Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64840AR | 5958-6046 5958-6063 64200-99901 64980-99902 | R2510 R2604 | | Right to Copy Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64840AU | 5958-6046 | R2510 | | 8080/8085 Assembler/Linker Update Operating Notice |
| 64840AX | 5958-6046 5958-6063 64200-99901 64980-99902 | R2510 R2604 | | One-Time Update Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64840M/001 | 5958-6046 5958-6049 5958-8877 64840-99901 | R2510 R2510 R2608 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|----------------------------------|--------|--|
| 64840M/003 | 64840-99902 | | | Media and Manual (VAX) Documentation Assembly |
| 64840M/004 | 5958-6046 5958-6049 5958-8860 5958-8877 | R2510 R2510 R2605 R2608 | | 300 Media and Manuals Operating Notice Operating Notice Operating Notice Operating Notice |
| 64840S/003 | 64840-99902 | | | 8080 Assembly VMS Documentation Assembly |
| 64840SR/001 | 64840-99901 | | | Right to Copy Documentation Assembly |
| 64840SR/003 | 64840-99902 | | | Right to Copy Documentation Assembly |
| 64840SR/004 | 64840-99901 | | | Right to Copy Documentation Assembly |
| 64840SX/001 | 64840-99901 | | | One-Time Update Documentation Assembly |
| 64840SX/003 | 64840-99902 | | | One-Time Update Documentation Assembly |
| 64840SX/004 | 64840-99901 | | | One-Time Update Documentation Assembly |
| 64841-99901 | 5958-8814 64841-90906 | R2604 SEP84 | | Documentation Assembly Software Notice for 64841-90906 (UX) 68000 Series Assembler/Linker |
| 64841-99902 | 5958-8815 64841-90907 | R2707 SEP84 | | Documentation Assembly Software Notice for 64841-90907 (VMS) 6800 Series Cross Assembler/Linker (VMS) |
| 64841AF | 5958-6046 5958-6063 5959-2126 64841-90905 64980-99902 | R2510 R2604 R2707 AUG84 | | 6800 Assembler Operating Notice Operating Notice Software Notice 6800/02/03 Assembler/Linker Supplement Documentation Assembly |
| 64841AR | 5958-6046 5958-6063 5959-2126 64841-90905 64980-99902 | R2510 R2604 R2707 AUG84 | | Right to Copy Operating Notice Operating Notice Software Notice 6800/02/03 Assembler/Linker Supplement Documentation Assembly |
| 64841AU | 5958-6046 | R2510 | | 6800 Assembler/Linker Update Operating Notice |
| 64841AX | 5958-6046 5958-6063 5959-2126 64841-90905 64980-99902 | R2510 R2604 R2707 AUG84 | | One-Time Update Operating Notice Operating Notice Software Notice 6800/02/03 Assembler/Linker Supplement Documentation Assembly |
| 64841M/001 | 5958-6046 | R2510 | | 500 Media and Manuals Operating Notice |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|-------------------------|--------|---|
| | 5958-6049 | R2510 | | Operating Notice |
| | 5958-8877 | R2608 | | Operating Notice |
| | 64841-99901 | | | Documentation Assembly |
| 64841M/003 | | | | VAX Media and Manuals |
| | 5958-6046 | R2510 | | Operating Notice |
| | 5958-6049 | R2510 | | Operating Notice |
| | 64841-99902 | | | Documentation Assembly |
| 64841M/004 | | | | 300 Media and Manuals |
| | 5958-6046 | R2510 | | Operating Notice |
| | 5958-6049 | R2510 | | Operating Notice |
| | 5958-8860 | R2605 | | Operating Notice |
| | 5958-8877 | R2608 | | Operating Notice |
| | 64841-99901 | | | Documentation Assembly |
| 64841S/001 | 64841-99901 | | | 500 6800 Assembler Documentation Assembly |
| 64841S/003 | 64841-99902 | | | VAX 6800 Assembler Documentation Assembly |
| 64841S/004 | 64841-99901 | | | 6800 Assembler (300) Documentation Assembly |
| 64841SR/001 | 64841-99901 | | | Right to Copy Documentation Assembly |
| 64841SR/003 | 64841-99902 | | | Right to Copy Documentation Assembly |
| 64841SR/004 | 64841-99901 | | | Right to Copy Documentation Assembly |
| 64841SX/001 | 64841-99901 | | | One-Time Update Documentation Assembly |
| 64841SX/003 | 64841-99902 | | | One-Time Update Documentation Assembly |
| 64841SX/004 | 64841-99901 | | | One-Time Update Documentation Assembly |
| 64842-99901 | 5958-8816 64842-90903 | R2610 NOV81 | | Documentation Assembly Software Notice for 64842-90903 Z80 Assembler/Linker Supplement |
| 64842-99902 | 5958-8817 5958-8880 64842-90904 | R2707 R2610 SEP84 | | Documentation Assembly Software Notice for 64842-90904 (UX) Software Notice Z80/NSC800 Cross Assembler/Linker |
| 64842-99903 | 5958-8818 5958-8881 64842-90905 | R2707 R2610 SEP84 | | Documentation Assembly Software Notice for 64842-90905 (VMS) Software Notice Z80/NSC800 Cross Assembler/Linker (VMS) |
| 64842-99904 | 5959-2184 64740-90912 64842-90906 | E0288 E0688 E0188 | | Documentation Assembly Map Unix HP 64000 Support Services Z80/NSC800 MS-DOS Cross Assembler/Linker User's Guide |
| 64842AF | 5958-6046 5958-6063 | R2510 R2604 | | Z80 Assembler Operating Notice Operating Notice |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|---|
| | 64842-99901 64980-99902 | | | Documentation Assembly Documentation Assembly |
| 64842AR | 5958-6046 5958-6063 64842-99901 64980-99902 | R2510 R2604 | | Right to Copy Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64842AU | 5958-6046 | R2510 | | Z80 Assembler/Linker Update Operating Notice |
| 64842AX | 5958-6046 5958-6063 64842-99901 64980-99902 | R2510 R2604 | | One-Time Update Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64842M/001 | 5958-6046 5958-6049 5958-8877 64842-99902 | R2510 R2510 R2608 | | Media and Manuals (500) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64842M/003 | 5958-6046 5958-6049 64842-99903 | R2510 | | Media and Manuals (VAX) Operating Notice Operating Notice Documentation Assembly |
| 64842M/004 | 5958-6049 5958-8860 5958-8877 64842-99902 | R2510 R2605 R2608 | | Media and Manuals (300) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64842S/001 | 64842-99902 | | | Z80 Assembler (500) Documentation Assembly |
| 64842S/003 | 64842-99903 | | | Z80 Assembler (VAX) Documentation Assembly |
| 64842S/004 | 64842-99902 | | | Z80 Assembler (300) Documentation Assembly |
| 64842S/006 | 64842-99904 | | | 64842 Host Interface on PC Documentation Assembly |
| 64842SR/001 | 64842-99902 | | | Right to Copy Documentation Assembly |
| 64842SR/003 | 64842-99903 | | | Right to Copy Documentation Assembly |
| 64842SR/004 | 64842-99902 | | | Right to Copy Documentation Assembly |
| 64842SR/006 | 64842-99904 | | | Right to Copy Documentation Assembly |
| 64842SX/001 | 64842-99902 | | | One-Time Update Documentation Assembly |
| 64842SX/003 | 64842-99903 | | | One-Time Update Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|----------------------------------|--------|---|
| 64842SX/004 | 64842-99902 | | | One-Time Update Documentation Assembly |
| 64842SX/006 | 64842-99904 | | | One-Time Update Documentation Assembly |
| 64843-99901 | 5958-8819 64843-90903 | R2701 SEP84 | | Documentation Assembly Software Notice for 64843-90902 (UX) 6500 Series Cross Assembler/linker (UX) |
| 64843-99902 | 5958-8820 64843-90904 | R2701 SEP84 | | Documentation Assembly Software Notice for 64843-90904 (VMS) 6500 Series Cross Assembler/Linker (VMS) |
| 64843AF | 5958-6046 5958-6063 64843-90902 64980-99902 | R2510 R2604 APR83 | | 6502 Assembler Operating Notice Operating Notice 6501/6505 Assembler & Linker Supplement Documentation Assembly |
| 64843AR | 5958-6046 5958-6063 64843-90902 64980-99902 | R2510 R2604 APR83 | | Right to Copy Operating Notice Operating Notice 6501/6505 Assembler & Linker Supplement Documentation Assembly |
| 64843AU | 5958-6046 | R2510 | | 6502 Assembler/Linker Update Operating Notice |
| 64843AX | 5958-6046 5958-6063 64843-90902 64980-99902 | R2510 R2604 APR83 | | One-Time Update Operating Notice Operating Notice 6501/6505 Assembler & Linker Supplement Documentation Assembly |
| 64843M/001 | 5958-6046 5958-6049 5958-8877 64843-99901 | R2510 R2510 R2608 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64843M/003 | 5958-6046 5958-6049 64843-99902 | R2510 R2510 | | Media and Manuals (VAX) Operating Notice Operating Notice Documentation Assembly |
| 64843M/004 | 5958-6046 5958-6049 5958-8860 5958-8877 64843-99901 | R2510 R2510 R2605 R2608 | | Media and Manuals (300) Operating Notice Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64843S/001 | 64843-99901 | | | 6502 Assembler (600) Documentation Assembly |
| 64843S/003 | 64843-99902 | | | 6502 Assembler (VAX) Documentation Assembly |
| 64843S/004 | 64843-99901 | | | 6502 Assembler (300) Documentation Assembly |
| 64843SR/001 | 64843-99901 | | | Right to Copy Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|---|
| 64843SR/003 | 64843-99902 | | | Right to Copy Documentation Assembly |
| 64843SR/004 | 64843-99901 | | | Right to Copy Documentation Assembly |
| 64843SX/001 | 64843-99901 | | | One-Time Update Documentation Assembly |
| 64843SX/003 | 64843-99902 | | | One-Time Update Documentation Assembly |
| 64843SX/004 | 64843-99901 | | | One-Time Update Documentation Assembly |
| 64844-99901 | 5958-8821 64844-90905 | R2707 SEP84 | | Documentation Assembly Software Notice for 64844-90905 (UX) 6805/09/09E Cross Assembler/Linker |
| 64844-99902 | 5958-8822 64844-90906 | R2707 SEP84 | | Documentation Assembly Software Notice for 64844-90906 (VMS) 6805/09/09E Cross Assembler/Linker (VMS) |
| 64844-99904 | 5958-8869 64844-90904 | R2608 E0786 | | Documentation Assembly Software Notice 6805/09/09E Assembler/Linker Supplement |
| 64844AF | 5958-6046 5958-6063 64844-99904 64980-99902 | R2510 R2604 | | 6805/6809 Assembler Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64844AR | 5958-6046 5958-6063 64844-99904 64980-99902 | R2510 R2604 | | Right to Copy Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64844AU | 5958-6046 | R2510 | | 6805/6809 Assembler/Linker Update Operating Notice |
| 64844AX | 5958-6063 64844-99904 64980-99902 | R2604 | | One-Time Update Operating Notice Documentation Assembly Documentation Assembly |
| 64844M/001 | 5958-6049 5958-8877 64844-99901 | R2510 R2608 | | Media and Manuals (500) Operating Notice Operating Notice Documentation Assembly |
| 64844M/003 | 5958-6049 64844-99902 | R2510 | | Media and Manuals (VAX) Operating Notice Documentation Assembly |
| 64844M/004 | 5958-6049 5958-8860 5958-8877 64844-99901 | R2510 R2605 R2608 | | Media and Manuals (300) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64844S/001 | 64844-99901 | | | 6805 Assembler (500) Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|--|
| 64844S/003 | 64844-99902 | | | 6805 Assembler (VAX) Documentation Assembly |
| 64844S/004 | 64844-99901 | | | 6805 Assembler (300) Documentation Assembly |
| 64844SR/001 | 64844-99901 | | | Right to Copy Documentation Assembly |
| 64844SR/003 | 64844-99902 | | | Right to Copy Documentation Assembly |
| 64844SR/004 | 64844-99901 | | | Right to Copy Documentation Assembly |
| 64844SX/001 | 64844-99901 | | | One-Time Update Documentation Assembly |
| 64844SX/003 | 64844-99902 | | | One-Time Update Documentation Assembly |
| 64844SX/004 | 64844-99901 | | | One-Time Update Documentation Assembly |
| 64845-99901 | 5958-8823 64845-90904 | R2701 AUG84 | | Documentation Assembly Software Notice for 64845-90904 68000/08/10 Assembler/Linker Supplement |
| 64845-99902 | 5958-8824 64845-90905 | R2707 SEP84 | U1287 | Documentation Assembly Software Notice for 64845-90905 (UX) 68000/08/10 Cross Assembler/Linker |
| 64845-99903 | 5958-8825 5958-8886 64845-90906 | R2707 R2701 SEP84 | U1087 | Documentation Assembly Software Notice for 64845-90906 (VMS) Software Notice 68000/08/10 Cross Assembler/Linker (VMS) |
| 64845-99904 | 5959-2184 64740-90912 64845-90908 | E0288 E0688 E0188 | | Documentation Assembly Map Unix HP 64000 Support Services 68000/08/10 PC Hosted Assembler/Linker |
| 64845AF | 5958-6046 5958-6063 64845-99901 64980-99902 | R2510 R2604 | | 68000 Assembler Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64845AR | 5958-6046 5958-6063 64845-99901 64980-99902 | R2510 R2604 | | Right to Copy Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64845AU | 5958-6046 | R2510 | | 68000 Assembler/Linker Update Operating Notice |
| 64845AX | 5958-6046 5958-6063 64845-99901 64980-99902 | R2510 R2604 | | One-Time Update Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64845M/001 | | | | Media and Manuals (500) |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|-----------------|---------|--------|---|
| | 5958-6046 | R2510 | | Operating Notice |
| | 5958-6049 | R2510 | | Operating Notice |
| | 5958-8877 | R2608 | | Operating Notice |
| | 64845-99902 | | | Documentation Assembly |
| 64845M/003 | | | | VAX Media and Manuals |
| | 5958-6046 | R2510 | | Operating Notice |
| | 5958-6049 | R2510 | | Operating Notice |
| | 64845-99903 | | | Documentation Assembly |
| 64845M/004 | | | | Media and Manuals (300) |
| | 5958-6046 | R2510 | | Operating Notice |
| | 5958-6049 | R2510 | | Operating Notice |
| | 5958-8860 | R2605 | | Operating Notice |
| | 5958-8877 | R2608 | | Operating Notice |
| | 64845-99902 | | | Documentation Assembly |
| 64845S/001 | | | | 68000 Assembler (500) |
| | 64845-99902 | | | Documentation Assembly |
| 64845S/003 | | | | VAX 68000 Assembler |
| | 5958-6046 | R2510 | | Operating Notice |
| | 5958-6049 | R2510 | | Operating Notice |
| | 64845-99903 | | | Documentation Assembly |
| 64845S/004 | | | | 68000 Assembler (300) |
| | 64845-99902 | | | Documentation Assembly |
| 64845S/006 | | | | 64845 Hosted on PC |
| | 64845-99904 | | | Documentation Assembly |
| 64845SR/001 | | | | Right to Copy |
| | 64845-99902 | | | Documentation Assembly |
| 64845SR/004 | | | | Right to Copy |
| | 64845-99902 | | | Documentation Assembly |
| 64845SR/006 | | | | Right to Copy |
| | 64845-99904 | | | Documentation Assembly |
| 64845SX/001 | | | | One-Time Update |
| | 64845-99902 | | | Documentation Assembly |
| 64845SX/004 | | | | One-Time Update |
| | 64845-99902 | | | Documentation Assembly |
| 64845SX/006 | | | | One-Time Update |
| | 64845-99904 | | | Documentation Assembly |
| 64846-99901 | | | | Documentation Assembly |
| | 5958-8826 | R2701 | | Software Notice for 64846-90903 (UX) |
| | 64846-90903 | SEP84 | | 8048 Cross Assembler/Linker (UX) |
| 64846-99902 | | | | Documentation Assembly |
| | 5958-8827 | R2701 | | Software Notice for 64846-90904 (VMS) |
| | 64846-90904 | SEP84 | | 8048 Cross Assembler/Linker (VMS) |
| 64846AF | | | | 8021/41/48 Assembler |
| | 5958-6046 | R2510 | | Operating Notice |
| | 5958-6063 | R2604 | | Operating Notice |
| | 64846-90905 | E0985 | | 8048 Series Assembler/Linker Supplement |
| 64846AR | | | | Right to Copy |
| | 5958-6046 | R2510 | | Operating Notice |
| | 5958-6063 | R2604 | | Operating Notice |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|----------------------------------|--------|---|
| | 64846-90905 | E0985 | | 8048 Series Assembler/Linker Supplement |
| 64846AU | 5958-6046 | R2510 | | 8021/41/48 Assembler Update Operating Notice |
| 64846AX | 5958-6046 64846-90905 | R2510 E0985 | | One-Time Update Operating Notice 8048 Series Assembler/Linker Supplement |
| 64846M/001 | 5958-6046 5958-6049 5958-8877 64846-99901 | R2510 R2510 R2608 | | 500 Media and Manuals Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64846M/003 | 5958-6046 5958-6049 64846-99902 | R2510 R2510 | | Media and Manuals (VAX) Operating Notice Operating Notice Documentation Assembly |
| 64846M/004 | 5958-6046 5958-6049 5958-8860 5958-8877 64846-99901 | R2510 R2510 R2605 R2608 | | 300 Media and Manuals Operating Notice Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64846S/003 | 64846-99902 | | | 8048 Assembler (VAX) Documentation Assembly |
| 64846SR/003 | 64846-99902 | | | Right to Copy Documentation Assembly |
| 64846SX/003 | 64846-99902 | | | One-Time Update Documentation Assembly |
| 64847-99901 | 5958-8828 64847-90904 | R2701 SEP84 | | Documentation Assembly Software Notice for 64847-90904 (UX) 9900/99000 Cross Assembler/Linker (UX) |
| 64847-99902 | 5958-8829 64847-90905 | R2701 SEP84 | | Documentation Assembly Software Notice 9900/99000 Cross Assembler/Linker (VMS) |
| 64847AF | 5958-6046 5958-6063 64847-90903 64980-99902 | R2510 R2604 SEP81 | | 9900 Assembler Operating Notice Operating Notice 9900 Series Assembler/Linker Supplement Documentation Assembly |
| 64847AR | 5958-6046 5958-6063 64847-90903 64980-99902 | R2510 R2604 SEP81 | | Right to Copy Operating Notice Operating Notice 9900 Series Assembler/Linker Supplement Documentation Assembly |
| 64847AU | 5958-6046 | R2510 | | 9900 Assembler/Linker Update Operating Notice |
| 64847AX | 5958-6046 5958-6063 64847-99902 64980-99902 | R2510 R2604 | | One-Time Update Operating Notice Operating Notice Documentation Assembly Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|-------------------------|----------------|---|
| 64847M/001 | 5958-6046 5958-6049 5958-8877 64847-99901 | R2510 | R2608 | Media and Manuals (500) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64847M/003 | 5958-6046 5958-6049 64847-99902 | R2510 | R2510 | Media and Manuals (VAX) Operating Notice Operating Notice Documentation Assembly |
| 64847M/004 | 5958-6046 5958-6049 5958-8860 5958-8877 64847-99901 | R2510 | R2605 R2608 | Media and Manuals (300) Operating Notice Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64847S/001 | 64847-99901 | | | 9900 Assembler (500) Documentation Assembly |
| 64847S/003 | 64847-99902 | | | 9900 Assembler (VAX) Documentation Assembly |
| 64847S/004 | 64847-99901 | | | 9900 Assembler (300) Documentation Assembly |
| 64847SR/001 | 64847-99901 | | | Right to Copy Documentation Assembly |
| 64847SR/003 | 64847-99902 | | | Right to Copy Documentation Assembly |
| 64847SR/004 | 64847-99901 | | | Right to Copy Documentation Assembly |
| 64847SX/001 | 64847-99901 | | | One-Time Update Documentation Assembly |
| 64847SX/003 | 64847-99902 | | | One-Time Update Documentation Assembly |
| 64847SX/004 | 64847-99901 | | | One-Time Update Documentation Assembly |
| 64848AF | 5958-6046 5958-6063 64848-90902 64980-99902 | R2510 R2604 MAY80 | | 1802 Assembler Operating Notice Operating Notice 1802 Assembler & Linker Supplement Documentation Assembly |
| 64848AR | 5958-6046 5958-6063 64848-90902 64980-99902 | R2510 R2604 MAY80 | | Right to Copy Operating Notice Operating Notice 1802 Assembler & Linker Supplement Documentation Assembly |
| 64848AU | 5958-6046 | R2510 | | 1802 Assembler/Linker Update Operating Notice |
| 64848AX | 5958-6046 5958-6063 64848-90902 | R2510 R2604 MAY80 | | One-Time Update Operating Notice Operating Notice 1802 Assembler & Linker Supplement |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|-----------------|---------|--------|--------------------------------------|
| | 64980-99902 | | | Documentation Assembly |
| 64849AF | 5958-6046 | R2510 | | F8/3870 Assembler |
| | 5958-6063 | R2604 | | Operating Notice |
| | 64849-90902 | JUL80 | | Operating Notice |
| | 64980-99902 | | | F3870/F38E70/F8 Assembler & Linker |
| 64849AR | 5958-6046 | R2510 | | Documentation Assembly |
| | 5958-6063 | R2604 | | Right to Copy |
| | 64849-90902 | JUL80 | | Operating Notice |
| | 64980-99902 | | | Operating Notice |
| 64849AU | 5958-6046 | R2510 | | F3870/F38E70/F8 Assembler & Linker |
| | | | | Documentation Assembly |
| 64849AX | 5958-6046 | R2510 | | F8/3870 Assembler/Linker Update |
| | 5958-6063 | R2604 | | Operating Notice |
| | 64849-90902 | JUL80 | | One-Time Update |
| | 64980-99902 | | | Operating Notice |
| 64850-99901 | 5958-8830 | R2604 | | F3870/F38E70/F8 Assembler & Linker |
| | 64850-90902 | JUN80 | U0887 | Documentation Assembly |
| | | | | Documentation Assembly |
| | | | | Software Notice |
| 64850AF | 5958-6046 | R2510 | | Z8 Assembler & Linker Supplement |
| | 5958-6063 | R2604 | | Operating Notice |
| | 64850-99901 | | | Operating Notice |
| | 64980-99902 | | | Documentation Assembly |
| 64850AR | 5958-6046 | R2510 | | Z8 Assembler |
| | 5958-6063 | R2604 | | Operating Notice |
| | 64850-99901 | | | Operating Notice |
| | 64980-99902 | | | Documentation Assembly |
| 64850AU | 5958-6046 | R2510 | | Documentation Assembly |
| | 5958-6063 | R2604 | | Right to Copy |
| | 64850-99901 | | | Operating Notice |
| | 64980-99902 | | | Operating Notice |
| 64850AX | 5958-6046 | R2510 | | Z8 Assembler/Linker Update |
| | 5958-6063 | R2604 | | Operating Notice |
| | 64850-99901 | | | Operating Notice |
| | 64980-99902 | | | Documentation Assembly |
| 64851-99902 | 5958-8832 | R2707 | | Documentation Assembly |
| | 64851-90906 | SEP84 | U1287 | Software Notice |
| | | | | User Definable Assembler/Linker |
| | | | | |
| 64851-99903 | 5958-8833 | R2707 | | Documentation Assembly |
| | 64851-90907 | SEP84 | U1287 | Software Notice |
| | | | | User Definable Assembler/Linker |
| | | | | |
| 64851AF | 5958-6046 | R2510 | | General Purpose Assembler/Linker |
| | 5958-6063 | R2604 | | Operating Notice |
| | 5958-8879 | R2610 | | Operating Notice |
| | 64861-90901 | E1185 | | Software Notice |
| | 64980-99902 | | | User Definable Microassembler/Linker |
| 64851AR | | | | Documentation Assembly |
| | 5958-6046 | R2510 | | Right to Copy |
| | | | | Operating Notice |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|----------------------------------|--------|---|
| | 5958-6063 5958-8879 64861-90901 64980-99902 | R2604 R2610 E1185 | | Operating Notice Software Notice User Definable Microassembler/Linker Documentation Assembly |
| 64851AU | 5958-6046 | R2510 | | General Purpose Assembler/Linker Update Operating Notice |
| 64851AX | 5958-6046 5958-6063 64980-99902 | R2510 R2604 | | One-Time Update Operating Notice Operating Notice Documentation Assembly |
| 64851M/001 | 5958-6046 5958-6049 5958-6063 5958-8877 64851-99902 | R2510 R2510 R2604 R2608 | | Media and Manuals (500) Operating Notice Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64851M/003 | 5958-6046 5958-6049 5958-6063 64851-99903 | R2510 R2510 R2604 | | Media and Manuals (VAX) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64851M/004 | 5958-6046 5958-6049 5958-8860 5958-8877 64851-99902 | R2510 R2510 R2605 R2608 | | Media and Manuals (300) Operating Notice Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64851S/001 | 64851-99902 | | | User Definable Assembler (500) Documentation Assembly |
| 64851S/003 | 64851-99903 | | | User Definable Assembler (VAX) Documentation Assembly |
| 64851S/004 | 64851-99902 | | | User Definable Assembler (300) Documentation Assembly |
| 64851SR/001 | 64851-99902 | | | Right to Copy Documentation Assembly |
| 64851SR/003 | 64851-99903 | | | Right to Copy Documentation Assembly |
| 64851SR/004 | 64851-99902 | | | Right to Copy Documentation Assembly |
| 64851SX/001 | 64851-99902 | | | One-Time Update Documentation Assembly |
| 64851SX/003 | 64851-99903 | | | One-Time Update Documentation Assembly |
| 64851SX/004 | 64851-99902 | | | One-Time Update Documentation Assembly |
| 64852AF | 5958-6046 5958-6063 64852-90902 64980-99902 | R2510 R2604 MAY81 | | 1000L Assembler/Linker Operating Notice Operating Notice 1000L Assembler & Linker Supplement Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|----------------------------------|--------|--|
| 64852AR | 5958-6046 5958-6063 64852-90902 64980-99902 | R2510 R2604 MAY81 | | Right to Copy Operating Notice Operating Notice 1000L Assembler & Linker Supplement Documentation Assembly |
| 64852AU | 5958-6046 | R2510 | | 1000L Assembler/Linker Update Operating Notice |
| 64852AX | 5958-6046 5958-6063 64852-90902 64980-99902 | R2510 R2604 MAY81 | | One-Time Update Operating Notice Operating Notice 1000L Assembler & Linker Supplement Documentation Assembly |
| 64853-99901 | 5958-8838 64853-90908 | R2701 E1186 | | Documentation Assembly Software Notice 8086/8089 Cross Assembler/Linker |
| 64853-99902 | 64740-90912 64853-90909 | E0688 E0288 | | Documentation Assembly HP 64000 Support Services 8086/88, 70108/116 Cross Assem.Lnk. MS-DOS User's Guide |
| 64853AF | 5958-6046 5958-6063 64853-99901 | R2510 R2604 | | 8086 Assembler/Linker Operating Notice Operating Notice Documentation Assembly |
| 64853AR | 5958-6046 5958-6063 64853-99901 | R2510 R2604 | | Right to Copy Operating Notice Operating Notice Documentation Assembly |
| 64853AU | 5958-6046 | R2510 | | 8086 Assembler/Linker Update Operating Notice |
| 64853AX | 5958-6046 5958-6063 64853-99901 | R2510 R2604 | | One-Time Update Operating Notice Operating Notice Documentation Assembly |
| 64853M/001 | 5958-6046 5958-6049 5958-8877 64853-90908 | R2510 R2510 R2608 E1186 | | Media and Manuals (500) Operating Notice Operating Notice Operating Notice 8086/8089 Cross Assembler/Linker |
| 64853M/003 | 5958-6046 5958-6049 | R2510 R2510 | | VAX Media and Manuals Operating Notice Operating Notice |
| 64853M/004 | 5958-6046 5958-6049 5958-8860 5958-8877 | R2510 R2510 R2605 R2608 | | 300 Media and Manuals Operating Notice Operating Notice Operating Notice Operating Notice |
| 64853S/001 | 64853-90908 | E1186 | | 8086 Assembler (500) 8086/8089 Cross Assembler/Linker |
| 64853S/006 | 64853-99902 | | | 64853 Hosted on PC Documentation Assembly |
| 64853SR/001 | | | | Right to Copy |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|----------------------------------|--------|---|
| | 64853-90908 | E1186 | | 8086/8089 Cross Assembler/Linker |
| 64853SR/006 | 64853-99902 | | | Right to Copy Documentation Assembly |
| 64853SX/001 | 64853-90908 | E1186 | | One-Time Update 8086/8089 Cross Assembler/Linker |
| 64853SX/006 | 64853-99902 | | | One Time Update for 64853S/006 Documentation Assembly |
| 64854-99901 | 5958-8836 64854-90903 | R2701 SEP84 | | Documentation Assembly Software Notice Z8001/Z8002 Cross Assembler/Linker (UX) |
| 64854-99902 | 5958-8837 64854-90904 | R2701 SEP84 | | Documentation Assembly Software Notice Z8001/Z8002 Cross Assembler?linker (VMS) |
| 64854AF | 5958-6046 5958-6063 64854-90902 64980-99902 | R2510 R2604 MAR84 | | Z8000 Assembler/Linker Operating Notice Operating Notice Z8000 Assembler & Linker Supplement Documentation Assembly |
| 64854AR | 5958-6046 5958-6063 64854-90902 64980-99902 | R2510 R2604 MAR84 | | Right to Copy Operating Notice Operating Notice Z8000 Assembler & Linker Supplement Documentation Assembly |
| 64854AU | 5958-6046 | R2510 | | Z8000 Assembler/Linker Update Operating Notice |
| 64854AX | 5958-6046 5958-6063 64854-90902 64980-99902 | R2510 R2604 MAR84 | | One-Time Update Operating Notice Operating Notice Z8000 Assembler & Linker Supplement Documentation Assembly |
| 64854M/001 | 5958-6046 5958-6049 64854-99901 | R2510 R2510 | | Media and Manuals (500) Operating Notice Operating Notice Documentation Assembly |
| 64854M/003 | 5958-6046 5958-6049 64854-99902 | R2510 R2510 | | Media and Manuals (VAX) Operating Notice Operating Notice Documentation Assembly |
| 64854M/004 | 5958-6046 5958-6049 5958-8860 5958-8877 64854-99901 | R2510 R2510 R2605 R2608 | | Media and Manuals (300) Operating Notice Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64854S/001 | 64854-99901 | | | Z8000 Assembler (500) Documentation Assembly |
| 64854S/003 | 64854-99902 | | | Z8000 Assembler (VAX) Documentation Assembly |
| 64854S/004 | 64854-99901 | | | Z8000 Assembler (300) Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|---|
| 64854SR/001 | 64854-99901 | | | Right to Copy Documentation Assembly |
| 64854SR/003 | 64854-99902 | | | Right to Copy Documentation Assembly |
| 64854SR/004 | 64854-99901 | | | Right to Copy Documentation Assembly |
| 64854SX/001 | 64854-99901 | | | One-Time Update Documentation Assembly |
| 64854SX/003 | 64854-99902 | | | One-Time Update Documentation Assembly |
| 64854SX/004 | 64854-99901 | | | One-Time Update Documentation Assembly |
| 64855-99901 | 5958-8840 64855-90903 | R2801 SEP84 | | Documentation Assembly Software Notice 8051 Hosted Cross Assembler/Linker |
| 64855-99902 | 5958-8841 64855-90904 | R2801 SEP84 | | Documentation Assembly Software Notice 8051 Cross Assembler/Linker (VMS) |
| 64855-99903 | 5958-8839 64855-90905 | R2801 E1085 | | Documentation Assembly Software Notice 8051 Assembler/Linker Supplement |
| 64855AF | 5958-6046 5958-6063 64855-99903 | R2510 R2604 | | 8051 Assembler/Linker Operating Notice Operating Notice Documentation Assembly |
| 64855AR | 5958-6046 5958-6063 64855-99903 | R2510 R2604 | | Right to Copy Operating Notice Operating Notice Documentation Assembly |
| 64855AU | 5958-6046 | R2510 | | 8051 Assembler/Linker Update Operating Notice |
| 64855AX | 5958-6046 5958-6063 64855-99903 | R2510 R2604 | | One-Time Update Operating Notice Operating Notice Documentation Assembly |
| 64855M/001 | 5958-6046 5958-6049 5958-8877 64855-99901 | R2510 R2510 R2608 | | Media and Manuals (500) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64855M/003 | 5958-6046 5958-6049 64855-99902 | R2510 R2510 | | Media and Manuals (VAX) Operating Notice Operating Notice Documentation Assembly |
| 64855M/004 | 5958-6046 5958-6049 5958-8877 64855-99901 | R2510 R2510 R2608 | | Media and Manuals (300) Operating Notice Operating Notice Operating Notice Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--------------------------|----------------|--------|--|
| 64855S/001 | 64855-99901 | | | 8051 Assembler (500) Documentation Assembly |
| 64855S/003 | 64855-99902 | | | 8051 Assembler (VAX) Documentation Assembly |
| 64855S/004 | 64855-99901 | | | Media and Manuals (300) Documentation Assembly |
| 64855SR/001 | 64855-99901 | | | Right to Copy Documentation Assembly |
| 64855SR/003 | 64855-99902 | | | Right to Copy Documentation Assembly |
| 64855SR/004 | 64855-99901 | | | Right to Copy Documentation Assembly |
| 64855SX/001 | 64855-99901 | | | One-Time Update Documentation Assembly |
| 64855SX/003 | 64855-99902 | | | One-Time Update Documentation Assembly |
| 64855SX/004 | 64855-99901 | | | One-Time Update Documentation Assembly |
| 64856AF | 5958-6046 64856-90901 | R2510 E0986 | | Inverse Assembler Operating Notice User-Definable Inverse Assembler |
| 64856AR | 5958-6046 64856-90901 | R2510 E0986 | | Right to Copy Operating Notice User-Definable Inverse Assembler |
| 64856AU | 5958-6046 | R2510 | | 8051 Update Operating Notice |
| 64856AX | 5958-6046 64856-90901 | R2510 E0986 | | One-Time Update Operating Notice User-Definable Inverse Assembler |
| 64856M/004 | 5958-6046 64856-90901 | R2510 E0986 | | Media and Manuals (300) Operating Notice User-Definable Inverse Assembler |
| 64856S/004 | 64856-90901 | E0986 | | User Definable Inverse Assembler (300) User-Definable Inverse Assembler |
| 64856SR/004 | 64856-90901 | E0986 | | Right to Copy User-Definable Inverse Assembler |
| 64856SX/004 | 64856-90901 | E0986 | | One-Time Update User-Definable Inverse Assembler |
| 64857-99901 | 5958-8842 64857-90901 | R2707 OCT83 | | Documentation Assembly Software Notice MIL-STD-1750A Assembler & Linker |
| 64857-99902 | 5958-8843 64857-90902 | R2701 SEP84 | U0985 | Documentation Assembly Software Notice MIL-STD-1750A Assembler/Linker (UX) |
| 64857-99903 | | | | Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|----------------------------------|--------|---|
| | 5958-8844 64857-90903 | R2701 SEP84 | | Software Notice MIL-STD-1750A Assembler/Linker (VMS) |
| 64857A | 5958-6046 5958-6063 64857-99901 64980-99902 | R2510 R2604 | | 1750A-Mil-Std Assembler Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64857AR | 5958-6046 5958-6063 64857-99901 64980-99902 | R2510 R2604 | | Right to Copy Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64857AU | 5958-6046 | R2510 | | 1750A Update Operating Notice |
| 64857AX | 5958-6046 5958-6063 64857-99901 64980-99902 | R2510 R2604 | | One-Time Update Operating Notice Operating Notice Documentation Assembly Documentation Assembly |
| 64857M/001 | 5958-6046 5958-6049 5958-8877 64857-99902 | R2510 R2510 R2608 | | Media and Manuals (500) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64857M/003 | 5958-6046 5958-6049 64857-99903 | R2510 R2510 | | Media and Manuals (VAX) Operating Notice Operating Notice Documentation Assembly |
| 64857M/004 | 5958-6046 5958-6049 5958-8860 5958-8877 64857-99902 | R2510 R2510 R2605 R2608 | | Media and Manuals (300) Operating Notice Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64857S/001 | 64857-99902 | | | Mil-Std Assembler (500) Documentation Assembly |
| 64857S/003 | 64857-99903 | | | Mil-Std Assembler Documentation Assembly |
| 64857S/004 | 64857-99902 | | | Mil-Std Assembler (300) Documentation Assembly |
| 64857SR/001 | 64857-99902 | | | Right to Copy Documentation Assembly |
| 64857SR/003 | 64857-99903 | | | Right to Copy Documentation Assembly |
| 64857SR/004 | 64857-99902 | | | Right to Copy Documentation Assembly |
| 64857SX/001 | 64857-99902 | | | One-Time Update Documentation Assembly |
| 64857SX/003 | 64857-99903 | | | One-Time Update Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|----------------------------------|--------|---|
| 64857SX/004 | 64857-99902 | | | One-Time Update Documentation Assembly |
| 64858-99901 | 5958-8845 64858-90902 | R2701 SEP84 | | Documentation Assembly Software Notice TMS320 Cross Assembler/Linker (UX) |
| 64858-99902 | 5958-8846 64858-90903 | R2701 SEP84 | | Documentation Assembly Software Notice TMS320 Cross Assembler/Linker (VMS) |
| 64858A | 5958-6046 5958-6063 64858-90901 64980-99902 | R2510 R2604 OCT83 | | TMS320 Assembler Operating Notice Operating Notice TMS320 Assembler/Linker Supplement Documentation Assembly |
| 64858AR | 5958-6046 5958-6063 64858-90901 64980-99902 | R2510 R2604 OCT83 | | Right to Copy Operating Notice Operating Notice TMS320 Assembler/Linker Supplement Documentation Assembly |
| 64858AU | 5958-6046 | R2510 | | One-Time Update Operating Notice |
| 64858AX | 5958-6046 5958-6063 64858-90901 64980-99902 | R2510 R2604 OCT83 | | One-Time Update Operating Notice Operating Notice TMS320 Assembler/Linker Supplement Documentation Assembly |
| 64858M/001 | 5958-6046 5958-6049 5958-8877 64858-99901 | R2510 R2510 R2608 | | Media and Manuals (500) Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64858M/003 | 5958-6046 5958-6049 64858-99902 | R2510 R2510 | | Media and Manuals (VAX) Operating Notice Operating Notice Documentation Assembly |
| 64858M/004 | 5958-6046 5958-6049 5958-8860 5958-8877 64858-99901 | R2510 R2510 R2605 R2608 | | Media and Manuals (300) Operating Notice Operating Notice Operating Notice Operating Notice Documentation Assembly |
| 64858S/001 | 64858-99901 | | | 500 TMS320 Assembler Documentation Assembly |
| 64858S/003 | 64858-99902 | | | TMS320 Assembler (VAX) Documentation Assembly |
| 64858S/004 | 64858-99901 | | | TMS320 Assembler (300) Documentation Assembly |
| 64858SR/001 | 64858-99901 | | | Right to Copy Documentation Assembly |
| 64858SR/003 | 64858-99902 | | | Right to Copy Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|-------------------------|--------|--|
| 64858SR/004 | 64858-99901 | | | Right to Copy Documentation Assembly |
| 64858SX/001 | 64858-99901 | | | One-Time Update Documentation Assembly |
| 64858SX/003 | 64858-99902 | | | One-Time Update Documentation Assembly |
| 64858SX/004 | 64858-99901 | | | One-Time Update Documentation Assembly |
| 64859A | 5958-6046 64859-90901 64859-90902 | R2510 E0786 E0686 | | 80286 Assembler Operating Notice 80286 Linker HP 64000/9000/HP-UX/VAX 80286 Assembler |
| 64859AR | 5958-6046 64859-90901 64859-90902 | R2510 E0786 E0686 | | Right to Copy Operating Notice 80286 Linker HP 64000/9000/HP-UX/VAX 80286 Assembler |
| 64859AX | 5958-6046 64859-90901 64859-90902 | R2510 E0786 E0686 | | One-Time Update Operating Notice 80286 Linker HP 64000/9000/HP-UX/VAX 80286 Assembler |
| 64859M/001 | 5958-6046 5958-6049 | R2510 R2510 | | 500 Media and Manuals Operating Notice Operating Notice |
| 64859M/003 | 5958-6046 5958-6049 | R2510 R2510 | | VAX Media and Manuals Operating Notice Operating Notice |
| 64859M/004 | 5958-6046 5958-6049 5958-8860 | R2510 R2510 R2605 | | 300 Media and Manuals Operating Notice Operating Notice Operating Notice |
| 64860-99901 | 64860-90901 | E0688 | U0985 | Documentation Assembly HP 64860 Cross Assemb/Lnkr:8096/80C196 User's Guide |
| 64860-99902 | 64740-90912 64860-90904 | E0688 E0588 | | Documentation Assembly HP 64000 Support Services 8096/80C196 User's Guide |
| 64860-99903 | 64740-90912 64860-90905 | E0688 E0588 | | Documentation Assembly HP 64000 Support Services 8096/80C196 Assembler/Linker |
| 64860-99904 | 64860-90906 | E0588 | | Documentation Assembly 8096/80C196 Cross Assembler/Linker User's Guide (VAX) |
| 64860A | 64860-99901 | | | 8096 Assembler Documentation Assembly |
| 64860AR | 64860-99901 | | | Right to Copy Documentation Assembly |
| 64860AX | 64860-99901 | | | One-Time Update Documentation Assembly |
| 64860M/001 | | | | Media and Manuals (300) |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|-----------------|---------|--------|--------------------------------------|
| | 5958-6049 | R2510 | | Operating Notice |
| | 5958-8877 | R2608 | | Operating Notice |
| | 64860-99903 | | | Documentation Assembly |
| 64860M/003 | 5958-6049 | R2510 | | Media and Manuals (VAX) |
| | 64860-99904 | | | Operating Notice |
| | | | | Documentation Assembly |
| 64860M/004 | 5958-6049 | R2510 | | Media and Manual (300) |
| | 5958-8860 | R2605 | | Operating Notice |
| | 5958-8877 | R2608 | | Operating Notice |
| | 64860-99903 | | | Operating Notice |
| | | | | Documentation Assembly |
| 64860S/006 | 64860-99902 | | | 8096/80196 Assembler/Linker |
| | | | | Documentation Assembly |
| 64860SX/006 | 64860-99902 | | | One Time Update for 64860S/006 |
| | | | | Documentation Assembly |
| 64861A | 5958-6046 | R2510 | | User Micro Assembler |
| | 5958-6063 | R2604 | | Operating Notice |
| | 5958-8879 | R2610 | | Operating Notice |
| | 64861-90901 | E1185 | | Software Notice |
| | 64980-99902 | | | User Definable Microassembler/Linker |
| | | | | Documentation Assembly |
| 64861AR | 5958-6046 | R2510 | | Right to Copy |
| | 5958-6063 | R2604 | | Operating Notice |
| | 5958-8879 | R2610 | | Operating Notice |
| | 64861-90901 | E1185 | | Software Notice |
| | 64980-99902 | | | User Definable Microassembler/Linker |
| | | | | Documentation Assembly |
| 64861AX | 5958-6046 | R2510 | | One-Time Update |
| | 5958-6063 | R2604 | | Operating Notice |
| | 5958-8879 | R2610 | | Operating Notice |
| | 64861-90901 | E1185 | | Software Notice |
| | 64980-99902 | | | User Definable Microassembler/Linker |
| | | | | Documentation Assembly |
| 64861M/001 | 5958-6046 | R2510 | | 500 Media and Manuals |
| | 5958-6049 | R2510 | | Operating Notice |
| | | | | Operating Notice |
| 64861M/003 | 5958-6046 | R2510 | | Media and Manuals (VAX) |
| | 5958-6049 | R2510 | | Operating Notice |
| | 64851-99903 | | | Operating Notice |
| | | | | Documentation Assembly |
| 64861M/004 | 5958-6046 | R2510 | | Media and Manuals (300) |
| | 5958-6049 | R2510 | | Operating Notice |
| | 64851-99902 | | | Operating Notice |
| | | | | Documentation Assembly |
| 64861S/003 | 64851-99903 | | | Micro Assembler (VMS) |
| | | | | Documentation Assembly |
| 64861S/004 | 64851-99902 | | | Micro Assembler (300) |
| | | | | Documentation Assembly |
| 64861SR/004 | 64851-99902 | | | Right to Copy |
| | | | | Documentation Assembly |
| 64861SX/001 | | | | One-Time Update |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---------------------------------------|-------------------------|--------|--|
| | 64851-99902 | | | Documentation Assembly |
| 64861SX/003 | 64851-99903 | | | One-Time Update Documentation Assembly |
| 64861SX/004 | 64851-99902 | | | One-Time Update Documentation Assembly |
| 64864A | 5958-6046 5958-6063 64980-99902 | R2510 R2604 | | 64180 Assembler/Linker Operating Notice Operating Notice Documentation Assembly |
| 64864AR | 5958-6046 5958-6063 64980-99902 | R2510 R2604 | | Right to Copy Operating Notice Operating Notice Documentation Assembly |
| 64865A | 5958-6046 64865-90901 | R2510 E0986 | | 68HC11 Assembler Operating Notice 68HC11 Cross Assembler/Linker |
| 64865AR | 5958-6046 64865-90901 | R2510 E0986 | | Right to Copy Operating Notice 68HC11 Cross Assembler/Linker |
| 64865AX | 5958-6046 64865-90901 | R2510 E0986 | | One-Time Update Operating Notice 68HC11 Cross Assembler/Linker |
| 64865M/001 | 5958-6046 5958-6049 64865-90901 | R2510 R2510 E0986 | | Media and Manuals (500) Operating Notice Operating Notice 68HC11 Cross Assembler/Linker |
| 64865M/003 | 5958-6046 5958-6049 64865-90901 | R2510 R2510 E0986 | | Media and Manuals (VAX) Operating Notice Operating Notice 68HC11 Cross Assembler/Linker |
| 64865M/004 | 5958-6046 5958-6049 64865-90901 | R2510 R2510 E0986 | | Media and Manuals (300) Operating Notice Operating Notice 68HC11 Cross Assembler/Linker |
| 64865S/001 | 5958-6046 64865-90901 | R2510 E0986 | | 68HC11 Assembler (500) Operating Notice 68HC11 Cross Assembler/Linker |
| 64865S/003 | 5958-6046 64865-90901 | R2510 E0986 | | 68HC11 Assembler (VAX) Operating Notice 68HC11 Cross Assembler/Linker |
| 64865S/004 | 5958-6046 64865-90901 | R2510 E0986 | | 68HC11 Assembler (300) Operating Notice 68HC11 Cross Assembler/Linker |
| 64865SR/001 | 5958-6046 64865-90901 | R2510 E0986 | | Right to Copy Operating Notice 68HC11 Cross Assembler/Linker |
| 64865SR/003 | 5958-6046 64865-90901 | R2510 E0986 | | Right to Copy Operating Notice 68HC11 Cross Assembler/Linker |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|---|--------|--|
| 64865SR/004 | 5958-6046 64865-90901 | R2510 E0986 | | Right to Copy Operating Notice 68HC11 Cross Assembler/Linker |
| 64865SX/001 | 5958-6046 64865-90901 | R2510 E0986 | | One-Time Update Operating Notice 68HC11 Cross Assembler/Linker |
| 64865SX/003 | 5958-6046 64865-90901 | R2510 E0986 | | One-Time Update Operating Notice 68HC11 Cross Assembler/Linker |
| 64865SX/004 | 5958-6046 64865-90901 | R2510 E0986 | | One-Time Update Operating Notice 68HC11 Cross Assembler/Linker |
| 64866A | 5958-6046 5958-6063 64980-99902 | R2510 R2604 | | 78310 Assembler/Linker Operating Notice Operating Notice Documentation Assembly |
| 64866AR | 5958-6046 5958-6063 64980-99902 | R2510 R2604 | | Right to Copy Operating Notice Operating Notice Documentation Assembly |
| 64867-99901 | 64740-90912 64867-90901 | E0688 E0588 | | Documentation Assembly HP 64000 Support Services PC Hosted Assembler/Linker User's Guide |
| 64867-99902 | 5959-2184 64740-90912 64867-90902 | E0288 E0688 E0488 | | Documentation Assembly Map Unix HP 64000 Support Services TMS32020/C25 Assembler/Linker User's Guide |
| 64867M/004 | 64867-99902 | | | Media and Manual (300) Documentation Assembly |
| 64867S/006 | 64867-99901 | | | 64867 Hosted on PC Documentation Assembly |
| 64867SX/006 | 64867-99901 | | | One Time Update Documentation Assembly |
| 64870-99901 | 5959-2108 64740-90904 64800-90910 64870-90901 64870-90902 | R2703 E1187 E0488 E0488 E0488 | | Documentation Assembly Operating Notice Terminal Interface: Support Services BTO-MNOP 68000/10/20 AssyLink/Libr Ref 68000/10/20 Assmb/Lnkr/Libr HP-UX Users Guide |
| 64870M/004 | 5958-6049 5959-2121 64870-99901 | R2510 R2707 | | Media and Manuals (300) Operating Notice Operating Notice Documentation Assembly |
| 64870M/005 | 64870-99901 | | | 68000/20 ASM Media and Manual Documentation Assembly |
| 64870S/001 | 64870-99901 | | | 68000/08/10/20 Documentation Assembly |
| 64870S/003 | 64870-99901 | | | 68000/08/10/20 Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|--|-------------------------|--------|--|
| 64870S/004 | 64870-99901 | | | 68000/08/10/20 Assembler/Linker Documentation Assembly |
| 64870SR/001 | 64870-99901 | | | Right to Copy Documentation Assembly |
| 64870SR/003 | 64870-90901 | E0488 | | Right to Copy 68000/10/20 AssyLink/Libr Ref |
| 64870SR/004 | 64870-99901 | | | Right to Copy Documentation Assembly |
| 64870SX/001 | 64870-99901 | | | One-Time Update Documentation Assembly |
| 64870SX/003 | 64870-90901 | E0488 | | 78310 Assembler Linker 68000/10/20 AssyLink/Libr Ref |
| 64870SX/004 | 64870-99901 | | | One-Time Update Documentation Assembly |
| 64871-99901 | 64740-90912 64871-90901 64871-90902 | E0688 E0588 E0588 | | Documentation Assembly HP 64000 Support Services BTO-MNOP BTO-MNOP |
| 64871M/004 | 64871-99901 | | | Media and Manual (300) Documentation Assembly |
| 64880-99902 | 64880-90902 | E0787 | U0688 | Documentation Assembly Development System User's Guide |
| 64880A | 64801-90909 64880-90901 | E1186 E0488 | | HP9000/500 Host HP Support Services 68000/10/20 AssyLink/Libr Ref |
| 64880AR | 64801-90909 64880-90901 64880-99902 | E1186 E0488 | | Right to Copy HP Support Services 68000/10/20 AssyLink/Libr Ref Documentation Assembly |
| 64880AX | 64801-90909 64880-90901 64880-90903 64880-99902 | E1186 E0488 E0687 | | One-Time Update HP Support Services 68000/10/20 AssyLink/Libr Ref Development System File Formats Documentation Assembly |
| 64880M/001 | 5958-6063 64801-90909 64880-90901 | R2604 E1186 E0488 | | Media and Manuals (500) Operating Notice HP Support Services 68000/10/20 AssyLink/Libr Ref |
| 64882-99902 | 64882-90902 | E0986 | | Documentation Assembly Development System User's Guide |
| 64882-99903 | 5958-8866 64882-90903 | R2610 E1086 | | Documentation Assembly Software Notice Development System File Formats |
| 64882-99904 | 64882-90904 | E0487 | U0987 | Documentation Assembly Development System Installation (VMS) |
| 64882A | 5958-6063 | R2604 | | VAX/VMS Host Operating Notice |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|-----------------|---------|--------|---------------------------------|
| | 64882-99902 | | | Documentation Assembly |
| | 64882-99903 | | | Documentation Assembly |
| | 64882-99904 | | | Documentation Assembly |
| 64882AR | | | | Right to Copy |
| | 64882-99902 | | | Documentation Assembly |
| | 64882-99903 | | | Documentation Assembly |
| | 64882-99904 | | | Documentation Assembly |
| 64882AX | 5958-6063 | R2604 | | One-Time Update |
| | 64882-99902 | | | Operating Notice |
| | 64882-99903 | | | Documentation Assembly |
| | 64882-99904 | | | Documentation Assembly |
| 64882M/003 | 5958-6063 | R2604 | | VAX Media and Manuals |
| | 64882-99902 | | | Operating Notice |
| | 64882-99903 | | | Documentation Assembly |
| | 64882-99904 | | | Documentation Assembly |
| 64883A | 64801-90909 | E1186 | | Software for 300 Host |
| | 64880-90901 | E0488 | | HP Support Services |
| | 64880-90903 | E0687 | | 68000/10/20 AssyLink/Libr Ref |
| | 64882-99902 | | | Development System File Formats |
| | | | | Documentation Assembly |
| 64883AR | 64801-90909 | E1186 | | Right to Copy |
| | 64880-90901 | E0488 | | HP Support Services |
| | 64880-90903 | E0687 | | 68000/10/20 AssyLink/Libr Ref |
| | 64880-99902 | | | Development System File Formats |
| | | | | Documentation Assembly |
| 64883AX | 64801-90909 | E1186 | | One-Time Update |
| | 64880-90901 | E0488 | | HP Support Services |
| | 64880-90903 | E0687 | | 68000/10/20 AssyLink/Libr Ref |
| | 64880-99902 | | | Development System File Formats |
| | | | | Documentation Assembly |
| 64883M/004 | 5958-8860 | R2605 | | 300 Media and Manuals |
| | 64801-90909 | E1186 | | Operating Notice |
| | 64880-90901 | E0488 | | HP Support Services |
| | 64880-90903 | E0687 | | 68000/10/20 AssyLink/Libr Ref |
| | 64880-99902 | | | Development System File Formats |
| | | | | Documentation Assembly |
| 64884A | 64801-90909 | E1186 | | RS232 Transfer (500) |
| | 64880-90901 | E0488 | | HP Support Services |
| | 64880-90903 | E0687 | | 68000/10/20 AssyLink/Libr Ref |
| | 64880-99902 | | | Development System File Formats |
| | | | | Documentation Assembly |
| 64884AR | 64801-90909 | E1186 | | Right to Copy |
| | 64880-90903 | E0687 | | HP Support Services |
| | 64880-99902 | | | Development System File Formats |
| | | | | Documentation Assembly |
| 64884AX | 64801-90909 | E1186 | | One-Time Update |
| | 64880-90901 | E0488 | | HP Support Services |
| | 64880-90903 | E0687 | | 68000/10/20 AssyLink/Libr Ref |
| | 64880-99902 | | | Development System File Formats |
| | | | | Documentation Assembly |
| 64884M/001 | 64801-90909 | E1186 | | Media and Manuals (500) |
| | | | | HP Support Services |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|-----------------|---------|--------|---------------------------------|
| | 64880-90901 | E0488 | | 68000/10/20 AssyLink/Libr Ref |
| | 64880-90903 | E0687 | | Development System File Formats |
| | 64880-99902 | | | Documentation Assembly |
| 64885A | | | | RS232 Transfer (300) |
| | 64801-90909 | E1186 | | HP Support Services |
| | 64880-90901 | E0488 | | 68000/10/20 AssyLink/Libr Ref |
| | 64880-90903 | E0687 | | Development System File Formats |
| | 64880-99902 | | | Documentation Assembly |
| 64885AR | | | | Right to Copy |
| | 64801-90909 | E1186 | | HP Support Services |
| | 64880-90901 | E0488 | | 68000/10/20 AssyLink/Libr Ref |
| | 64880-90903 | E0687 | | Development System File Formats |
| | 64880-99902 | | | Documentation Assembly |
| 64885AX | | | | One-Time Update |
| | 64801-90909 | E1186 | | HP Support Services |
| | 64880-90901 | E0488 | | 68000/10/20 AssyLink/Libr Ref |
| | 64880-90903 | E0687 | | Development System File Formats |
| | 64880-99902 | | | Documentation Assembly |
| 64885M/004 | | | | Media and Manuals (300) |
| | 5958-8860 | R2605 | | Operating Notice |
| | 64801-90909 | E1186 | | HP Support Services |
| | 64880-90901 | E0488 | | 68000/10/20 AssyLink/Libr Ref |
| | 64880-90903 | E0687 | | Development System File Formats |
| | 64880-99902 | | | Documentation Assembly |
| 64886A | | | | RS232 Transfer VAX |
| | 64882-99902 | | | Documentation Assembly |
| | 64882-99903 | | | Documentation Assembly |
| 64886AR | | | | Right to Copy |
| | 64882-99902 | | | Documentation Assembly |
| | 64882-99903 | | | Documentation Assembly |
| 64886AX | | | | One-Time Update |
| | 64882-99902 | | | Documentation Assembly |
| | 64882-99903 | | | Documentation Assembly |
| 64886M/003 | | | | Media and Manual (VAX) |
| | 64882-99902 | | | Documentation Assembly |
| | 64882-99903 | | | Documentation Assembly |
| 64887-99901 | | | | Documentation Assembly |
| | 64801-90909 | E1186 | | HP Support Services |
| | 64887-90901 | E0187 | U0387 | Network Transfer |
| 64887-99902 | | | | Documentation Assembly |
| | 64801-90909 | E1186 | | HP Support Services |
| | 64887-90901 | E0187 | U0387 | Network Transfer |
| 64887M/003 | | | | Media and Manual (VAX) |
| | 64887-99902 | | | Documentation Assembly |
| 64887M/004 | | | | Media and Manual (300) |
| | 64887-99901 | | | Documentation Assembly |
| 64887S/003 | | | | Network Transfer VAX |
| | 64887-99902 | | | Documentation Assembly |
| 64887S/004 | | | | Network Transfer (300) |
| | 64887-99901 | | | Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---|-------------------------|--------|--|
| 64887SR/003 | 64887-99902 | | | Right to Copy Documentation Assembly |
| 64887SR/004 | 64887-99901 | | | Right to Copy Documentation Assembly |
| 64887SX/003 | 64887-99902 | | | One-Time Update Documentation Assembly |
| 64887SX/004 | 64887-99901 | | | One-Time Update Documentation Assembly |
| 64888M/001 | 64888-90901 | E1087 | | Media and Manuals (500) File Format Converter |
| 64888M/003 | 64888-90901 | E1087 | | Media and Manuals (VAX) File Format Converter |
| 64888M/004 | 64888-90901 | E1087 | | Media and Manuals (300) File Format Converter |
| 64888S/001 | 64801-90909 64888-90901 | E1186 E1087 | | Utility Package (500) HP Support Services File Format Converter |
| 64888S/003 | 64801-90909 64888-90901 | E1186 E1087 | | Utility Package (VAX) HP Support Services File Format Converter |
| 64888S/004 | 64801-90909 64888-90901 | E1186 E1087 | | Utility Package (300) HP Support Services File Format Converter |
| 64888SR/001 | 64801-90909 64888-90901 | E1186 E1087 | | Right to Copy HP Support Services File Format Converter |
| 64888SR/003 | 64801-90909 64888-90901 | E1186 E1087 | | Right to Copy HP Support Services File Format Converter |
| 64888SR/004 | 64801-90909 64888-90901 | E1186 E1087 | | Right to Copy HP Support Services File Format Converter |
| 64888SX/001 | 64801-90909 64888-90901 | E1186 E1087 | | One-Time Update HP Support Services File Format Converter |
| 64888SX/003 | 64801-90909 64888-90901 | E1186 E1087 | | One-Time Update HP Support Services File Format Converter |
| 64888SX/004 | 64801-90909 64888-90901 | E1186 E1087 | | One-Time Update HP Support Services File Format Converter |
| 64902-13521 | 5959-6240 | R2807 | | 680XX C Cont. SW Operating Notice for 64902-13521 |
| 64902-99901 | 5959-2191 64740-90912 64800-90910 | E1088 E0688 E0488 | | Documentation Assembly Operating Notice for HP 64902 Options 004 and 005 HP 64000 Support Services BTO-MNOP |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|-----------------|---------|--------|--|
| | 64902-90901 | E1088 | | 68000 C Cross Compiler |
| | 64902-90902 | E1088 | | 68000 C Cross Compiler User's Guide (UX) |
| 64902M/004 | 64902-13521 | | | Media and Manual (300) |
| | 64902-99901 | | | 680XX C Cont. SW |
| | 9320-4991 | 1978 | | Documentation Assembly The C Programming Language |
| 64902M/005 | 64800-90910 | E0488 | | 68000 AxLS C Media & Manual |
| | 64902-99901 | | | BTO-MNOP |
| | 9320-4991 | 1978 | | Documentation Assembly The C Programming Language |
| 64902S/004 | 64902-13521 | | | 64902 Host Interface on Series (300) |
| | 64902-99901 | | | 680XX C Cont. SW |
| | | | | Documentation Assembly |
| 64902SR/004 | 64902-99901 | | | Right to Copy |
| | | | | Documentation Assembly |
| 64902SX/004 | 64902-13521 | | | One-Time Update (300) |
| | 64902-99901 | | | 680XX C Cont. SW |
| | | | | Documentation Assembly |
| 64903-99901 | 5959-2140 | E1088 | | Documentation Assembly |
| | 64740-90912 | E0688 | | Operating Notice for HP 64903 Options 004 and 005 |
| | 64800-90910 | E0488 | | HP 64000 Support Services |
| | 64903-90901 | E1088 | | BTO-MNOP |
| | 64903-90902 | E1088 | | 68020 C Cross Compiler |
| | | | | 68020 C Cross Compiler |
| 64903M/004 | 64903-99901 | | | Media and Manual (300) |
| | 9320-4991 | 1978 | | Documentation Assembly |
| | | | | The C Programming Language |
| 64903M/005 | 64800-90910 | E0488 | | 68020 AxLS C Media & Manual |
| | 64903-99901 | | | BTO-MNOP |
| | 9320-4991 | 1978 | | Documentation Assembly |
| | | | | The C Programming Language |
| 64903S/004 | 64903-99901 | | | C 68020 (300) |
| | | | | Documentation Assembly |
| 64903SR/004 | 64903-99901 | | | Right to Copy |
| | | | | Documentation Assembly |
| 64903SX/004 | 64903-99901 | | | One-Time Update |
| | | | | Documentation Assembly |
| 64904-99901 | 64740-90912 | E0688 | | Documentation Assembly |
| | 64904-90901 | E0988 | | HP 64000 Support Services |
| | 64904-90902 | E0988 | | BTO-MNOP |
| | 64904-99901 | | | BTO-MNOP |
| | | | | Documentation Assembly |
| 64904M/004 | 64904-99901 | | | Media and Manual (300) |
| | | | | Documentation Assembly |
| 64934A | 64110-90903 | JUL82 | | Common PSP Mainframe |
| | 64932-90904 | OCT81 | | 64100A POWER SUPPLY TEST BOARD |
| | 64934-90902 | JAN83 | | Disc Diagnostic Package |
| | | | | Disc to Disc Transfer |
| 64934B | 64934-90901 | FEB83 | | State / Timing PSP |
| | | | | State & Timing Support Package |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|---------------------------------------|-------------------------|--------|---|
| 64941-99901 | 64941-90906 64941-90907 | JAN84 E1287 | | Documentation Assembly Flexible Disc Drives Floppy Disk Sub-Assembly |
| 64941A | 64941-99901 | | | Floppy Disk Sub-Assembly Documentation Assembly |
| 64971-99901 | 64882-90904 | E0487 | U0987 | Documentation Assembly Development System Installation (VMS) |
| 64971-99902 | 64801-90907 | E0787 | | Documentation Assembly Software Installation |
| 64971S/003 | 64971-99901 | | | Host Interface VAX/VMS Documentation Assembly |
| 64971S/004 | 64971-99902 | | | Host Interface Series (300) Documentation Assembly |
| 64971S/006 | 64971-99903 | | | PC Hosted Documentation Assembly |
| 64980-99901 | 5958-8848 64980-90935 | R2606 JAN85 | | Documentation Assembly Software Notice Terminal Mode |
| 64980-99902 | 5958-8849 64980-90997 | R2701 E1185 | | Documentation Assembly Software Notice Assembler and Linker Reference |
| 64980-99932 | 5958-8885 64980-90932 | R2610 FEB84 | | Documentation Assembly Software Notice 68000/10 Emulation with Internal Analysis |
| 64980-99934 | 5958-8892 5959-2127 64980-90934 | R2610 R2707 E1186 | | Documentation Assembly Software Notice Software Notice System Software Reference |
| 64980A/001 | 64202-90902 64203-90902 | E0985 E0582 | U1286 | 8080 Emulation Pod 8085 Emulation Pod |
| B1400A/0A6 | 64716-99901 64723-99901 | | | 10 User Series (300) Documentation Assembly Documentation Assembly |
| B1400A/0AE | 64716-99901 64723-99901 | | | 15 User Series (300) Documentation Assembly Documentation Assembly |
| B1400A/0AF | 64716-99901 64723-99901 | | | 20 User Series (300) Documentation Assembly Documentation Assembly |
| B1402A | 64710-99901 | | | Structured Analysis (300) Documentation Assembly |
| B1404A | 64716-99901 | | | Information Modeling (300) Documentation Assembly |
| B1405A | 64720-99901 | | | Structure Design (300) Documentation Assembly |

| Product/Assembly # | Assembly/Part # | Edition | Update | Description |
|--------------------|----------------------------|---------|--------|---|
| B1407A | 64710-99901 | | | Structured Analysis (800) Documentation Assembly |
| B1408A | 64715-99901 | | | Realtime (800) Documentation Assembly |
| B1409A | 64716-99901 | | | Information Modeling (300) Documentation Assembly |
| B1410A | 64720-99901 | | | Structure Design (800) Documentation Assembly |
| B1412A | 64716-99901 64723-99901 | | | 5 User Ug (300) Documentation Assembly Documentation Assembly |
| | 64297S/004 64846AX | | | 9000 Host Interface (300) One-Time Update |

| Part Number | Change Sheet Issue Code | Change Sheet Issue Date | Description |
|-------------|-------------------------|---|---|
| 64032-90901 | A | April 30, 1984 | 16K MEMORY EXPANSION MODULE |
| 64050-90901 | A B | February 22, 1983 March 08, 1984 | Screen Printer Interface |
| 64191-90901 | A | January 20, 1984 | 6805 SERIES EMULATION CONTROL |
| 64192-90901 | A | May 21, 1984 | 6805R/U Emulation Pod |
| 64193-90901 | A | May 21, 1983 | 6805P Emulation Pod |
| 64193-90903 | A | August 01, 1983 | 6805P Emulation with Internal Analysis |
| 64210-90906 | A | April 15, 1983 | 6800/6802 Emulation with Internal Analysis |
| 64211-90902 | A | May 14, 1984 | 6800/6802 Emulator Control |
| 64214-90901 | A | June 29, 1983 | 6809/6809E Emulator Control |
| 64214-90903 | A | February 01, 1983 | 6809/6809E Emulation with Internal Analysis |
| 64215-90902 | A B | July 26, 1983 November 08, 1983 | 6809 Emulator Pod |
| 64216-90901 | A B C | August 04, 1983 January 30, 1984 September 14, 1984 | 6809E Emulator Pod |
| 64232-90902 | A B | August 02, 1983 November 08, 1983 | Z8001 Emulation Pod |
| 64242-90903 | A | March 07, 1984 | 68000 Emulator Pod |
| 64251-90901 | A | July 31, 1984 | Z80 Emulator Control |
| 64252-90902 | A B | September 06, 1983 November 08, 1983 | Z80 Emulator Pod |
| 64255-90905 | A | March 02, 1984 | 6801/6803 Emulation Control |
| 64256-90903 | A | March 24, 1984 | 6801/6803 Emulator Pod |
| 64261-90901 | A | August 29, 1983 | 8048 Series Emulator Control |

| Part Number | Change Sheet Issue Code | Change Sheet Issue Date | Description |
|-------------|-------------------------|--|---|
| 64262-90901 | A B C | October 05, 1982 August 29, 1983 November 08, 1983 | 8048 Series Emulator Pod |
| 64271-90902 | A | March 22, 1985 | General Purpose Emulator Control |
| 64272-90901 | A B | April 28, 1983 March 07, 1984 | ROM Emulator Pod |
| 64274-90901 | A | November 19, 1982 | User Definable Emulation with Internal Analysis |
| 64274-90902 | B | November 01, 1983 | User-Definable Emulation with Internal Analysis |
| 64292-90902 | B | August 27, 1984 | NSC800 Emulator Pod |
| 64292-90903 | A | July 29, 1983 | NSC800 Emulation with Internal Analysis |
| 64300-90904 | A | May 16, 1984 | Internal Logic Analyzer |
| 64303-90902 | A | March 07, 1984 | IMB Extender |
| 64304-90901 | A | April 30, 1984 | Emulation Bus Preprocessor |
| 64310-90901 | A | May 23, 1984 | Software Performance Analyzer |
| 64310-90902 | A | November 15, 1983 | Software Performance Analyzer |
| 64500-90911 | A B | April 30, 1984 August 07, 1984 | Positive PROM Programmer |
| 64502-90903 | A | October 25, 1982 | PROM Programmer Module (2716) |
| 64507-90901 | A | January 23, 1980 | PROM Programmer Module (2704/2708) |
| 64514-90901 | A | October 29, 1984 | PROM Programmer Module (68764/766) |
| 64601-90904 | A B | December 12, 1983 March 08, 1984 | Timing/Hardware Analyzer Control |
| 64622-90902 | A | March 07, 1984 | 40 Channel State Acquisition |
| 64623-90902 | A | March 07, 1984 | 20 Channel State Acquisition |
| 64635-90901 | A | March 08, 1984 | 20 Channel Data Probe |

| Part Number | Change Sheet | Issue Code | Change Sheet Issue Date | Description |
|-------------|--------------|------------|-------------------------|--|
| 64650-90905 | | A | April 12, 1984 | General Purpose Preprocessor |
| 64811-90903 | | A | December 17, 1984 | 6800/01/02/03 Pascal Cross Compiler |
| | | B | June 01, 1985 | |
| 64811-90904 | | A | December 17, 1984 | 6800/01/02/03 Pascal Compiler (VMS) |
| 64816-90903 | | B | March 01, 1984 | 28001/Z8002 Pascal Compiler Supplement |
| 64816-90904 | | A | December 01, 1984 | 28001/Z8002 Pascal Cross Compiler (UX) |
| | | B | June 01, 1985 | |
| 64816-90905 | | A | December 01, 1984 | 28001/Z8002 Pascal Cross Compiler (VMS) |
| 64820-90901 | | A | November 01, 1983 | 28001/Z8002 C Compiler Supplement |
| 64821-90901 | | B | October 01, 1983 | 6800 C Compiler Supplement |
| 64822-90902 | | A | April 04, 1985 | 6809/6809E C Compiler Supplement (UX) |
| 64823-90902 | | A | December 01, 1984 | Z80/NSC800 Pascal Cross Compiler (UX) |
| | | B | June 01, 1985 | |
| 64823-90903 | | A | December 01, 1984 | Z80/NSC800 Pascal Cross Compiler (VMS) |
| 64825-90902 | | A | December 01, 1984 | 8085 Hosted Pascal Compiler (UX) |
| | | B | June 01, 1985 | |
| 64825-90903 | | A | December 01, 1984 | 8085 Pascal Cross Compiler (VMS) |
| 64830-90902 | | A | July 09, 1981 | Emulation Terminal Supplement (Tape) |
| 64840-90902 | | A | December 01, 1984 | 8080/8085 Cross Assembler/Linker |
| | | B | June 01, 1985 | |
| 64840-90903 | | A | December 01, 1984 | 8080/8085 Cross Assembler/Linker (VMS) |
| 64841-90906 | | A | December 01, 1984 | 68000 Series Assembler/Linker |
| | | B | June 01, 1985 | |
| 64841-90907 | | A | December 01, 1984 | 6800 Series Cross Assembler/Linker (VMS) |
| 64842-90904 | | A | December 01, 1984 | Z80/NSC800 Cross Assembler/Linker |
| | | B | June 01, 1985 | |

Page 4

| Part Number | Change Sheet Issue Code | Change Sheet Issue Date | Description |
|-------------|-------------------------|-------------------------|--|
| 64842-90905 | A | December 01, 1984 | Z80/NSC800 Cross Assembler/Linker (VMS) |
| 64843-90903 | A | December 01, 1984 | 6500 Series Cross Assembler/linker (UX) |
| | B | June 01, 1985 | |
| 64843-90904 | A | December 01, 1984 | 6500 Series Cross Assembler/Linker (VMS) |
| 64844-90905 | A | December 01, 1984 | 6805/09/09E Cross Assembler/Linker |
| | B | June 01, 1985 | |
| 64844-90906 | A | December 01, 1984 | 6805/09/09E Cross Assembler/Linker (VMS) |
| 64846-90903 | A | December 01, 1984 | 8048 Cross Assembler/Linker (UX) |
| | B | June 01, 1985 | |
| 64846-90904 | A | December 01, 1984 | 8048 Cross Assembler/Linker (VMS) |
| 64847-90903 | A | August 19, 1983 | 9900 Series Assembler/Linker Supplement |
| | B | June 01, 1985 | |
| 64847-90904 | A | December 01, 1984 | 9900/99000 Cross Assembler/Linker (UX) |
| | B | June 01, 1985 | |
| 64847-90905 | A | December 01, 1984 | 9900/99000 Cross Assembler/Linker (VMS) |
| 64849-90902 | A | October 29, 1980 | F3870/F38E70/F8 Assembler & Linker |
| 64854-90903 | A | December 01, 1984 | Z8001/Z8002 Cross Assembler/Linker (UX) |
| | B | June 01, 1985 | |
| 64854-90904 | A | December 01, 1984 | Z8001/Z8002 Cross Assembler?linker (VMS) |
| 64855-90903 | A | December 01, 1984 | 8051 Hosted Cross Assembler/Linker |
| | B | June 01, 1985 | |
| 64855-90904 | A | December 01, 1984 | 8051 Cross Assembler/Linker (VMS) |
| 64857-90901 | A | February 07, 1984 | MIL-STD-1750A Assembler & Linker |
| 64857-90903 | A | December 01, 1984 | MIL-STD-1750A Assembler/Linker (VMS) |
| 64858-90902 | A | December 01, 1984 | TMS320 Cross Assembler/Linker (UX) |
| | B | June 01, 1985 | |
| 64858-90903 | A | December 01, 1984 | TMS320 Cross Assembler/Linker (VMS) |

Logic Systems Division

Change Sheet Catalog

October 24, 1988

Page 5

| Part Number | Change Sheet Issue Code | Change Sheet Issue Date | Description |
|-------------|-------------------------|---------------------------------------|--|
| 64934-90902 | A | October 01, 1984 | Disc to Disc Transfer |
| 64940-90905 | A | April 30, 1984 | Tape Control and Drive |
| 64980-90929 | A B | November 03, 1983 October 01, 1984 | Installation and Configuration Reference |
| 64980-90931 | A | February 04, 1985 | 8086/8088 Emulation with Internal Analysis |



HEWLETT
PACKARD

5958-6021, November 1988
E1188

Printed in U.S.A.