Workstation Architecture

by R. Belleville, Mgr. Advanced Design

- 1. Workstation Requirements and Goals
- 2. Discussion of alternative approaches
- 3. The concept of a synchronous multi-tasking processor
- 4. The Dandelion Workstation
- 5. The Cub Workstation

Workstation-Architecture.bravo

Star Workstation Constraints


- 1. Support large format display (1024x808)
- 2. Support Ethernet communication
- 3. Support high performance rigid disks
- 4. Support Low Speed Electronic Printer
- 5. Support Mesa Emulation
- 6. Support a number of slow devices

ws-constraints.bravo


Star Workstation Design Alternatives


- 1. Commercial LSI Microprocessors
- 2. Bus-Organized Distributed Systems
- 3. Custom LSI
- 4. Synchronous Multi-Tasking Microprocessors

ws-alternatives.bravo




Bus Organized Workstation Microprocessor







What Effect Micro-Instructions have on Microprocessors




Micro-Instruction




Micro-Sequence.sil



The Dandelion System



Workstation Configuration




February 26, 1980 Logic-Configuration.Sil RLB

Dandelion Chip Count

- 1. Memory and Memory Control Ram 88, Other 70, Total 158
- 2. 128K Storage Ram 176, Other 26, Total 202
- 3. Central Processor

 Control store 49, Other 118, Total 167
- 4. Input/Output Processor
 Ram 32, Prom 4, Floppy 27, Kbd 12, Other
 88, Total 163
- 5. High Speed I/O
 Clocks 19, Display 56, Disk 65, Total 140
- 6. Option Type I RS232 & LSEP 39, Ethernet (est) 55, Total 94

Workstation Development Environment



Workstation Design's Tasks

Bob Garner

ALU Desgin, Emulator microcode

Don Charnley

Ron Crane Memory system, Display controller, related microcode

Dan Davies

Disk Controllers, Xerox Wire Controller

Roy Ogus

Xerox Wire microcode

Dick Snow

Development tools environment

Don Charnley
Jim Frandeen

Microassembler Micorassembler

Pat Olmstead

LSEP interface microcode, printing application w/ Dandelion

Pitts Jarvis

LSEP controller

Roy Ogus

IOP

Neil Hansen Jim Cucinitti Model building, logics

Jim Peterson

Diagnostics and Field Service

Bob Belleville

Everything else

wd-tasks.sli

The Dandelion Empire

ТРМ		Hal Lazar/ Hans Scharmann	EL Segundo
Industrial Design		Robin Kincaid/ Claude Hutcheson	Dallas
Package		Dick Hanson & Allen Bell	Dallas
Power Supply		Avi Kandola EL Segun	
PWBA Manufacture		ED EL Segui	
Conponent Qual		ED EL Segu	
Other Engineering Support		ED	EL Segundo
Manufacture		Bill Powers	Dallas
Field Service		Art Johnson	EL Segundo
LSEP	TPM	John Michell	EL Segundo
	ROS	Joe Hruchak et al	Webster
	Engine	John Forester et al	Webster

I am sure there are more I haven't found yet.

dandellon-empire.sii

Workstation Design's

Tasks

Tom Chang Ethernet support

Don Charnley Microassembler, Design review

Jim Cucinitti Memory system mechanization, Tech. Support

Ron Crane Memory system, Display controller, related microcode

Dan Davies Disk Controllers

Bob Garner ALU Desgin, Emulator microcode, Ethernet controller

Neil Hansen Model building, Tech. Support

Pitts Jarvis Development tools (Burdock), LSEP controller

Roy Ogus IOP, IOP software, Maintenance panel

Pat Olmstead LSEP interface microcode, printing application w/ Dandelion

Dick Snow Development tools environment

Ken Yamanaka RS-232 controller Bob Belleville Everything else

KAR MARS Purchasing/Frpredite


wd-tasks.sil August 7, 1980


Development Time Schedule

1978	4th Quarter	October Study
1979	1st Quarter	February Study Begin design
	2nd Quarter	IOP up
	3rd Quarter	CP up Teals up
	4th Quarter	Display up Microcode based example programs
1980	1st Quarter	Disks up Logic design to mechanization
	2nd Quarter	Mesa up Some first etch under test
	3rd Quarter	Pilot up 3 EMs up
	4th Quarter	PPMs (6) Servers to field (2?)
1981	1st Quarter	200 machines
	2nd Quarter	
	3rd Quanter	1000 - to 1800 machines
	4th Quarter	

wd-timeline.sil August 7, 1980

- 1. Minimum hardware
- 2. Microcode to simulate the "Alto/Orbit"
- 3. Use whole machine during printing
- 4. Very limited bandwidth to the printer





All are ECL balanced pairs Receivers are MC10125 Transmitters are MC10124

MSEP should be the same; however, a Page Sync may have to be added to insure page registration.